



AbileneMachine®
Ag Replacement Parts

**FOR FORD®/NEW HOLLAND®
TRACTORS**







AbileneMachine.com



My Shed Feature on AbileneMachine.com

**Narrow down your parts search
specifically to your equipment**

Select the make, equipment and model of your machine in the dropdown menus located at the top of the home page. Then select a category or select "Any Category" to search all. Click the "Go" button.

SELECT YOUR EQUIPMENT  Search for parts 



Make*  Equipment Type* 





Models*  Categories  **GO**




ADD EQUIPMENT

To access your saved equipment
[Sign in](#)



SELECT YOUR EQUIPMENT  Search for parts 


Make*  John Deere  Equipment*  Tractor 

Model*  4440  Categories  **GO**



ADD EQUIPMENT

To access your saved equipment
[Sign in](#)

With your equipment selected, enter the product you are searching for (or part number if you have it). Suggested results will be displayed, or press enter to go to a list of all product results for your machine.

John Deere Tractor 4440  What part do you need today? 



John Deere Tractor 4440  **Seat Assembly** 


SUGGESTIONS


seat assembly
seat and suspension assembly
seat assembly with
grammer seat assembly
grammer seat and suspension assembly


CATEGORY


Seat & Suspension Assemblies
Seat Assemblies


PRODUCTS [VIEW ALL](#)


 **Grammer® Tractor Seat Assembly - Brown Matrix Fabric (AMSS11055)**
For Grammer Suspensions
OEM X-Reference number: undefined
\$ 847.00






 **Seat and Suspension Assembly (AMSS8093)**
Case®
Tractors - 1190, 1194, 1290, 1294, 1390, 1394, 1490, 1494, 1594, 1690...
OEM X-Reference number: 30-3050890, 30-3053350, 44907538, 533813M96, 81874576, 83982816, E9NN400AA, E9NN400AB99M, K307863
\$ 92.00
★★★★★


 **Grammer® Tractor Seat and Suspension Assembly for John Deere® (AMSS10078)**
John Deere® Tractors without IVT™ Transmission - 7200, 7210, 7400, 7410, 7510, 7600, 7610, 7630, 7700, 7710, 7720, 7730, 7800, 7810, 7820, 7830, 7920, 7930
OEM X-Reference number: undefined
\$ 1,470.00




MAKE 


☒ JOHN DEERE 






EQUIPMENT TYPE 


☐ BACKHOE-LOADER  1
☐ COMBINE  3
☐ COTTON HARVESTING  3
☐ SPRAYERS  3
☐ SWATHER  1
...



CATEGORY 


☐ SEAT & SUSPENSION ASSEMBLIES  6
☐ SEAT ASSEMBLIES  7
☐ SHOCK ABSORBERS  1



MODELS 


☐ 1020  2
☐ 1025R UTILITY  2
☐ 1025R UTILITY  2
☐ 1030  1
☐ 1040  1
...

CONDITION 


☐ NEW  12
☐ REMANUFACTURED  2

JOHN DEERE TRACTOR 4440  [Close All](#)


SORT BY: RELEVANCE  **14 RESULTS** [ITEMS PER PAGE: 12](#) 

 **SEAT ASSEMBLY, BROWN FABRIC FOR JOHN DEERE® TRACTOR (AMJD4240BRF)** **\$ 710.50** **ADD TO CART**

John Deere®
Tractors - 2010, 2350, 2355, 2510, 2520, 2550, 2555, 2750, 2755, 2855N, 2940, 2950, 2955, 3010, 3020, 3055, 3140, 3150, 3155, 3255, 4000, 4010,

 **SEAT ASSEMBLY, YELLOW VINYL FOR JOHN DEERE® TRACTOR, COMBINE AND SPRAYER (AMSS7896)** **\$ 453.50** **ADD TO CART**

John Deere®
Tractors - 2955, 3055, 3150, 3155, 3255, 4020, 4030, 4040, 4050, 4055, 4230, 4240, 4250, 4255, 4320, 4430, 4440, 4450, 4455, 4555, 4560, 4630,

 **DELUXE SEAT ASSEMBLY, BLACK FABRIC (AMSS72899)** **\$ 741.00** **ADD TO CART**



John Deere®
Tractors - 2010, 2350, 2355, 2510, 2520, 2550, 2555, 2750, 2755, 2855N, 2940, 2950, 2955, 3010, 3020, 3055, 3140, 3150, 3155, 3255, 4000, 4010,

With the My Shed feature, your equipment selections can now be saved to your account to make future searching convenient and easy!


Once you create an account to access "My Shed," your equipment can be saved and you can also view past order history. This makes yearly maintenance easier and faster when it comes to getting the parts you need.

To create an account, select the Account icon to the right of the search bar and select "Create an account."

Follow the next screen to enter your information and create the account. If you made an equipment selection in the parts search, it will automatically be added to "My Shed" and will also be viewable on your Account Dashboard. Additional equipment can be added by clicking the "Add Equipment" button from either screen (prompts the dropdown menu at the top to open again) or by going directly to the parts search at the top of the page and making a new selection. When you hit "Go," this selection is automatically added to your shed.



Quickly switch between equipment in your Shed by clicking the dropdown menu at the top of the page and selecting between machines. The page will reload to that selection and is ready to search for the products you need.



Abilene Machine LLC

Abilene, Kansas
Bishopville, South Carolina
Sioux Falls, South Dakota
Billings, Montana

785-670-6741 | AbileneMachine.com

Table of Contents

| | |
|--|-----|
| Ford®/New Holland®—Tractor | 3 |
| Air Cleaner Components | 42 |
| Air Conditioning and Components | 125 |
| Alternators | 42 |
| Axle Center Tubes and Beams | 77 |
| Axle Knee Extensions | 77 |
| Battery Box Components | 109 |
| Belts | 27 |
| Brake Components | 98 |
| Brake Shoes | 97 |
| Cab Components—Miscellaneous | 120 |
| Cab Doors | 120 |
| Camshafts and Lifters | 8 |
| Carburetors | 28 |
| Connecting Rods | 7 |
| Crankshaft Pulleys and Dampers | 7 |
| Crankshafts | 5 |
| Cylinder Heads, Bare | 9 |
| Differentials and Components | 95 |
| Distributors | 41 |
| Drawbars and Components | 100 |
| Engine Fans and Components | 22 |
| Fan Clutches | 26 |
| Fenders and Components | 110 |
| Flywheels and Components | 22 |
| Front Grilles, Nose Cones and Components | 110 |
| Fuel Components | 29 |
| Fuel Lift Pumps | 29 |
| Fuel Tanks | 125 |
| Gas Struts | 124 |
| Glass | 120 |
| Hammer Straps | 101 |
| Hydraulic Lift Components | 105 |
| Hydraulic Oil Coolers | 82 |
| Hydraulic Pumps | 82 |
| Hydrostats and Components | 87 |
| Injection Pumps | 29 |
| Injectors | 32 |
| Lift Link Assemblies and Components | 102 |
| Lighting | 111 |
| Longblock Assemblies | 3 |
| Lower Lift Links | 104 |
| Manifolds and Components | 35 |
| Manual Steering Gearbox Assemblies | 99 |
| Mechanical Front Wheel Drive Parts | 46 |
| MFWD Differentials and Components | 54 |
| MFWD Driveshafts | 57 |
| MFWD Hub Components | 51 |
| MFWD Hubs and Housings | 46 |
| Mufflers and Exhaust | 36 |
| Oil Cooler, Engine | 11 |
| Oil Pumps, Engine | 9 |
| Overhaul Kits | 3 |
| Power Steering Cylinders and Components | 78 |
| Power Steering Gearbox Assembly and Components | 99 |
| Power Steering Orbit Motors | 87 |
| Power Steering Pumps and Conversion Kits | 85 |

| | |
|---|-----|
| PTO Adapters | 97 |
| PTO Assembly Components | 92 |
| PTO Clutch Parts | 94 |
| PTO Gears | 97 |
| PTO Output Shafts | 96 |
| PTO Shafts and Hubs | 93 |
| Quick Hitch | 105 |
| Radiator Hoses | 14 |
| Radiators and Components | 11 |
| Rear Axles and Components | 95 |
| Remote Valves | 80 |
| Rockshaft Components | 102 |
| Sensors | 44 |
| Shop Manuals and Collections | 146 |
| Shortblock Assemblies | 3 |
| Side Panels and Hoods | 109 |
| Spindles | 65 |
| Starters | 39 |
| Steering Arms | 77 |
| Steering Shafts | 100 |
| Steering Wheels | 125 |
| Sway Blocks | 108 |
| Tachometers and Instrument Clusters | 45 |
| Three Point Hitch Components | 104 |
| Tie Rods and Components | 58 |
| Toplink Assemblies | 108 |
| Transmission Components | 87 |
| Transmission Discs | 92 |
| Turbochargers | 33 |
| Water Pumps and Components | 22 |
| Wheel Bearing Kits | 70 |
| Wheel Hubs and Components | 69 |

Ford®/New Holland®—Tractor

Longblock Assemblies

| Description | Part Number | Retail Price | Core |
|---|------------------|--------------|-------------|
| Application: 8970, 8970A | | | |
| Reman Longblock Assembly Replaces 87800718BR | LBFD456T8970 | \$ 8,900.00 | \$ 2,500.00 |
| Application: TG215, TG275, TG305, T8010, T8020, T8030, T8040, Versatile® Tractors: 250, 305 | | | |
| Reman Longblock Assembly | LBCUM8304HPCR24V | \$ 11,000.00 | \$ 2,000.00 |
| Application: Ind: (345C, 445C, 545C - 12/1988-08/92 w/ 3 Cylinder Engine), (345D, 445D - 09/1992-10/2000 w/ 3 Cylinder Engine), 545D 11/1988-2001 w/ 3 Cylinder Engine | | | |
| Longblock Assembly | AM87801544 | \$ 3,750.00 | \$ 1,000.00 |
| Application: Combines: CR9040, CR9060 | | | |
| Reman Longblock Assembly Replaces 87603080, 87603080R | LBCUM8.9 | \$ 12,500.00 | \$ 5,000.00 |
| Application: T6010, TS100A | | | |
| Reman Engine, Complete 4.5 Liter NF 45 | AM87318785ER | \$ 8,500.00 | \$ 2,500.00 |
| Application: T6030 | | | |
| New Engine, Complete 6.7 Liter NEF 67 Replaces 50427568ER | AM87318901ER | \$ 11,000.00 | \$ 5,000.00 |
| Application: T6030, T6050, T6070, T6080 | | | |
| New Engine, Complete 6.7 Liter NEF 67 Replaces 87312077ER, 87516256ER | AM87312078ER | \$ 12,500.00 | \$ 5,000.00 |
| Application: 7840, 8240, 8340, TS115 | | | |
| New Engine, Complete Emission Engine Replaces 87800805, 87801845, 87840842 | AM87802221 | \$ 12,500.00 | \$ 5,000.00 |
| Application: Combines: (CR9040, CR9060, CR9065, CR9070 BSN Y8G112001) | | | |
| New Engine, Complete 10.3 Liter Iveco® Replaces 87283632 | AM504099224 | \$ 17,500.00 | \$ 7,500.00 |

Shortblock Assemblies

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 3230, 3430, 3930, 4130, 4630 - w/ 201 Ford® Engine | | | |
| Shortblock Assembly Includes cam gear, timing gears and steel timing plate | AM87800041 | \$ 4,100.00 | \$ 500.00 |

Overhaul Kits

| Description | Part Number | Retail Price | Core |
|--|-----------------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| 120 Engine - Gas 0.04" Wall Thickness | Inframe Kit AMOH1162 | \$ 286.00 | |
| | Overhaul Kit AMOH1163 | \$ 297.00 | |
| 120 Engine - Gas 0.09" Wall Thickness | Inframe Kit AMOH1164 | \$ 286.00 | |
| | Overhaul Kit AMOH1165 | \$ 297.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Overhaul Kits (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------------|--------------|------|
| Application: 600 & 700 Series, NAA | | | |
| 134 Engine - Gas | Inframe Kit AMOH1166 | \$ 485.00 | |
| | Overhaul Kit AMOH1167 | \$ 440.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 3000, 3055, 3100, 3120, 3190, 3330, 3400, 3500, 3550 | | | |
| 158 Engine - Gas | Inframe Kit AMOH1170 | \$ 668.00 | |
| | Overhaul Kit AMOH1171 | \$ 584.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310 | | | |
| 158 Engine - Diesel | Inframe Kit AMOH1168 | \$ 463.00 | |
| | Overhaul Kit AMOH1169 | \$ 537.00 | |
| Application: 800, 900, 1800 & 4000 Series | | | |
| 172 Engine - Gas Non-Sleeved | Inframe Kit AMOH1176 | \$ 451.00 | |
| | Overhaul Kit AMOH1177 | \$ 474.00 | |
| Application: 800, 900, 1800 & 4000 Series - 1958-81 | | | |
| 172 Engine - Diesel Non-Sleeved | Inframe Kit AMOH1172 | \$ 776.00 | |
| | Overhaul Kit AMOH1173 | \$ 838.00 | |
| 172 Engine - Diesel Sleeved | Inframe Kit AMOH1174 | \$ 679.00 | |
| | Overhaul Kit AMOH1175 | \$ 696.00 | |
| Application: 3000, 3100, 3110, 3120, 3150, 3190, 3300, 3310, 3330, 3400, 3500 | | | |
| 175 Engine - Diesel | Inframe Kit AMOH1180 | \$ 456.00 | |
| | Overhaul Kit AMOH1181 | \$ 485.00 | |
| Application: 4000, 4100, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4500 - 1965-68 | | | |
| 192 Engine - Gas | Inframe Kit AMOH1184 | \$ 662.00 | |
| | Overhaul Kit AMOH1185 | \$ 668.00 | |
| Application: 3610, 3910 | | | |
| 192 Engine - Diesel | Overhaul Kit AMOH1183 | \$ 531.00 | |
| Application: 4000, 4100, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500 | | | |
| 201 Engine - Diesel 01/1965-05/69 | Inframe Kit AMOH1186 | \$ 491.00 | |
| | Overhaul Kit AMOH1187 | \$ 543.00 | |
| Application: 4000, 4100, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, Ind: 515, 530A, 531, 532, 535, 540A, 540B, 545, 545A, Backhoe-Loaders: 550, 555, 555A, 555B | | | |
| 201 Engine - Diesel 06/1969-12/74 | Inframe Kit AMOH1188 | \$ 405.00 | |
| Application: 5000, 5100, 5190, 5200, 5500, 5600, 5700 | | | |
| 233 Engine - Diesel | Inframe Kit AMOH1190 | \$ 600.00 | |
| | Overhaul Kit AMOH1191 | \$ 702.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Overhaul Kits (...continued)

| Description | Part Number | Retail Price | Core |
|--|-----------------------------|--------------|------|
| Application: 5000, 5100, 5190, 5200, 5340, 5600, 5610, 5900, 6600, 6700, Ind/Const: 5500, 5550, 6500, Swathers: 907, 909, 910, 912, 1100, 1112, 1114, Mower Conditioner: 1495 | | | |
| 256 Engine - Diesel | Inframe Kit AMOH1192 | \$ 582.00 | |
| | Overhaul Kit AMOH1193 | \$ 600.00 | |
| Application: 7000, 7100, 7200, 7500, 7600, 7700 | | | |
| 256T Engine - Diesel | Inframe Kit AMOH1194 | \$ 600.00 | |
| | Overhaul Kit AMOH1195 | \$ 679.00 | |
| Application: 5610S, 5640 | | | |
| 268 Engine - Diesel 09/1990-07/96 | Inframe Kit AMOH1198 | \$ 633.00 | |
| | Overhaul Kit AMOH1199 | \$ 696.00 | |
| Application: 6610, Ind: 655C, 655D | | | |
| 268 Engine - Diesel | Major Overhaul Kit AMOH1646 | \$ 689.00 | |
| Application: 6810, 7610, 7710, Ind: 755B | | | |
| 268T Engine - Diesel | Major Overhaul Kit AMOH1645 | \$ 884.00 | |
| Application: 3610, 3910 | | | |
| 192 Engine - Diesel | Inframe Kit AMOH1182 | \$ 423.00 | |

Crankshafts

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Crankshaft | AM9N6303A | \$ 445.00 | |
| Application: 650, 5000 Major, 5000 Super Major, 5000, 5100, 5190, 5200, 5500, 5600, 5610, 5700, 6000, 6500, 6600, 6610, 6700, 6710, 7000, 7100, 7200, 7500, 7600, 7610, 7700, 7710, Combines: 620, 622 Replaces 1595N, 6110A | | | |
| Crankshaft w/ Gear BSD442 4.2 Stroke 256 CID 4.2 Liter 4 Cylinder Engine 4.203" Stroke, 4.4007" - 4.4032" Bore, 2.7496" - 2.7504" Rod, 3.3713" - 3.3723" Main Flange - Centering Ring, 6 Bolt Holes, 1 Dowel Hole Snout - 1 Bolt Hole, 1 Keyway, w/ 78 Tooth Balance Drive Gear 12.50 mm Wide, Right Hand Helix | AMC5NE6303K | \$ 561.00 | |
| Application: 801, 901, 1801, 4000 Series Replaces B9NN6302B | | | |
| Crankshaft 172D 172 CID 2.8 Liter 4 Cylinder Diesel Engine 3.60" Stroke, 3.8998" - 3.9018" Bore, 2.2978" - 2.2988" Rod, 2.4978" - 2.4988" Main Flange - No Centering Ring, Flat, 6 Bolt Holes, 1 Dowel Hole Snout - Splined, 1 Keyway, w/ 74 Tooth Straight Balance Gear Replaces B9NN6302B | AMEZIL6300BA-2 | \$ 828.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2610, 2910, 3000, 3000 Super Dexta, 3055, 3100, 3110, 3120, 3150, 3190, 3230, 3300, 3310, 3330, 3350, 3600, 3610, 3900, 3910, (4100, 4110, 4130, 4140, 4200, 4330, 4400, 4410, 4500, 4600, 4610, 4630 - w/ Gas), Ind: 230A, 234, 333, 335, 336, 340, 340A, 445, 450, 3400, 3550 | | | |
| Crankshaft BSD329, D175, D183, D192 - 3 Cylinder Engines 4.200" Stroke, 4.200" Bore, 2.7496" - 2.750" Rod, 3.3713" - 3.3723" Main Flange - Centering Ring, 6 Bolt Holes, 1 Dowel Hole Snout - Keyed, 1 Bolt Hole | AME0NN6303AA | \$ 475.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Crankshafts (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------------|--------------|------|
| Application: 3930, 3930H, 3930N, 3930NO, 4000, 4000 Major, 4100, 4110, 4130, 4130N, 4130NO, 4140, 4190, 4200, 4330, 4340, 4410, 4600, 4600SU, 4610, 4610SU, 4630, Ind: 260C, 455C, 455D, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 555, 555A, 555B Replaces C5NE6303N, E5NN6306N | | | |
| Crankshaft BSD333 4.4 Stroke 201 CID 3.3 Liter 3 Cylinder Engine 4.400" Stroke, 4.4007" - 4.4032" Bore, 2.7496" - 2.7504" Rod, 3.3713" - 3.3723" Main Flange - 6 Bolt Holes, 1 Dowel Hole, Centering Ring Snout - Keyed, 1 Bolt Hole | AMF0NN6303MA | \$ 545.00 | |
| Application: 6000, 6600, 6610, 6700, 7000, 7100, 7200, 7600, 7610, 7700, 7710 Replaces D5NN6303FA, D9NN6110AA, D9NN6303A, D9NN6303AA, E5NN6303CA | | | |
| Crankshaft w/ Gear BSD444 268 CID 4.4 Liter 4 Cylinder Engine 4.400" Stroke, 4.4007" - 4.403" Bore, 2.7496" - 2.7504" Rod, 3.3713" - 3.3723" Main Flange - Centering Ring, 6 Bolt Holes, 1 Dowel Hole Snout - 1 Bolt Hole, 1 Keyway, w/ 76 Tooth Balance Drive Gear 15.00 mm Wide, Right Hand Helix | AME5NN6303DA-76-2 | \$ 505.00 | |
| Application: 6000, 6600, 6610, 6700, 7000, 7100, 7200, 7600, 7610, 7700, 7710 Replaces 1598N, D5NN6303FA, D9NN6110AA, D9NN6303A, D9NN6303AA, E5NN6303CA | | | |
| Crankshaft w/ Gear BSD444 268 CID 4.4 Liter 4 Cylinder Engine 4.400" Stroke, 4.4007" - 4.403" Bore, 2.7496" - 2.7504" Rod, 3.3713" - 3.3723" Main Flange - Centering Ring, 6 Bolt Holes, 1 Dowel Hole Snout - 1 Bolt Hole, 1 Keyway, w/ 78 Tooth Balance Drive Gear 12.50 mm Wide, Right Hand Helix | AME5NN6303DA-2 | \$ 495.00 | |
| Application: T6030, T6050, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7.170, T7.185, T7.200, T7.210, T7.220, T7.235, T7.250, T7.260, T7.270, TS125A, TS130A, TS135A Replaces 2830398, 2831071, 2831402, 2856281, 2856282, 2859446, 504347348 | | | |
| Crankshaft 6.7 Liter Mechanical Injection Engine | AM504203869 | \$ 1,650.00 | |
| Application: (T9030, T9040, T9050 ASN Z7F204001), TJ380, TJ430 | | | |
| Crankshaft Cursor 13 Engine | AM99438979 | \$ 2,750.00 | |

Ford®/New Holland®—Tractor

Connecting Rods

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|----------|
| Application: 455, 550, 555, 655, 3230, 3930, 4130, 4630, 5030, 5110, 5610, 5640, 5900, 6410, 6610, 6640, 6710, 6810, 7000, 7410, 7600, 7610, 7810, 7910, 8210, 8240, 8260, 8340, 8530, TS115 | | | |
| Connecting Rod Bushing end is straight not tapered 4.40" Bore, 1.49" Pin Diameter Replaces 81875622, 83958631, 83972114 | AM87801218 | \$ 122.70 | |
| Application: 3230, 3430, 3610, 3910, 3930, 4000, 4110, 4120, 4130, 4140, 4330, 4340, 4600, 4610, 4630, 4830, 5000, 5030, 5100, 5600, 5900, 6600, 6700, 6710, 7910, 8000, 8210, 8530, 8600, 8700, TW5, TW10 - w/ 192, 201, 233, 256, 268 or 401 Engine | | | |
| Connecting Rod 1.50" Pin Diameter | AMC7NN6205 | \$ 100.00 | |
| Application: 7000, 7100, 7200, 7400, 7600, 7700, 7710, 8630, 8730, 8830, 9000, 9600, 9700, TW15, TW20, TW25, TW30, TW35 - w/ 256T, 268T or 401T Engine | | | |
| Connecting Rod w/ Flat Wrist Pin, 1.625" Pin Diameter | AM87801220 | \$ 90.00 | |
| Application: 9000, 9600, TW20, TW30, TW35 | | | |
| Reman Connecting Rod 1.50" Pin Diameter | AMCR6205S-R | \$ 185.00 | \$ 30.00 |
| Reman Connecting Rod 1.625" Pin Diameter | AMCR6205L-R | \$ 185.00 | \$ 40.00 |
| Application: Genesis Engine | | | |
| Reman Connecting Rod w/ Tapered Wrist Pin, 1.625" Pin Diameter | AMCR6205LGEN-R | \$ 185.00 | \$ 40.00 |
| Application: T8050, T9020, TJ325 w/ 6TAA-9004 Engine, TJ330, Combines: (CR9040, CR9060 BSN Y8G112001) | | | |
| Connecting Rod Bolt Replaces J944679 | AM3944679 | \$ 3.00 | |

Crankshaft Pulleys and Dampers

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 7910, 8210, 8530, 8630, 8730, 8830, 9700, TW5, TW10, TW20, TW25, TW30, TW35 | | | |
| Crankshaft Damper Pulley 3-Groove | AMD8NN6316AC | \$ 274.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 - w/ 6CT, 6CTA, 6CTAA or QSC 8.3 Liter Cummins® Engine | | | |
| Crankshaft Damper Pulley Replaces 87773050, J910907, J914456 | AMJ925570 | \$ 97.00 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Crankshaft Damper Pulley 2.24" Thick, 0.95" ID, 9.67" OD Replaces 39255568, J910907, J914456 | AMJ925568 | \$ 128.00 | |
| Application: TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Crankshaft Damper Pulley 10 Spline, 13.701" OD, 1.575" Spline Diameter Replaces 5187845 | AM87304267 | \$ 375.50 | |

Ford®/New Holland®—Tractor

Camshafts and Lifters

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: 401 Engine | | | |
| Camshaft 6 Cylinder | AM87802904 | \$ 200.00 | |
| Application: 8N w/ Side Mount Distributor | | | |
| Camshaft | AM8N6250 | \$ 179.00 | |
| Application: 501, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, 1801, 1811, 1821, 1841, 1871, 1881, 2000 Series, 4000 Series, NAA - w/ 4 Cylinder 134/172 Gas Engine | | | |
| Camshaft and Reman Lifters Kit Includes New Camshaft and Reman Lifters | AMC0NN6251A-K | \$ 405.00 | |
| Lifter | AMF3JL6500AA | \$ 8.00 | |
| Application: 2000, 2600, 2610, 3000, 3055, 3100, 3400, 3500, 3550, 3600, 3610, 3900, 3910, 4000, 4100, 4110, 4140, 4200, 4400, 4410, 4500, 4600, 4610, Ind: 335, 340, 420, 515, 532, 535, 545, 550, 555 | | | |
| Camshaft 3 Cylinder | AM87800323 | \$ 110.00 | |
| Application: 4230, 4430, 4835, 5635 | | | |
| Camshaft Includes Gear, Key and Thrust Plate | AM98425868 | \$ 2,101.00 | |
| Application: 5000, 5100, 5200, 5590, 5600, 5610, 6600, 6610, 6700, 6710, 7200, 7600, 7610, 7700, 7710, Ind: 650, 655, 750, 755, 5500, 6500, 7500 | | | |
| Camshaft 4 Cylinder Replaces 84157722 | AM87800353 | \$ 90.00 | |
| Application: Versatile®: 276 | | | |
| Camshaft 3.9 Cummins® Engine | AMJ929039 | \$ 95.00 | |
| Application: Most 3 Cylinder, 4 Cylinder and 6 Cylinder Engines | | | |
| Lifter | AMC7NN6500B | \$ 8.00 | |
| Application: TG210, TG230 | | | |
| Push Rod 8.3 Cummins® Engine | AMJ905194 | \$ 10.25 | |

Ford®/New Holland®—Tractor

Cylinder Heads, Bare

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Cylinder Head, Bare Replaces 8N6050 | AM9N6050 | \$ 235.00 | |
| Valve Train Kit Free Rotating Valves For Engines w/ Adjustable Lifters Includes (4) Rotating Exhaust Valves, (4) Intake Valves, (8) 1-Piece Solid Guides with Guide Seals, (8) Springs, (4) Intake Spring Retainers, (4) Exhaust Spring Retainers, (4) Lash Caps, (8) Guide Locking Clips and (16) Valve Lock Keepers | AMVK1000 | \$ 180.00 | |
| Application: 501 Series, 600 Series, 601 Series, 700 Series, 701 Series, 800 Series, 801 Series, 900 Series, 901, 1801 Series, 2000 Series, 2100, 4000 Series, Golden Jubilee, NAA, NAB, Swathers: 907, 909 | | | |
| Valve Train Kit Includes (4) Intake Valves, (4) Free-Rotating Exhaust Valves, (16) Valve Keepers, (8) Valve Springs and (8) Valve Guides | AMVK1029 | \$ 107.00 | |
| Application: 801 Series, 901, 1801 Series, 4000 Series | | | |
| Valve Train Kit | AMVK1021 | \$ 154.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3190, 3230, 3300, 3310, 3430, 3550, 3600, 3610, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, Indl/Const: 230A, 231, 233, 234, 250C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 455, 515, 530A, 531, 532, 535, 540, 540A, 545, 545A, 550, 555, 555A | | | |
| Valve Train Kit Includes (3) Exhaust Valves*, (3) Intake Valves**, (6) Valve Springs, (6) Valve Spring Retainers, (6) Valve Spring Retainer Sleeves, (12) Valve Keepers and (6) Valve Seals *5.766" Long, 45° **5.746" Long, 45° | AMVK1045 | \$ 144.00 | |
| Application: TG210, TG230, Power Units: SE190, SE215, SE240 | | | |
| Valve Train Kit Includes (6) Intake Valve, (6) Exhaust Valve, (24) Valve Keeper, (12) Valve Spring, (12) Valve Guide For C8.3, 6CT8.3, 6CTA8.3, 6CT8.3M, 6CTA8.3M and 6CTA8.3F Engine | AMVK1024 | \$ 220.00 | |

Oil Pumps, Engine

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 600, 700, 800, 900 Series - w/ 4 Cylinder Engine | | | |
| Engine Oil Pump Hex Drive, Gear Type Output Mounting Flange Has Square Opening | AMEAE6621AB | \$ 61.00 | |
| Application: 501, 601, 701, 801, 901, (2000, 4000 - w/ 4 Cylinder Engine) | | | |
| Engine Oil Pump Hex Drive, Roto Type Output Mounting Flange Has Slotted Opening | AMD1NL6600A | \$ 180.00 | |
| Application: (2000, 3000, 4000, 5000 1965-75), (2600, 3600, 3900, 4600, 5600, 6600 1975-81), (2310, 2610, 2810, 2910, 3910, 4110, 4610 1981-10/91), (3230, 3430, 3930, 4130, 4930, 4830, 5030 3/90-5/94), Ind: 230A, 231, 233, 234, 333, 334, 335, 420, 515, 530A, 531 | | | |
| Engine Oil Pump Replaces E1NN6600DA, E1NN6600DB, E1NN6600DC | AME1NN6600DD | \$ 66.00 | |
| Application: 4630, 5030, 7000 Series 10/71 and Later, (7600, 7700 - 1975-81), Swather: 1118 | | | |
| Engine Oil Pump Replaces E1NN6600CB | AME1NN6600CC | \$ 70.00 | |
| Application: 6640, 7740 - w/ 340 or 304T Engine | | | |
| Engine Oil Pump | AM81868537 | \$ 115.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Oil Pumps, Engine (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 7810, 9700 | | | |
| Engine Oil Pump Replaces E7NN6600AA | AM83961087 | \$ 249.00 | |
| Application: 7840, 8240, 8340 - w/ 401 or 456 Engine | | | |
| Engine Oil Pump | AME9NN6600BB | \$ 110.00 | |
| Application: 8630, 8730, 8830, TW15, TW20, TW25, TW30, TW35 - w/ Turbo Engines Only | | | |
| Engine Oil Pump Replaces D8NN6600AJ | AM87840275 | \$ 380.00 | |
| Application: 8700 | | | |
| Engine Oil Pump | AME1NN6600BC | \$ 126.00 | |
| Application: 9700 | | | |
| Engine Oil Pump Replaces 81826405, 83961087 | AMD1NN6600A | \$ 220.60 | |
| Application: Dexta, Super Dexta - w/ Perkins® 144 CID or 152 CID Engine | | | |
| Engine Oil Pump Replaces 957E6600C, 41314078 | AM41314187 | \$ 80.50 | |
| Application: T8010, T8020, T8030, T8040 | | | |
| Engine Oil Pump | AM3991123 | \$ 217.00 | |
| Application: TG210, TG230, TG255, TG285, TJ275, TJ325, TJ450 | | | |
| Engine Oil Pump Replaces 3948072, 87775216, J942723 | AMJ948072 | \$ 235.00 | |
| Application: Swathers: HW305, HW305S, HW325 - w/ N45 Fiat® Diesel Engine | | | |
| Engine Oil Pump | AM4897480 | \$ 219.00 | |
| Application: 2000, 2100, 3000, 3100, 3400, 3500, 4000, 4110, 4400, 4500, 5000, Ind: 3550, 5500, 5550 | | | |
| Oil Filter Adapter Kit Spin-On, Pre-Assembled O-Ring Not Included Replaces 309825F, 1821119, DBPN309825 | AM309825 | \$ 40.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, TG215, TG245, TG275, TG305, (TJ275, TJ325 - w/ 6TAA-8304 or 6TAA-9004 Engine), TJ280, Combines: CR9040, CR9060 BSN Y8G112001) | | | |
| Gasket, Oil Pump Pickup Tube Replaces 3914302, 87775049, A77583, J908540, J914302 | AM87447959 | \$ 4.00 | |

Ford®/New Holland®—Tractor

Oil Cooler, Engine

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 5610S, 6610S, 7610S, TS6020, TS6030 | | | |
| Oil Cooler N45 Fiat® Diesel, 5 Fins | AM2853722 | \$ 102.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, TM125, TM135, TM150, TM165, Combines: TR87, TR88, TR89, TR98 | | | |
| Oil Cooler Replaces E9HN6A640AA | AM87380919 | \$ 788.75 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, TJ280, TJ330 | | | |
| Oil Cooler 8.9 Cummins®, 14 Fins | AM87452245 | \$ 215.00 | |
| Application: T9.450, T9.505, T9.560 | | | |
| Oil Cooler Replaces 504221052 | AM5802247668 | \$ 435.68 | |

Radiators and Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Radiator Overall: 16 1/2" x 23 1/2" Core: 15 3/8" x 17" x 2" Replaces 86551430 | AM8N8005 | \$ 185.00 | |
| Application: 250C, 260C, 532 w/ Torque Conversion 1975-07/81, (2000, 4000 - w/ 3 Cylinder Engine w/ Oil Cooler), (2100, 2110, 2120, 2300, 2310, 3000, 3055, 3100, 3110, 3120, 3150, 3190, 3300, 3310, 3330, 3400, 4100 - 1965 and Later), Ind/Const: (340A, 340B, 540A, 540B - 08/1981 and Later), 420 w/ Torque Conversion 1975-07/81, 445 Prior to 09/1978, 540 Prior to 07/1981, (3500, 3550, 4400 - 1965 and Later) | | | |
| Radiator Overall: 19" x 22 1/2"* Core: 17 1/4" x 16" x 2" 3 Rows, 8 Fins per Inch *Overall Height Does Not Include Filler Neck Oil Cooler Ports Are on the Grille Side Replaces 82847505, C5NN8005J, C5NN8005T, E1NN8005AB15M | AMD8NN8005PA | \$ 250.00 | |
| Application: 5000, 5100, 5600, 6600 - w/o Oil Cooler | | | |
| Radiator Overall: 18 3/4" x 24" Core: 18" x 17 3/4" x 1 3/4" 3 Rows, 9 Fins per Inch Replaces C5NN8005N, D6NN8005A, D6NN8005B | AMC7NN8005E | \$ 217.00 | |
| Application: 600, 700, 800, 900, 2000, 4000, NAA - w/ 4 Cylinder Engine | | | |
| Radiator Overall: 17 5/8" x 24" Core: 17 1/4" x 17 1/2" x 2" 3 Rows, 8 Fins per Inch | AMC5NN8005AB | \$ 215.00 | |
| Application: 2000, 2100, 2120, 2300, 2600, 2610, 3000, 3100, 3400, 3550, 3600, 3610, 3900, 3910, 4000, 4110, 4140, 4400, 4410, 4600, 4610 | | | |
| Radiator Overall: 19" x 22 1/2" x 17 3/8" Core: 16" x 2" 3 Rows, 9 Fins per Inch | AMC7NN8005H | \$ 200.00 | |

Ford®/New Holland®—Tractor

Radiators and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|------|
| Application: 2600, 3600, 4100, 4600, 5600, 6600, 6700, 7600, 7700 - w/ Oil Cooler | | | |
| Radiator Overall: 18 3/4" x 24 1/4"* Core: 18" x 17 3/4" x 2 3/4" 4 Rows, 9 Fins per Inch *Overall Height Does Not Include Filler Neck Oil Cooler Ports Are on the Engine Side | AMD5NN8005A | \$ 481.00 | |
| Application: 3230, 3430, 3930, 3930H, 3930N, 4130, 4130N, 4630, 4630N, 4630NO, 4630O - 1990 and Later | | | |
| Radiator Overall: 19" x 21 1/2"* Core: 18" x 16" 3 Rows, 8 Fins per Inch *Overall Height Does Not Include Filler Neck | AME9NN8005AB15M | \$ 260.00 | |
| Application: 5640, 6640 - w/ or w/o A/C | | | |
| Radiator Core: 19 1/8" x 20 1/8" x 3" 5 Rows, 8 Fins per Inch | AM82015101 | \$ 560.00 | |
| Application: 5700, 6700 - 1976 and Later w/ Cab | | | |
| Radiator Overall: 21 11/16" x 25 7/8"* Core: 19 3/4" x 19 15/16" 3 Rows, 7 Fins per Inch *Overall Height Does Not Include Filler Neck | AMD6NN8005D | \$ 595.00 | |
| Application: 6710, 7700, 7710 | | | |
| Radiator Replaces E1NN8005EA15M, D8NN8005LA15M, D6NN8005SF | AME1NN8005EB15M | \$ 595.00 | |
| Application: (5110, 6410, 7410 - w/o A/C), 5610, 6610, (6810, 7610 - w/o A/C and w/o Viscous Fan) | | | |
| Radiator Oil Cooler Ports are on the Engine Side | AME7NN8005BA | \$ 534.50 | |
| Application: 7000, 7100, 7200 | | | |
| Radiator Core: 18" x 17 3/4" x 2 3/4" Oil Cooler Ports are on the Engine Side | AMD3NN8005B | \$ 305.00 | |
| Application: 7910, 8210 - 1982 and Later | | | |
| Radiator w/o Cooler | AME1NN8005BD15M | \$ 868.50 | |
| Application: 8530, 8630, TW5, TW10, TW15, TW20 | | | |
| Radiator Replaces E3NN8005BD15M, E3NN8005AD15M | AM82847503 | \$ 925.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8970, 8970A | | | |
| Radiator Core: 26.875" x 27.50" x 3.50" | AM86013980 | \$ 1,750.00 | |
| Application: 8730, 8830, TW25, TW35 - w/ Oil Cooler | | | |
| Radiator Core: 22 1/8" x 25" x 2 3/4" 4 Rows, 11 Fins per Inch | AME3NN8005DE15M | \$ 911.50 | |

Ford®/New Holland®—Tractor

Radiators and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|------|
| Application: 8830, TW30, TW35 | | | |
| Radiator w/o Hydraulic Oil Cooler Overall: 24 9/16" x 31"* Core: 22" x 25" 4 Rows, 10 Fins per Inch *Overall Height Does Not Include Filler Neck | AME3NN8005CE15M | \$ 775.00 | |
| Application: PowerStar™ 65, PowerStar™ 75, T4020, T4030, T4040, T4050, T4.55K, T4.65, T4.75 w/ PowerStar™, T5040, T5050, T5060, T5070 | | | |
| Radiator | AM87335352 | \$ 675.00 | |
| Application: PowerStar™ 90, PowerStar™ 100, PowerStar™ 120, T4.75, T4.85, T4.90, T4.95, T4.100, T4.105, T4.110, T4.115, T4.120, T5.90, T5.100, T5.110, T5.120, Workmaster 95, Workmaster 105, Workmaster 120 | | | |
| Radiator Overall: 20.50" x 20.4375" x 5.25" | AM84271052 | \$ 650.00 | |
| Application: T2310 | | | |
| Radiator Core: 17 5/8" x 16 3/4" x 1 7/8" | AM87305450 | \$ 458.00 | |
| Application: T6030, T6050, T6070, T6080 | | | |
| Radiator Aluminum Core: 20.72" x 23.44" x 4.80" 4 Rows, 4.80 Fins per Inch Replaces 84160716, 87575998, 87737096 | AM87575996 | \$ 1,110.00 | |
| Application: (T6030, T6050, T6070, T6080 BSN Z*BK40000) | | | |
| Radiator 6 Rows Replaces 87575996, 87575998, 87737096 | AM87737098 | \$ 1,011.90 | |
| Application: T6070 | | | |
| Radiator | AM87574213 | \$ 908.00 | |
| Application: T8030, T8040, T8050, TG275, TG305 | | | |
| Radiator Core: 20" x 31.50" x 4" 6 Rows, 7 Fins per Inch | AM87448824 | \$ 1,233.50 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D | | | |
| Radiator Core: 21.375" x 18" x 2.375" Replaces 5093940, 5096063, 5096073, 5096595, 5099122 | AM84172100 | \$ 664.40 | |
| Application: TM120, TM130 | | | |
| Radiator Overall: 31" x 22 1/4" Core: 22 1/8" x 21" x 4" | AM87352188 | \$ 1,231.50 | |
| Application: TM140, TM155, TS115A, TS125A, TS135A | | | |
| Radiator Overall: 31" x 22 1/4" Core: 23 1/2" x 20 1/2" x 5" There is a 5/8" heater bypass connection to the right of the outlet connection | AM87352191 | \$ 1,139.50 | |
| Application: TM175, TM190 | | | |
| Radiator Core: 21 1/4" x 27 3/4" x 5" 7 Rows, 7 Fins per Inch Outlet is left of center Replaces 82033525, 82033792, 82038688, 87306754 | AM87352193 | \$ 1,050.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiators and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: TS115A, TS125A, TS135A | | | |
| Radiator Outlet is right of center, 3/8" vent tube on top of tank, 5/8" vent tube on bottom of tank Replaces 82033774 | AM87306756 | \$ 1,489.50 | |
| Application: Workmaster 65, Workmaster 75 | | | |
| Radiator | AM87480079 | \$ 870.00 | |
| Application: Utility: 1530, 1630, 1725, 1925, TC25, TC25D, TC29, TC29D, TC29DA, TC33, TC33D, TC33DA | | | |
| Radiator Core: 15.50" x 15.75" x 1.75" Includes Bracket for Shield Screen w/ Remote Drain | AM86402723 | \$ 595.00 | |
| Application: Utility: T2210, T2220, TC31DA, TC34DA | | | |
| Radiator Core: 17.625" x 14.875" x 1.75" 2 Rows, 10 Fins per Inch | AM87305451 | \$ 415.00 | |
| Application: Utility: T2320, T2330, TC45A, TC45DA | | | |
| Radiator Core: 17.625" x 16.75" x 2.25" 2 Rows, 10 Fins per Inch | AM87305449 | \$ 539.00 | |
| Application: Utility: TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA | | | |
| Radiator Core: 17 3/8" x 14 3/4" 3 Rows Includes Cap Replaces 86400443, 86401465, 86402465 | AM86402724 | \$ 469.00 | |
| Application: Workmaster 55, Workmaster 65, Workmaster 75 | | | |
| Fan Shroud | AM87757220 | \$ 20.25 | |
| Application: T9.615, T9.670 | | | |
| Charge Air Cooler | AM84286668 | \$ 2,390.00 | |
| Application: (3010S, 3230, 3830 Orchard, 4010S, 4030 Orchard, TT55, TT60A, TT65 - w/ 3 Cylinder Engine), (4230 Orchard, 4330V, 4430 Orchard, 5010S, 5530, 6530, TT45A, TT50A, TT75, TT75A, Workmaster 55, Workmaster 65, Workmaster 75 - w/ 4 Cylinder Engine), 4835, 5635, 6635, 7635, 8160, 8260, 8360, 8560, (8830, TV140, Workmaster 45 - w/ 6 Cylinder Engine), L65, PowerStar™ 65, PowerStar™ 75, T4020, T4020V, T4030, T4030F, T4030N, T4030V, T4040, T4040F, T4040N, T4040V, T4050, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T4.55, T4.65, T4.65V, T4.75, T4.75F, T4.75V, T4.85F, T4.85V, T4.95F, T4.95V, T4.105F, T4.105V, T5040, T5050, T5060, T5070, TD60D, TD70D, TD75D, TD80D, TD85F, TD90D, TD95D, TD4020F, TD4030F, TD4040F, TD5010, TD5020, TD5030, TD5050, TD4.90F, TL70, TL80, TL80A, TL90, TL90A, TL100, TL100A, TM115, TM125, TM135, TM150, TM165, TN55, TN55D, TN55S, TN60A, TN60DA, TN60SA, TN60VA, TN65, TN65D, TN65F Orchard, TN65S, TN65V, TN70, TN70A, TN70D, TN70DA, TN70F Orchard, TN70NA, TN70S, TN70SA, TN70VA, TN75, TN75A, TN75D, TN75DA, TN75F Orchard, TN75FA, TN75S, TN75SA, TN75V, TN75VA, TN80F Orchard, TN85A, TN85DA, TN85FA Orchard, TN85SA, TN90F Orchard, TN95A, TN95DA, TN95F Orchard, TN95FA Orchard, TN95NA, TN95VA, Workmaster 75 | | | |
| Rubber Mount | AM5108225 | \$ 9.00 | |

Radiator Hoses

| Description | Part Number | Retail Price | Core |
|----------------------------------|-------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Radiator Hose, Upper 1.50" ID | AM2N8260 | \$ 7.00 | |

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 60 1959-63, (501, 601 - 1957-62), (541, 611 - 1959-64), 600 1957, 620 1954-64, (621, 631, 641, 651 - 1958-64), (630, 640 - 1955-57), 650 1956-57, 700, 800, 900, (2000, 4000 - 1962-64), (2031, 4031 - 1960-62), (2111, 2120, 2130, 2131, 4110TR, 4120, 4121, 4130, 4131, 4140 - 1963-64), (4030, 4040 - 1961-62), Jubilee, NAA - All w/ 4 Cylinder Engine | | | |
| Radiator Hose, Upper 1.25" ID Replaces 310048 | AMNAA8260B | \$ 5.00 | |
| Application: (230A, 334, 3610V 1981-04/83 - w/ 3 Cylinder Engine), (231, 233, 333, 531, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4600O - 1975-81 w/ 3 Cylinder Engine), (234 1975-04/83, 2000, 2100 03/1965-74, 2310 03/1982-83, 2600V 10/1975-09/76, 2610V 1970-02/90, 3600R 1975-77, 3610NO 08/1981-04/83, 3910 05/1983-02/90, 3910R (981-84, 3910V 12/1983-02/90, 4000 Diesel, 4110N 12/1981-02/90, 4410 1969-74, 4600NO 10/1975-81, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (335, 340, 2610, 2810, 3000, 3055, 3100, 3400, 3610, 4000SU, 4100, 4110, 4600, 4610, 5600 w/ Transmission Oil Cooler - Diesel), (2110, 2120, 2300, 4190, 4200, 4330, 4340 - 1965-74 w/ 3 Cylinder Engine), 2600, 5000, 5100, 6600, 6700, 7000, 7100, 7600, (2910, 3910H, 3910N - 1983-02/90 w/ 3 Cylinder Engine), (4110NO, 4110O, 4110V, 4610NO - 1981-02/90 w/ 3 Cylinder Engine), (5110 05/1984-10/91, 6710 1981-09/85, 7610O 10/1981-91, 7700 1976 -80, 7710 1981-10/91 w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 - w/ 4 Cylinder Engine), (5610, 5900, 6610, 7610 - Prior to 07/31/1987), Ind: (420, 445, 445A, 515, 535, 540, 540A, 540B, 545, 545A, 3500, 3550, 4500 - Diesel) | | | |
| Radiator Hose, Upper 1.50" ID Replaces 81805628, 83907414, C5NN8260A, C5NN8260B, D5NN8260DV | AMD5NN8260D | \$ 6.00 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 5700 - 1975-81 w/ 3 Cylinder Engine), (2600V 10/1975-09/76, 3600R 1975-77, 4600NO 10/1975-81, 4600O, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5900 05/1985-93, 7610 1981-10/91, 7610O 10/1981-91, 7710 Prior to 07/1987 w/o A/C - w/ 4 Cylinder Engine), (5610, 6610 - 1981-93 w/ 4 Cylinder Engine), (6710, 7700 - w/o A/C w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 w/ 4 Cylinder Engine) | | | |
| Radiator Hose, Upper 1.50" ID Replaces 83905554, D5NN8260CV, K916316 | AMD5NN8260C | \$ 13.80 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600O - 1975-81 w/ 3 Cylinder Engine), (2600V 10/1975-09/76, 3600R 1975-77, 4600NO 10/1975-81, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5900 05/1985-93, 6710, 7610 1981-10/91, 7610O 10/1981-91, 7700, 7710 - w/ 4 Cylinder Engine), (5610, 6610 - 1981-93 w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 w/ 4 Cylinder Engine) | | | |
| Radiator Hose, Upper 1.50" ID | AMD4NN8260C | \$ 16.30 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600O - 1975-81 w/ 3 Cylinder Engine), (2600V 10/1975-09/76, 3600R 1975-77, 4600 w/ Cab and A/C, 4600NO 10/1975-81, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (4610, 7700 1976-80 - w/ 4 Cylinder Engine) | | | |
| Radiator Hose, Upper 1.50" ID | AMD6NN8260A | \$ 17.90 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3190, 3300, 3310, 3330, 3400, 3600, 3610, 3910, 4000, 4100, 4110, 4330, 4340, 4400, 4410, 4600, 4610, 5600, 6600, 7600, Ind: 230A, 234, 334, 340, 340A, 445, 445A, 450, 530A, 540, 540A, 540B, 545, 545A, 3500, 3550, 4500 | | | |
| Radiator Hose, Upper 1.50" ID | AMC5NN8260D | \$ 7.75 | |
| Application: 3230 03/1990-09/94, 3430, 3930 05/1990-07/99, 3930N 03/1990-06/95, (3930NO, 4130NO, 4630N, 4630NO, 4630O - 03/1990-08/99), 4130 03/1990-07/99, 4630 - All w/ 3 Cylinder Engine | | | |
| Radiator Hose, Upper 1.50" ID | AME9NN8260AA | \$ 19.50 | |
| Application: (3230, 3430, 4630 - w/ 3 Cylinder Engine w/o Spigot), (3930, 3930N 03/1990-06/95, 4130 03/1990-07/99 - w/ 3 Cylinder Engine), (3930NO, 4130NO, 4630N, 4630NO, 4630O - 03/1990-08/99 w/ 3 Cylinder Engine) | | | |
| Radiator Hose, Upper 1.50" ID Replaces 82015118 | AMF0NN8260AA | \$ 13.10 | |
| Application: (4000, 4110, 4190, 4330, 4340 - 1965-74 w/ 3 Cylinder Engine), 4100 w/ 3 Cylinder Engine, 4200 Gas or Diesel, 5200, 4410 1969-74 w/ 3 Cylinder Engine, Ind: 4500 1965-74 w/ 3 Cylinder Engine | | | |
| Radiator Hose, Upper 1.50" ID | AMC5NN8260E | \$ 14.10 | |
| Application: 4010S 1996 and Later w/ 3 Cylinder Engine, (5530, 6530 - 03/1992-97 w/ 4 Cylinder Engine) | | | |
| Radiator Hose, Upper 1.687" ID | AM5104825 | \$ 29.40 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 4830, 4830N 07/1990-05/94 w/ 4 Cylinder Engine, 5030, 5030O 06/1994-04/98 w/ 4 Cylinder Engine | | | |
| Radiator Hose, Upper 1.50" ID | AMF0NN8260BB | \$ 25.10 | |
| Application: 5110 05/1984-10/91, (5610, 6610 - 1981-93), 5900 05/1985-93, 6710 1981-09/85, (6810, 7410 - 04/1989-10/91), 7610 1981-10/91, 7610O 10/1981-91, 7710 08/1987 and Later w/ A/C - All w/ 4 Cylinder Engine | | | |
| Radiator Hose, Upper 1.50" ID | AME6NN8260AA | \$ 21.90 | |
| Application: (5110 05/1984-10/91, 5610S 1993 and Later, 6710 1981-09/85, 7610O 10/1981-91, 7710 1981-10/91 - w/ 4 Cylinder Engine), (6610S, 7610S - 1994 and Later w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 w/ 4 Cylinder Engine), (5610, 5900, 6610, 7610 - 08/1987 and Later), Backhoe-Loaders: 655, 655A 08/1987 and Later, 655C Prior to 08/1993 | | | |
| Radiator Hose, Upper 1.625" ID Replaces E7NN8260BA | AME6NN8260CA | \$ 9.50 | |
| Application: 5640, 6640, 7740 | | | |
| Radiator Hose, Upper 1.50" ID Replaces 81862934, 87745807, D0NN8260CA | AMF0NN8260CA | \$ 9.60 | |
| Application: 7810 w/ BSD666 Engine, (7810O 02/1988-10/91, 8010 04/1996 and Later - w/ 6 Cylinder Engine), 7810S | | | |
| Radiator Hose, Upper 1.75" ID Replaces 83961073, 87745813 | AME7NN8260AA | \$ 13.10 | |
| Application: 7840, 7840O 02/1993-01/98 w/ 6 Cylinder Engine, 8240, 8340 | | | |
| Radiator Hose, Upper 1.50" ID Replaces 81862935 | AMF0NN8260DA | \$ 15.10 | |
| Application: (7910, 8210 - w/ BSD666 Engine) | | | |
| Radiator Hose, Upper 1.75" ID Replaces 83929875 | AME0NN8260AA | \$ 35.20 | |
| Application: (8000 1968-78, 8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9200 1969-09/72, 9600 10/1973-07/76, 9700 08/1976-78 - w/ 6 Cylinder Engine), 9000 Prior to 09/1972, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Upper 1.75" ID | AMC9NN8260A | \$ 35.10 | |
| Application: 8000 Prior to 07/1976, (8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9000 1969-78, 9200 1969-09/72, 9600 1973-07/76, 9700 1976-78 - w/ 6 Cylinder Engine), Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Upper 1.50" ID | AMD2NN8260B | \$ 20.00 | |
| Application: (8000 1968-78, 8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9200 1969-09/72, 9600 10/1973-07/76, 9700 08/1976-78 - w/ 6 Cylinder Engine), 9000 Prior to 07/1976, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Upper 1.75" ID | AMD2NN8260C | \$ 19.10 | |
| Application: (8000 1968-78, 8200 1968-09/72, 8600 10/1972-07/76, (8700, 9700 - 08/1976-78), 9000 1969-78, 9200 1969-09/72, 9600 10/1973-07/76 - w/ 6 Cylinder Engine), TW10, TW20, TW30, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Upper 1.75" ID | AMD8NN8260BB | \$ 26.90 | |
| Application: (8000, 9000 - 08/1976 and Later), 8700, 9700, 8200 1968-09/72, 8600 10/1972-07/76, 9200 1969-09/72, 9600 10/1973-07/76, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Upper 1.75" ID Replaces 83914013 | AMD8NN8260CA | \$ 20.10 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: (8530, 8630, 8730 - 03/1990-93 w/ 6 Cylinder Engine), 8830, TW5, TW15, TW25, TW35 | | | |
| Radiator Hose, Upper 1.75" ID Replaces 83918850, 83933451, 83934898 | AME3NN8333AA | \$ 16.40 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Radiator Hose, Upper 2" ID Replaces 86013975 | AM9821598 | \$ 28.60 | |
| Application: Dexta | | | |
| Radiator Hose, Upper 1.625" ID Replaces 81718085, 87295814 | AM957E8260A | \$ 21.20 | |
| Application: Major, Super Major | | | |
| Radiator Hose, Upper 1.75" ID Replaces 87295271, E1ADKN8260 | AM81718084 | \$ 12.20 | |
| Application: Super Dexta | | | |
| Radiator Hose, Upper 1.75" ID Replaces 81805632 | AM957E8260B | \$ 22.50 | |
| Application: Utility: 1100 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160320 | \$ 20.50 | |
| Application: Utility: 1110 w/ Manual Transmission | | | |
| Radiator Hose, Upper 1.312" ID | AMSBA310160780 | \$ 11.20 | |
| Application: Utility: 1120, 1210, 1215, 1220, 1310 | | | |
| Radiator Hose, Upper 1" ID | AMSBA310160730 | \$ 19.00 | |
| Application: Utility: 1200 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160460 | \$ 42.00 | |
| Application: Utility: 1320, 1520, 1620, 1715, 1720, 1920, T1520, TC30 | | | |
| Radiator Hose, Upper 1.312" ID | AMSBA310160932 | \$ 18.30 | |
| Application: Utility: 1300 | | | |
| Radiator Hose, Upper 1" & 1.25" ID | AMSBA310160290 | \$ 29.40 | |
| Application: Utility: 1500 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160380 | \$ 26.80 | |
| Application: Utility: 1510 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160750 | \$ 20.20 | |
| Application: Utility: 1530, 1630, 1725, 1925, TC25, TC25D, TC29, TC29D, TC33, TC33D | | | |
| Radiator Hose, Upper 1.312" ID | AM86519847 | \$ 9.90 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: Utility: 1600 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160050 | \$ 22.10 | |
| Application: Utility: 1700 10/1979 and Later, 1710 | | | |
| Radiator Hose, Upper 1.312" ID | AMSBA310160450 | \$ 23.70 | |
| Application: Utility: 1700, 1900 1979-09/79 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160170 | \$ 22.40 | |
| Application: Utility: 1900 ASN U902326 10/1979 and Later | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160430 | \$ 32.20 | |
| Application: Utility: 1910 | | | |
| Radiator Hose, Upper 1.25" ID | AMSBA310160840 | \$ 22.90 | |
| Application: 2N, 8N, 9N | | | |
| Radiator Hose, Lower 1.562" ID | AM8N8286 | \$ 9.35 | |
| Application: 2N, 8N, 9N, 501 Series, 600, 601 Series, 650, 701 Series, 800, 801 Series, 1800 Series, (2000, 4000 - 1962-64 w/ 4 Cylinder Engine), 2030, 2120, 2130, 4030, 4040, 4120, 4130, 4140, Ind: 660 | | | |
| Radiator Hose, Lower 1.50" ID | AM312588 | \$ 5.00 | |
| Application: (230A, 334, 3610V - 1981-04/83 w/ 3 Cylinder Engine), (231, 233, 333, 531, 2600N, 2600R, 3600N, 3600V, 3900, 4600O - 1975-81 w/ 3 Cylinder Engine), (234 1975-04/83, 2310 03/1982-83, 2600V 10/1975-09/76, 2610V 1970-02/1990, 3600R 1975-77, 3610NO 08/1981-04/83, 3910 05/1983-02/90, 3910R 1981-84, 3910V 12/1983-02/90, 3930N 03/1990-06/95, 4110N 12/1981-02/90, 4410 1969-12/74, 4600NO 10/1975-81, 4600SU 1975-07/81 - w/ 3 Cylinder Engine, (2000, 3230, 3930, 4000, 4630 - w/ 3 Cylinder Engine), 340, 2600, 2610, 2810, 3000, 3055, 3100, 3400, 3430, 3600, 3610, 4100, 4110, 4600, 4610, 4830, 5030, 6600, (2100, 2110, 2120, 2300, 2310, 3110, 3120, 3190, 3300, 3310, 3330, 4190, 4200, 4330, 4340 - 1965-74 w/ 3 Cylinder Engine), (2910, 3910H, 3910N - 1983-02/90 w/ 3 Cylinder Engine), (3930NO, 4130NO, 4630N, 4630NO, 4630O - 03/1990-08/99 w/ 3 Cylinder Engine), (4110NO, 4110O, 4110V, 4610NO - 1981-02/90 w/ 3 Cylinder Engine), (4830N 07/1990-05/94, 5030O 06/1994-04/98, 7700 1976-80 - w/ 4 Cylinder Engine), Ind: 420, 445, 515, 540, 3500, 3550, 4130 1963-64, 4500 1965-74 w/ 3 Cylinder Engine | | | |
| Radiator Hose, Lower 1.725" ID | AMC5NN8286B | \$ 13.30 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600NO, 4600O - 1975-81 w/ 3 Cylinder Engine), 335, 2100 03/1965-74, 2600V 10/1975-09/76, 3600R 1975-77, 4600SU 1975-07/81, 5000, 5100, 5600, 5900, 7000, 7100, 7600, (2000, 2110, 2120, 2300, 3055, 4000, 4100, 4110, 4190, 4200, 4330, 4340, 4410 - 1965-74 w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5610 1981-93, 5610S 12/1993 and Later, 6600 w/o Oil Cooler, 6610 1981-93, 6610S 1994 and Later, 6710 1981-09/85, 7010 04/1996 and Later, 7610O 10/1981-91, 7610S 1994 and Later, 7700 1976-80 - w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 w/ 4 Cylinder Engine), (7610, 7710 - 1981-10/91 w/ 4 Cylinder Engine), Ind: 445 Gas or Diesel, 535, 540A Diesel, 540B Diesel, 545, 545A Diesel, (3500, 3550 1965-74 w/ 3 Cylinder Engine), 4500 | | | |
| Radiator Hose, Lower 1.645" & 1.757" ID Replaces 81805638, 83907879, 87745803, C5NN8286CV | AMC5NN8286C | \$ 13.20 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600O - 1975-81 w/ 3 Cylinder Engine), (4600NO 10/1975-81, 2600V 10/1975-09/76, 3600R 1975-77, 4600SU 1975-07/81 w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5610S 12/1993 and Later, 5900 05/1985-12/93, 6710 1981-09/85, 7010 04/1996 and Later, 7610O 10/1981-91, 7700 1976-80, 7710 1981-10/91 - w/ 4 Cylinder Engine), (5600, 6600 - w/ 4 Cylinder Engine w/ Transmission Oil Cooler), 5610, 6610, (6610S, 7610S - 1994 and Later w/ 4 Cylinder Engine), (6810, 7410 - 04/1989-10/91 w/ 4 Cylinder Engine), 7610 | | | |
| Radiator Hose, Lower 1.812" ID Replaces 83907879, 87745809 | AMD5NN8286F | \$ 16.80 | |
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600O - 1975-81 w/ 3 Cylinder Engine), (2600V 10/1975-9/76, 3600R 1975-77, 4600NO 10/1975-81, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (4000, 4110, 4190, 4200, 4330, 4340 - 1965-74 w/ 3 Cylinder Engine), 4410 1969-74 w/ 3 Cylinder Engine, 5200, 6600C, 7200, 7600C, 7700 1976-80 w/ 4 Cylinder Engine, Ind: 4500 1965-74 w/ 3 Cylinder Engine | | | |
| Radiator Hose, Lower 1.75" ID | AMD0NN8286A | \$ 27.40 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: (231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600O - 1975-81 w/ 3 Cylinder Engine), (4600NO 10/1975-81, 4600SU 1975-07/81, 2600V 10/1975-09/76, 3600R 1975-77 - w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5610 1981-93, 6610 1981-93, 6710 w/o A/C, 6810 04/1989-10/91, 7410 04/1989-10/91, 7610 1981-10/91, 7610O 10/1981-91, 7700 1976-80, 7710 w/o A/C - w/ 4 Cylinder Engine), 5700, 6700 Radiator Hose, Lower 1.75" ID Replaces 83909073 | AMD6NN8286B | \$ 24.40 | |
| Application: 231, 233, 333, 531, 2600, 2600N, 2600R, 3600, 3600N, 3600V, 3900, 4100, 4600, 4600NO, 4600O - 1975-81 w/ 3 Cylinder Engine), (2600V 10/1975-09/76, 3600R 1975-77, 4600SU 1975-07/81 - w/ 3 Cylinder Engine), (5110 05/1984-10/91, 5610 1981-93, 6610 1981-93, 5900 1985-93, 6710 w/ A/C, 6810 04/1989-10/91, 7410 04/1989-10/91, 7610 1981-10/91, 7610O 10/1981-91, 7710 w/ A/C - w/ 4 Cylinder Engine), 7700 Radiator Hose, Lower 1.75" ID | AME8NN8286BA | \$ 23.20 | |
| Application: 1000, Utility: 1600 Radiator Hose, Lower 2.75" & 2.875" ID | AMSBA310160060 | \$ 31.70 | |
| Application: 2000, 2120, 2150, 2300, 2310, 2600, 2600V, 2610, 2810, 2910, 3000, 3055, 3110, 3120, 3150, 3190, 3230, 3300, 3310, 3330, 3400, 3430, 3500, 3600, 3600V, 3610, 3900, 3910, 3930, 4110, 4130, 4140, 4190, 4330, 4340, 4400, 4410, 4600, 4600SU, 4610, 4630, 4830, 5000, 5030, 5190, 5340, 5600, 5700, 6600, 6700, 7000, 7600, 7700, Ind: 230A, 231, 233, 234, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 420, 445, 445A, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 3550 Radiator Hose, Lower 1.725" ID Replaces C5NN8286B | AM81805637 | \$ 11.00 | |
| Application: (4000, 4110, 4190, 4330, 4340 - 1965-74 w/ 3 Cylinder Engine), 4100 w/ 3 Cylinder Engine, 4200 Gas or Diesel, 4410 1969-74 w/ 3 Cylinder Engine, Ind: 4500 1965-74 w/ 3 Cylinder Engine Radiator Hose, Lower 1.75" ID | AMC5NN8286D | \$ 23.50 | |
| Application: (5610S 12/1993 and Later, 6610S 1994 and Later, 7610O 10/1981-91 - w/ 4 Cylinder Engine), (6810, 7610 - 06/1989 and Later w/ A/C), 7610S 10/1997 and Later, 7810 w/ BSD666 Engine, 7810S, (7810O 02/1988-10/91, 8010 04/1996 and Later - w/ 6 Cylinder Engine) Radiator Hose, Lower 1.97" ID Replaces 83961071, 83976368, 87745812 | AME7NN8286AA | \$ 29.60 | |
| Application: 5640, 6640, 7740, 7840, 7840O 02/1993-01/98 w/ 6 Cylinder Engine, 8240, 8340 Radiator Hose, Lower 1.75" ID Replaces 81868754 | AMF0NN8286AB | \$ 21.30 | |
| Application: 6000 Radiator Hose, Lower 1.875" ID | AMCONN8286A | \$ 8.40 | |
| Application: (7910, 8210 - w/ BSD666 Engine), (8000 1968-78, 8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9000 1969-78, 9200 1969-09/72, 9600 10/1973-07/76, 9700 08/1976-78 - w/ 6 Cylinder Engine), TW10, TW20, TW30, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine Radiator Hose w/ Clamps, Lower 1.75" ID | AMD8NN8B274AB | \$ 13.60 | |
| Application: 8000 Prior to 07/31/76, 9600 Radiator to Cooler, (8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9000 10/1972-07/76, 9200 1969-09/72, 9700 08/1976-78 - w/ 6 Cylinder Engine), Ind: 8400 1971-09/72 w/ 6 Cylinder Engine Radiator Hose, Lower 2" & 2.375" ID | AMC7NN8286A | \$ 16.50 | |
| Application: (8000 1968-78, 8200 1968-09/72, 8600 10/1972-07/76, 8700 08/1976-78, 9200 1969-09/72, 9600 10/1973-07/76, 9700 1976-78 - w/ 6 Cylinder Engine), 9000 Prior to 07/1976, Ind: 8400 1971-09/72 w/ 6 Cylinder Engine Radiator Hose, Lower 2" ID | AMC9NN8286A | \$ 18.10 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: (8000, 8700, 9000 - 08/1976 and Later), 9700, (8200 1968-09/72, 8600 10/1972-07/76, 9200 1969-09/72, 9600 10/1973-07/76 - w/ 6 Cylinder Engine), Ind: 8400 1971-09/72 w/ 6 Cylinder Engine | | | |
| Radiator Hose, Lower 1.75" & 2" ID Replaces 86620261 | AMD6NN8286C | \$ 33.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Radiator Hose, Lower 2" & 2.06" ID | AM9821599 | \$ 30.00 | |
| Application: Dexta, Super Dexta | | | |
| Radiator Hose, Lower 1.28" & 1.40" ID | AM957E8286 | \$ 30.00 | |
| Application: Major, Super Major, Power Major | | | |
| Radiator Hose, Lower 1.75" ID Replaces E1ADDN8286 | AM81718086 | \$ 18.50 | |
| Application: (Workmaster 65, Workmaster 75 - Prior to 09/2018) | | | |
| Radiator Hose, Lower | AM87473908 | \$ 14.00 | |
| Application: Ind: 7500 | | | |
| Radiator Hose, Lower 1.75" ID | AMD1NN8286B | \$ 39.20 | |
| Application: Utility: 1110 w/ Hydrostatic Transmission | | | |
| Radiator Hose, Lower | AMSBA310160770 | \$ 9.50 | |
| Application: Utility: 1110 w/ Manual Transmission | | | |
| Radiator Hose, Lower 1.312" ID | AMSBA310160790 | \$ 9.50 | |
| Application: Utility: 1120, 1210, 1215, 1220, 1310 | | | |
| Radiator Hose, Lower 1" ID | AMSBA310160740 | \$ 21.80 | |
| Application: Utility: 1320, 1520, 1620, 1715 | | | |
| Radiator Hose, Lower 1.25" ID | AMSBA310161091 | \$ 10.90 | |
| Application: Utility: 1500 | | | |
| Radiator Hose, Lower 1.25" ID | AMSBA310160310 | \$ 32.80 | |
| Application: Utility: 1510, 1710 | | | |
| Radiator Hose, Lower 1.312" ID | AMSBA310160441 | \$ 22.40 | |
| Application: Utility: 1530, 1630, 1725, TC25, TC25D, TC29, TC29D | | | |
| Radiator Hose, Lower 1.312" ID | AM86519855 | \$ 14.40 | |
| Application: Utility: (1700, 1900 - 1979-09/79) | | | |
| Radiator Hose, Lower 1.312" ID | AMSBA310160150 | \$ 32.30 | |
| Application: Utility: (1700, 1900 - 10/1979 and Later) | | | |
| Radiator Hose, Lower 1.25" ID | AMSBA310160350 | \$ 33.10 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Radiator Hoses (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: Utility: 1720, 1920 | | | |
| Radiator Hose, Lower 1.312" ID | AMSBA310161031 | \$ 14.30 | |
| Application: Utility: 1910 | | | |
| Radiator Hose, Lower 1.25" & 1.532" ID | AMSBA310160850 | \$ 27.70 | |
| Application: Utility: 1925, TC33, TC33D | | | |
| Radiator Hose, Lower 1.312" ID | AM86526943 | \$ 12.80 | |
| Application: Utility: T1520, TC30 | | | |
| Radiator Hose, Lower 1.312" ID | AMSBA310161630 | \$ 17.90 | |
| Application: (Dexta, Super Dexta - Prior to 09/30/1989) | | | |
| Radiator Hose 1.625" ID Replaces 957E8333B | AM81718101 | \$ 21.70 | |
| Application: Fordson Major, Fordson Super Major, Fordson Power Major | | | |
| Radiator Hose 1.75" ID | AM81718097 | \$ 8.90 | |
| Application: 1320, 1520, 1530, 1620, 1630, 1710, 17100, 1715, 1720, 1725, 1920, 1925, 2030, 2120, 3415, Boomer 1020, Boomer 1025, Boomer 1030, Boomer 2035, Boomer 3040, Boomer 3045, Boomer 3050, Boomer 4055, Boomer 4060, T1010, T1030, T1110, T1510, T1520, T2210, T2220, T2310, T2320, T2330, T2410, T2420, TC23DA, TC24D, TC24DA, TC25, TC25D, TC26DA, TC29, TC29D, TC29DA, TC30, TC31DA, TC33, TC33D, TC33DA, TC34DA, TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA, TC45, TC45A, TC45D, TC45DA, TC48DA, TC55DA, TT45A, TT50A, TZ18DA, TZ22DA, TZ25DA | | | |
| Bypass Hose 0.54" ID Replaces 83966732, 87772767, 87780789 | AMSBA145536051 | \$ 7.40 | |
| Application: Dexta, Super Dexta | | | |
| Bypass Hose 1.125" ID Replaces 747936M91, 81716947, 86513585, E6CJ9, E15CJ9 | AM731256M1 | \$ 6.60 | |
| Application: Dexta, Super Dexta | | | |
| Water Pump Inlet Hose 1.375" ID Replaces 8176946 | AM732443M1 | \$ 9.60 | |

Ford®/New Holland®—Tractor

Engine Fans and Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 500 Series, 600 Series, 800 Series, 900 Series, 2000, 4000 - Gas | | | |
| Engine Fan 3 Blade, 16" Diameter, 3.12" Bolt Circle Diameter, 0.625" Pilot Hole Diameter | AMNCA8600S | \$ 53.10 | |
| Application: 5610S ASN 308716M, 6610S ASN 359818M, 6810S, 7600, 7610, 7610S, 7810, 7810S, 8010, TB80, TB85, TB90, TB100, TB110, TB120 | | | |
| Engine Fan 7 Blade, 17.50" Diameter, 5/8" Pilot Hole | AME8NN8600DB | \$ 75.00 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Fan 8 Blade, 6-Bolt Hub Replaces 87778091 | AM278432A1 | \$ 385.00 | |
| Application: 501, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, 2000, 2031, 2111, 2130, 2131, 4000, 4030, 4031, 4110, 4120, 4121, 4130, 4140 | | | |
| Fan Shroud Replaces NCA8146A | AM86551380 | \$ 80.00 | |

Flywheels and Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|----------|
| Application: 2N, 8N, 9N, 600, 700, 800, 900, (2000, 4000 - Prior to 1964), NAA, NAB | | | |
| Flywheel Ring Gear 134 Tooth, 11.994" ID, 13.552" OD | AM9N6384 | \$ 28.50 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3120, 3190, 3300, 3310, 3330, 3400, 3600, 3610, 3900, 3910, 4000, 4100, 4110, 4190, 4200, 4330, 4340, 4410, 4600, 4610, 5000, 5100, 5190, 5200, Ind/Const: 230A, 231, 233, 234, 333, 334, 335, 340, 340A, 340B, 420, 445, 445A, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 550, 555, 555A, 555B, 655, 655A, 3500, 3550, 4400, 4500, 5500, 5550 | | | |
| Flywheel Ring Gear 162 Tooth, 14.634" ID, 16.245" OD | AMCSNE6384B | \$ 200.80 | |
| Application: 2000, 2600, 2610, 3000, 3230, 3430, 3600, 3610, 3930, 4000, 4110, 4200, 4430, 4600, 4610, 4630, 5000, 5600, 5700, 6600, 6700, 7000, 7600, 7700, 8000, 9000, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| Flywheel Ring Gear 128 Tooth, 16.115" OD, 14.52" ID, 0.625" Wide | AME2NN6384AA | \$ 47.00 | |
| Application: Dexta, Super Dexta | | | |
| Flywheel Ring Gear Replaces 957E6384, 81804209 | AM957E6384B | \$ 84.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Drive Plate 36 Splines, 13" OD | AM9825201 | \$ 580.00 | \$ 15.00 |

Water Pumps and Components

| Description | Part Number | Retail Price | Core |
|---------------------------------------|-------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Water Pump w/ Single Groove Pulley | AMCDPN8501A | \$ 55.00 | |

Ford®/New Holland®—Tractor

Water Pumps and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|----------|
| Application: 230A, 231, 233, 234, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 455, 455C, 455D, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 550, 555, 555A, 555B, 650, 655, 655A, 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3120, 3230, 3300V, 3310N, 3330NO, 3400U, 3430, 3500, 3550, 3600, 3610, 3910, 3930, 4000, 4100, 4110, 4130, 4140SU, 4200, 4330NO, 4340, 4400, 4410, 4500, 4600, 4610, 4630, 4830, 5000, 5030, 5100, 5110, 5200, 53400, 5600, 5610, 5700, 5900, 6410 United Kingdom, 6500, 6600, 6600C, 6610, 6700, 6710, 6800, 6810, 7000, 7100, 7200, 7410, 7600, 7600C, 7610, 7700, 7710, Ind/Const: 750TLB, 755TLB, 755ATLB, 755BTLB, 3500, 3550 - All 1965-88 w/ 3 Cylinder or 4 Cylinder Engine, Engines: BSD332, BSD333, BSD333H, BSD442, BSD444, BSD444H, BSD444T | | | |
| Water Pump w/ Single Groove Pulley, 5/16" and 3/8" Bolts Replaces EGP8A513DA, EAPN8A513F, FAPN8A513GG | AM82845215 | \$ 54.00 | |
| Application: 230A, 231, 234, 334, 335, 340, 340B, 420, 445, 445A, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 650, 750, 755, 755A, 2000, 2110, 2310, 2600, 2610, 2610N, 2810, 2910, 3000, 3400, 3600, 3610, 3610NO, 3610V, 3910, 4000, 4100, 4110, 4110N, 4400, 4410, 4500, 4600, 4600O, 4600SU, 4610, 4610O, 5000, 5200, 5500, 5600, 5610, 6500, 6600, 6610, 6610N, 6700, 6710, 7000, 7200, 7500, 7600, 7610, 7700, 7710, Ind: 3500, 3550 - All w/ 3 and 4 Cylinder Engine, 1965-11/1986 | | | |
| Reman Water Pump w/ Double Groove Pulley, 5/16" and 3/8" Bolts | AMEAPN8A513E-R | \$ 90.00 | \$ 25.00 |
| Application: 501, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, 1801, 1811, 1821, 1841, 1871, 1881, 2000 Series 1955 and Later, 2030, 2031, 2110TR, 2111, 2120, 2130, 2131, 4000 Series 1955 and Later, 4030, 4031, 4040, 4110TR, 4120, 4121, 4130, 4131, 4140 - 1955-64 w/ 172 CID Gas or Diesel Engine | | | |
| Water Pump w/ Hub For Bolt-on Pulley Pulley Not Included Replaces CDPN8501C, DCPN8501A | AM3971351 | \$ 50.00 | |
| Application: 501, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, 2031, 2110, 2111, 2120, 4030, 4031, 4040, 4110, 4120, 4121, 4131, 4130, 4140, Ind: 1801, 1811, 1821, 1841, 1871, 1881, 2030, 2130, 2131 - All 1955-64 w/ 172 CID 4 Cylinder Gas or Diesel Engine | | | |
| Water Pump w/ Single Groove Pulley Replaces 3971351, DCPN8501A | AMCDPN8501C | \$ 85.00 | |
| Application: 1120, 1210, 1215, 1220, 1310 | | | |
| Water Pump | AMSBA145017300 | \$ 99.00 | |
| Application: 1164 1972-07/76, (8000, 8200 - 1968-07/76), 8600 1972 and Later, Ind: 8400 1972 and Later | | | |
| Reman Water Pump w/ Single Groove Pulley, 5/16" and 3/8" Bolts 5 5/8" Diameter Pulley, 2 5/8" Tall, 4" Diameter Impeller | AMDHPN8A513B-R | \$ 110.00 | \$ 25.00 |
| Application: 1500, 1700, 1900 | | | |
| Water Pump | AMSBA145016120 | \$ 78.00 | |
| Application: 1710 - 1983-86 | | | |
| Water Pump Replaces 83940738, SBA145016510 | AMSBA145016450 | \$ 107.00 | |
| Application: (1720, 1920, 3415 - 1987 and Later), 2120 03/1999 and Later, Boomer 4055, Boomer 4060, T1510, T1520, T2210, T2220, T2310, T2320, T2330, T2410, T2420, TC33, TC33D, TC34DA, TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA, TC45, TC45A, TC45D, TC45DA, TC48DA, TC55DA, TT45A, TT50A | | | |
| Water Pump | AMSBA145017790 | \$ 180.30 | |
| Application: (2000, 3000, 4000, 5000, 7000 - w/ 3 and 4 Cylinder Engines, 1965-75), (2600, 3600, 4100, 4600, 5600, 5700, 6600, 6700, 7600, 7700 - w/ 3 and 4 Cylinder Engines, 1975-81), (2310, 2610, 2810, 2910, 3610, 3910, 4110, 4610 - w/ 3 and 4 Cylinder Engines, 1981-02/90), (5110, 5610, 6610, 6710, 7610, 7710 - w/ 3 and 4 Cylinder Engines, 1981-10/88) | | | |
| Water Pump w/ Double Groove Pulley, 5/16" and 7/16" Bolts Replaces EAPN8A513E, EGP8A513CA, FAPN8A513DD | AM87800109 | \$ 60.00 | |
| Application: 3010S, 3830, 4230, 4330V, 4430, 4835, 5530, 5635, 6530, 6635, 7635, TL100, TL70, TL80, TL90, TN55, TN55D, TN55S, TN60VA, TN65, TN65D, TN65F, TN65S, TN65V, TN70, TN70D, TN70F, TN70S, TN75, TN75D, TN75F, TN75S, TN74V, TN80F, TN90F, TN95F, TT55, TT75 | | | |
| Water Pump | AM99454833 | \$ 133.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Water Pumps and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|----------|
| Application: 4830, 4830N, 4830O, 5030, 5030O, 5110, 5610, 6410, 6610, 6610O, 6710, 6810, 7410, 7610O, 7710 | | | |
| Water Pump Replaces 81872278, 83960873, E6NN8501HA | AM87800119 | \$ 160.40 | |
| Application: 5110, 5610, 5910, 6410, 6810, 7610, 7710 - 11/88-10/91 w/ 4 Cylinder Diesel Engine | | | |
| Water Pump w/ Single Groove Pulley, Threaded for Fan Replaces FAPN8A513HH | AMFAPN8A513HH | \$ 139.00 | |
| Water Pump w/ Fan Clutch Replaces EJP8A513FB | AMFAPN8A513AA | \$ 170.00 | |
| Water Pump w/ Double Groove Pulley | AMEAPN8A513D | \$ 82.50 | |
| Application: 5640, 6640, 7740, 7840 | | | |
| Water Pump w/ Serpentine Pulley, 147 mm Diameter Will not fit models equipped w/ Mando A/C | AM87800714 | \$ 230.00 | |
| Water Pump w/ Serpentine Pulley, 140 mm Diameter Will not fit models w/ Mando A/C | AM87800712 | \$ 185.00 | |
| Application: 7740, 7840, 8240, 8340 - w/ Mando A/C | | | |
| Water Pump Includes Mounting Gasket | AM87840257 | \$ 208.50 | |
| Application: 7810, 7810S, 8010, TB120 | | | |
| Water Pump Includes Mounting Gasket Replaces 81863835, 83926130, 83961310, EJP8A513BA, SW06499, VPE1038 | AMFAPN8A513CC | \$ 180.00 | |
| Application: (7910, 8210 - 02/1982-10/91), (8530, 8630, 8730, 8830 - 03/1990 and Later), (8700, 9700 - 08/1976-78), (TW5, TW15, TW25, TW35 - 1983-02/90), (TW10, TW20, TW30 - 1979-82) | | | |
| Water Pump w/ Single Groove Pulley, Mounts w/ 5/16" and 7/16" Bolts Replaces EAPN8A513G, EGP8A513BA | AMFAPN8A513LL | \$ 138.00 | |
| Application: 7910 02/1982-11/86, 8700 1976 and Later, 9700, (TW5, TW10, TW15, TW20, TW25, TW30, TW35 - 08/1976-11/87) | | | |
| Reman Water Pump w/ Single Groove Pulley, 5/16" and 3/8" Bolts | AMEAPN8A513G-R | \$ 95.00 | \$ 25.00 |
| Application: 8000, 8200, 8400, 8600 | | | |
| Water Pump Includes Mounting Gasket Pulley and Hub Not Included Replaces 8508AB, 83912464 | AMDHPN8A513B | \$ 106.50 | |
| Application: 8160, 8260, 8360, 8560, TM115, TM125, TM135, TM150, TM165, TV140 | | | |
| Water Pump Replaces 82847714, 87840689, 87840823 | AM82847712 | \$ 170.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Water Pump w/ O-Ring Seal Replaces 87800490, 87800491, 87840704, 87840705 | AM87801873 | \$ 206.00 | |
| Application: 9000, 9200, 9600 - 1969-07/76 | | | |
| Reman Water Pump w/ Single Groove Pulley, 5/16" and 3/8" Bolts 4 1/2" Diameter Pulley, 2 5/8" Tall, 4" Diameter Impeller | AMDHPN8A513A-R | \$ 95.00 | \$ 25.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Water Pumps and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|----------|
| Application: 9000, 9600 - 1968-07/76 | | | |
| Water Pump w/ Single Groove Pulley, 4.50" Diameter Pulley Includes Mounting Gasket Replaces 83912463 | AMDHPN8A513A | \$ 95.00 | |
| Application: Dexta, Super Dexta | | | |
| Water Pump w/ Hub | AM957E8501B | \$ 100.00 | |
| Application: Fordson Major Diesel, Fordson Super Major | | | |
| Water Pump w/ Hub w/o Pulley Replaces DKN8501A, DKN8501B, DKN8501C, E1ADKN8501A, E1ADKN8501C | AME1ADKN8501B | \$ 50.50 | |
| Application: NAA (Golden Jubilee) 1953-54 | | | |
| Water Pump w/ Single Groove Pulley Replaces CPN8591B, EAF8501B | AMCDPN8501B | \$ 73.00 | |
| Application: T9030, T9040, T9050, T9.450, T9.505, T9.560 | | | |
| Water Pump | AM5801931144 | \$ 303.00 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Water Pump Replaces 86993431 | AM87453208 | \$ 145.00 | |
| Application: TL70A, TL80A, TL90A, TL100A, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
| Water Pump w/o O-Ring Seal | AM2852114 | \$ 50.00 | |
| Application: TJ275, TJ325 | | | |
| Water Pump Replaces 87308650, 87774990, J940052 | AMJ804927 | \$ 80.50 | |
| Application: TJ380, TJ430, T9030, T9040, T9050, Combine: CR9070 | | | |
| Water Pump Replaces 504079715 | AM504102491 | \$ 145.00 | |
| Application: TM120, TM130 | | | |
| Water Pump Replaces 87384587 | AM87802491 | \$ 280.00 | |
| Application: TM120, TM130, TM140, TM155, TM175, TM190, TV145 | | | |
| Water Pump w/o O-Ring Seal w/ Dual Serpentine Pulley, Threaded Hub for Fan Clutch | AM87384588 | \$ 120.00 | |
| Application: TM140, TM155, TM175, TM190 | | | |
| Water Pump Replaces 87384586 | AM87802490 | \$ 245.00 | |
| Application: Ind: 550, 555, 555A - 1975-12/86 | | | |
| Reman Water Pump w/ Double Groove Pulley, 5/16" and 3/8" Bolts 5 5/8" Diameter Pulley, 3 3/4" Tall, 4" Diameter Impeller | AMEAPN8A513H-R | \$ 85.00 | \$ 10.00 |
| Application: Utility: 1530, 1630, 1725, TC25, TC25D, TC29, TC29D, TC29DA | | | |
| Water Pump Includes Mounting Gasket Replaces 87761849, SBA145016891, SBA145017660 | AMSBA145017661 | \$ 156.00 | |
| Application: Utility: 1720, 1920, 2120 ASN UV32235, 3415 | | | |
| Water Pump | AMSBA145017730 | \$ 77.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Water Pumps and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 5640, 6640, 7740, 8240, 8340, TS90, TS100, TS110, TS115 | | | |
| Belt Tensioner Replaces 83998237, F0NN6B209AA, F1NN6B209AA | AM87801689 | \$ 55.00 | |
| Application: T6010, T6020, T6030 SN Z*BK40001-Z*BK50000 Excluding Power Command, T6040, (T6050, T6070, T6080 SN Z*BK40001-Z*BK50000 Excluding Power Command and Range Command), T6060, (TS100A, TS115A - Excluding Plus and Deluxe), TS125A, TS130A, TS135A, TS6020, TS6030, TV6070 Bi-Directional | | | |
| Belt Tensioner Replaces 2852161, 2853680, 2854611, 2855622, 2856687, 87415847, 87415848, 87803067 | AM504028028 | \$ 85.00 | |
| Application: 8160, 8260, 8360, 8560, TC140, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, WDX2302 | | | |
| Belt Tensioner | AM87801838 | \$ 109.30 | |
| Application: TG210, TG230, TG255, TG285, TJ280, TJ330, T9020 Replaces 87409564, 87775209 | | | |
| Belt Tensioner | AM87436755 | \$ 78.00 | |
| Application: Versatile®: 276 | | | |
| Belt Tensioner Replaces 47683084, 3802287, 3914086, 3917485, 3918944, 3922900, 3934817, 3934818, 3936201, 3936202, 3937553, 3973822, 3978022, 87326910, 391420A1, J904370, J911315, J914086, J918944, J934817, J936201, J936202, J936203, J937553 | AM87327014 | \$ 64.00 | |

Fan Clutches

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 5640, 6640, 7740, 7840, 8240, 8340, T6010, T6020, T6030, T6050, T6070, T6.120, T6.140, T6.150, T6.155, T6.160, T6.165, T6.175, TM120, TM130, TM140, TM175, TM190, TS90, TS100, TS100A, TS110, TS110A, TS115A, TS125A, TS130A, TS135A, TS6.110, TS6.120, TS6.125, TS6.130, TS6.140 | | | |
| Fan Clutch Assembly | AM81862862 | \$ 225.00 | |
| Application: 8530, 8630, 8730, TW5, TW15, TW25 | | | |
| Fan Clutch Assembly 4-Bolt Mount Replaces 83932779, E4NN8A616BC | AM81865533 | \$ 270.00 | |
| Application: T9030, T9040, T9050, TJ375, TJ380, TJ425, TJ430, TJ450, TJ500 | | | |
| Fan Clutch Assembly Replaces 388716A1 | AM430406A1 | \$ 1,275.00 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Fan Clutch Assembly Replaces 255031A2, 427510A2, 87776351 | AM447916A1 | \$ 575.00 | |
| Application: Workmaster 65, Workmaster 75 - Prior to 09/2018 | | | |
| Fan 6 Blade | AM87479461 | \$ 70.00 | |
| Application: 2N, 8N, 9N, NAA, NAB | | | |
| Fan w/ Spacer 4 Blade | AM8N8600A | \$ 57.00 | |
| Application: Workmaster 65, Workmaster 75 - Prior to 09/2018 | | | |
| Fan Drive Spacer | AM87479460 | \$ 17.00 | |

Ford®/New Holland®—Tractor

Belts

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 5640, 6640, 7740, 7840, 8240, 8340 - Models Prior to 11/91 w/ AC | | | |
| Fan Belt, Alt / Gen Belt | AMF3NN8620AA | \$ 39.50 | |
| Application: 8000 1960-01/73 (Alt Belt - 1968-07/76) | | | |
| Fan Belt | AM86518907 | \$ 12.50 | |
| Application: 8000 02/73-07/76 | | | |
| Fan Belt, Alt / Gen Belt | AMD2NN8620A | \$ 15.00 | |
| Application: 8670, 8770, 8870, 8970 - 09/93 | | | |
| Fan Belt, Water Pump Belt | AM86013678 | \$ 49.50 | |
| Application: 8700, 9700 - 08/1976-78 | | | |
| Fan Belt, Alt / Gen Belt | AM9625879 | \$ 15.00 | |
| Application: TW5, TW15, TW25, TW35 | | | |
| Fan Belt | AMAD6NN8620B | \$ 15.00 | |
| Alt / Gen Belt | AM9842660 | \$ 15.00 | |
| Application: 8160, 8260, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TV140 | | | |
| Belt Tensioner | AMAH155348 | \$ 73.00 | |

Ford®/New Holland®—Tractor

Carburetors

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 2N, 8N, 9N | | | |
| Carburetor | AMTSX241C | \$ 160.00 | |
| Application: 600, 700, 800, 900, 2000, 4000 | | | |
| Carburetor, Zenith | AMX82003 | \$ 550.00 | |
| Application: 600, 700, 2000 | | | |
| Carburetor, Zenith | AMX82002 | \$ 556.00 | |
| Replaces Marvel-Schebler TSX13, TSX28, TSX34, TSX42, TSX43, TSX49, TSX55, TSX58, TSX74, TSX88, TSX89, TSX91, TSX114, TSX120, TSX138, TSX154, TSX155, TSX156, TSX157, TSX171, TSX186, TSX188, TSX198, TSX212, TSX248, TSX253, TSX264, TSX272, TSX305, TSX308, TSX309, TSX312, TSX319, TSX333, TSX348, TSX361A, TSX363, TSX380, TSX403, TSX405, TSX418, TSX458, TSX474, TSX480, TSX500, TSX520, TSX531, TSX541, TSX653, TSX665, TSX668, TSX685, TSX730, TSX744, TSX748, TSX827, TSX864, TSX926, Zenith 09749, 09752, 10386, 10441, 10698, 11106, 11141, 11142, 11506, 12225, 12475, 12522, 13800, 13873 | | | |
| Carburetor, Zenith Replaces Marvel-Schebler TSX692, TSX765 | AMTSX765 | \$ 425.00 | |
| Application: 800 w/ 172 CID Engine | | | |
| Reman Carburetor | AMEAF9510G | \$ 195.00 | \$ 100.00 |
| Application: 800, 900, 4000 | | | |
| Carburetor | AMX82007 | \$ 567.00 | |
| Application: 800, 4000 | | | |
| Carburetor, Zenith Replaces Marvel-Schebler TSX813 | AMTSX813 | \$ 457.00 | |
| Carburetor, Zenith Replaces Marvel-Schebler TSX662, TSX769 | AMTSX769 | \$ 489.00 | |
| Application: 800, 900, 4000 | | | |
| Carburetor, Zenith | AMTSX706 | \$ 524.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, Ind: 230A, 231 | | | |
| Carburetor, Zenith | AMR8552 | \$ 646.00 | |
| Application: 2000, 2100, 2120, 2300, 2310, 2600, 2610 - w/ 3 Cylinder Engine | | | |
| Carburetor, Zenith Replaces C5NN-L | AMR3656 | \$ 669.00 | |
| Application: 2000, 3000, 4000 - w/ 3 Cylinder Engine | | | |
| Reman Holley Carburetor | AME1NN9510A | \$ 225.00 | \$ 100.00 |
| Application: 3055, 3100, 3120, 3190, 3330, 3400, 3500, 3600, Ind: 335, 340, 420, 445 | | | |
| Carburetor, Zenith | AMR7893 | \$ 634.00 | |
| Application: 4000, 4100, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4500, 4600, 4610, Ind: 515, 531, 535, 545, 550, 555 | | | |
| Carburetor, Zenith | AMR8554 | \$ 588.00 | |
| Application: 4000, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610 - w/ 3 Cylinder Engine | | | |
| Carburetor Replaces C5NN-N | AMR3657 | \$ 825.00 | |

Ford®/New Holland®—Tractor

Fuel Lift Pumps

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: Models 1965 and Later Used on Most 3, 4 and 6 Cylinder Diesel Engines | | | |
| Fuel Lift Pump | AMD8NN9350AB | \$ 20.00 | |
| Application: 5610S, 6610S, 6810S, 7010 ASN 850179M, 7610S, 8010, 8160, 8260, 8360, 8560, TB80, TB85, TB90, TB100, TB110, TB120, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115 ASN 170078, TV145 | | | |
| Fuel Lift Pump | AM87802238 | \$ 90.00 | |
| Application: 5610S, 6610S, 7610S, T4020, T4020V, T4030, T4030F, T4030N, T4030V, T4040, T4040F, T4040N, T4040V, T4050, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T5040, T5050, T5060, T5070, T6010, T6020, T6030, T6050, T6070, T4.65, T4.65V, T4.75, T4.75F, T4.75V, T4.85F, T4.85V, T4.95F, T4.95V, T4.105F, T4.105V, TD4040F, TD5010, TD5020, TD5030, TD5050, TL80A, TL90A, TL100A, TN85A, TN85DA, TN85SA, TN95A, TN95DA, TS100A, TS110A, TS115A, TS125A, TS130A, TS6000, TS6020, TS6030, TV6070, Workmaster 45, Workmaster 55, Workmaster 65, Workmaster 75, Ind/Const: B90B, B95, B95LR, B95TC, B110, B115, E175B, E215B, LB75.B, LB90.B, LB110.B, LB115.B, LM415A, LM435A, LM445A, LM1340, LM1440, LM1740, LM5040, LM5060, LM5080, LW110.B, LW130.B, M357, M427, M428, M459, M551, T13, T14, T17, VL5080, VL5090, VL6040, VL6050, VL6060, VL6090, VM370, VM460, VN2090, VM3080, VM3090, VM4090, VX7090, W110, W110TC, W130, W130TC | | | |
| Fuel Lift Pump Replaces 84268475, 84269570, 504146090 | AM2830266 | \$ 37.00 | |
| Application: 7010, 8010, TB80, TB85, TB90, TB100, TB110, TB120 | | | |
| Fuel Lift Pump | AM82980167 | \$ 75.00 | |
| Application: 5640, 6640, 7740, 7840, 8240, 8340 | | | |
| Fuel Primer Pump All Primer Assembly | AM81866602 | \$ 69.00 | |
| Application: Ind: LV80, U80 | | | |
| Fuel Transfer Pump Replaces 87473337, J917998 | AM87648717 | \$ 87.00 | |
| Application: 7530 | | | |
| Fuel Lift Pump Replaces 4765158 | AM4757884 | \$ 35.00 | |

Fuel Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 2000, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3600, 3610, 3900, 3910, 4110, 4330, 4340, 4400, 4410, 4500, 4600, 4600SU, 4610, 5000, 5340, 5600, 6600, 7000, 7600 | | | |
| Fuel Sending Unit Replaces 87712903, D8NN9A316EA, D8NN9A316EB | AMC5NN9A316B | \$ 50.00 | |
| Application: 5000, 5100, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 7000, 7100, 7600, 7610 | | | |
| Fuel Sending Unit Replaces 83917697, D8NN9A316DA, D8NN9A316DB | AMC5NN9A316A | \$ 73.10 | |
| Application: T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 | | | |
| Sensor, Fuel Pressure | AM5801567640 | \$ 200.00 | |

Injection Pumps

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 2000 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F151 | AMP2000-DPA | \$ 1,075.00 | \$ 200.00 |

Ford®/New Holland®—Tractor

Injection Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|-----------|
| Application: 2310, 2600 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F661 | AMP2310-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 2610 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F900 | AMP2610-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 3000 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F380 | AMP3000-DPA | \$ 1,075.00 | \$ 200.00 |
| Reman Injection Pump Simms, Mfg # - P4665/6 | AMP4665-6 | \$ 1,725.00 | \$ 200.00 |
| Application: 3600 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F631 | AMP3600-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 3610 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F880 | AMP3610-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 4000 | | | |
| Reman Injection Pump Roosa Master, Mfg # - DBGVCC4298AJ24A | AMP192-DBGVCC | \$ 1,350.00 | \$ 500.00 |
| Reman Injection Pump CAV, Mfg # - 3233F171, F390 | AMP4000-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 4100 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F641 | AMP4100-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 4110 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F890 | AMP4110-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 4600, 4610, Ind: 550, 555 | | | |
| Reman Injection Pump CAV, Mfg # - 3233F651, F770 | AMP4600-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 4610 | | | |
| Reman Injection Pump CAV, Mfg # - 3238F060 | AMP4600-DPAF060 | \$ 1,075.00 | \$ 200.00 |
| Reman Injection Pump CAV, Mfg # - 3233F860 | AMP4610-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 5000, Ind: 5500 | | | |
| Reman Injection Pump CAV, Mfg # - 3249F771 | AMP5000-DPA | \$ 1,075.00 | \$ 200.00 |
| Reman Injection Pump Simms, Mfg # - P4666/1 | AMP46661 | \$ 1,725.00 | \$ 200.00 |
| Reman Injection Pump Simms, Mfg # - P5024/8A | AMP5024 | \$ 1,725.00 | \$ 300.00 |
| Application: 5600 | | | |
| Reman Injection Pump CAV, Mfg # - 3249F921, F951 | AMP5600-DPA | \$ 1,097.00 | \$ 200.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Injection Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 5610 | | | |
| Reman Injection Pump CAV, Mfg # - 3242F771 | AMP5610-DPA | \$ 1,075.00 | \$ 200.00 |
| Application: 6000 | | | |
| Reman Injection Pump Simms, Mfg # - P4573/2A | AMP4573-2A | \$ 1,875.00 | \$ 300.00 |
| Application: 6600, 6700 | | | |
| Reman Injection Pump CAV, Mfg # - 3249F951 | AMP6600-DPA | \$ 1,075.00 | \$ 200.00 |
| Reman Injection Pump Simms, Mfg # - P4862/9B, P4862/9D, P5438/3A | AMP4862 | \$ 1,725.00 | \$ 300.00 |
| Application: 6610, 6710 | | | |
| Reman Injection Pump Simms, Mfg # - P5498/A, P5598/1D | AMP5498-A | \$ 1,875.00 | \$ 300.00 |
| Application: 7000 | | | |
| Reman Injection Pump Simms, Mfg # - P5144/4, P5147/4 | AMP5144-4 | \$ 1,725.00 | \$ 300.00 |
| Reman Injection Pump Simms, Mfg # - P5147 | AMP5147-4 | \$ 1,725.00 | \$ 300.00 |
| Application: 7600, 7700 | | | |
| Reman Injection Pump Simms, Mfg # - P5319/1A, P5319/5H, P5319/5J | AMP5319 | \$ 1,725.00 | \$ 300.00 |
| Application: 7610, 7710 | | | |
| Reman Injection Pump Simms, Mfg # - P5494A, P5597/1D | AMP5597 | \$ 1,875.00 | \$ 300.00 |
| Application: 8000, 8600 Early | | | |
| Reman Injection Pump Simms, Mfg # - P4784/6 | AMP4784-6 | \$ 1,875.00 | \$ 300.00 |
| Application: 8600, 8700 | | | |
| Reman Injection Pump Simms, Mfg # - P5376, P5376/2R | AMP5376-2R | \$ 1,900.00 | \$ 300.00 |
| Application: 9000, 9600 | | | |
| Reman Injection Pump Simms, Mfg # - P4784/6A | AMP4784-6A | \$ 1,913.00 | \$ 300.00 |
| Application: 9700 | | | |
| Reman Injection Pump Simms, Mfg # - P5376/H, P5376/2H | AMP5376-2H | \$ 1,865.00 | \$ 300.00 |
| Application: TW5, TW10 | | | |
| Reman Injection Pump Simms, Mfg # - P5419/A, P5579/1A | AMP5419 | \$ 1,865.00 | \$ 300.00 |
| Application: TW15 | | | |
| Reman Injection Pump Simms, Mfg # - P5636 | AMP5636 | \$ 1,875.00 | \$ 300.00 |
| Application: TW20 | | | |
| Reman Injection Pump Simms, Mfg # - P5450, P5580/1 | AMP5450 | \$ 1,900.00 | \$ 300.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Injection Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|-----------|
| Application: TW25 | | | |
| Reman Injection Pump Simms, Mfg # - P5637 | AMP5637 | \$ 1,865.00 | \$ 300.00 |
| Application: TW30 | | | |
| Reman Injection Pump Simms, Mfg # - P5451, P5581/1 | AMP5451 | \$ 1,875.00 | \$ 300.00 |
| Reman Injection Pump Simms, Mfg # - P5351 | AMP5351-TW30 | \$ 1,865.00 | \$ 300.00 |
| Application: TW35 | | | |
| Reman Injection Pump Simms, Mfg # - P5638 | AMP5638 | \$ 1,875.00 | \$ 300.00 |
| Application: TG255, TG285, TJ275, TJ325 | | | |
| CAPS Pump Replacement Kit Includes In-Line "P" 7100 Fuel Injection Pump HD, Fuel Injection Lines, Installation Components and Hardware | AMX36274 | \$ 10,700.00 | |

Injectors

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|----------|
| Application: 231, 232, 234, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 530A, 531, (2000, 3000 - w/ 3 Cylinder Engine), 2300, 2310, 2600, 2610, 2810, 2910, 3055, 3120, 3150, 3190, 3300, 3310, 3330, 3400, 3550, 4110, 4140, 4200, 4330, 4400, 4410, 4600, 4610, 5000, 5110, 5600, 5610, 5700, 5900, 6000, 6410, 6600, 6610, 6700, 6710, 6810, 7000, 7410, 7610, 7700, 7710, 7810, 7910, 8000, 8200, 8210, 8400, 8530, 8600, 8630, 8700, 8730, 8830, 9000, 9200, 9600, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35, Ind/Const: 420, 445, 445A, 450, 455, 455C, 515, 535, 540, 540A, 540B, 545, 545A, 550, 555, 555A, 555B, 655, 655A, 755, 755A, 755B, 3500, 4500, 5550, 6500, 7500 | | | |
| Fuel Injector Washers and Seals Not Included Replaces C9NN9F593B | AMC5NE9F593A | \$ 73.00 | |
| Application: 231, 233, 333, 335, 340, 450, 445, 450, 515, 532, 535, 540, 545, 2600, 3600, 3900, 4100, 4600, 5600, 5700, 6600, 6700, 7600, 7700, D175, D256 | | | |
| Injector | AMD4NN9F593A | \$ 89.40 | |
| Application: 4130, 4630 | | | |
| Injector For 201 Diesel Engine | AME9NN9F593CA | \$ 210.00 | |
| Application: 4630, 4830, 5030, 5110, 5610, 5900, 6410, 6610, 6810, 7410, 7610, 7710 | | | |
| Injector | AME7NN9F593CA | \$ 98.40 | |
| Application: 8000, 8600 | | | |
| Reman Injector Holder # - BKBL 80S 5204 Valve # - BDLL-150S6476 | NBKBL80-6476 | \$ 65.00 | \$ 30.00 |
| Application: 9000, 9600, 9700, TW20, TW30 | | | |
| Reman Injector Holder # - BKBL 80S 5389 Valve # - BDLL-150S6552 | NBKBL80-6552 | \$ 65.00 | \$ 30.00 |
| Application: TW10 | | | |
| Reman Injector Holder # - BKBL 80S 5388 Valve # - BDLL-150S6764 | NBKBL80-6764 | \$ 65.00 | \$ 35.00 |

Ford®/New Holland®—Tractor

Turbochargers

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|-----------|
| Application: Boomer 4055, Boomer 4060, T2410, T2420, TC55DA | | | |
| Turbocharger Replaces 87780726, SBA135756170, SBA135756171 | AMSBA135756172 | \$ 400.00 | |
| Application: 4630, 4630N, 4630NO, 4630O, Ind/Const: 345C, 345D, 445C, 445D, 545C, 545D - All w/ Emissionized Engine | | | |
| Turbocharger Replaces 465209-0004, 87801364 | AM87801413 | \$ 622.50 | |
| Application: 6600, 6610, 6810, 7410, 7600, 7610, 7700, 7710, Ind/Const: A62, A64, A66, 750, 753, 755A, 755B, 6500, 7500, Swather: 1118 | | | |
| Turbocharger Replaces 83959416, E6NN6K682AA | AM466746-9003 | \$ 495.00 | |
| Application: 6610S, 7010, 7610S, 7740, TB100, TB110, TS100, TS110, Backhoe-Loaders: (575E, 675E ASN 31009910), LB90, (LB110, LB115 - 4WS), Swather: 2550 ASN 60631 - All w/ Emissioned Engine | | | |
| Turbocharger T250 Replaces 87800859, 87800959 | AM465153-5004 | \$ 1,150.00 | |
| Application: (7010 ASN 850001M, TB100, TB110 - w/ Non-Emissionized Engine), 7610S, 7740, TB85, Swather: 2550 BSN 606630 | | | |
| Turbocharger Replaces 83991489, F0NN6K682AA, F0NN6K682BA | AM83999247 | \$ 1,155.50 | |
| Application: 7700 | | | |
| Turbocharger 3LDA168, Schwitzer Replaces 182990R, 83910864, 87764591, D3NN6K682A | AM182990 | \$ 811.00 | |
| Application: 8630, 8730, TW15, TW20, TW25 | | | |
| Turbocharger Replaces E2NN6K682BC | AM81868484 | \$ 692.00 | |
| Reman Turbocharger TO4B09, AiResearch Replaces 81868484, E2NN6K682BC | AM465218-4 | \$ 735.00 | \$ 200.00 |
| Application: 8670, 8670A, 8770 | | | |
| Turbocharger Replaces 87840269, 87840269T | AM87840269 | \$ 493.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970 | | | |
| Turbocharger Replaces 452173-0001 | AM87800544 | \$ 450.00 | |
| Application: 8830, TW30, TW35 | | | |
| Reman Turbocharger TO4B09, AiResearch Replaces D8NN6K682FB | AM465218-2 | \$ 710.00 | \$ 200.00 |
| Application: 8970, 8970A | | | |
| Turbocharger Replaces 81876813, 81876980, F2NN6K682CA | AM87840271 | \$ 433.50 | |
| Application: 9000, 9200, 9600 | | | |
| Reman Turbocharger Replaces 150627, C9NN6K682B | AM146718 | \$ 920.00 | \$ 200.00 |
| Application: 9700 | | | |
| Reman Turbocharger Replaces D6NN6K382C, D8NN6K682DA | AM180316 | \$ 885.00 | \$ 200.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Turbochargers (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|-----------|
| Application: T2410, T2420, TC55DA | | | |
| Turbocharger Replaces 4T507, 87772751, 87780726, 135756172 | AMSBA135756171 | \$ 454.00 | |
| Application: TD70D, TD90D, TD95D, TN70, TN70A, TN70D, TN70NA, TN70S, TN70SA, TN70VA, TN75, TN75A, TN75D, TN75S, TN75SA, TN75V, TN75VA | | | |
| Turbocharger Replaces 454163-5002S | AM99462782 | \$ 425.00 | |
| Application: TR70, TR75 | | | |
| Reman Turbocharger H54375(3LD), Holset | AM54375 | \$ 840.00 | \$ 400.00 |
| Application: Combines: TR86, TR87, TR96, TR97 | | | |
| Reman Turbocharger TO4E14, Garrett Replaces E6NN6K682CA | AM466290-9 | \$ 1,225.00 | \$ 200.00 |
| Application: Versatile®: 835, 875, 895 | | | |
| Turbocharger | AM167050 | \$ 865.00 | |
| Application: Versatile®: 836, 846 | | | |
| Turbocharger | AM178022 | \$ 800.00 | |
| Application: Versatile®: 850 | | | |
| Turbocharger | AM193903 | \$ 1,000.00 | |
| Application: Versatile®: 876 | | | |
| Turbocharger | AM168823 | \$ 710.00 | |
| Application: Versatile®: 935, 950, 956 | | | |
| Turbocharger | AM196390 | \$ 875.00 | |
| Application: Versatile®: 936, 945, 946, 955 | | | |
| Turbocharger | AM167713 | \$ 715.00 | |
| Application: S215, SE190, SE215, SE240 | | | |
| Cooler, Air-to-Air Core: 23 7/16" x 2 5/8" x 25 1/2" 3" Inlet and Outlet | AM437249A1 | \$ 1,376.00 | |
| Application: TM120, TM130, TM140, TM155 | | | |
| Cooler, Air-to-Air Core: 17 7/8" x 2 3/4" x 14 3/4" 2 1/2" Inlet and Outlet | AM82028450 | \$ 774.00 | |

Ford®/New Holland®—Tractor

Manifolds and Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Intake and Exhaust Manifold | AM9N9425 | \$ 64.00 | |
| Manifold Gasket Set Replaces 9N9448 | AMX36206 | \$ 6.00 | |
| Application: 600, 700, 800, 900, 2000, 4000, NAA - w/ 172 CID Gas Engine | | | |
| Intake and Exhaust Manifold Replaces 500683 | AMB9NN9425A | \$ 125.00 | |
| Manifold Gasket Set Replaces CONN9448C | AMX36237 | \$ 14.00 | |
| Application: 2000, 2600, 3000, 3600, 4000, 4600 - w/ 3 Cylinder Gas or Diesel Engine w/ Horizontal Exhaust | | | |
| Exhaust Manifold | AMC5NE9430A | \$ 36.00 | |
| Manifold Gasket Replaces E8NN9448AA | AMX36238 | \$ 11.00 | |
| Application: (2000 Series 1965-74, 2100, 2110, 2120, 2300, 2310, 3000 Series 1965-74, 3055, 3100, 3120, 3190, 3300 Vineyard, 3400 Utility, 3500, 3550, 4000 Series 1965-74, 4100, 4110 LCG, 4140, 4190, 4200, 4330 Narrow Orchard, 4340 Orchard, 4400, 4500 - w/ 3 Cylinder Gas or Diesel Engine), (3310, 3330 - Narrow w/ 3 Cylinder Gas or Diesel Engine) | | | |
| Exhaust Manifold | AMC5NE9430E | \$ 46.00 | |
| Application: 2310, 2600, 2610, 2810, 2910, 3600, 3610, 3910, 3930, 4110, 4600, 4610, 4630 - w/ 3 Cylinder Diesel Engine w/ Vertical Exhaust | | | |
| Exhaust Manifold | AMD3NN9430A | \$ 37.00 | |
| Manifold Gasket Replaces E8NN9448AA | AMX36238 | \$ 11.00 | |
| Application: 5000, 5100, 5200, 5340, 5900, Ind: 5190, 5500, 6500 - All w/ 4 Cylinder Diesel Engine w/ Vertical Exhaust | | | |
| Exhaust Manifold | AMC5NE9430D | \$ 46.00 | |
| Manifold Gasket Ref# C5NE9448B, E8NN9448BA, 83983680 | AMX36239 | \$ 11.00 | |
| Application: 5600, 5610, 6600 - w/ 4 Cylinder Engine | | | |
| Exhaust Manifold | AMD3NN9430B | \$ 75.00 | |
| Application: 7000, 7100, 7200 | | | |
| Exhaust Manifold | AMD1NN9430A | \$ 261.40 | |
| Application: 7910, 8210, 8700, 9700, TW10, TW20, TW30, TW35 | | | |
| Exhaust Manifold - Front Section | AMD8NN9430AB | \$ 155.00 | |
| Manifold Gasket Replaces E2NN5C250BA, C5NE9448A, E8NN9448AA | AMX36240 | \$ 14.00 | |
| Exhaust Manifold - Rear Section | AMD5NN9431A | \$ 80.00 | |
| Application: 8000, 8200, 8400, 8600, 9000, 9200, 9600 | | | |
| Exhaust Manifold - Front Section | AMC9NN9430B | \$ 128.00 | |
| Manifold Gasket Replaces E2NN5C250BA, C5NE9448A, E8NN9448AA | AMX36240 | \$ 14.00 | |
| Exhaust Manifold - Rear Section Has 4-Bolt Pattern on Top Side of Manifold Replaces C7NN9428A, C9NN9431A | AMC9NN9431B | \$ 235.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, TG215, TG245, TG275, TG305, TJ280, TJ330, Combines: (CR9040, CR9060 BSN Y8G112001) | | | |
| Exhaust Manifold - Front Section | AM87344861 | \$ 170.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mufflers and Exhaust

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: Universal Tractors | | | |
| Exhaust Pipe Diameter 3.50", Length 48" | AMS312X48 | \$ 89.00 | |
| Application: 2N, 8N, 9N | | | |
| Exhaust System - Horizontal Welded 1-Piece Muffler & Pipe Assembly w/ Flared Pipe Inlet Uses Clamp for Flared Inlet | AM8N5230 | \$ 44.00 | |
| Exhaust Pipe Assembly Inlet ID: 1 1/2", Outlet OD: 1 1/2" Includes Support Bracket Replaces LB154079, 115466 | AMAS115466AP | \$ 45.00 | |
| Application: 230A, 231, 233, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445A, 445C, 445D, 450, 455, 455D, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 550, 555, 555A, 555B, 655, 655A, 2310, 2600, 2600N, 2610, 2610V, 2910, 3230, 3430, 3600, 3600N, 3600NO, 3600V, 3610, 3610NO, 3910, 3910H, 3910N, 3910R, 3910V, 3930, 3930H, 3930N, 3930NO, 4100, 4110, 4110N, 4110O, 4110NO, 4110V, 4130, 4130N, 4130NO, 4600, 4600O, 4600NO, 4600SU, 4610LCG, 4610N, 4610O, 4610NO, 4610SU, 4610V, 4630, 4630N, 4630NO, 4630O, 5110, 5600, 5610, 5700, 5900, 6410, 6600, 6600C, 6600O, 6700, 6710, 6810, 7610, 7610O - w/ 3 or 4 Cylinder Gas or Diesel Engine w/ Vertical Exhaust w/ 3-Bolt Flange | | | |
| Exhaust Pipe Elbow Replaces D3NN5246G, D4NN5246E, D6NN5246U | AMD6NN5246N | \$ 77.00 | |
| Application: (501, 601, 701, 2000 - w/ 172 CID Gas or Diesel Engine), (801, 901, 1801, 4000 - w/ 3 Cylinder Diesel Engine), (3600, 4000, 4600 - w/ 144 CID Diesel Engine) | | | |
| Muffler Round, Inlet 2", Length 17 1/2" | AM310079 | \$ 38.50 | |
| Inlet Clamp | CL-200 | \$ 6.00 | |
| Outlet Clamp | CL-200 | \$ 6.00 | |
| Application: (600, 700 - w/ 134 CID Gas Engines 1955-57), (601, 701 - w/ 134 CID Gas Engines 1958-62), (800, 900 - w/ 172 CID Gas Engines 1955-57), (2000 Series 1963-64, NAA 1953-54 - w/ 134 CID Gas Engines) | | | |
| Muffler Horizontal Round, Inlet 1 5/8", Length 17 1/2" Replaces NAA5230E | AMNAA5230E | \$ 30.50 | |
| Inlet Clamp | CL-158 | \$ 6.00 | |
| Outlet Clamp | CL-158 | \$ 6.00 | |
| Application: 1110, 1210, 1310, 1510, 1710, 1710O, 1910, 2110 | | | |
| Muffler Vertical Replaces SBA314100541 | AMSB314100521 | \$ 95.00 | |
| Application: 2000 Series, 2100, (2110, 2120, 4140 - w/ 3 Cylinder Engines), 2300, 2310, 3000 Series, 3055, 3100, 3190, 3300, 3310, 3330, 3400, 3500, 3550, 4000 Series, 4100, 4110 01/1965-74, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 5000 Series, 5100, 5110, 5190, 5200, 5340, 5610, 5900, 6610, 6610O, 6710, 6810 04/1989-10/91, 7610, 7610O, Super Dexta | | | |
| Muffler | AMC7NN5230R | \$ 50.00 | |
| Application: 2000 Series, (2100, 3100 - 1969-1975), 2110, 2600, 3000 Series, 3600, 4110, Ind: (31, 531 -1965-81) - All w/ 3 Cylinder Diesel | | | |
| Muffler w/ Hanger Bracket Horizontal Oval, Inlet 1 3/4", Length 20 1/2" | AMC7NN5230G | \$ 55.00 | |
| Inlet Clamp | CL-134 | \$ 6.00 | |
| Application: (2000, 3000 - 1969 and Later), 2100, 2110, 2600, 3100, 3600, 4110, Ind: (231, 531 -1965 and Later) | | | |
| Horizontal Tailpipe Inlet Inside Diameter 2", Horizontal Length 47", Vertical Length 24", Outlet OD 1 3/4" | AMC7NN5245B | \$ 52.00 | |
| Application: 2000, 2600, 2610, 3000, 3600, 3610, Ind/Const: 230A, 231, 335, 340, 420, 445, 540, 540A, 540B, 2110, 3400, 3500 | | | |
| Muffler Vertical Oval Body, Inlet 6", Length 49" | AME4NN5230FA | \$ 147.50 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mufflers and Exhaust (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|------|
| Application: 2000, 3000, 4000, 4400, 5000, 5100 - w/ 3 or 4 Cylinder Gas or Diesel Engine, 1968 and Later | | | |
| Muffler Vertical Round, Inlet 1 7/8", Length 29" Replaces C7NN5230AB, C7NN5230AC | AMC7NN5230Z | \$ 46.50 | |
| Inlet Clamp | CL-178 | \$ 6.00 | |
| Rain Cap | RC-2 | \$ 20.50 | |
| Application: 2000, 3000, 4000, 4200, 5000, 5100 Series - w/ 3 or 4 Cylinder Gas, LPG or Diesel Engine, 1975 and Later | | | |
| Muffler Vertical Oval, Inlet 1 7/8", Length 39" | AMD5NN5230D | \$ 113.00 | |
| Inlet Clamp | CL-178 | \$ 6.00 | |
| Rain Cap | RC-2 | \$ 20.50 | |
| Application: 2000, 3000 Series - w/ 3 Cylinder Gas or Diesel Engine, 1964-69 | | | |
| Muffler w/ Hanger Bracket Horizontal Oval, Inlet 1 3/4", Length 29" | AMC5NN5230AH | \$ 73.00 | |
| Outlet Clamp | CL-134 | \$ 6.00 | |
| Application: 2100, 2110, 2120, 2300, 2310, 3055, 3100, 3120, 3190, 3300, 3310, 3330, 3400, 3500, 3550, 4100, 4110, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 5100, 5110, 5190, 5200, 5340, 5610, 5900, 6410, 6610, 6610O, 6710, 6810, 7610, 7610O, Super Dexta | | | |
| Muffler Replaces C7NN5230R | AM81817063 | \$ 55.00 | |
| Application: 2910, (3910, 4110 - 1981-85), 4000, (4600, 4610 - 1965-82), (6600, 6700 - 1965-80), 5000, 5600, 5700 | | | |
| Muffler Vertical Oval, Inlet 1 7/8", Length 41" | AME4NN5230GB | \$ 92.50 | |
| Application: 3000, 4000, 4100, 4600, 5000, 6600 | | | |
| Muffler Vertical Oval, Inlet 1 7/8", Length 28.25" | AMC5NN5230AR | \$ 75.00 | |
| Application: 3230, 3430, 3930, 4000, 4100, 4130, 4610, 4610SU | | | |
| Muffler Horizontal Replaces C7NN5230H | AM87704574 | \$ 65.00 | |
| Application: (5000 Series, 5600 Series, 6600 Series, 6700 Series, 7600 Series, 7700 Series - w/ 4 Cylinder Diesel 1965-75), Ind: (231, 232 - 1975-81 w/ 3 Cylinder Diesel), 4600 Series | | | |
| Muffler Vertical Oval, Inlet 1 7/8", Length 49" | AMD6NN5230T | \$ 114.00 | |
| Inlet Clamp | CL-178 | \$ 6.00 | |
| Rain Cap | RC-2 | \$ 20.50 | |
| Application: 5030, 5610, 6610, 6710, 7600, 7610, 7700, 7710 | | | |
| Muffler Vertical Oval, Inlet 2 1/2", 33 1/4" | AME5NN5230HA | \$ 75.00 | |
| Application: 5110, 5610, 5900, 6410, 6610, 6710, 6810, 7610 - w/ Vertical Exhaust w/ 4-Bolt Rectangular Flange | | | |
| Exhaust Pipe Elbow Replaces E0NN5246AA | AME0NN5246AA12B | \$ 126.00 | |
| Application: 5110, 5610, 6610, 6710, 7000, 7100, 7200, 7600, 7610, 7700, 7710 | | | |
| Muffler Vertical Oval, Inlet 4", Length 38" Replaces 83908348, 83910404, 83919567, 83919568, 83932274, 83949814, 84362368, 87295250, 87704570, D5NN5230R, D9NN5230FA, D9NN5230GA, E4NN5230DA, E4NN5230DA17M | AMD5NN5230V | \$ 121.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mufflers and Exhaust (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|------|
| Application: 5610S, 5640, 6610S, 6640, 6640O, 6810S, 7610S, 7740, TS90, TS115 | | | |
| Muffler Replaces 82011360 | AM82011369 | \$ 275.00 | |
| Application: 5640, 6640, 6640O, 7740 | | | |
| Muffler Replaces 81871353, 81874712, 83990910, 89843678, E9NN5230CA, E9NN5230CB, E9NN5230CC17M, E9NN5230CD17M, E9NN5230CE17M | AM87704575 | \$ 406.00 | |
| Application: 5640, 6640, 7740, 7740O, TS90, TS100, TS110 | | | |
| Muffler Replaces 82010856 | AM87704566 | \$ 332.00 | |
| Application: 7840, 8240, 8340 | | | |
| Muffler Replaces 82001308, 82003116, 82003737 | AM82009296 | \$ 245.00 | |
| Application: (8200, 8600 - 1968-76), (9200, 9600 - 1969-76) - All w/ 6 Cylinder Diesel Engines | | | |
| Muffler Vertical Round, Inlet 2 7/8", Length 41" | AMC9NN5230C | \$ 102.50 | |
| Application: 8360, 8560, TM125, TM135, TM150, TM165, TV140 | | | |
| Muffler Replaces 82008337, 82010811 | AM87344289 | \$ 325.00 | |
| Application: 8700 1976-78, TW10 1979-82 | | | |
| Muffler Vertical Oval, Inlet 2 3/4", Length 44" | AMD5NN5230S | \$ 191.50 | |
| Inlet Clamp | CL-234 | \$ 16.50 | |
| Rain Cap | RC-4 | \$ 23.50 | |
| Application: 9030E, 9030V | | | |
| Muffler Vertical Oval, Inlet 3", Length 43" | AM9702857 | \$ 179.00 | |
| Inlet Clamp | CL-234 | \$ 16.50 | |
| Application: 9600, 9700, TW10, TW20 | | | |
| Muffler Vertical Oval, Inlet 3 1/2", Length 44 1/2" | AMD6NN5230AJ | \$ 235.50 | |
| Inlet Clamp | CL-312 | \$ 9.00 | |
| Rain Cap | RC-8 | \$ 26.00 | |
| Application: TD55D, TD60D, TD65D, TD70D, TD75D, TD80D, TD85D, TD90D, TD95D, TD5040, TD5050, TN55, TN55D, TN55S, TN55V, TN60A, TN60DA, TN60SA, TN60VA, TN65, TN65D, TN65F, TN65N, TN65S, TN65V, TN70, TN70A, TN70F, TN70NA, TN70VA, TN75, TN75A, TN75F, TN75FA, TN80F | | | |
| Muffler Vertical Oval Body, Inlet 2", Length 14" | AM5172649 | \$ 125.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 | | | |
| Muffler Extension | AM87623361 | \$ 149.50 | |
| Application: TM120, TM130, TM140, TM155 | | | |
| Muffler, Underhood | AM82022922 | \$ 167.00 | |
| Application: TW30 | | | |
| Muffler | AME4NN5230AA17M | \$ 210.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mufflers and Exhaust (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: Versatile®: 256, 276 | | | |
| Muffler Vertical Oval, Inlet 3", Length 33 1/2" | AM9700143 | \$ 214.50 | |
| Inlet Clamp | CL-212 | \$ 6.50 | |
| Application: Versatile®: 750, 800, 825, 835, 850, 855, 875, 895 | | | |
| Muffler Vertical Oval, Inlet 5", Length 46" | AMV108431 | \$ 719.00 | |
| Rain Cap | RC-11 | \$ 37.50 | |
| Application: Versatile®: 836, 846, 856, 876 | | | |
| Muffler Inlet 4", Length 36 1/2" | AMV108093 | \$ 1,056.50 | |
| Clamp | CL-400 | \$ 9.50 | |
| Application: Versatile®: 936, 946, 956, 976 | | | |
| Muffler Inlet 5", Length 45 1/2" | AMV108094 | \$ 949.50 | |

Starters

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Starter, 6 Volt Delco 10MT | AM8N11001 | \$ 130.00 | |
| Application: 501, 600, 601, 700, 701, 800, 801, 900, 901, 4000, NAA, Jubilee | | | |
| Starter, 6 Volt 9 Tooth, CW Rotation Replaces C3NF11001A, FAC11000, FAC11001 | AMFAC11001P | \$ 206.00 | |
| Application: 600, 650, 660, 800, (2000, 4000 - w/ 4 Cylinder Engines, 1962-64), 2030, 2120, 2130, 4030, 4040, 4120, 4130, 4140 | | | |
| Starter w/ Drive Direct Drive, CW Rotation | AMC3NF11002D | \$ 170.00 | |
| Starter w/o Drive Direct Drive, CW Rotation | AMC3NF11002 | \$ 140.00 | |
| Application: 2000, 3000, 5000, 6600, 6610, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7500, 7600, 7610, 7700, 7710, 7810, 7910, 8000, 8200, 8210, 8530, 8600, 8630, 8700, 8730, 8830, 9000, 9030, 9600, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 - Diesel | | | |
| Starter, 12 Volt Lucas M50G | AM26395 | \$ 199.00 | |
| Application: 3230, 3430, 3930, 4130, 4830, 5030, 5610S, 5640, 6810S, 7010, 7610S, 7630, 7740, 7810S, 7840, 8240, 8340, LB115, TM115, TM125, TM135, TM150, TM165, TS90, TS100 | | | |
| Starter, 12 Volt Lucas M50G, 10 Tooth, 3.20kW Replaces Bosch | AM86513093 | \$ 225.00 | |
| Application: 3430, 3930, 4130, 4630, 4830, 4835, 5030, 5610S, 5640, 6610S, 6640, 7010, 7610S, 7740, 7840, 8010, 8010HC, 8160, 8240, 8260, 8340, 8360, TB80, TB85, TB90, TB100, TB110, TB120, TM115, TM125, TM135, TM150, TM165, TS100, TS115, TS125, TV140, Swathers: HW300, HW320, HW340, HW345, HW365 | | | |
| Starter, 12 Volt Planetary Gear Reduction, 10 Tooth, 3kW, CW Rotation Note: Special Order Item | AM82021372 | \$ 328.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Starters (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A - Diesel | | | |
| Starter, 12 Volt HD Planetary Gear Reduction, 10 Tooth Steel Pinions, Steel Ring Gear, 4kW, CW Rotation For Diesel Engines Replaces 1113391, 1113672 | AMX34112 | \$ 335.00 | |
| Solenoid Use w/ AMX34112 Starter | AMX34113 | \$ 68.00 | |
| Application: 8670, 8770, 8870, 8970, TV140, TV145 | | | |
| Starter, 12 Volt Delco 37MT, 10 Tooth, Direct Drive, CW Rotation Replaces 9842667 | AM1903109M91 | \$ 399.00 | |
| Application: Fordson, Fordson Hi-Drive, Fordson Super Major | | | |
| Starter, 12 Volt 11 Tooth, CW Rotation Replaces 81712422, E1ADDN11000D | AM26072 | \$ 631.50 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9020, TG215, TG245, TG275 | | | |
| Starter, 12 Volt Gear Reduction, 10 Tooth, 4.20kW Note: Special Order Item Replaces 84213446 | AM87425232 | \$ 385.00 | |
| Application: PowerStar™ 90, PowerStar™ 100, PowerStar™ 110, PowerStar™ 120, T4030F, T4040, T4040F, T4050, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T5040, T5050, T5060, T5070, T4.75F, T4.85F, T4.90, T4.95F, T4.95V, T4.100, T4.105F, T4.105V, T4.110, T4.120, T5.90, T5.95, T5.100, T5.105, T5.110, T5.115, T5.120, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T6.120, T6.140, T6.150, T6.160, T6.175, T7030, T7040, T7050, T7060, T7070, T7.170, T7.185, T7.200, T7.210, T7.220, T7.230, T7.235, T7.240, T7.245, T7.250, T7.255, T7.260, T7.270, TC5070, TD5050, TD5.105, TD5.95, TK4050, TL80A, TL100A, TM7010, TM7020, TM7030, TM7040, TN85A, TN85SA, TN95A, TS90, TS100, TS110, TS6.100, TS6.120, TS6.125, TS6.140, TS7020, TT60A, Workmaster 95, Workmaster 105, Workmaster 120 | | | |
| Starter Bosch, 10 Tooth, 4kW, CW Rotation Bosch Mfg # - 504357110 Iskra Mfg # - IS1109 | AM84151331 | \$ 335.00 | |
| Application: TD60D, TD70D, TD80D, (TD90D, TD95D - Upgrade) | | | |
| Starter, 12 Volt 9 Tooth, CW Rotation | AM84273182 | \$ 391.90 | |
| Application: TD75D, TD80D, TD90D, TD95D, TL70, TL80, TL90, TL100, TN65F, TN70F, TN75F, TN75FA, TN80F, TN85FA, TN90F, TN95F, TN95FA, TN95NA, TN95VA, TT55, TT60A, TT65, TT75, TT75A | | | |
| Starter, 12 Volt Replaces 82980757, 87538219, 500338952 | AM5801441814 | \$ 195.00 | |
| Application: Utility: 1320, 1520, 1530, 1620, 1630, 1710, 1715, 1720, 1725, 1925, T1510, T1520, T2210, TC25, TC25D, TC29, TC29D, TC29DA, TC30, TC31DA, TC33, TC33D, TC33DA | | | |
| Starter, 12 Volt 9 Tooth | AMSBA185086551 | \$ 107.00 | |
| Application: Utility: 1920, 2120 ASN UV32235, 3415, T1520, T2220, T2310, T2320, T2330, T2410, T2420, TC34DA, TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA, TC45, TC45A, TC45D, TC45DA, TC48DA, TC55DA, TT45A, TT50A | | | |
| Starter, 12 Volt 11 Tooth | AMSBA185086530 | \$ 145.00 | |
| Application: Versatile®: 256 | | | |
| Starter, 12 Volt Delco 28MT 10 Tooth, 2.5 kW, CW Rotation | AM82501755 | \$ 290.00 | |

Ford®/New Holland®—Tractor

Starters (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: Swathers: H8040, H8060, H8080, Speedrower Swathers: 130, 200, 240 | | | |
| Starter, 12 Volt Gear Reduction, 10 Tooth, 4.20kW Replaces 87054526 | AM87577368 | \$ 341.00 | |
| Application: TR75, TR85, TR86, TR87, TR88, TR89, TR95, TR96, TR97, TR98, TR99, Swathers: 1100 ASN 425318, 1112 ASN 325611, 1114, 1116, 1118, 2450, 2550, HW300, HW305, HW305S, HW320, HW340 | | | |
| Ignition Switch Replaces 529713, 8641833, 80641833 | AM641833 | \$ 22.40 | |
| Application: Utility: 1000, 1100, 1110, 1200, 1210, 1300, 1310, 1500, 1510, 1600, 1700, 1710, 1900, 1910, 2110 | | | |
| Ignition Switch | AMSBA385200331 | \$ 49.90 | |
| Application: 2N, 8N BSN 263844, 9N | | | |
| Resistor Replaces 501933 | AM8NE10306 | \$ 6.00 | |

Distributors

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 2N, 8N BSN 263844, 9N | | | |
| Distributor, Front Mount | AM9N12100 | \$ 160.00 | |
| Application: 8N ASN 263843 | | | |
| Distributor, Side Mount | AM8N12127B | \$ 200.00 | |
| Application: 600, 700, 800, 2000, 4000 - w/ 4 Cylinder Engines | | | |
| Distributor | AMFDN12127A | \$ 159.00 | |
| Application: 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, 3330, 3400, 3500, 3600, 3610, 3910, 4000, 4100, 4110, 4140, 4200, 4330, 4340, 4400, 4500, 4600, 4600SU, 4610, 4610SU, Ind/Const: 230A, 234, 334, 335, 340, 340A, 340B, 420, 445, 450, 3550 | | | |
| Distributor For 3 Cylinder Engines Replaces 47821367, C7NF12127D, F0NN12100AA, F1NN12100AA, FDS3329 | AM47573265 | \$ 115.00 | |
| Application: Jubilee, NAA | | | |
| Distributor w/ Slotted Shaft Replaces FAC12127D | AM86643560 | \$ 115.00 | |

Ford®/New Holland®—Tractor

Air Cleaner Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 8N | | | |
| Air Cleaner Assembly | AM8N9600B | \$ 100.00 | |
| Application: 233, 2000 Series, 2100, (2110, 2120 - w/ 3 Cylinder), 2300, 2310, 2600, 2600N, 2600R, 2600V, 3000 Series, 3055, 3100, 3120, 3190, 3300, 3310, 3330, 3600, 3600N, 3600NO, 3600R, 3600V, 4000 Series, 4100, (4110, 4140 - 1965-74), 4190, 4200, 4330, 4340, 4600, 4600NO, 4600O, 4600SU, 5000 Series, 5100, 5190, 5200, 5340, 5600, 6600C, 6600O, 6700, Super Dexta, Ind: 231, 333, 531, 532, 3400, 4400, 4410 | | | |
| Air Cleaner Assembly | AMC5NE9600E | \$ 75.00 | |
| | AMC5NE9600F | \$ 75.00 | |
| Application: (600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000, NAA - w/ 4 Cylinder Engine) | | | |
| Air Funnel | AMNAA9684A | \$ 34.50 | |
| Air Cleaner Vent Tunnel | | | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3120, 3190, 3230, 3300, 3310, 3330, 3400, 3430, 3600, 3610, 3900, 3910, 3930, 4000, 4110, 4130, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4600, 4610, 4630, 4830, 5000, 5030, 5200, 5340, 5600, 5610, 5700, 5900, 6000, 6410, 6600, 6610, 6700, 6710, 6810, 7410, 7600, 7610, 7700, 7710, Ind/Const: 230A, 231, 233, 234, 334, 335, 530A, 531, 532 Replaces CONN9A633A | | | |
| Small Precleaner Bowl 7" Diameter | AMP02-0227 | \$ 10.00 | |
| Application: 2N, 8N, 9N, 600, 620, 630, 640, 650, 660, 700, 740, 800, 820, 840, 850, 860, 900, 950, 960, NAA, NAB | | | |
| Air Cleaner Hose 1.50" ID, 1.875" OD, 2.562" Long | AM9N9652 | \$ 4.00 | |
| Application: (500 Series, 600 Series, 700 Series, 800 Series, 900 Series, 2031, 2111, 2120, 2131, 4030, 4031, 4040, 4120, 4121, 4130, 4131 - w/ 134" Gas Engine), (501, 601 - w/ 4 Cylinder Engine, 1957-62), (541, 611 - w/ 4 Cylinder Engine, 1959-64), 620 w/ 4 Cylinder Engine, 1954-64, (621, 631, 641, 651 - w/ 4 Cylinder Engine, 1958-64), (2000, 4000 - Prior to 1964 w/ 134" Gas Engine), (4110TR, 4140 - w/ 4 Cylinder Engine, 1963-64), Ind: (1801, 1811, 1821, 1841, 1871, 1881, 2030, 2130 - w 134" Gas Engine) | | | |
| Air Cleaner Hose 1.50" ID | AM311112 | \$ 46.60 | |
| Application: (2000, 3000, 4000 - Diesel), 2100 03/1965-74 w/ 3 Cylinder Engine, (2110, 2300, 3055, 4100, 4110, 4190, 4200, 4330, 4340, 4410 - 1965-74 w/ 3 Cylinder Engine), Ind: 3500, 3550, 4500 1965-74 w/ 3 Cylinder Engine | | | |
| Air Cleaner Hose, Lower 2" & 2.25" ID | AMCSNN9B640B | \$ 16.80 | |
| Application: 2600, 2610, 2810, 2910, 3230, 3430, 3600, 3610, 3900, 3910, 3930, 4100, 4110, 4130, 4600, 4610, 4630, 4830, 5030, 5110, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6610, 6640, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7600, 7610, 7700, 7740, 7810, 7910, 8000, 8200, 8210, 8400, 8530, 8600, 8630, 8700, 9000, 9030E, 9030V, 9200, 9600, 9700, TS90, TW5, TW10, TW15, TW20, Ind/Const: 230A, 231, 233, 234, 333, 334, 335, 515, 530A, 531, 532 Replaces 594075 | | | |
| Large Precleaner Bowl 10.50" Diameter | AMP01-6330 | \$ 12.00 | |

Alternators

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 2N, 8N w/ Front Mount Distributor, 9N | | | |
| Alternator Conversion Kit Includes 12 Volt Alternator, Brackets, Coil, Wiring Harness and Resistor | AMX19007 | \$ 183.00 | |
| Application: 8N w/ Side Mount Distributor | | | |
| Alternator Conversion Kit Includes 12 Volt Alternator, Brackets, Wiring Harness and Resistor | AMX34152 | \$ 159.00 | |
| Application: 501, 600, 700, 800, 900, (2000, 4000 - w/ 4 Cylinder Engine) | | | |
| Alternator Conversion Kit Includes 12 Volt Alternator, Brackets, Wiring Harness and Resistor | AMX34153 | \$ 435.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Alternators (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 230A, 231, 233, 234, 333, 334, 335, 530A, 531, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2810, 2910, 3600, 3600NO, 3600R, 3600V, 3610, 3610NO, 3900, 3910, 3910H, 3910N, 3910R, 4110, 4110N, 4600, 4600NO, 4600O, 4600SU, 4610, 4610O, 4610SU, 5600, 5700, 6600, 6600C, 6600O, 6700, 7600, 7700 Alternator w/ 6-Groove Pulley Lucas, Mfg # - 23814, 24211, 12 Volt, 43 Amps, IR/IF, CW Rotation Replaces D6NN10B376A | AM23814 | \$ 175.00 | |
| Application: 2310, 2600, 2610, 2810, 2910, 3600, 3610, 3900, 3910, 4100, 4110, 4600, 4610, 5600, 5610, 5900, 6600, 6610, 6700, 6710, 7600, 7610, 7700, 7710, 8600, 8700, 9600, 9700, Ind: 231, 233, 234, 250C, 260C, 333, 334, 335, 340, 345C, 420, 445, 445A, 445C, 450, 515, 530A, 531, 532, 535, 540, 545, 545A, 545C, 550, 555, 555A, 555B, 655A, 750, 755, 755A Alternator 12 Volt, 51 Amps Replaces Motorola 8AL2055FA, 8AL2056K, 8AL2056KA | AMD5NN10300E | \$ 164.00 | |
| Application: 2600, 2610, 2810, 2910, 3230, 3430, 3600, 3610, 3900, 3910, 3930, 4100, 4110, 4130, 4600, 4610, 4630, 4830, 5030, 5110, 5610, 5610S, 5640, 6610, 6640, 7610, 7710, 7740, 7810, 7840, 8240, 8340, Ind: 231, 233, 234, 250C, 260C, 333, 334, 335, 345C, 345D, 420, 445C, 445D, 455, 455C, 455D, 515, 531, 532, 535, 530A, 545C, 545D, 555C, 555D, 575D, 655C, 655D, 675D Alternator Lucas, 12 Volt, 45 Amps, IR/EF, CW Rotation 1-Groove Pulley Replaces 81863039, 81868798, 83961474 | AM82857207 | \$ 135.00 | |
| Application: T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T5.95, T5.105, T5.115, T6.120, T6.140, T6.150, T6.160, T6.175, T7.170, T7.185, T7.200, TD5.85, TD5.95, TD5.105, TD5.115 Alternator 14 Volt, 120 Amps Note: Special Order Item Replaces 84141452 | AM87361082 | \$ 225.00 | |
| Application: T7030, T7040, T7050, T7060 Alternator w/o Pulley 12 Volt, 150 Amps, IR/IF, CW Rotation | AM87452821 | \$ 220.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, T9030, T9040, T9050, T9060, T9.450, T9.480, T9.505, T9.530, T9.560, T9.565, T9.615, T9.670, TG215, TG245, TG275, TG305, TJ280, TJ330, TJ380, TJ430, TJ480, TJ530 Alternator 12 Volt, 200 Amps, IR/IF | AM87715398 | \$ 434.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305, Sprayers: Patriot 250, SP2500 Alternator 14 Volt, 175 Amps Note: Special Order Item Replaces 87645567 | AM87418226 | \$ 360.00 | |
| Application: (TG210, TG230, TG255, TG285 BSN JAW135316), TJ275, TJ325, TJ375, TJ425, TJ450, TJ500 Alternator w/o Pulley 12 Volt, 135 Amps, IR, CW Rotation Replaces 91448C1, 86994128 | AM125849A1 | \$ 250.00 | |
| Application: TL70, TL80, TL90, TL100 - w/ Cab Alternator 14 Volt, 65 Amps Replaces 84402418, 84402419, 84522025 | AM84402417 | \$ 160.00 | |
| Application: TM120, TM130, TM140, TM155, TM175, TM190 Alternator 14 Volt, 120 Amps Note: Special Order Item Replaces 47744887 | AM87361085 | \$ 285.00 | |

Ford®/New Holland®—Tractor

Alternators (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: Ind/Const: B95, B95LR, B95TC, B110, B115 | | | |
| Alternator 14 Volt, 60 Amps Replaces 84254289, 84416587, Denso 1022119090 | AM87422777 | \$ 161.00 | |
| Application: Utility: 1320, 1520, (1530, 1630, 1725, 1925, T2210, T2220, TC31DA, TC34DA - w/o Cab), 1620, 1715, 1720, 1920, 2120, 3415, T1510, T1520, T2310, T2320, T2330, TC25, TC25D, TC29, TC29D, TC29DA, TC30, TC33, TC33D, TC33DA, TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA, TC45, TC45A, TC45D, TC45DA, TT45A, TT50A | | | |
| Alternator 12 Volt, 40 Amps | AMSBA185046320 | \$ 149.00 | |
| Application: 1100, 1120, 1200, 1210, 1220, 1300 Replaes SBA185516010 | | | |
| Voltage Regulator 12 Volt - 14.30 volt setting, B-circuit, Single multi-spade (6) connector w/ pins: I - N - F - E - L - B, +IG female bullet pigtail Solid State unit to replace original mechanical unit | AM70000-65398 | \$ 67.00 | |

Sensors

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: Powerstar 65, Powerstar 75, T3.60F, T3.70F, T3.80F, T4.55, T4.65, T4.75, T4.80F, T4.85, T4.90F, T4.95, T4.100F, T4.105, T4.110F, T4.115, T4.120F, T5050, T5060, T5070, T5.95, T5040, T6010, T6020, T6030, T6.120, T6.140, T6.150, T6.155, T6.160, T6.165, T6.175, TS.105, TS.115 | | | |
| Solenoid Valve | AM84273815 | \$ 194.50 | |
| Application: (5110, 5610, 5610S, 5640, 6410, 6610, 6610S, 6640, 6810, 6810S, 7010, 7610, 7710, 7740, 7810, 7810S, 7840, 7910, 8010, 8210, 8240, 8340, 8530, 8630, 8730, 8830, TB80, TB85, TB90, TB100, TB110, TB120, TS90, TS100, TS110, TS6000, TS6020, TS6030 - w/ Carraro™ Front Axle 1987 and Later), 77400 11/1991-01/98 - w/ 4 Cylinder Engine, (78100 02/1988-10/91, 78400 02/1993-01/98 - w/ 6 Cylinder Engine) | | | |
| Solenoid Valve, 4WD Engage Replaces 100739A1, 139307A1 | AM81870291 | \$ 227.30 | |
| Application: T6030, T6050, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T6.125, T6.145, T6.155, T6.165, T6.175, T6.180, T7.165, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.220, T7.225, T7.235, T7.250, T7.260 | | | |
| Sensor, Fuel Pressure Replaces 2859145, 504123163, 504222094 | AM2854542 | \$ 170.00 | |
| Application: T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, (T9030, T9040 ASN Z6F200013), T9050 ASN Z7F204001, T7.165S, T7.175, T7.190, T7.210, T7.225, T7.230, T7.245, T7.260, T7.270, T7.315, TJ380, TJ430 | | | |
| Sensor, Oil Pressure and Temperature Replaces 4890193 | AM504358206 | \$ 76.10 | |
| Application: T7.290, T7.315 | | | |
| Switch, Engine Exhaust Pressure Replaces 2859674, 4890193, 6901334 | AM504358206 | \$ 76.10 | |
| Application: T9030, T9040, T9050, TJ380, TJ430 | | | |
| Sensor, Clogged Fuel Filter Indicator | AM500346371 | \$ 40.00 | |
| Application: T5.110, T5.120, T5.130, T5.140, T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7030, T7040, T7050, T7060, T7070, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.275, T7.290, T7.300, T7.315, TM175, TM190, TS100A, TS110A, TS115A, TS130A, TS135A | | | |
| Solenoid Valve 4.44" Long, 2 Terminals For Transmission or PTO Valves | AM87472229 | \$ 171.10 | |
| Application: T5.110, T5.120, T5.130, T5.140, T6.125, T6.145, T6.155, T6.160, T6.165, T6.175, T6.180, T7.195S, T7.215S, T7.230, T7.245, T7.260, T7.270, T7.275, T7.290, T7.315, T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 | | | |
| Steering Angle Sensor | AM47700274 | \$ 220.00 | |

Ford®/New Holland®—Tractor

Tachometers and Instrument Clusters







| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 500, 600, 700, 800, 900, 2000, 4000 Series, Jubilee, NAA - 1953-64 4 Cylinder with 4-Speed Transmission | | | |
| Tachometer | AMC3NN17360N | \$ 44.50 | |
| Application: (600 Series, 800 Series, 900 Series, 2000 Series, 4000 Series - 1955-64 w/ 4 Cylinder Engine, w/ 5-Speed Transmission) | | | |
| Tachometer | AMC3NN17360K | \$ 25.00 | |
| Application: 2000, 3000, 4000, 5000, 7000 Series, 7100, 7200, Ind: 3500, 3550 | | | |
| Instrument Cluster For 3 and 4 Cylinder Tractors Equipped w/ Generators, CW Sweep | AMEHPN10849A | \$ 153.00 | |
| Application: 2310, 2600, 2610, 2810, 2910, 3600, 3610, 3910, 4610, 5600, 5610 Prior to 1987, 6600, 6610 Prior to 10/1985, 7600, Ind: 231, 335, 340, 445, 531, 540 | | | |
| Instrument Cluster CCW Sweep Replaces E5NN10849BA, E7NN10849BA | AMD8NN10849TB | \$ 152.00 | |
| Application: 2600, 2610, 3600, 3610, 4100, 4110, 4600, 4610, 5600, 5610, 6600, 6610, 7600, 7610 | | | |
| Instrument Cluster For 3 and 4 Cylinder Tractors Equipped w/ Alternators, CCW Sweep | AME5NN10849BA | \$ 147.00 | |
| Application: 3830, 4030, 4230, 4330, 4430, 7530 | | | |
| Instrument Cluster Replaces 5125046, 5133783 | AM5145186 | \$ 240.00 | |
| Application: 2600, 2610, 2810, 3230, 3430, 3600, 3610, 3930, 4100, 4110, 4130, 4600, 4610, 4630, 4830, 5030, 5110, 5600, 5610, 5700, 5900, 6500, 6600, 6610, 6700, 6710, 7600, 7610, 7700, 7710, Ind/Const: 230A, 231, 233, 234, 250C, 260C, 333, 335, 340, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 545, 545D, 550, 555, 655, 750, 755 | | | |
| Tachometer Drive Assembly Replaces 87800006 | AMD3NN17N264B | \$ 30.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3100, 3110, 3120, 3230, 3300, 3400, 3430, 3500, 3550, 3600, 3610, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4200, 4330, 4340, 4400, 4410, 4500, 4600SU, 4610, 4630, 4830, 5000, 5030, 5100, 5200, 5340, 5600, 5610, 5900, 6600, 6610, 6710, 7000, 7600, 7610, Fordson Major, Fordson Super Major, Ind/Const: 230A, 233, 234, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 540A, 545, 545A, 545C, 545D, 750, 755A, 755B, 3500, 3550, 4140, 4400, 4500 | | | |
| Tachometer Cable Replaces C7NN17365B, D3NN17365C, D9NN17365AA, D9NN17365AB, E1ADDN17365C, E1NN17365BA, E9NN17365AA | AMD3NN17365F | \$ 12.00 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3100, 3110, 3120, 3230, 3300, 3400, 3430, 3500, 3550, 3600, 3610, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4200, 4330, 4340, 4400, 4410, 4500, 4600SU, 4610, 4630, 4830, 5000, 5030, 5100, 5200, 5340, 5600, 5610, 5900, 6600, 6610, 6710, 7000, 7600, 7610, Fordson Major, Fordson Super Major, Ind/Const: 230A, 233, 234, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 750, 755A, 755B, 3500, 3550, 4140, 4400, 4500 | | | |
| Tachometer Cable Replaces C7NN17365B, D3NN17365C, D3NN17365F, D9NN17365AA, D9NN17365AB, E1ADDN17365C, E1NN17365BA, E9NN17365AA | AM1970820C1 | \$ 14.00 | |
| Application: 2000, 2110, 2120, 2150, 2300, 2310, 3000, 3055, 3300, 3310, 3330, 3400, 3500, 3550, 4110, 4140, 4330, 4340, 4400, 4410, 4500, 5340 | | | |
| Tachometer Cable | AMC7NN17365A | \$ 11.00 | |
| Application: (2000, 2110, 2120, 4000, 4130 w/o Cab, 4140 - w/ 3 Cylinder Engine), 2100, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, (3230, 3430, 3930, 4630, 4830 - w/o Cab), 3300, 3310, 3330, 3400, 3500, 3550, 3600, 3610, 3900, 3910, 4100, 4110, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, 4610SU, 5000, 5030, 5100, 5110, 5200, 5340, 5600, 5610, 5900, 6410, 6600, 6610, 6810, 7000, 7100, 7200, 7600, 7610, Ind/Const: 30A, 231, 233, 234, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 750, 755, 755A, 755B | | | |
| Tachometer Cable 47 7/16" Long Replaces 82847520, E1ADDN17365C, E9NN17365AA | AMD9NN17365AB | \$ 15.10 | |
| Application: (5110, 5610, 6410, 6610, 6810, 7610 - w/ Q-Cab and Mechanical Instrument Cluster), 5700, 6700, 6710, 7700, 7710 | | | |
| Tachometer Cable Replaces 83904959 | AMD5NN17365D | \$ 20.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor








Mechanical Front Wheel Drive Parts

MFWD Hubs and Housings

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 5600, 5700, 6600, 6700 - w/ APL1351 Front Axle  Front Axle Replaces ZP1927860 | AMAL33349 | \$ 200.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 Front Axle Housing, Super Steer | AM87404286 | \$ 6,500.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, T8.275*, T8.330*, T8.360*, T8.390*, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12-Bolt Hubs), (TG210, TG230 BSN MY00182861 w/ 10-Bolt Hubs) *Prior to 06/14/2013 w/o CVT w/ DANA® Axle w/ Differential Lock  Axle Housing For Suspended Axles w/ Differential Lock | AM87404290 | \$ 3,250.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275*, T8.330*, T8.360*, T8.390 w/o CVT, TG210**, TG215, TG230**, TG245, TG255, TG275, TG285, TG305 *w/o CVT w/ DANA® Axle or w/ CVT w/ DANA® Axle w/o Differential Lock **BSN MY00184591 w/o Differential Lock or All w/ Differential Lock  Axle Housing For Standard Axles w/ 12-Bolt Hubs w/ or w/o Differential Lock | AM87404249 | \$ 3,500.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305  Axle Housing For Standard Axles w/ 10-Bolt Hubs w/ or w/o Differential Lock For Specialty Axles w/ 10-Bolt Hubs w/o Differential Lock | AM87404246 | \$ 3,250.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285  Axle Housing Suspended Axles w/ 10-Bolt Hubs w/ Differential Lock | AM87404289 | \$ 5,835.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ DANA® Axle), (T8.275, T8.330, T8.360, T8.390 - w/ DANA® Axle w/o CVT)  Cradle For Suspended Axles | AM87406430 | \$ 1,150.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245 - w/ Suspended Axles w/ 12-Bolt Hubs or w/ 10-Bolt Hubs w/ Differential Lock), (TG255, TG285 - w/ Suspended Axles w/ 12-Bolt Hubs or ASN MY00183034 w/ 10-Bolt Hubs w/ Differential Lock), (TG275, TG305, T8.275*, T8.330*, T8.360*, T8.390* - w/ Suspended Axles w/ 12-Bolt Hubs) *Prior to 06/14/2013 w/o CVT w/ DANA® Axle w/ Differential Lock Front Axle Pin | AM87406480 | \$ 245.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Suspended Axle Suspension Cylinder Pin For Upper and Lower Ends of Cylinder | AM87406468 | \$ 200.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 Pivot Pin For Suspended Suspension | AM87406467 | \$ 300.00 | |

Ford®/New Holland®—Tractor








Mechanical Front Wheel Drive Parts MFWD Hubs and Housings (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, (T8.275, T8.330, T8.360, T8.390 - w/ DANA® Axle), TG210, TG215, TG245, TG255, TG275, TG285, TG305 | | | |
|  Suspension Cylinder, Right Hand For Suspended Axles | AM87406484 | \$ 2,325.00 | |
|  Suspension Cylinder, Left Hand For Suspended Axles | AM87406483 | \$ 985.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, (T8.275, T8.330, T8.360 - w/ DANA® Axle), TG210, TG215, TG245, TG255, TG275, TG285, TG305 | | | |
|  Lower Swing Arm For Suspended Axles | AM87406431 | \$ 1,850.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Suspended Axles), (T8.275, T8.330, T8.360 - w/ Suspended Axles w/o CVT w/ DANA® Axle) | | | |
| Upper Swing Arm Pin | AM87406452 | \$ 265.00 | |
| Lower Swing Arm Pin | AM87406451 | \$ 265.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Suspended Axle), (T8.275, T8.330, T8.360 - w/ Suspended Axle w/ DANA® Axle) | | | |
| Swing Arm Pin | AM87406453 | \$ 450.00 | |
| Application: 8530, 8630, 8670, 8730, 8770, 8830, 8870, 8970 - w/ Standard Steer Axle | | | |
|  Hub Assembly w/ Knuckle, Right Hand | AMX4110102 | \$ 5,500.00 | |
|  Hub Assembly w/ Knuckle, Left Hand | AMX4110103 | \$ 5,500.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Hub Assembly w/ Knuckle, Right Hand 12-Bolt For Super Steer Replaces 302174A1, 87404300 | AMX41136 | \$ 4,750.00 | |
|  Hub Assembly w/ Knuckle, Left Hand 12-Bolt For Super Steer Replaces 302174A1, 87404298 | AMX41135 | \$ 4,750.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Mechanical Front Wheel Drive Parts MFWD Hubs and Housings (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|----------------|--------------|------|
| Application: | 8530, 8630, 8670, 8730, 8770, 8830, 8870, 8970 | | | |
|  | Hub Assembly | AMX411116 | \$ 3,675.00 | |
| Application: | 8670, 8770, 8870, 8970 | | | |
| | Hub Assembly | AM86025945 | \$ 4,500.00 | |
| | 10-Bolt Hub | | | |
| | 4-Gear Assembly | | | |
| Application: | 5600, 5700, 6600, 6700 - w/ APL1351 Front Axle | | | |
|  | Steering Knuckle, Right Hand | AMZP4468358032 | \$ 390.00 | |
|  | Steering Knuckle, Left Hand | AMZP4468358031 | \$ 390.00 | |
| Application: | 8670, 8770, 8870, 8970 | | | |
|  | Steering Knuckle, Right Hand 1 1/4" Tie Rod Hole Diameter For Super Steer | AM86015342 | \$ 650.00 | |
|  | Steering Knuckle, Left Hand 1 1/4" Tie Rod Hole Diameter For Super Steer | AM86015341 | \$ 650.00 | |
|  | Steering Knuckle, Right Hand 10-Bolt, 1 1/8" Tie Rod Hole Diameter | AM86015340 | \$ 650.00 | |
|  | Steering Knuckle, Left Hand 10-Bolt, 1 1/8" Tie Rod Hole Diameter For Standard Steer | AM86015339 | \$ 650.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.







Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts MFWD Hubs and Housings (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: T4020, T4030, T4030F, T4030N, T4040, T4040F, T4040N, T4050, T4050F, T4050N, T4060F, T4060N, T4.75F, T4.80F, T4.85F, T4.90F, T4.95F, T4.100F, TN55S, TN60SA, TN70NA, TN70S, TN70SA, TN75DA, TN75FA, TN75SA, TN85FA, TN85SA, TN90F, TN95FA, TN95NA | | | |
|  Steering Knuckle, Right Hand | AM5184889 | \$ 265.00 | |
|  Steering Knuckle, Left Hand | AM5184894 | \$ 265.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 | | | |
|  Steering Knuckle, Right Hand For Super Steer | AM87404296 | \$ 1,495.00 | |
| Steering Knuckle, Left Hand For Super Steer | AM87404291 | \$ 1,600.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 | | | |
|  Steering Knuckle, Right Hand 12-Bolt For Super Steer | AM87404300 | \$ 1,700.00 | |
| Steering Knuckle, Left Hand 12-Bolt For Super Steer | AM87404298 | \$ 2,065.00 | |
| Application: 5640, 6640, 6640O, 7740, 7740O, 7840, 7840O, 8240, 8340 | | | |
|  Trunnion, Upper Replaces 1995414C1, B503049, CAR125149 | AM81863173 | \$ 110.00 | |
| Application: 5640, 6640, 6640O, 7740, 7740O, 7840, 7840O, 8240, 8340, Ind/Utility: 250C, 340B, 345C, 345D, 445, 445A, 445C, 445D, 450, 455, 455C, 455D, 540, 540B, 545, 545A, 545C, 545D | | | |
|  Trunnion, Lower Replaces 3475348M1, 83952503, 153326212 | AMN13504 | \$ 83.00 | |

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts MFWD Hubs and Housings (...continued)







| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 5600, 5700, 6600, 6700 | | | |
|  Trunnion Replaces 122259A1, 3311329M91, 3311331M91, 3523550M1, 6190566M1, 47108554, 81863002, 82850292, 137700410855, CAR12881 | AML35606 | \$ 30.00 | |
| Application: 5610S, 6610S, 6810S, 7610S, TB80, TB85, TB90, TB100, TB110B, TB120, TS6000, TS6020, TS6030 | | | |
|  Trunnion Replaces 122259A1, 3311329M91, 3311331M91, 3523550M1, 6190566M1, 47108554, 81863002, 82850292, 137700410855, CAR12881 | AM9968025 | \$ 65.00 | |
| Application: (5640, 6640, 7740 - 10/1994 and Later), (7840, 8240, 8340 - 1995 and Later), 8160, 8260, TD75D, TD80D, TD90D, TD95D, TD5030 (Tier 3), TD5050, TL80, TL80A, TL90, TL90A, TL100, TL100A, TM115, TM120, TM125, TM130, TM135, TM140, TS90, TS100, TS100A, TS110, TS110A, TS115, TS115A, TS125A, TS130A, TS135A | | | |
| Trunnion | AM5137239 | \$ 82.20 | |
| Application: 5640, 6640, 7740, 7840, 8240, 8340, Ind/Const: 345C, 345D, 445C, 445D, 455C, 455D, 545C, 545D, 555C, 555D, 555E, 575E, 655, 655A, 655C, 655D, 655E, 675D, 675E | | | |
|  Upper Bearing, King Pin 1.378" ID, 2.047" OD, 0.65" Thick Replaces N14372 | AM9967999 | \$ 39.50 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 | | | |
|  Shim Kit Replaces 1277247C1, B94587, B94585 | AM1981236C1 | \$ 35.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, T8.275 w/o CVT, TG255, TG275, TG285, TG305 - w/ Standard Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Suspended Axle w/ 12-Bolt Hubs w/ Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ SuperSteer™ Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), T8.275* w/ Suspended Axle w/ 12-Bolt Hubs w/ Differential Lock, (TG210, TG215, TG230 ASN MY00184591, TG245 - w/ Standard Axle w/ 12-Bolt Hubs w/ Differential Lock), (TG210 ASN MY00184591, TG230 - w/ Standard Axle w/ 12-Bolt Hubs w/o Differential Lock), (T8.275 w/o CVT w/ DANA® Axle w/ 12-Bolt Hubs w/o Differential Lock) *Prior to 06/14/13 w/o CVT | | | |
|  Shim Kit For Upper and Lower Trunnion Caps | AM313557A1 | \$ 125.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Shim Kit | AM310960A1 | \$ 125.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Suspended Axles), (T8.275, T8.330, T8.360 - w/ Suspended Axles w/o CVT w/ DANA® Axle) | | | |
| Plate | AM87406476 | \$ 800.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts






MFWD Hub Components

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: 8670, 8770, 8870, 8910, 8920, 8970  Carrier Flange Assembly 3-Pin Hub 86017447, 87780417, B94587 | AM86020261 | \$ 1,800.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285  Carrier Flange Assembly 4-Pin Hub, 10-Bolt Flange Includes Flange, Gears, Needle Bearings and Thrust Washers | AM302251A2 | \$ 1,960.00 | |
| Application: 8670, 8770, 8870, 8970 Flange Assembly 10-Bolt Hub Replaces 86002342, 86505121 | AM86025944 | \$ 1,000.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285  Flange Assembly 10-Bolt Hub Replaces 295165A1, 87588833 | AM302173A1 | \$ 950.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 Flange 10-Bolt Hub Bolts and Bearings Not Included | AM87588833 | \$ 850.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305  Planetary Gear Kit For 10-Bolt Hub | AM316330A2 | \$ 700.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305  Planetary Gear Kit For 12-Bolt Hub | AM316328A1 | \$ 120.00 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030  Planetary Pinion Carrier Replaces 81879351 | AMRE45942 | \$ 533.00 | |
| Application: 5610, 6610, 6710, 7610, 7710, 7910, 8210 - w/ APL325 Front Axle Planetary Pinion Carrier | AME1NN1N045AA | \$ 1,971.50 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.





Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts MFWD Hub Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: (3600, 4100, 4600, 5600, 5700 - 1977 and Later), 6600, 6700 | | | |
| Planetary Pinion Gear 26 Tooth Replaces 3230261R1, L35588 | AMZP1927562 | \$ 176.50 | |
| Application: (5110, 5610, 6410, 6610, 7610 - Prior to 02/1987) | | | |
| Planetary Pinion Gear Replaces 83946053, 4472352014, ZP4472352014 | AM81325C1 | \$ 63.50 | |
| Application: 5610, 6610, 6710, 7610, 7710, 7910, 8210 - w/ APL325 Front Axle | | | |
|  Planetary Pinion Gear | AME1NN4044AB | \$ 200.00 | |
| Application: (6710, 7610, 7710 - w/ APL345 Front Axle), (6710, 7710, 7910, 8210 - w/ APL350 Front Axle), (7910, 8210, TW5, TW12, TW25 - w/ APL355 Front Axle) | | | |
|  Planetary Pinion Gear | AMZP4472353463 | \$ 180.00 | |
| Application: 4WD: 5110, 5610, 6610, 7610 - Prior to 02/1987 w/ APL335 Front Axle | | | |
| Planetary Pinion Shaft Replaces 83946032, 83949049, ZP4472352075 | AM81320C1 | \$ 56.50 | |
| Application: 5610, 6610, 6710, 7610, 7710, 7910, 8210 - w/ APL325 Front Axle | | | |
|  Planetary Pinion Shaft | AME1NN3A328AB | \$ 235.00 | |
| Application: (6710, 7610, 7710, TW5, TW25 - w/ APL345 Front Axle), (6710, 7710, 7910, 8250 - w/ APL350 Front Axle) | | | |
|  Planetary Pinion Shaft | AMZP4472353158 | \$ 180.00 | |
| Application: 4WD: 5110, 5610, 6610, 7610 - Prior to 02/1987 w/ APL335 Front Axle | | | |
| Ring Gear Replaces 83946031, 83954879, ZP4472352168 | AM81319C1 | \$ 365.00 | |
| Application: 5110, 5610, 5610S, 5640, 6410, 6610, 6610O, 6610S, 6640, 6640O, 6710, 6810, 6810S, 7010, 7410, 7610, 7610O, 7610S, 7710, 7740, 7740O, 7810S, 7840, 7840O, 8010, TB80, TB85, TB90, TB100, TB110, TB120, TS6000, TS6020, TS6030, Ind/Utility: 250C, 260C, 345C, 345D, 445C, 445D, 455, 455C, 455D, 545C, 545D | | | |
| Ring Gear Replaces 83952533, H437677, K395126 | AM9968069 | \$ 322.50 | |
|  | | | |






Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts MFWD Hub Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 5610S, 5640, 6610S, 6640, 6640O, 6810, 6810S, 7610, 7610O, 7610S, 7710, 7740, 7740O, 7810, 7810O, 7840, 7840O, 7910, 8010 ASN 800001M, TB80, TB85, TB90, TB100, TB110, TB120, TS6000, TS6020, TS6030, Ind/Const: 345C, 345D, 445, 445A, 445C, 445D, 450, 545, 545A, 545C, 545D, 555C, 555D, 575D, 655C, 655D, 675D Ring Gear Replaces 3475610M1, 83954696, 137700420856 | AMN13513 | \$ 95.00 | |
| Application: 8670, 8770, 8870, 8970  Ring Gear Replaces 86505064 | AM1277250C1 | \$ 475.00 | |
| Application: 5640, 6640, 6640O, 6810, 7010, 7610, 7610O, 7710, 7740, 7740O, 7810O, 7810S, 7840, 8010, Ind: 250C, 260C, 345C, 345D, 445C, 445D, 455C, 455D, 545C, 545D, 555C, 555D, 555E, 575D, 575E, 655C, 655D, 655E, 675D, 675E Inner Plate, Planetary Ring Gear Replaces 44079R1, 9968065, 83952534 | AMH437678 | \$ 134.50 | |
| Application: 8530, 8630, 8670, 8730, 8770, 8830, 8870, 8970  Sun Shaft Replaces 1961770C1, 86016137 | AM250728A1 | \$ 165.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305  Sun Shaft | AM281982A3 | \$ 402.00 | |
| Application: (8670, 8770, 8870, 8970 - 09/1993 and Later), T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, (T8.275*, T8.300**, T8.330***, T8.360**** - w/ DANA® MFWD Axle) *Prior to 06/14/2013 w/o CVT w/ Suspended Axle w/ Differential Lock and 12-Bolt Hubs or All w/o CVT w/ Standard Axle **Prior to 06/14/2013 w/o CVT and Suspended Axle w/o Differential Lock and 12-Bolt Hubs or All w/o CVT w/ Standard Axle, or All w/o CVT and DANA® Suspended Axle ***Prior to 06/14/2013 w/o CVT and Suspended Axle w/o Differential Lock and 12-Bolt Hubs, or All w/o CVT w/ Standard Axle, or All w/o CVT and Suspended Axle w/o Differential Lock and 12-Bolt Hubs, or All w/o CVT and Standard Axle w/o Differential Lock and 12-Bolt Hubs ****Prior to 06/14/2013 w/ CVT and Suspended Axle w/ Differential Lock and 12-Bolt Hubs, or All w/ CVT and Suspended Axle w/ Differential Lock and 12-Bolt Hubs, or All w/ CVT and Standard Axle w/ 12-Bolt Hubs, or All w/o CVT w/ Standard Axle | | | |
|  Oil Seal, Sunshaft 0.499" Wide, 1.563" ID, 2.129" OD Replaces 86508079, 87759992 | AM128647A1 | \$ 45.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, (T8.275, T8.330, T8.360, T8.390 - w/o CVT), TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - All w/ 12-Bolt Hubs Bearing Cup, Inner Planetary Hub 1.9375" Wide, 7.1875" OD | AML31698 | \$ 77.00 | |

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts MFWD Differentials and Components


| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Differential Carrier Assembly, MFWD For Axles w/ 10-Bolt Hubs w/ Differential Lock Replaces 87404543 | AM87324474 | \$ 9,315.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 | | | |
| Differential Carrier Assembly, MFWD For Axles w/ 10-Bolt Hubs w/o Differential Lock Replaces 87404055 | AM87324562 | \$ 5,350.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12-Bolt Hubs | | | |
|  Differential Carrier Assembly, MFWD For Axles w/o Differential Lock Replaces 87404092 | AM87324564 | \$ 10,375.00 | |
| Application: 8160, 8260, TM115, TM120, TM125, TM130, TM135, TM140, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Ring Gear and Pinion Set 10 and 46 Tooth | AM5145486 | \$ 750.00 | |
| Application: 8670, 8770, 8870, 8970 | | | |
| Ring Gear and Pinion Set, MFWD Replaces 86002330 | AM86017483 | \$ 1,150.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Ring Gear and Pinion Set, MFWD 12-Bolt | AM87324538 | \$ 1,171.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG285 | | | |
|  Ring Gear and Pinion Set, MFWD Replaces 84427940 | AM1968293C1 | \$ 450.00 | |
| Application: TG210, TG230, TG255, TG285 | | | |
|  Ring Gear and Pinion Set, MFWD 30 km/hr | AM321516A1 | \$ 750.00 | |
| Application: 8670, 8770, 8870, 8970 | | | |
| Axle Shaft Assembly, Right Hand | AM86505032 | \$ 920.00 | |
| Axle Shaft Assembly, Left Hand | AM86505031 | \$ 1,725.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts

MFWD Differentials and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|---|--------------|-----------|
| Application: 5600, 5700, 6600, 6700 - w/ APL1351 Front Axle  Axle Shaft, Long For 35.50" Axles Only | AMZP1927573 | \$ 415.60 | |
| Application: T8010, T8020, T8030, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 Differential Clutch Disc and Gear Kit, MFWD Includes Bevel Gears, Pinion Gears, Cross Shaft, Clutch Discs, Clutch Plates and Thrust Washers For Axles w/o Differential Lock Replaces 377176A1, 87775804 | AM377176A3 | \$ 1,350.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305  Differential Carrier Assembly, MFWD For Axles w/ 10-Bolt or 12-Bolt Hubs w/o Differential Lock Replaces 345688A1, 345688A2 | AM345688A4 | \$ 1,750.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050 - w/ 10-Bolt or 12-Bolt Hubs), (T8.275, T8.330, T8.360 - Prior to 06/14/2013 w/ 12-Bolt Hubs w/ DANA® Axle w/o CVT), (TG210, TG230, TG255, TG285 ASN MY00184591), TG215, TG245, TG275, TG305 - All w/ 12-Bolt Hubs), (TG210, TG230, TG255, TG285 ASN MY00195879), TG215, TG245 - All w/ 10-Bolt Hubs) Differential Clutch Piston, MFWD For Axles w/ Differential Lock | AM87324486 | \$ 310.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050 - w/ 10-Bolt or 12-Bolt Hubs w/ Differential Lock), (TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12-Bolt Hubs w/ Differential Lock), (TG210, TG230, TG255, TG285 ASN MY00195879), TG215, TG245 - All w/ 10-Bolt Hubs w/ Differential Lock) Differential Housing Assembly, MFWD w/ Bare Carrier Differential, Ring Gear and Pinion Not Included Replaces 87310140, 87404545 | AM87324492 | \$ 6,750.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050 - w/ 10-Bolt and 12-Bolt Hubs w/ Differential Lock), (T8.275, T8.330, T8.360 - Prior to 06/14/2013 w/ 12-Bolt Hubs w/ Differential Lock w/ DANA® Axle w/o CVT), (TG210, TG230, TG255, TG285 ASN MY 00184591), TG275, TG305 - All w/ 12-Bolt Hubs w/ Differential Lock), (TG210, TG230, TG255, TG285 ASN MY 00195879 - w/ 10-Bolt Hubs w/ Differential Lock), (TG215, TG245 - w/ 10-Bolt and 12-Bolt Hubs w/ Differential Lock) Differential Clutch Disc Kit, MFWD Includes (9) Clutch Discs and (10) Clutch Plates | AM87324488 | \$ 515.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050 - w/ 10-Bolt and 12-Bolt Hubs w/ Differential Lock), (T8.275, T8.330, T8.360 - Prior to 06/14/2013 w/ 12-Bolt Hubs w/ Differential Lock w/ DANA® Axle w/o CVT), (TG210, TG230, TG255, TG285 ASN MY00184591 - w/ 12-Bolt Hubs w/ Differential Lock), (TG210, TG230, TG255, TG285 ASN MY 00195879 - w/ 10-Bolt Hubs w/ Differential Lock), (TG215, TG245 - w/ 10-Bolt and 12-Bolt Hubs w/ Differential Lock), (TG275, TG305 - w/ 12-Bolt Hubs w/ Differential Lock) Differential Gear Kit, MFWD Includes Bevel Gears, Pinion Gears, Cross Shaft and Thrust Washers | AM87324491 | \$ 2,200.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, (TG210, TG230, TG255, TG285 ASN MY00184591), TG215, TG245, TG275, TG305 - All w/ 12-Bolt Hubs Differential Carrier Bearing Cone, MFWD | AM87324516 | \$ 365.00 | |
| | Differential Carrier Yoke, MFWD | AM87324528 | \$ 380.00 |
| Application: (TG210, TG230 BSN MY00164725 w/ 10-Bolt Hubs), (TG210, TG230, TG255, TG285 BSN MY00182905 w/ 12-Bolt Hubs) Differential Clutch Driver, MFWD For Axles w/ Differential Lock | AM87404485 | \$ 360.00 | |
| | Differential Clutch Disc Kit, MFWD Includes (13) Clutch Discs and (14) Clutch Plates For Axles w/ Differential Lock | AM87405209 | \$ 725.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor











Mechanical Front Wheel Drive Parts MFWD Differentials and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, (TG210, TG230, TG255, TG285 ASN MY00184591), TG215, TG245, TG275, TG305 - All w/ 12-Bolt Hubs w/ Differential Lock | | | |
| Differential Carrier, MFWD | AM87324513 | \$ 1,950.00 | |
| Bare Carrier | | | |
| Ring Gear and Pinion Not Included | | | |
| Application: ((T8010, T8020, T8030, T8040, T8050, (T8.275, T8.330 - Prior to 06/14/2013 w/o CVT w/ DANA® Axle), T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12-Bolt Hubs w/ Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255*, TG285* - w/ 10-Bolt Hubs w/ Differential Lock) *ASN MY00195879 w/ Standard Axle, ASN MY00183034 w/ Suspended Axle or ASN MY00193740 w/ SuperSteer™ Axle | | | |
| Seal Retainer | AM87404997 | \$ 250.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, T8.275*, T8.330*, T8.360*, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12-Bolt Hubs w/ Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255 ASN MY0019587, TG285 ASN MY00195879 - w/ Standard Axle w/ 10-Bolt Hubs w/ Differential Lock), (TG255 ASN MY00183034, TG285 ASN MY00184588 - w/ Suspended Axle w/ 10-Bolt Hubs w/ Differential Lock) *Prior to 06/14/2013 w/out CVT w/ DANA® Axle | | | |
| Seal | AM87404471 | \$ 120.00 | |
| Application: Ford®/New Holland® Tractors: (T8010, T8020, T8030, T8040, T8050, (TG210, TG230, TG255, TG285 ASN MY00184591), TG275, TG305 - w/ Standard Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 - w/ Suspended Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock or w/ SuperSteer™ Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8.275**, T8.330**, T8.360** - w/ Standard Axle w/ 12-Bolt Hubs w/ Differential Lock), (TG210***, TG230***, TG255***, TG285*** - w/ Suspended Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (TG210****, TG230****, TG255****, TG285**** - w/ SuperSteer™ Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (TG215, TG245 - w/ Standard Axle w/ 12-Bolt Hubs w/ Differential Lock) **Prior to 06/14/2013 w/o CVT w/ DANA® Axle ***ASN MY00184588 w/ Differential Lock or ASN MY00195684 w/o Differential Lock ****ASN MY00195701 w/ Differential Lock or ASN MY00190632 w/o Differential Lock | | | |
| Shim Kit, Differential Pinion Shaft | AM87324518 | \$ 325.00 | |
| Application: ((T8010, T8020, T8030, T8040, T8050, (TG210, TG230, TG255, TG285 ASN MY00184591), TG275, TG305 - w/ Standard Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210**, TG215, TG230**, TG245, TG255**, TG275, TG285**, TG305 - w/ Suspended Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8010, T8020, T8030, T8040, T8050, TG210***, TG215, TG230***, TG245, TG255***, TG275, TG285***, TG305 - w/ SuperSteer™ Axle w/ 12-Bolt Hubs w/ and w/o Differential Lock), (T8.275*, T8.330*, T8.360*, TG215, TG245 - w/ Standard Axle w/ 12-Bolt Hubs w/ Differential Lock) *Prior to 06/14/2013 w/o CVT w/ DANA® Axle **ASN MY00184588 w/ Differential Lock or ASN MY00195684 w/o Differential Lock ***ASN MY00195701 w/ Differential Lock or ASN MY00190632 w/o Differential Lock | | | |
| Shim Kit, Differential Carrier Yoke | AM87324536 | \$ 180.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245 - w/ 10-Bolt or 12-Bolt Hubs), (TG255, TG285 - w/ 10-Bolt Hubs w/o Differential Lock or ASN MY00195879 w/ Differential Lock), (T8.275*, T8.330, T8.360*, TG255, TG275, TG305 - w/ 12-Bolt Hubs) *Prior to 06/14/2013 w/o CVT w/ DANA® Axle w/ Differential Lock | | | |
| Adjusting Ring, MFWD Differential Bearing | AM1277233C1 | \$ 200.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245 - w/ 10-Bolt or 12-Bolt Hubs w/ Differential Lock), (T8.275*, T8.330*, T8.360*, TG275, TG305 - w/ 12-Bolt Hubs w/ Differential Lock), (TG255**, TG285** - w/ 10-Bolt Hubs w/ Differential Lock) *Prior to 06/14/2013 w/o CVT w/ DANA® Axle **ASN MY00195879 w/ Standard Axle, ASN MY0183034 w/ Suspended Axle, ASN MY0193740 w/ SuperSteer™ | | | |
| Nipple Coupling, MFWD | AM87404480 | \$ 120.00 | |

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts

MFWD Driveshafts

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: (TG210, TG230*** - w/ Standard, Suspended or Super Steer Axle w/ 10-Bolt Hubs), (TG210, TG230, TG255, TG285**** - w/ Standard, Suspended or Super Steer Axle w/ 12-Bolt Hubs) ***BSN MY00164725 w/ Standard Axle, BSN MY00182861 w/ Suspended Axle or BSN MY00184573 w/ Super Steer Axle ****BSN MY00182905 w/ Standard Axle, BSN MY00178966 w/ Suspended Axle or BSN MY00164720 w/ Super Steer Axle | | | |
|  Drive Shaft Assembly, Right Hand For Axles w/ Differential Lock | AM87404999 | \$ 625.00 | |
|  Drive Shaft Assembly, Left Hand For Axles w/ Differential Lock | AM87405000 | \$ 575.00 | |
| Application: T9020, TJ275, TJ280, TJ325, TJ330 - w/ Powershift Transmission | | | |
|  Drive Shaft Engine to Transmission Driveline | AM402177A1 | \$ 1,095.00 | |
| Application: T7030, T7040, T7050, T7060, T7070, T6.120, T6.125, (T6.140, T6.150, T6.160 - Electro Command), T6.145, T6.155, T6.165, T6.175, T6.180, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.290, T7.315, TM175, TM190 | | | |
| Friction Disc, MFWD Engagement Clutch | AM5163844 | \$ 11.10 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Axle Shaft Assembly, Right Hand w/ Differential Lock | AM87324476 | \$ 1,090.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Inner Yoke, Right Hand w/ Differential Lock | AM87325892 | \$ 815.00 | |
|  Inner Yoke, Left Hand w/ Differential Lock | AM87307641 | \$ 1,250.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Inner Yoke, Right Hand w/o Differential Lock | AM395741A1 | \$ 900.00 | |
|  Inner Yoke, Left Hand w/o Differential Lock | AM395743A1 | \$ 1,000.00 | |
|  Outer Yoke | AM395737A1 | \$ 345.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Center Yoke | AM395740A1 | \$ 375.00 | |


Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Mechanical Front Wheel Drive Parts

MFWD Driveshafts (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320 04/2014-11/19, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435, TG215, TG245, TG275, TG305 | | | |
| U-Joint Replaces 259076A1, 259076A2 | AM84355365 | \$ 95.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.330, T8.360, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Seal | AM302957A1 | \$ 34.00 | |










Tie Rods and Components

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: 2N, 9N | | | |
| Tie Rod 3.187" Long, 0.687" Diameter 18 Right Hand Thread | AM9N3270 | \$ 10.00 | |
| Application: 2N, 8N, 9N, 600, 800, 2000, 4000 Series, NAA - w/ 4 Cylinder Engines | | | |
| Tie Rod, Rear Drag Link End 4.25" Long, 0.687" Diameter 18 Right Hand Thread | AMNAA33271A | \$ 13.00 | |
| Application: (2N, 8N, 9N, 600 Series, 700 Series, 800 Series, 900 Series, 2000 Series, 4000 Series, NAA - w/ 4 Cylinder Engines Prior to 1964), (2000 Series, 3000 Series, 4000 Series - w/ 3 Cylinder Engines 1965-74), (2310, 2600, 2610, 2810, 2910, 3600, 3610, 3910, 4600SU, 4610SU - w/ 3 Cylinder Engines) | | | |
| Radius Rod Ball Cap | AME0NN3N406BA | \$ 10.00 | |
| Application: (2N, 8N, 9N, 600 Series, 700 Series, 800 Series, 900 Series, 2000 Series, 4000 Series, NAA - w/ 4 Cylinder Engine, Prior to 1964), (2000 Series, 3000 Series, 4000 Series - w/ 3 Cylinder Engines, 1965-75), (2310, 2600, 2610, 2810, 2910, 3600, 3610, 3910, 4600SU, 4610SU - w/ 3 Cylinder Engine) | | | |
| Radius Rod Ball Socket | AME0NN3N442BA | \$ 18.40 | |



Ford®/New Holland®—Tractor










Tie Rods and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 8N | | | |
|  <p>Tie Rod, Front Drag Link End 3.375" Long, 0.687" Diameter 18 Left Hand Thread</p> | AM8N3270 | \$ 10.00 | |
| Tie Rod Tube 32.75" Long, 0.875" OD | AM8N3314D | \$ 66.30 | |
| Application: 230A, 231, 234, 334, 335, 530A, 531, 532, 2000, 2100, 2110, 2120, 2150, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2810, 2910, 3000, 3055, 3100, 3150, 3330, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 3900, 3910, 3910H, 3910N, 3910R, 3910V, 4000, 4100, 4110, 4110N, 4110NO, 4110O, 4140, 4330, 4340, 4600, 4600SU, 4610, 4610NO, 4610SU, 4610V | | | |
|  <p>Tie Rod, Rear Drag Link End, Left Hand 28.125" Long Replaces 81802895</p> | AMC5NN3308E | \$ 134.10 | |
| Application: 234, 334, 335, 2000, 2310, 2600, 2610, 2810, 2910, 3000, 3600, 3610, 3900, 3910, 4000, 4100, 4110, 4140, 4330, 4340, 4600SU, 4610, Ind: 530A - w/ Power Steering | | | |
|  <p>Tie Rod 3.312" Long, 0.75" Diameter 16 Left Hand Thread</p> | AMC5NN3A300B | \$ 13.00 | |
| Application: 250C, 260C, 345C, 345D, 445A, 445C, 445D, 450, 455, 455C, 455D, 545, 545A, 545C, 545D, 550, 555, 555A, 555B, 555C, 555D, 575D, 655 - w/ MFWD | | | |
| <p>Inner Tie Rod, Right Hand M24x1.50 mm Thread Replaces 8390617</p> | AMCAR87031 | \$ 29.00 | |
| Application: 600, 800, 2000, 4000 Series, NAA - w/ 4 Cylinder Engines | | | |
|  <p>Tie Rod, Front Drag Link End 3.875" Long, 0.687" Diameter 18 Left Hand Thread</p> | AMNAA3270A | \$ 11.00 | |
| Application: 2000 w/ 3 Cylinder Engine w/ Power Steering, 2100, (2120, 4140 - w/ 3 Cylinder Engine), (2600, 2610, 3600, 3610, 3910, 4100 - w/o Cab w/ Power Steering), 2810, 2910, 3000, 3330, 3900, 4000, 4110, 4330, 4340, 4600, Ind: 230A, 231, 234, 334, 335, 531 | | | |
|  <p>Rear Drag Link End, Right Hand 29.625" from Grease Zerk to End of Shaft</p> | AMC5NN3307G | \$ 140.20 | |
| Application: 2000, 2600, 2610, 2910, 3000, 3600, 3610, 3910, 4000, 4100, 4110, 4600SU, 4610SU, Super Dexta - w/ Manual Steering | | | |
|  <p>Tie Rod, Front Drag Link End 4" Long, 0.687" Diameter 18 Left Hand Thread</p> | AM957E3290B | \$ 10.00 | |
|  <p>Tie Rod, Rear Drag Link End 4.50" Long, 0.687" Diameter 18 Right Hand Thread</p> | AM957E3307B | \$ 12.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor










Tie Rods and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: (3000, 3400, 3600, 4000, 4100, 4410, 4600 - European), Ind: 335, 532  Tie Rod 4" Long 13/16"-16 Left Hand Thread | AMC5NN3A300C | \$ 34.00 | |
| Application: (3010S, 4010S, 5010S ASN 702415M), 5610S ASN 310660M, 6610S ASN 362005M, 7610S ASN 258571M, TB80, TB85, TB90, TB100M, TB110, TB120, TT55, TT65, TT75  Outer Tie Rod End, Right Hand 30" Long, 1" Diameter | AM82981599 | \$ 135.00 | |
| Application: (3010S, 4010S, 5010S ASN 400001M), TD60D, TD70D, TT55, TT60A, TT65, TT75, TT75A  Tie Rod Assembly 49.88" Long | AM5135076 | \$ 200.00 | |
| Application: (3010S, 4010S, 5010S ASN 400001M), TT55, (TT60A, TT75A - w/ MFWD), TT65, TT75  Tie Rod 51.94" Long 1 1/8" Internal Threads | AM5135075 | \$ 220.00 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030 - w/ 4WD Carraro™ Axle  Tie Rod End 6.625" Long M18x1.50" Left Hand Internal Thread Replaces 1537611C1, 81875596, 81878537 | AMVPJ3210 | \$ 133.00 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030  Tie Rod 7 Holes in Side 0.935" ID, 17.812" Long Replaces 83983704 | AME7NN3278AA | \$ 95.00 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030, 5610, 5610S, 6610, 6610S, 6810, 6810S, 7010, 7610, 7610S, 7810, 7910, 8010  Ball Joint, Left Hand 7.04" Long M20x1.50" Right Hand Thread M18x1.50" Left Hand Thread Replaces 48084983, 83957148, 87714488 | AMCAR49006 | \$ 59.00 | |
| Application: 3430, 3930, 4000, 4100, 4330, 4340, 4600, 4610, 4630, 4830, 5030  Tie Rod, Front Drag Link End 9" Long, 0.865" Diameter, Notched Replaces C5NN3A300A | AMD0NN3A300A | \$ 21.00 | |
| Application: 3430 w/ Manual Steering, 4000, 4130, 4600, 4610  Outer Tie Rod, Right Hand 3.75" Long, 0.75" Diameter 16 Internal Thread | AMC5NN3289C | \$ 18.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.










Ford®/New Holland®—Tractor

Tie Rods and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 3600, 4100, 4600, 5610, 5700, 6610, 6700, 6710, 7410, 7610, 7700, 7710, 7810, 78100, 7910, 8000, 8210, 8530, 8630, 8700, 8730, 8830, 9000, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35, Utility: 532 | | | |
|  Tie Rod, Short 8.625" Long, 1" Diameter, 16 Right Hand Thread Replaces 83906918, 83929289, D5NN3289A | AME1NN3289AA | \$ 30.50 | |
| Application: 4000, 4600, 4610 | | | |
|  Outer Tie Rod, Left Hand 19" Long, 0.75" Diameter | AMC5NN3278A | \$ 24.00 | |
| Application: 5000, 5100, 5340, 7000, 7100 - w/ Manual Steering | | | |
|  Drag Link End 5.031" Long, 1" Diameter 16 Right Hand Thread | AMC5NN3307E | \$ 32.90 | |
| Application: (5000, 5340, 5600, 5610, 6600, 6610, 7000, 7100 - 1965-05/31/67 w/ Manual Steering) | | | |
|  Outer Tie Rod, Left Hand 0.94" Diameter, 17.50" Long 7 Notches | AMC5NN3281C | \$ 45.00 | |
| Application: 5000, 5100, 5600, 5900, 6600, 6610, 7000, 7100, 7600, 7610 - w/ Power Steering | | | |
|  Outer Tie Rod, Right Hand 15.375" Long, 0.937" Diameter, 7 Notches | AMC7NN3280E | \$ 25.00 | |
|  Outer Tie Rod, Left Hand 15.375" Long, 0.937" Diameter, 7 Notches | AMC7NN3281A | \$ 26.00 | |
| Application: 5000, 5100, (5600, 6600 - Hi-Clearance), 5610, 5900, 6610, 6700, 7000, 7100, 7600, 7700, 7710 | | | |
|  Inner Tie Rod, Right Hand 3.75" Long, 1" Diameter 16 Thread | AMC7NN3289D | \$ 15.00 | |
| Application: 5000, 5100, 5600, 5610, 5900, 6600, 6610, 7000, 7100, 7600, 7610 | | | |
|  Drag Link Assembly 50.50" Long | AME0NN3304CA | \$ 95.00 | |
| Application: 5000, 5600, 5610, 6600, 6610, 7000 - 1965-06/67 w/ Manual Steering | | | |
|  Outer Tie Rod, Right Hand 17.50" Long, 0.94" Diameter | AMC5NN3280F | \$ 35.00 | |

Ford®/New Holland®—Tractor








Tie Rods and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|---|----------------|-----------|
| Application: 5100, 5600, (5600, 6600, 7600 - Hi-Clearance), 5610, 5900, 6600, 6610, 7100, 7600, 7610 - w/ Power Steering  | Tie Rod, Left Hand 18.125" Long | AMC7NN3B161A | \$ 23.60 |
| Application: 5110, 5610, 5910, 6610, 6710, 6810, 7410, 7610, 7710  | Ball Joint 7.54" Overall Length M20x1.50" Right Hand External Thread M22x1.50" Right Hand External Thread Replaces 1968463C1, 1968468C1, 83957098 | AMZP0501310060 | \$ 50.00 |
| Application: 5110, 5610, 6410, 6610, 66100, 6710, 6810, 7410, 7610, 76100, 7710  | Outer Tie Rod, Right Hand 13.375" Long M22x1.50" Right Hand Thread Replaces 83984963, ZP0501205469 | AMZP0501206191 | \$ 202.10 |
| Application: 5640, 6640, 7740, 7840, 8240, 8340 - w/ MFWD  | Tie Rod End 9.50" Long M24x1.50" Left Hand Thread Replaces 81863335, CAR48978 | AM81863221 | \$ 127.00 |
| Application: 5640, (T6020, T6030 - Tier 3 Delta or Tier 3 Plus), 6640, 7740, (7840, 8240, 8340 - 11/1991 and Later), T6010, TS90, TS100, TS100A, TS110, TS115A, TS130A  | Outer Tie Rod, Right Hand 19.875" Long, 1.375" Diameter Replaces E9NN3278AA | AM81864106 | \$ 122.10 |
| Application: 5700, 6700, 6710, 7700, 7710, 8000, 8700, 9000, 9700, TW5, TW15, TW25, TW30  | Tie Rod 3.75" Long, 1" Diameter 16 Right Hand Thread | AMD8NN3A302AA | \$ 40.00 |
| Application: 7840, 78400, 8240, 8340, T6010, T6020, T6030, T6050, T6070, TS90, TS100, TS100A, TS110, TS110A, TS115A, TS125A, TS130A, TS135A  | Tie Rod End 4" Long 1 1/4"x12 UNC Right Hand Thread | AM81863815 | \$ 185.00 |
| Application: 8000, 8200, 8400, 8600, 8700, 9200, 9600 - w/ Wide or All Purpose Axle  | Tie Rod 3.812" Long, 1" Diameter 16 Right Hand Thread Use w/ AMC7NN3280D Tie Rod Replaces C5NN3280R, C5NN3307F | AME3NN3307AA | \$ 20.00 |
|  | Tie Rod 19.625" Long, 0.937" Diameter, 9 Notches | AMC7NN3280D | \$ 36.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.










Ford®/New Holland®—Tractor

Tie Rods and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 - w/ Heavy Duty Wide Adjustable Axle | | | |
|  Tie Rod 7 Cross Holes 1.187" Diameter, 29.50" Long | AME2NN3280BA | \$ 195.40 | |
| Application: 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 - w/ APL 365 Axle | | | |
| Ball Joint 9" Long M22x1.50" Right Hand Thread M28x1.50" Right Hand Thread Replaces 3957095 | AMZP0501205394 | \$ 95.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  Tie Rod 4.125" Long, 1.125" Diameter 12 Right Hand Thread | AM86502997 | \$ 55.00 | |
|  Tie Rod 7.25" Long, 1.25" Diameter 12 Right Hand Thread | AM86020750 | \$ 31.00 | |
|  Tie Rod 7.25" Long, 1.25" Diameter 12 Left Hand Thread | AM86020751 | \$ 60.00 | |
| Application: 8670, 8770, 8870, 8970 - w/ MFWD | | | |
| Tie Rod, Right Hand 12.75" Long, 1.25" Diameter 12 Right Hand Thread | AM86024885 | \$ 210.00 | |
|  Tie Rod, Left Hand 12.75" Long, 1.25" Diameter 12 Left Hand Thread | AM86024884 | \$ 279.60 | |
| Application: 8700, 9700, (TW10, TW20 - w/ Standard Short Wheelbase) | | | |
|  Tie Rod 8 Cross Holes 33.062" Long, 1.187" Diameter | AME1NN3280AA | \$ 50.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, TS110A, TS115A, TS125A, TS135A | | | |
|  Tie Rod Assembly 58.875" Long M18x1.50" Right Hand Thread M24x1.50" Right Hand Thread | AM5197798 | \$ 250.00 | |

Ford®/New Holland®—Tractor

Tie Rods and Components (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|-------------|--------------|------|
| Application: | T6010, T6020, T6030, T6050, T6070, T6.125, T6.145, T6.155, T6.165, T6.175, T6.180 | | | |
| | Tie Rod End 3.75" Long, 0.875" ID 14 UNF Right Hand Thread | AM81863813 | \$ 25.50 | |
| Application: | T6010, T6020, T6030, T6050, T6070, T6.125, T6.145, T6.155, T6.165, T6.175, T6.180, TS125A, TS135A - w/ Heavy Duty Axle | | | |
|  | Tie Rod 20.50" Long, 1.362" Diameter | AM81863803 | \$ 150.00 | |
| Application: | T6030, T6050, T6070, T6080 | | | |
|  | Tie Rod Assembly 58 7/8" Long M18x1.50" Right Hand Thread M24x1.50" Right Hand Thread | AM87332622 | \$ 190.00 | |
| Application: | T7030, T7040, T7050, T7060, TM175, TM190 | | | |
|  | Tie Rod End 4" Long 7/8"x14 Right Hand Internal Thread | AM44995130 | \$ 85.00 | |
| Application: | T7030, TM175, TM190 | | | |
|  | Tie Rod End, Left Hand 4.31" Long M24x1.50" Right Hand Thread | AM5198880 | \$ 70.00 | |
| Application: | T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| | Tie Rod Tube For 10-Bolt Axle | AM87455775 | \$ 299.00 | |
|  | Tie Rod, Right Hand 20.21" Long M36x1.50" Right Hand Thread | AM87455779 | \$ 235.00 | |
|  | Tie Rod, Left Hand 20.21" Long M36x1.50" Left Hand Thread | AM87455778 | \$ 445.00 | |
| Application: | T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ SuperSteer™ Axle | | | |
|  | Tie Rod End, Right Hand 16" Long M38x1.50" Left Hand Thread Original assembly must be updated to metric to use this end Replaces 409569A2 | AM87417424 | \$ 265.00 | |
|  | Tie Rod End, Left Hand 16" Long M38x1.50" Left Hand Thread Original assembly must be updated to metric to use this end Replaces 409568A2 | AM87417425 | \$ 265.00 | |
|  | Tie Rod End, Right Hand 6.37" Long M38x1.50" Right Hand Thread Original assembly must be updated to metric to use this end Replaces 402341A2 | AM87417426 | \$ 200.00 | |



Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Tie Rods and Components (...continued)






| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: TB80, TB90, TB100, TB110, TB120, TS6020, TS6030  Tie Rod and Coupling, Right Hand Replaces 48084958 | AM1997712C2 | \$ 210.00 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5050  Tie Rod End 21 3/8" Long Replaces 5086980 | AM5085085 | \$ 65.00 | |
| Application: TG210, TG215  Tie Rod M38 Right Hand Thread | AM87455743 | \$ 275.00 | |
|  Tie Rod M38 Left Hand Thread | AM87455742 | \$ 240.00 | |
| Application: TS100A, TS110A, TS115A  Tie Rod Assembly 54.375" Long M18x1.50" Right Hand Thread M24x1.50" Right Hand Thread | AM5196358 | \$ 200.00 | |
| Application: TT45A, TT50A, TT60A, TT75A  Outer Tie Rod End, Left Hand 27 1/2" Long, 0.867" Diameter | AM9970790 | \$ 35.00 | |

Spindles

| Description | Part Number | Retail Price | Core |
|---|---|--|------|
| Application: 8N 1948-52, NAA 1953-54  Spindle A - 10.750" B - 1.250" C - 1.187" D - 0.750" | Right Hand AM8N3105B Left Hand AM8N3106B Bushing - Upper AM2N3109 Thrust Bearing AMC0NN3123B Wheel Bearing Kit WBK-FD-1 | \$ 90.00 \$ 90.00 \$ 4.00 \$ 5.00 \$ 30.00 | |
| Application: 2N, 9N - 1939-47  Spindle A - 11.00" B - 1.25" C - 1.187" D - 0.75" | Right Hand AM2N3105 Left Hand AM2N3106 Bushing - Upper AM2N3109 Thrust Bearing AMC0NN3123B Wheel Bearing Kit WBK-FD-1 | \$ 50.00 \$ 65.00 \$ 4.00 \$ 5.00 \$ 30.00 | |







Ford®/New Holland®—Tractor

Spindles (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------------|--------------|-----------|
| Application: (600, 700, 800, 900, 2000, 4000 - 1955-64) BSN 137818 use WBK-FD-2 ASN 137818 use WBK-FD-3 | | | |
|  <p>Spindle Replaces 957E3105 A - 10.687" B - 1.250" C - 1.340" D - 1.250" E - 0.750"</p> | Right Hand | AMNCA3105B | \$ 80.00 |
| | Left Hand | AMNCA3106B | \$ 60.00 |
| | Bushing - Upper | AM2N3109 | \$ 4.00 |
| | Bushing - Lower | AMNCA3110A | \$ 5.20 |
| | Thrust Bearing | AMCONN3123B | \$ 5.00 |
| | Wheel Bearing Kit | WBK-FD-2 | \$ 30.00 |
| | Wheel Bearing Kit | WBK-FD-3 | \$ 28.00 |
| Application: (2000, 3000 - 1965-75 Vineyard), (2600, 2610, 3600, 3610, 3900, 4100 - 1976-81 w/o Cab) | | | |
|  <p>Spindle - Keyed Heat Treated A - 11.687" B - 1.250" C - 1.340" D - 1.250" E - 0.750"</p> | Right Hand | AMC5NN3105U | \$ 71.00 |
| | Left Hand | AMC5NN3106R | \$ 71.00 |
| | Bushing - Upper | AM2N3109 | \$ 4.00 |
| | Bushing - Lower | AMNCA3110A | \$ 5.20 |
| | Thrust Bearing | AMCONN3123B | \$ 5.00 |
| Application: 2310, 2610, 2910, 3610, 3910, 4110, 4410SU, 4610 Standard, 4610SU - 1981 and Later | | | |
|  <p>Spindle - Keyed Standard A - 11.75" B - 1.246" C - 1.464" D - 1.375" E - 0.75"</p> | Right Hand | AME0NN3105AA | \$ 166.70 |
| | Left Hand | AME0NN3106AA | \$ 75.00 |
| | Bushing - Upper | AM2N3109 | \$ 4.00 |
| | Bushing - Lower | AMC5NN3110B | \$ 4.25 |
| | Thrust Bearing | AMC5NN3A299A | \$ 6.00 |
| Application: 2600, 3600, 3900, 4100 - 1976-81 w/ Cab | | | |
|  <p>Spindle - Keyed Standard A - 12.000" B - 1.340" C - 1.250" D - 0.750"</p> | Right Hand | AMD4NN3105B | \$ 171.60 |
| | Thrust Bearing | AM138712 | \$ 13.00 |
| | Bushing - Lower | AMNCA3110A | \$ 5.20 |
| | Wheel Bearing Kit | WBK-FD-4 | \$ 29.00 |
| Application: (3600, 4100, 4600 - 1975-81 w/ 3 Cylinder Engine), 5700, 6700, 7700 | | | |
|  <p>Spindle A - 16.875" B - 1.722" C - 1.934" D - 1.794" E - 1.125"</p> | Right Hand | AMD5NN3105E | \$ 442.70 |
| | Left Hand | AMD5NN3106E | \$ 442.70 |
| Application: 3600, 4100, 4600, 5610, 5700, 6610, 6700, 6710, 7410, 7610, 7700, 7710, 7810, 7810O, 7910, 8210, Utility: 532 | | | |
| Spindle | Right Hand | AMD5NN3105F | \$ 409.10 |
| A - 12.875" B - 1.722" C - 1.934" D - 1.625" E - 0.842" | | | |








Ford®/New Holland®—Tractor

Spindles (...continued)

| Description | | Part Number | Retail Price | Core |
|--|-------------------|--------------------|--------------|-----------|
| Application: 4000 1965-75, Excluding Vineyard | | | | |
|  | Spindle | Right Hand | AMC5NN3105T | \$ 70.00 |
| | Standard | Left Hand | AMC5NN3106N | \$ 71.00 |
| | A - 12.125" | Bushing - Upper | AM2N3109 | \$ 4.00 |
| | B - 1.244" | Bushing - Lower | AMC5NN3110B | \$ 4.25 |
| | C - 1.465" | Thrust Bearing | AMC5NN3A299A | \$ 6.00 |
| | D - 1.375" | | | |
| | E - 0.750" | | | |
| Application: 4600 1976-81, 4610 1981-02/90 | | | | |
|  | Spindle | Right Hand | AMD4NN3105A | \$ 85.00 |
| | Standard | Left Hand | AMD4NN3106A | \$ 132.00 |
| | A - 12.250" | Bushing - Lower | AMC5NN3110B | \$ 4.25 |
| | B - 1.464" | Thrust Bearing | AMC5NN3A299A | \$ 6.00 |
| | C - 1.375" | Wheel Bearing Kit | WBK-FD-5 | \$ 50.00 |
| | D - 0.750" | | | |
| Application: 5000, 5100, 5600, 6600, 7000, 7100, 7600 - 1963-75 w/ 10x16 Tires | | | | |
|  | Spindle | Right Hand | AMD2NN3105C | \$ 311.20 |
| | A - 10.687" | Left Hand | AMD2NN3106C | \$ 360.20 |
| | B - 1.498" | Thrust Bearing | AM138712 | \$ 13.00 |
| | C - 1.784" | Bushing | AMC5NN3109A | \$ 5.50 |
| | D - 1.797" | Bushing | AMC5NN3110A | \$ 4.50 |
| | E - 1.125" | | | |
| Application: (5000, 7000 - 1965-75 w/o 10x16 Tires), (5600, 6600 - 1976-81), (5610, 6610 - 1981 and Later), (7600, 7610, 7700 - 1976 and Later) | | | | |
|  | Spindle - Keyed | Right Hand | AMC5NN3105M | \$ 71.00 |
| | A - 10.625" | Left Hand | AMC5NN3106J | \$ 70.00 |
| | B - 1.498" | Thrust Bearing | AM138712 | \$ 13.00 |
| | C - 1.748" | Bushing | AMC5NN3109A | \$ 5.50 |
| | D - 1.625" | Bushing | AMC5NN3110A | \$ 4.50 |
| | E - 0.843" | | | |
| Application: 5640, 6640, 6640O, 7740, 7740O, 7840, 7840O, 8240, 8340, TS90, TS100, TS100A, TS110, TS110A, TS115A, TS125A, TS130A, TS135A | | | | |
|  | Spindle | Right or Left Hand | AME9NN3105EB | \$ 154.50 |
| | A - 12.00" | | | |
| | B - 1.722" | | | |
| | C - 1.934" | | | |
| | D - 1.625" | | | |
| | E - 0.843" | | | |
| Application: 5700, 6700, 6710, 7700, 7710 | | | | |
|  | Spindle | Left Hand | AMD5NN3106F | \$ 502.90 |
| | Replaces 83908153 | | | |
| | A - 12.875" | | | |
| | B - 1.722" | | | |
| | C - 1.934" | | | |
| | D - 1.625" | | | |
| | E - 0.842" | | | |


Ford®/New Holland®—Tractor

Spindles (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|--------------------|--------------|-----------|
| Application: 5700, 6700, 6710, 7700, 7710 - Hi-Clearance | | | | |
|  | Spindle | Right Hand | AMD5NN3105D | \$ 696.50 |
| | A - 16.775" | Left Hand | AMD5NN3106D | \$ 667.80 |
| | B - 1.722" | Thrust Bearing | AM138712 | \$ 13.00 |
| | C - 1.934" | Wheel Bearing Kit | WBK-FD-6 | \$ 54.00 |
| | D - 1.625" | Wheel Hub | AMC9NN1104D | \$ 59.00 |
| E - 0.842" | | | | |
| Application: 8000, 8530, 8630, 8700, 8730, 8830, 9700, TW10, TW20, TW30, TW35 | | | | |
|  | Spindle | Left or Right Hand | AMD9NN3105AA | \$ 982.00 |
| | 42 Spline | Thrust Bearing | AM138712 | \$ 13.00 |
| | | | | |
| Application: 8000, 9000 | | | | |
|  | Spindle | Right Hand | AMC9NN3105C | \$ 561.20 |
| | 36 Spline | Left Hand | AMC9NN3106B | \$ 651.40 |
| | A - 16.775" | Thrust Bearing | AM138712 | \$ 13.00 |
| | B - 1.638" | Bushing | AMC5NN3109A | \$ 5.50 |
| | C - 1.722" | Wheel Bearing Kit | WBK-FD-7 | \$ 45.00 |
| D - 1.934" | | | | |
| E - 1.794" | | | | |
| F - 1.125" | | | | |
| Application: 8700, 9700, TW5, TW10, TW15, TW20, TW25, TW35 | | | | |
|  | Spindle | Right Hand | AMD5NN3105C | \$ 513.10 |
| | A - 16.775" | Left Hand | AMD5NN3106C | \$ 498.80 |
| | B - 1.722" | Thrust Bearing | AM138712 | \$ 13.00 |
| | C - 1.934" | Wheel Bearing Kit | WBK-FD-7 | \$ 45.00 |
| D - 1.794" | | | | |
| E - 1.125" | | | | |
| Application: (2000, 3000, 4000 - 1965-07/70), 4110, 4140 | | | | |
|  | Front Axle Support Pin | | AMC5NN3127B | \$ 24.00 |
| | 1.75" OD, 4.25" Long Replaces C5NN3127A | Bushing | AMC5NN3153C | \$ 12.00 |
| Application: (2000, 3000, 4000 - 08/70 and Later), 2100, 2110, 2120, 2310, 2600, 2610, 3055, 3100, 3120, 3310, 3600, 3610, 3910, 4100, 4110, 4140, 4600 | | | | |
|  | Front Axle Support Pin | | AMC7NN3127D | \$ 46.00 |
| | 2" OD, 5.50" Long | Bushing | AMC7NN3153B | \$ 4.60 |
| Application: (5000, 7000, 5600, 6600, 7600, 5610, 6610, 7610 - 1981-03/85) | | | | |
|  | Front Axle Support Pin, Front | | AMC5NN3N159A | \$ 36.00 |
| | 1.875" OD, 9" Long | Bushing | AMC5NN3153A | \$ 5.00 |

Ford®/New Holland®—Tractor

Spindles (...continued)







| Description | Part Number | Retail Price | Core |
|--|---------------------|--------------|------|
| Application: (5000, 5100, 5110, 5200, 5600, 5610, 6410, 6600, 6610, 6710, 7000, 7100, 7200, 7600, 7610, 7710 - 1981-03/85) | | | |
|  Front Axle Support Pin, Rear 1.25" OD, 5.15" Long | AMC5NN3N160A | \$ 34.90 | |
| | Bushing AMC5NN3446A | \$ 9.00 | |

Wheel Hubs and Components

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 8N, 501, 600, 601, 700, 800, 801, 900, 2000, 2100, 2600, 2810, 2910, 3000, 3055, 3100, 3230, 3600, 3910, 4000, 4100, 4110, 4140, 4600, 4610, 4630, NAA, Dexta | | | |
| Hub Cap | AM957E1139 | \$ 7.00 | |
| Application: 601, 801, 2100, 2310, 2610, 2810, 2910, 3055, 3230, 3610, 3910, 3930, 4000, 4100, 4110, 4130AP, 4130N, 4410SU, 4600, 4610, 4610N, 4610SU 1981 and Later, 4630 | | | |
| Wheel Hub, 6-Bolt | AMC9NN1104E | \$ 52.00 | |
| Hub Cap | AM2N1139B | \$ 10.80 | |
| Application: 501, 600, 700, 800, 900, 2000, 2100, 2300, 2600, 2610 1976-81 w/o Cab, 2910, 3000, 3100, 3300, 3600, 3610 1976-81 w/o Cab, 3900, 3910, 4000 1955-64 Orchard, 4100, 4140, Dexta | | | |
| Wheel Hub, 6-Bolt Hardware Not Included Replaces C5NN1104B, C9NN1104C | AMC9NN1104F | \$ 62.50 | |
| Application: 2030, 3400 1965-74, 3500, 3550, 3910, 4400, 4410, 4500, 4610, 5100, 5110, 5200, 5600, 5610, 5700, 5900, 6000, 6410, 6600, 6600C, 6610, 6700, 6710, 6810, 7100, 7200, 7410, 7600, 7600C, 7610, 7700, 7710, 8000, 8240, 8340, 8700, 9000, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| Wheel Hub, 6-Bolt Press-In Hub Cap Use w/ WBK-FD-7 Wheel Bearing Kit | AM313020 | \$ 54.00 | |
| Application: 5000, 5100, 5110, 5200, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6610, 6640, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7600, 7610, 7710, 7740, 7810, 7840, 7910, 8210 | | | |
| Wheel Hub, 6-Bolt Requires AMC5NN1130A Threaded Hub Cap Use w/ WBK-FD-6 Wheel Bearing Kit Replaces C5NN1104F, C9NN1104B | AMC9NN1104D | \$ 59.00 | |
| Hub Cap, Threaded | AMC5NN1130A | \$ 4.00 | |
| Application: 8530, 8630, 8730, 8830, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| Wheel Hub, 8-Bolt Standard Duty | AME1NN1104AA | \$ 219.20 | |

Ford®/New Holland®—Tractor







Wheel Bearing Kits

| Description | | Part Number | | Retail Price | Core |
|---|---|-------------|-------------|--------------|------|
| Application: | 2N 1939-47, 8N 1948-52, 9N, NAA 1953-54 | | | | |
|  | Wheel Bearing Kit | | WBK-FD-1 | \$ 30.00 | |
| | | | Components: | | |
|  | Inner Cone | 1 | 15118 | \$ 8.00 | |
|  | Inner Cup | 1 | 15250 | \$ 4.75 | |
|  | Outer Cone | 1 | 09074 | \$ 3.20 | |
|  | Outer Cup | 1 | 09196 | \$ 5.00 | |
|  | Seal | 1 | AP19220 | \$ 3.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.







Ford®/New Holland®—Tractor

Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|---|---|-------------------|----------|--------------|---------|
| Application: (600, 700, 800, 900, 2000, 4000 - 1955-64) Measure spindle bearing size prior to ordering kit, same applications could use WBK-FD-3 |  | Wheel Bearing Kit | WBK-FD-2 | \$ 30.00 | |
| | Components: | | | | |
| |  | Inner Cone | 1 | 15123 | \$ 6.00 |
| |  | Inner Cup | 1 | 15245 | \$ 4.00 |
| |  | Outer Cone | 1 | 09067 | \$ 3.12 |
| |  | Outer Cup | 1 | 09195 | \$ 2.45 |
| |  | Seal | 1 | AP19220 | \$ 3.00 |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.


Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|---|--|-------------|----------|--------------|------|
| Application: | (600, 700, 800, 900, 2000, 4000 - 1955-64) | | | | |
| | Measure spindle bearing size prior to ordering kit, same applications could use WBK-FD-2 | | | | |
|  | Wheel Bearing Kit | | WBK-FD-3 | \$ 28.00 | |
| Components: | | | | | |
|  | Inner Cone | 1 | LM67048 | \$ 7.00 | |
|  | Inner Cup | 1 | LM67010 | \$ 2.75 | |
|  | Outer Cone | 1 | LM11949 | \$ 2.99 | |
|  | Outer Cup | 1 | LM11910 | \$ 1.70 | |
|  | Seal | 1 | AP19220 | \$ 3.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|--|---|-------------|----------|--------------|------|
| Application: | 1830, 2310, 2610, 2830, 2910, 2930, 3610, 3910, 3930, 4000 1965-75 Except Vineyard, 4100, 4110, 4130AP, 4130N, 4610N, 4610SU 1981 and Later, 4630 | | | | |
|  | Wheel Bearing Kit | | WBK-FD-5 | \$ 50.00 | |
| | Components: | | | | |
| | Inner Cone | 1 | LM48548 | \$ 6.00 | |
| | Inner Cup | 1 | LM48510 | \$ 4.00 | |
| | Outer Cone | 1 | LM11949 | \$ 2.99 | |
| | Outer Cup | 1 | LM11910 | \$ 1.70 | |
| | Seal | 1 | AM310195 | \$ 6.40 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|---|---|-------------|----------|--------------|------|
| Application: | (2000, 3000 - 1965-75), (2600, 3600, 3900, 4100 - 1975-81), (2610, 3610, 3910, 4110 - 1981 and Later), Dexta, Super Dexta | | | | |
|  | Wheel Bearing Kit | | WBK-FD-4 | \$ 29.00 | |
| Components: | | | | | |
|  | Inner Cone | 1 | LM67048 | \$ 7.00 | |
|  | Inner Cup | 1 | LM67010 | \$ 2.75 | |
|  | Outer Cone | 1 | LM11949 | \$ 2.99 | |
|  | Outer Cup | 1 | LM11910 | \$ 1.70 | |
|  | Seal | 1 | AP19060 | \$ 3.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.






Ford®/New Holland®—Tractor

Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|---|---|-------------------|---------|--------------|----------|
| Application: | (5000, 7000 - w/o 10x16 Tires, 1965-75), 5100, 5110, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6610, 6640, (6700, 6710, 7710 - w/ Lo- or Hi-Clearance), 6810, 7100 (Left Hand Only), 7600, 7610, 7700, 7740, 7840 | | | | |
| |  | Wheel Bearing Kit | | WBK-FD-6 | \$ 54.00 |
| | Components: | | | | |
| |  | Inner Cone | 1 | LM501349 | \$ 6.00 |
| |  | Inner Cup | 1 | LM501310 | \$ 7.50 |
| |  | Outer Cone | 1 | M12649 | \$ 4.50 |
| |  | Outer Cup | 1 | M12610 | \$ 2.00 |
|  | Seal | 1 | AP19195 | \$ 5.60 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Wheel Bearing Kits (...continued)

| Description | | Part Number | | Retail Price | Core |
|---|-------------------|--|-------|--------------|------|
| Application: | | (5000, 7000 - w/ 10x16 Tires, 1963-75), (8000, 8600, 8700, 9000, 9600, 9700, TW5, TW10, TW15, TW20, TW25 - w/ Standard Axle) | | | |
|  | Wheel Bearing Kit | WBK-FD-7 | | \$ 45.00 | |
| Components: | | | | | |
|  | Inner Cone | 1 | 25590 | \$ 11.00 | |
|  | Inner Cup | 1 | 25521 | \$ 7.50 | |
|  | Outer Cone | 1 | 02474 | \$ 16.00 | |
|  | Outer Cup | 1 | 02420 | \$ 5.85 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Steering Arms

| Description | Part Number | Retail Price | Core |
|---|------------------------|--------------|------|
| Application: (5000, 7000 - 06/1966 and Later), 5600, 5610, 6600, 7600, 6610, 7610 - w/ Power Steering | | | |
| Steering Arm | Center AMD6NN3N670A | \$ 75.00 | |
| Steering Arm | Right Hand AMC5NN3130A | \$ 56.00 | |
| Tie Rod attaches from bottom of steering arm | | | |
| Steering Arm | Left Hand AMC5NN3131A | \$ 56.00 | |
| Tie Rod attaches from bottom of steering arm | | | |
| Application: 5700, 6700, 6710, 7700, 7710, 7810, 7910, 8210, 8700, 9700, TW10, TW20, TW30 | | | |
| Steering Arm, Left Hand | AMD5NN3131B | \$ 332.50 | |
| 39 Spline | | | |
| Application: Major, Super Major, Power Major | | | |
| Steering Arm | AME1ADKN3133B | \$ 87.00 | |
| Replaces E1ADKN-3133C | | | |
| Application: (5000, 7000 Series - 06/1966-74), 5600, 5610, 6600, 6610, 7600, 7610 | | | |
| Center Steering Shaft | AMC5NN3N703C | \$ 28.00 | |
| 4.78" Long | | | |
| Steering Shaft Bushing | Upper AMC5NN3179B | \$ 6.00 | |
| 1.375" (35 mm) Diameter | | | |
| Steering Shaft Bushing | Lower AMC5NN3179A | \$ 5.00 | |
| 1" Tall, 1.625" OD | | | |
| Application: 2N, 8N, 9N, 501, 531, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, 2000, 2110, 2120, 2310, 2600, 2810, 2910, 3000, 3100, 3110, 3120, 3310, 3600, 3610, 3900, 3910, 4000, 4100, 4110, 4120, 4140, 4200, 4330, 4340, 4600SU, 4610SU | | | |
| Dust Seal, Steering Arm | AMC5NN3125A | \$ 2.50 | |

Axle Center Tubes and Beams

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 2000, 2100, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, Ind: 231, 233, 234 | | | |
| Front Axle Assembly w/ Bushing | AMC7NN3010F | \$ 143.00 | |

Axle Knee Extensions

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 231, 233, 333, 531, 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 3000, 3055, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3600, 3900, 4000, 4110, 4140, 4600 - w/ 3 Cylinder Engine | | | |
| Axle Knee Extension, Left Hand | AMC7NN3007J | \$ 211.60 | |
| Replaces 81822704 | | | |
| Application: 2000, 2100, 2110, 2120, 2150, 2310, 3000, 3055, 3100, 3110, 3120, 3150, 3310, 4000, 4110, 4140 - w/ 3 Cylinder Engine | | | |
| Axle Knee Extension, Right Hand | AMC5NN3006G | \$ 206.20 | |

Ford®/New Holland®—Tractor

Power Steering Cylinders and Components

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: 601, 801, 2000, 3000, 3600, 4600 | | | |
| Power Steering Cylinder Right or Left Hand, 5/8" Diameter Rod 7/16" Male Thread Replaces 81846467 | AMD4NN3A540A | \$ 175.00 | |
| Application: 601, 801, 2000, 3000, 3600, 4600, Ind/Utility: 230A, 231, 234, 355, 531 | | | |
| Power Steering Cylinder, Right or Left Hand 1/2" Diameter Rod 7/16" Male Thread | AME2NN3A540BA | \$ 318.00 | |
| Application: 2310 03/1982-83, 2810, 2910, 3610, 3910, 3910V, 4110 1981-02/90, 4110V, 4610, 4610V | | | |
| Power Steering Cylinder Used w/ 13" Clutch | AME6NN3A540CA | \$ 630.00 | |
| Application: 3010S, 4010S, 5010S, 5530, 6530, 7530, TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD95DHC Plus, TD5010, TD5020, TD5030, TD5050, TD5.75, TT55, TT60A, TT65, TT75, TT75A, Workmaster 55, Workmaster 65, Workmaster 75 | | | |
| Power Steering Cylinder | AM5189895 | \$ 150.00 | |
| Application: 5610, 5610S, 5900, 6610, 6610S, 7610, 7610S, 7810, 7810S | | | |
| Power Steering Cylinder | AME3NN3A540BA | \$ 316.00 | |
| Application: 5640, 6640, 6640O, 7740, 7740O, T6010, T6020, T6030, TS90, TS100, TS100A, TS110, TS115A | | | |
| Power Steering Cylinder Replaces 8865697, 81864108, 81865697, 81869701, E9NN3A540BA, E9NN3A540BB, E9NN3A540BC | AM82037177 | \$ 355.00 | |
| Application: 7530 | | | |
| Power Steering Cylinder Replaces 5140638, 5143022, 5189897 | AM5113130 | \$ 295.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245 | | | |
| Power Steering Cylinder, Right Hand For 10-Bolt Hub | AM87455637 | \$ 2,975.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ Super Steer Axle | | | |
| Power Steering Cylinder, Right Hand Replaces 87455625 | AM87455620 | \$ 1,200.00 | |
| Power Steering Cylinder, Left Hand Replaces 87421635, 87455621 | AM87455619 | \$ 1,224.00 | |
| Application: T8010, T8020, T8040, T8050, TG210, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Power Steering Cylinder, Right Hand For 12-Bolt Axle | AM87455648 | \$ 971.00 | |
| Power Steering Cylinder, Left Hand For 12-Bolt Axle | AM87455647 | \$ 1,825.00 | |
| Seal Kit Use w/ AM87455647 or AM87455648 Power Steering Cylinder | AM87455632 | \$ 250.00 | |
| Application: TG210, TG230 - w/ 10-Bolt Hubs w/ SupersSeer™ Axle | | | |
| Power Steering Cylinder MFWD, Right or Left Hand | AM87404328 | \$ 375.00 | |
| Application: TG210, TG230, TG255, TG285 - w/ 12-Bolt Hub w/o SuperSteer™ Axle | | | |
| Power Steering Cylinder, Right or Left Hand DANA® MFWD Replaces 293678A2, 87455650 | AM293678A2 | \$ 725.00 | |
| Application: Ind: (535, 545, 555 Early), 4500 - w/ HD Axles | | | |
| Power Steering Cylinder, Right or Left Hand 0.75" Diameter Rod | AMD8NN3A540AB | \$ 387.20 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Power Steering Cylinders and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 601, 801, 2000, 3000, 3600, 4600, Ind/Utility: 230A, 231, 234, 335, 531 | | | |
| Power Steering Cylinder End 7/16" 20 Female Thread, 2.75" Long Use w/ AME2NN3A540BA Cylinder | AMC5NN3A302B | \$ 13.00 | |
| Application: 5100, 5600, 5610, 5900, 6410, 6600, 6610, 6710, 6810, 7100, 7600, 7610, 7810, 8010 04/1996 and Later | | | |
| Power Steering Cylinder End 3.625" Long, 0.875" Diameter Internal 14 Thread | AME3NN3B539AA | \$ 24.50 | |
| Application: 5640, 6640, 7740, 7840, TS90, TS100, TS110 | | | |
| Power Steering Cylinder End 2.875" Long, 1.25" Diameter 12 Right Hand Thread | AM81864115 | \$ 35.00 | |
| Application: 5700, 6700, 6710, 7700, 7710, 8000, 8700, 9700, TW10, TW20, TW30 | | | |
| Power Steering Cylinder End 3.75" Long, 0.875" Diameter 18 Female Thread Replaces D5NN3B539C, D8NN3B539AA | AMD8NN3B539AB | \$ 40.00 | |
| Application: 5700, 6700, 6710, 7700, 7710, 7810, 7910, 8000, 8210, 8530, 8630, 8700, 8730, 8830, 9000, 9700, TW5, TW15, TW25, TW30, TW35 | | | |
| Power Steering Cylinder End 3.75" Long, 1" Diameter 16 Right Hand Thread Replaces E6NN3N81AA, D5NN3A302C, D5NN3A302D, D8NN3A302AA | AME6NN3N981AA | \$ 40.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 - w/ 12 Bolt Hubs w/ SuperSteer™ Axle | | | |
| Power Steering Cylinder End 4" Long, 0.89" Thread Length M22x1.50" Right Hand Thread 1.25"x12 UNF Right Hand Thread Replaces 87421641, 87455618 | AM47381302 | \$ 151.30 | |
| Application: For Aftermarket Power Steering Cylinders that Replace OEM E2NN3A540BA, D4NN3A540A, C5NN3A739B | | | |
| Power Steering Cylinder End 2.125" Long, 0.687", 18 Thread Not used on OEM Power Steering Cylinders | AME2NN3A540BJ | \$ 20.00 | |
| Application: Ind: (535, 545, 555 Early), 4500 - w/ HD Axles | | | |
| Power Steering Cylinder End Female Thread Use w/ AMD8NN3A540AB Cylinder | AMD8NN3A540BJF | \$ 17.00 | |
| Application: For C5NN3A739B Power Steering Cylinder | | | |
| Power Steering Ball Joint 20 Female Thread | AMCAPN3300A | \$ 20.00 | |
| Application: 5640, 6640, 7740, 7840, 8210, 8240, 8340 | | | |
| Power Steering Ball Joint 8.21" Long M22x1.50" and M24x1.50" Right Hand Thread Replaces 247522A1, 83957792, N14377 | AM9968018 | \$ 90.00 | |
| Application: Ind: (535, 545, 555 Early), 4500 - w/ HD Axles | | | |
| Power Steering Ball Joint Male Thread | AMD8NN3A540BJM | \$ 14.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Power Steering Cylinders and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: (T8010, T8020, T8030, T8040, T8050 - w/ 10-Bolt Hubs or 12-Bolt Hubs), (T8.275, T8.330, T8.360 - w/ 12-Bolt Hubs All w/ or w/o CVT models w/ DANA® Axle w/o Differential Lock), T8.390 w/ 12-Bolt Hubs w/o CVT, (TG210, TG215, TG230, TG245, (TG275, TG285 - w/ Differential Lock) - w/ 10-Bolt Hubs), (TG255, TG285 - w/ 10-Bolt Hubs All w/o Differential Lock or ASN MY00195879 w/ Differential Lock), (TG255, TG275, TG285, (TG215, TG245 - w/ Differential Lock) - w/ 12-Bolt Hubs), (TG210, TG230 - w/ 12-Bolt Hubs All w/ Differential Lock or ASN MY00184591 w/o Differential Lock) | | | |
| Power Steering Cylinder Pin | AM292565A1 | \$ 117.00 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030, (5110, 5610, 6610, 7610, 7710, 7810, 7910 - 02/1987 and Later), 5610S, 6610S, 6810, 7010 ASN 850001M, 7610S, 8010 ASN 800001M, TB80, TB85, TB90, TB100, TB110, TB120 - w/ MFWD | | | |
| Power Steering Cylinder Seal Kit Axle Reference # - 124961, 149749 Replaces CAR49101 | AM83957762 | \$ 64.60 | |
| Application: (4030, 4230, 4430, TM115, TM125, TM135 ASN D4628 w/ 4WD Front Axle), (TD55D, TD60D, TD70D, TD85D ASN D5665 w/ 4WD Front Axle), (TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5040, TD5050, TM120, TM130, TM140, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A - 4WD Front Axle), TL70 ASN 1198664 w/ 4WD Front Axle | | | |
| Power Steering Cylinder Seal Kit Use w/ 5098111, 5189887, 5189887R, 5189888 Steering Cylinders | AM5190591 | \$ 33.10 | |

Remote Valves

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, TS100A, TS115A, TS125A, TS135A | | | |
| Remote Valve | AM84125295 | \$ 2,650.00 | |
| Application: T6020, T6030, T6050, T6070, TS115A | | | |
| Remote Valve | AM87328572 | \$ 1,850.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.225 | | | |
| Control Valve Replaces R917006069, R917008844 | AM84230181 | \$ 2,050.00 | |
| Application: T6030 BSN Z*BK 40001-50000 01/2007-09/13, T6050 BSN Z*BK 40001-50000 01/07-10/2016, T6070 BSN Z*BK 40001-50000, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T7.170, T7.185, T7.200, T7.210, T7.220, T7.235, T7.250, T7.260, T7.270 | | | |
| Control Valve Replaces R917005998, R917006594 | AM84214463 | \$ 2,735.00 | |
| Application: T7030, T7040, T7050, T7060, T7.195S, T7.215S, T7.230, T7.245, T7.260, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190 | | | |
| Control Valve Replaces 5190713, 5195165, 87779662 | AM87526168 | \$ 1,400.00 | |
| Application: T7.220 12/2010-02/16, T7.250, (T7.230, T7.245, T7.260 - 04/2014-MY18), (T7030, T7040, T7050, T7060 - 2007-11) | | | |
| Control Valve Replaces 873134310 | AM87313431 | \$ 1,725.00 | |
| Application: 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, 3230, 3300, 3310, 3330, 3400, 3430, 3500, 3550, 3600, 3610, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4140, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, 4630, 4830, 5000, 5030, 5100, 5200, 5340, 7000, 7100, 7200 | | | |
| Hydraulic Selector Valve Replaces C5NN0960D, E0NND960AA | AMCSNND960C | \$ 175.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435, T9010, T9020, T9030, T9040, T9050, T9060, T9.390, T9.435, T9.450, T9.470, T9.480, T9.505, T9.520, T9.530, T9.560, T9.565, T9.580, T9.600, T9.615, T9.645, T9.655, T9.670, T9.700, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 | | | |
| Hydraulic Coupler M27 x 2.0 Thread | AM298291A1 | \$ 96.40 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Remote Valves (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: T4020, T4020V, T4030, T4030F, T4030N, T4030V, T4040, T4040F, T4040N, T4040V, T4050, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T4.100, T4.100F, T4.105, T4.105F, T4.105V, T4.110, T4.110F, T4.110LP, T4.110V, T4.115, T4.120, T4.55, T4.65, T4.65V, T4.75, T4.75F, T4.85, T4.85F, T4.85V, T4.90, T4.90F, T4.90LP, T4.90V, T4.95, T4.95F, T4.95V, TN55, TN55D, TN55S, TN60A, TN60DA, TN60SA, TN60VA, TN65, TN65D, TN65F, TN65S, TN65V, TN70, TN70A, TN70D, TN70F, TN70NA, TN70S, TN70SA, TN75, TN75A, TN75D, TN75DA, TN75F, TN75FA | | | |
| Hydraulic Coupler, Female Faster Couplers® 22 mm x 1 1/2" ORB Male Threads | AM5179558 | \$ 76.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9020, T9030, T9040, T9050, T9060, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 | | | |
| Internal Female Coupler Kit Recommended to purchase in quantities of two (pressure and return) Genuine OEM Coupler includes HA345193 O-Ring and Seal Kit Replaces 93328C1, 275182A1, 87776294 | AM84262367 | \$ 155.00 | |
| Application: T5.105, T5.115, T6.140, T6.150, T6.155, T6.160, T6.175, T7.210, T7.260, T7.270, TS6.110, TS6.120, TS6.125, TS6.140 | | | |
| Hydraulic Remote Valve Coupling M22x1.50" Male Thread Quick Release | AM47370116 | \$ 89.00 | |
| Application: Versatile®: 190, 220, 250, 260, 270, 290, 300, 305, 310, 320 | | | |
| Hydraulic Breakaway Coupler Push-Pull Style 3625 Max PSI, 22 mm x 1.50" ORB Male Threads Recommended to purchase in quantities of two (pressure and return) Replaces 86040428 | AM86038744 | \$ 95.00 | |

Ford®/New Holland®—Tractor

Hydraulic Oil Coolers

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: (2600, 3600, 4600, 5600, 6600, 7000, 7600 - w/o Cab), (7100, 7200 - w/ Dual Power), Ind: (231, 233, 333, 335, 531, 532 - w/o Cab) | | | |
| Hydraulic Oil Cooler | AMD3NNH860A | \$ 316.00 | |
| Application: 5110, 5610, 6610, 6610O, 6710, 6810, 7410, 7610, 7610O, 7710 | | | |
| Hydraulic Oil Cooler, Power Steering Core: 3" x 5 1/2" x 1" | AM83954673 | \$ 279.00 | |
| Application: T2310, T2320, TC40DA, TC45DA | | | |
| Hydraulic Oil Cooler Core: 15" x 16" x 1 1/8" | AM87344149 | \$ 495.00 | |
| Application: T9010, T9020, (T9030, T9040 ASN Z6F200013), TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ500 | | | |
| Hydraulic Oil Cooler Core: 36" x 29" x 2 1/2" Replaces 345228A1, 361082A1 | AM87312759 | \$ 1,608.50 | |
| Application: T9.615, T9.670 | | | |
| Hydraulic Oil Cooler Core: 24.60" x 19.50" x 4" | AM84252569 | \$ 1,356.50 | |
| Transmission Oil Cooler Core: 19.50" x 24.60" x 4" | AM84210954 | \$ 1,440.00 | |
| Application: (2310, 2610, 2810, 2910, 3610, 3910, 4610 - w/ Transmission Cooler), (2600, 3230, 3430, 3600, 3930, 4130, 4600, 4630, 4830, 5030, 5600, 6600, 7600 - w/ Hydraulic Cooler) | | | |
| Hydraulic Cooler/Transmission Oil Cooler Replaces 83902919 | AMD4NNH860A | \$ 195.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Charge Oil Cooler Core: 30 1/4" x 21.00" x 2 5/8" Replaces 9860029, 89821609, 89860029 | AM86011668 | \$ 1,375.00 | |

Hydraulic Pumps

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Hydraulic Pump Rebuild Kit Replaces PTO shaft bushing, PTO shaft gasket, base gasket, safety valve, sump plug gasket, side gasket, piston, side plate gasket, cam block and includes chamber repair kit | AMX47114 | \$ 310.00 | |
| Application: 775 1995-10/95, (5640, 6640O, 7740, 7740O, 7840, 8240, 8340 - 11/91 and Later), 7840O 2/93 and Later | | | |
| Hydraulic Pump - Engine Mount Auxiliary Pump | AMF0NN600AA | \$ 365.00 | |
| Application: 1920, 2120, 3415, T1530, T2310, T2320, T2330, TC35, TC40, TC45 | | | |
| Hydraulic Pump | AMSBA340450991 | \$ 960.00 | |
| Application: 2310, 2600, 2600N, 2600R, 2600V, 2610, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 4100, (4110NO, 4110O, 4110V - Prior to 04/1983), 5610, 6610, 6710, 7610, 7710, 7910, 8210, TW5, TW15, TW25, TW35, Ind/Utility: 233 | | | |
| Hydraulic Pump - Engine Mount (Optional) Uses a spin-on oil filter | AME1NN600AB | \$ 350.00 | |
| Application: (2910, 3910, 4110, 4610 - 04/83 and Later), 4610O, 4610SU | | | |
| Hydraulic Pump - Engine Mount (Optional) | AME2NN600AB | \$ 365.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Hydraulic Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 3010S, 4010S, 4030, 4230, 4430, TD80D Standard Model, TD85F, TD95DHC Plus, TT55, TT65, TT75 | | | |
| Hydraulic Pump 14.35 cc, 10.80 GPM Replaces 1909915, 1909919, 1930068, 5086286, 5094391, 5113284, 5120849, 5129483, 5169772, 5179719, 8280127, 9967928, 84467651, 85086286, 87325370, 87721169, 87737603, 153634445, 320446000 | AM84530156 | \$ 160.00 | |
| Application: 3010S, 4010S, 5010S, TD60D, TD70D, TD75D, TD80D, TD90D, TD90F, TD95, (TT55, TT65, TT75 ASN T00352M) | | | |
| Hydraulic Pump - Engine Mount 19.33 cc, 10.80 GPM Replaces 2040333, 5093658, 5094394, 5169770, 5179414, 5179711, 5179714, 9967782, 47562399, 82987745, 87716629, 87737605 | AM84530154 | \$ 173.00 | |
| Application: 3230, 3400, 3430, 3550, 3930, 4100, 4110, 4400, 4410, 4500, 4600, 4610, 4630, Ind: 340, 345C, 345D, 420, 515, 535, 540, 545 | | | |
| Hydraulic Pump - Transmission Mount Does not use a spin-on oil filter | AMD8NN600LB | \$ 301.00 | |
| Application: 4000 1965 and Later, Ind: 3550 | | | |
| Hydraulic Pump - Transmission Mount | AMD0NN600F | \$ 565.00 | |
| Application: 4030, 4230, 4430, TN55, TN60A, TN60DA, TN60SA, TN65, TN65D, TN65F, TN65S, TN70, TN70A, TN70D, TN70DA, TN70F, TN70S, TN70SA, TN75, TN75A, TN75DA, TN75F, TN75FA, TN75S, TN75SA, TN80F, TN85FA, TN90F, TN95F, TN95FA | | | |
| Hydraulic Steering Pump Replaces 569306, 1901323, 1930058, 5088381, 5120406, 5129478, 5179730, 44900783, 87326060, 98420895, 153630659, 153634396, 153634432 | AM5179729 | \$ 125.00 | |
| Application: 4835, TL70 | | | |
| Hydraulic Pump Replaces 5129486, 5169039 | AM5179728 | \$ 125.00 | |
| Application: 5000, 5100, 5200, 7000, 7100, 7200 1965-75 | | | |
| Hydraulic Pump - Transmission Mount | AMD0NN600G | \$ 300.00 | |
| Application: 5100, 5200, 7100, 7200 | | | |
| Hydraulic Pump - Transmission Mount 20 GPM | AMD2NN600B | \$ 480.00 | |
| Application: 5100, 5600, 5610, 6600, 6610, 6700, 6710, 7100, 7600, 7610, 7700, 7710, 7910, 8210 | | | |
| Hydraulic Pump - Transmission Mount Uses a spin-on oil filter | AME0NN600AC | \$ 375.00 | |
| Application: 5600, 5700, 6600, 6700, 7600, 7700 | | | |
| Hydraulic Pump - Transmission Mount | AMD8NN600KB | \$ 495.00 | |
| Application: 5635, 6635, 7635, 8160, 8260, 8360, 8560, TL80, TL90, TL100, TM115, TM120, TM125 | | | |
| Hydraulic Lift Pump 19.33 cc Replaces 5129493, 5143768, 5169041, 5179726 | AM84530167 | \$ 200.00 | |
| Application: 5640, 6640, 7740, 7840, 8240, 8340, TS90, TS100, TS110 | | | |
| Hydraulic Pump - Transmission Mount Tandem Gear Pump | AMF0NN600BB | \$ 450.00 | |
| Application: 5640, 6640, 7740, 7840, TS90, TS100, TS110, TS115 | | | |
| Hydraulic Pump - Transmission Mount Replaces 25917715, F0NN600CE, VPK1109 | AM82850804 | \$ 3,885.00 | |
| Application: 8000, 8600, 8700, 9000, 9600, 9700 1968-78 | | | |
| Hydraulic Pump - Transmission Mount 16 GPM | AMD5NN600C | \$ 634.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Hydraulic Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|-----------|
| Application: 8430, 8530, 8630, 8830, TW30, TW35 | | | |
| Hydraulic Pump - Transmission Mount 20 GPM | AME2NN600BA | \$ 295.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| Hydraulic Pump | AM86018162 | \$ 2,600.00 | |
| Application: Boomer 8N, Boomer 45D, Boomer 46D, Boomer 50D, Boomer 54D, Boomer 2030, Boomer 2035, Boomer 3040, Boomer 3045, Boomer 3050, Boomer 4055, Boomer 4060, T1530, T2210, T2220, T2310, T2320, T2330, T2410, T2420, TC29DA, TC31DA, TC33DA, TC34DA, TC35, TC35A, TC35D, TC35DA, TC40, TC40A, TC40D, TC40DA, TC45, TC45A, TC45D, TC45DA, TT45A, TT50A, Workmaster 45, Workmaster 55 | | | |
| Hydraulic Pump | AMSBA340451020 | \$ 595.00 | |
| Application: T4020V, T4030F, T4030N, T4030V, T4040, T4040F, T4040N, T4040V, T4050, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T5040, T5050, T5060, T5070, T4.105F, T4.105V, T4.65V, T4.75F, T4.75V, T4.85F, T4.85V, T4.95F, T4.95V, TD5050, TL80A, TL90A, TL100A, TN85A, TN95DA | | | |
| Hydraulic Pump | AM47129337 | \$ 602.50 | |
| Application: (T6010, T6020, T6030, T6040, T6050, T6060, T6070 - Prior to 12/2009), T7030, T7040, T7050, T7060, TM175, TM190, (TS100A, TS115A - Plus/Deluxe Only), TS125A, TS135A | | | |
| Hydraulic Pump 45 cc, 113 Liters per Minute Replaces 47127050, 87725827 | AM5198694 | \$ 4,295.00 | |
| Application: T6030, T6040, T6060, T6070, T6080, T6090, T6.120, T6.125, T7.165, T7.175, T7.185, T7.210, T7.225 (MY15 and Later), (T6050, T7.170 - Power Command™ and Range Command™), (T6.140, T6.150, T7.200 - Excluding Auto Command™), (T6.145, T6.180 - Tier 4B 03/2015-01/18, Tier 4B MY18 and Electro Command™), (T6.155, T6.165, T6.175 - Tier 4, Tier 4B 03/2015-01/18, Tier 4B MY18 and Electro Command™), T6.160 (Tier 4, Tier 4B MY18 and Electro Command™), T7.190 (Excluding Auto Command™ MY15) | | | |
| Hydraulic Pump 45 cc, 29.80 GPM Replaces 8416091 | AM84471387 | \$ 2,495.00 | |
| Application: T7030, T7040, T7050, T7060, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270 | | | |
| Hydraulic Pump | AM84471388 | \$ 2,625.00 | |
| Application: T9010, T9020, T9030, T9040, T9050, T9060, TJ275, TJ280, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 | | | |
| Reman Hydraulic Pump | AM432244A3 | \$ 850.00 | \$ 500.00 |
| Application: (T9050, T9060 SN Z6F200013-Z7F204001), TJ480, TJ530 | | | |
| Hydraulic Fan Drive Pump 45 cc | AM87434402 | \$ 2,005.00 | |
| Application: TL80A, TL90A, TL100A, TN85A, TN85DA, TN95A, TN95DA | | | |
| Hydraulic Pump | AM47129338 | \$ 425.00 | |
| Application: T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, (T8.380, T8.410, T8.435 - SmartTrax™), T8.390, T8.410, T8.420, T8.435 | | | |
| Hydraulic Pump 85 cc, 55.60 GPM, High Capacity | AM47473854 | \$ 2,260.00 | |
| Application: T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, (T8.380, T8.410, T8.435 - SmartTrax™), T8.390, T8.410, T8.435 | | | |
| Hydraulic Pump 63 cc, 41.30 GPM, Standard Capacity Replaces 87538166 | AM87538174 | \$ 2,150.00 | |
| Application: T9.390, T9.615, T9.670, (T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 - Optional Equipment on MY17), (T9.435 HD, T9.450, T9.480 HD, T9.505, T9.530 HD, T9.560, T9.565 HD, T9.600 HD, T9.645 HD, T9.700 HD - Optional Equipment) | | | |
| Hydraulic Pump 85 cc Mega Flow Pump Replaces 84178463 | AM47764642 | \$ 2,940.00 | |

Ford®/New Holland®—Tractor

Hydraulic Pumps (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-------------|
| Application: T9.615, T9.670 | | | |
| Hydraulic Pump Replaces 84194336 | AM47528844 | \$ 2,355.00 | |
| Application: T9.600, T9.645, T9.700 | | | |
| Hydraulic Fan Drive Pump Replaces 84194336 | AM47528844 | \$ 2,355.00 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D Upgrade Model | | | |
| Hydraulic Lift Pump 11.26 cc Replaces 1901322, 1930061, 5085685, 5088382, 5094395, 5094396, 5129481, 5143767, 5179722, 8273385, 8273973, 9967929, 84467650, 87325369, 87725756, 153633457 | AM84530166 | \$ 160.00 | |
| Application: TJ425, TJ450, TJ500 | | | |
| Hydraulic Fan Drive Pump 100 cc | AM413152A1 | \$ 3,520.00 | |
| Application: TL70 | | | |
| Hydraulic Pump | AM82991209 | \$ 425.00 | |
| Application: TL70, TL80, TL90, TL100, TN55, TN55D, TN55S, TN60A, TN60SA, TN65, TN65D, TN65F, TN65S, TN70, TN70A, TN70D, TN70F, TN75, TN75A, TN75D, TN75F, TN75FA, TN75S, TN80F, TN85FA, TN85SA, TN90F, TN95F, TN95FA | | | |
| Hydraulic Pump | AM5168841 | \$ 498.20 | |
| Application: (TW5, TW10, TW20 - 1979-82), TW15, TW25 | | | |
| Hydraulic Pump - Transmission Mount 16 GPM | AMD8NN600FA | \$ 588.00 | |
| Application: 2N, 8N, 9N | | | |
| Hydraulic Pump Shaft 6 Spline, 13" Long, 3/4" Diameter | AM194354 | \$ 30.75 | |
| Hydraulic Pump Drive Shaft 13.06" Long, 0.75" Diameter 5/8" Right Hand Thread | AM190760 | \$ 34.20 | |
| Hydraulic Pump Drive Shaft 10 Spline, 3/8" Long | AM195454 | \$ 41.50 | |
| Hydraulic Pump Drive Hub 3" Diameter 18 UNF Left Hand Thread | AM191196 | \$ 54.00 | |
| Application: CR9065, CR9080, CR6.90, CR7.80, CR7.90, CR8.90, CR9.90, CR10.90, CX8.80, CX8.90 | | | |
| Reman Cam Lobe Motor | AM87661746R | \$ 6,000.00 | \$ 1,000.00 |

Power Steering Pumps and Conversion Kits

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 455C, 555C, 575D, 655C | | | |
| Power Steering Pump Replaces E9NN3K514BA, E9NN3K514BB | AM81871798 | \$ 672.50 | |
| Application: 2110, 2600, 3500, 3550, 3600, 4100, 4100SU, 4500, 4600, 5100, 5600, 6600, 7100, 7600, Ind: 231, 233, 420, 3500 | | | |
| Power Steering Pump, Reservoir Style 2.74 GPM at 1100 PSI Replaces D8NN3K514CC, E6NN3K514CA, E6NN3K514FA, E6NN3K514GA, E6NN3K514HA, E6NN3K514KC | AME6NN3K514EA | \$ 260.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Power Steering Pumps and Conversion Kits (...continued)

| Description | Part Number | Retail Price | Core |
|---|-----------------|--------------|------|
| Application: 3230, 3430, 3930, 3930H, 3930N, 3930NO, 4130, 4130N, 4130NO, 4630, 4630O, 4830, 5030 Prior to 05/1993 | | | |
| Power Steering Pump w/ Flat Face Fittings | AME8NN3K514BA | \$ 496.50 | |
| Application: 4100, 4600, 4610, 4630, 5100, 5600, 6610, 7100, 7600, 7610 | | | |
| Power Steering Pump, Reservoir Style Used w/ Flare Fittings | AME6NN3K514PA99 | \$ 260.00 | |
| Application: 4200, 5200, 7200 | | | |
| Power Steering Pump, Non-Reservoir Style 3.50 GPM at 1100 PSI Replaces 81851286 | AMC7NN3A674G | \$ 750.00 | |
| Application: 4610V 04/88-04/89, 5610, 5900, 6610, 6610O | | | |
| Power Steering Pump, Reservoir Style Replaces E4NN3K514AA, E4NN3K514AB, E6NN3K514AA | AME6NN3K514AB | \$ 365.00 | |
| Application: 6710, 7710, 7910, 8210 | | | |
| Power Steering Pump, Reservoir Style | AME6NN3K514TA | \$ 775.00 | |
| Application: 8000, 8600, 9000, 9600 | | | |
| Power Steering Pump, Reservoir Style Replaces D2NN3A674B, D3NN3A674B | AMD6NN3K514B | \$ 1,045.00 | |
| Application: 8000, 8600, 8700, 9000, 9600, 9700 1968-02/73 | | | |
| Power Steering Pump, Non-Reservoir Style 4.20 GPM at 1500 PSI | AMC7NN3A674B | \$ 560.00 | |
| Application: 8530, 8630, 8730, 8830, TW30, TW35 | | | |
| Power Steering Pump Replaces 3924997, 83924997, D8NN3K514JD | AMD8NN3K514JC | \$ 517.00 | |
| Application: 8700, 9700, TW5, TW10, TW15, TW20, TW25 | | | |
| Power Steering Pump, Reservoir Style Replaces D6NN3A674B, D7NN3A674H, D7NN3K514G, E0NN3K514AA | AME0NN3K514AB | \$ 415.00 | |
| Application: 8730, 8830, 9700 08/1978 and Later, TW30, TW35 | | | |
| Power Steering Pump, Reservoir Style Replaces D8NN3K514JC | AMD8NN3K514JD | \$ 750.80 | |
| Application: Ind: 445, 445A, 445C, 445D, 450, 545A, 545C, 545D | | | |
| Power Steering Pump, Reservoir Style Flows 2.74 GPM at 1600 PSI, 1000 RPM 5/8" Port Diameter | AME7NN3K514CA | \$ 480.00 | |
| Application: Ind: 4000, 4500 | | | |
| Power Steering Pump, Reservoir Style Flows 2.74 GPM at 1250 PSI, 1000 RPM Replaces 83928652, D8NN3K514KB, D8NN3K514KC | AMD8NN3K514C | \$ 868.00 | |
| Application: 2000, 3000, 3600, 3610 - w/ 3 Cylinder Engines | | | |
| Power Steering Conversion Kit Kit includes oil reservoir, hydraulic steering pump, cylinder bracket, steering cylinder & valve, tie rod and hoses | AMX47103 | \$ 995.00 | |
| Application: 5000 Series w/ 4 Cylinder Engines, 5600, 6600, 6610 | | | |
| Power Steering Conversion Kit Kit includes oil reservoir, hydraulic steering pump, cylinder bracket, steering cylinder, drag link, 5/8" hose clamp, 5/16" pressure hose and 3/8" return hose | AMX47102 | \$ 535.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Power Steering Orbit Motors

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 500, 555, (700, 755, 800, 825, 850, 900, 950 - All Series II) | | | |
| Power Steering Orbit Motor 5-Line, Ross Style Pump | AMV53616 | \$ 1,870.00 | |
| Application: 756, 836, 846, 856, 876 | | | |
| Power Steering Orbit Motor 4-Line, Char-Lynn Style Pump | AMV90159 | \$ 2,050.00 | |
| Application: 835, 855, 875, 895, 945, 950, 955, 975 | | | |
| Power Steering Orbit Motor 4-Line, Ross Style Pump | AMV72318 | \$ 1,950.00 | |
| Application: 5110, 5610, 5610S, 5900, 6410, 6610, 6610O, 6610S, 6810, 6810S, 7610, 7610O, 7700, 7710, 7810, 7810S | | | |
| Power Steering Orbit Motor w/ Relief Valve Replaces 83948972, 86602590, E4NN3A244AA | AM86602557 | \$ 705.00 | |
| Application: 8000, 8700, 9000, 9700, TW10, TW20, TW30 | | | |
| Power Steering Orbital Motor Roll-Pin Style Replaces 81875266, E3NN3A244CB | AM86585453 | \$ 1,000.00 | |
| Application: (3230, 3430, 3930, 4130, 4630, 4830, 5030, 7010, 8010 - 10/1996 and Later), 5640, 6640, 7740, 7840, 8240, 8340, TD80D, TD90D, TD95D, TD5030, TD5050, TL70, TL80, TL80A, TL90, TL90A, TL100, TL100A, TS90, TS100, TS100A, TS110, TS110A, TS115, TS115A, TS130A, TT55, TT65, TT75, Ind: (345D, 445D, 545D ASN A442030) | | | |
| Orbital Steering Motor Seal Kit Replaces 82010262 | AM9966147 | \$ 88.30 | |

Hydrostats and Components

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 276 Versatile® Bi-Directional | | | |
| Reman Hydrostat 2-Piece Eaton Hydrostat | H276E-46/46 | \$ 3,550.00 | \$ 500.00 |








Transmission Components

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 231, 335, 340, 445, 531, 540, 2000, 2310, 2600, 2610, 2810, 2910, 3000, 3400, 3500, 3600, 3610, 3910, 4000, 4000SU, 4500, 4600SU, 4610 | | | |
| Shift Cover w/ Levers Replaces 82004680 | AMC5NN7211F | \$ 85.00 | |
| Application: (2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 3000, 3055, 3100, 3110, 3120, 3150, 3190, 3300, 3310, 3330, 3400, 3500, 3550, 3600, 3900, 4000, 4100, 4110, 4140, 4200, 4330, 4340, 4400, 4410, 4500, 4600 - w/ 3 Cylinder Engine), Ind/Const: 231, 233, 333, 335, 420, 515, 531, 532, 533 | | | |
| Shift Lever 13 1/4" Long | AMC7NN7210AD | \$ 39.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor








Transmission Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 8N 1948-52  Countershaft | AM8N7111 | \$ 170.00 | |
| Application: 8N, 600, 800, 900, 2000, 4000, NAA  2nd Mainshaft Gear | AMB9NN7A381B | \$ 165.00 | |
| Application: 2000, 2310, 2600, 2610, 3000, 3600, 3610, 3910, 4000, 4110, 4600, 4610  Main Drive Bearing Retainer For Models w/ Transmission Drive PTO or w/o PTO | AMC5NN7050A | \$ 90.00 | |
| Application: 2000, 2600, 2810, 2910, 3000, 3600, 3910, 4000, 4110, 4600, 4610 PTO Input Shaft w/ IPTO | AMD1NN772B | \$ 288.10 | |
| Application: 5000 Series, 5600, 5700, 6600, 6700, 7000 Series, 7600, 7700  Main Input Shaft 19.125" Long, 25 Spline For Models w/o Dual Power Transmissions | AMC5NN7017A | \$ 87.30 | |
| Application: 5610, 5900, 6610, 6710, 7610, 7710 - 1981-04/84  Main Input Shaft 19.22" Long, 20 Tooth, 10 Spline For Models w/ 8 Speed Transmissions w/o Dual Power | AME0NN7017HA | \$ 161.70 | |
| Application: 5110, 5610, 5610S, 5640, 6610, 6610O, 6610S, 6640, 6640O, 6710, 6810, 7010, 7610, 7610O, 7610S, 7710, 7740, 7740O, 7810S, 7840, 7840O, 7910, 8010, 8240, TB100, TB110, TB120, TS90, TS100, TS110  Main Input Shaft 19.22" Long, 20 Tooth, 10 Spline For 05/1984 and Later Models w/ 8X2 Transmissions w/o Dual Power, Non-Synchro | AME2NN7017EA | \$ 195.00 | |
| Application: (230A, 231, 233, 234, 333, 334, 335, 530A, 531, 2000 Series, 2100, 2110, 2120, 2300, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 3000 Series, 3100, 3110, 3120, 3190, 3300, 3310, 3330, 3400, 3500, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 4000 Series, 4110, Ind: 3500 - All w/ Dual Range 7 or 8 Speed Transmissions)  Rear Mainshaft 30 Tooth, 17/28 Spline | AMC5NN7C095D | \$ 298.80 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Transmission Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: (5000 Series, 5100, 5190, 5200, 5340, 7000 Series, 7100, 7200 - w/ 7 Speed Transmissions, 01/1965-03/68), (5000 Series, 5100, 5190, 5200, 5340, 7000 Series, 7100, 7200 - w/ 8 Speed Transmissions, 01/1965-09/65) | | | |
|  Mainshaft 30/16 Tooth | AMC5NN7C094A | \$ 364.30 | |
| Application: (5000 Series, 7000 Series - w/ 7 & 8 Speed Transmission, 1968 and Later), (5600, 5700, 6600, 6700 - w/ IPTO), (5610, 6610, 6710 - 1981-4/84) | | | |
|  Mainshaft 9.937" Long, 30 Tooth, 18/16 Spline For Models w/o Dual Power | AMC9NN7C094B | \$ 304.60 | |
| Application: 230A, 231, 233, 234, 333, 334, 335, 530A, 531, 2000 Series, 2100, 2110, 2120, 2300, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 3000 Series, 3100, 3110, 3120, 3190, 3300, 3310, 3330, 3400, 3500, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 4000 Series, 4110, Ind: 3500 - All w/ Transmission Drive PTO | | | |
|  Countershaft 28 Tooth, 23 Internal Spline and 26 External Spline | AMC5NN7111M | \$ 70.00 | |
| Application: (5610, 6610, 7610, 7710 - Prior to 1984 w/ 8-Speed Non-Synchro Transmission w/o Dual Power), Ind/Const: 5550 Series Prior to 10/1970 | | | |
|  Countershaft 11.75" Long, 28/30 Tooth, 20/17 Spline | AMC9NN7111B | \$ 69.00 | |
| Application: 230A, 231, 233, 234, 333, 334, 335, 530A, 531, 2000 Series, 2100, 2110, 2120, 2300, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 3000 Series, 3100, 3110, 3120, 3190, 3300, 3310, 3330, 3400, 3500, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 4000 Series, 4110, Ind: 3500 - All w/ Dual Range 8-Speed Transmissions | | | |
|  Countershaft Gear 30/56 Tooth | AMC5NN7113D | \$ 291.00 | |
| Application: 2000, 3000, 4000 Series, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3110, 3120, 3190, 3230, 3310, 3330, 3400, 3430, 3600, 3610, 3910, 3930, 4100, 4110, 4130, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4600, 4610, 4830, 5000 Series, 5100, 5110, 5190, 5200, 5340, 5600, 5610, 5640, 5700, 6600, 6610, 6640, 6700, 6710, 6810, 7000 Series, 7010 ASN 850001M, 7100, 7200, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 8010 ASN 800001M, 8240, TS90, TS100, TS110 | | | |
|  Output Gear Assembly 28/49 Tooth For most 3, 4 and 6 Cylinder Tractors w/ 7 or 8 Speed Transmissions | AME6NN7145AA | \$ 350.00 | |
| Application: (3000, 4000 Series - w/ 8 Speed Transmission 1965-9/65), (5000, 7000 Series - w/ 7 Speed Transmission 1965-3/68 or 8 Speed Transmission 1965-9/65) | | | |
|  1st Gear 49/28 Tooth | AMC5NN7N100A | \$ 95.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.






Ford®/New Holland®—Tractor

Transmission Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: (230A, 231, 233, 234, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345D, 445, 445A, 445D, 2000 Series, 2100, 2110, 2120, 2300, 2310, 2600, 2610, 2810, 2910, 3000 Series, 3100, 3110, 3120, 3190, 3230, 3300, 3310, 3400, 3430, 3600, 3610, 3910, 3930, 4000 Series, 4100, 4110, 4130, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, 4630 - 09/1965 and Later w/ 3 Cylinder Engine and 8-Speed Transmission), (515, 530A, 531, 532, 540, 540A, 540B, 545, 545A, 545D, 4830, 5000 Series, 5030, 5100, 5110, 5190, 5200, 5340, 5600, 5610, 5700, 6600, 6610, 6700, 6710, 6810, 7000 Series, 7100, 7200, 7600, 7610, 7700 - 09/1965 and Later w/ 4 Cylinder Engine and 7-Speed or 8-Speed Transmission), Ind: (3500, 3550 - 09/1965 and Later w/ 3 Cylinder Engine and 8-Speed Transmission) | | | |
|  1st Gear 46/28 Tooth Replaces C5NN7N100C | AME6NN7N100AA | \$ 191.50 | |
| Application: (2810, 2910, 3910, 4110, 4610 - w/ Non-Synchro Transmission 1981-02/89), 4100, 4600, (5000, 5100, 5200, 5340, 7000, 7100, 7200 - 1973 and Later w/ Independent PTO w/ Dual Power), (5110, 5610, 6610, 6710, 6810, 7610, 7710, 7810 - w/ Non-Synchro Transmission), 5600, 5640, 5700, 6600, 6700, 7010 ASN 850001M, (7600, 7700 - w/ Independent PTO w/ or w/o Dual Power), 7740, 7840, 8010 ASN 800001M, 8240, TB100, TB110, TB120, TS90, TS100, TS110, Ind/Const: 340, (340A, 445 - 1982-05/85), (340B, 540A - 1982 and Later), 420, 445A, 515, 532, 540, (540B, 545A - 06/1985-07/87), 545 | | | |
|  2nd Gear 28/43 Tooth w/ 8 Speed Transmission | AME6NN7N101BA | \$ 160.80 | |
| Application: 2000, 2310, 2600, 2610, 3000, 3600, 3610, 4000 | | | |
|  3rd Gear 28/35 Tooth | AMC5NN7B340A | \$ 105.00 | |
| Application: 4000 Series, 4100, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 5000 Series, 5100, 5110 w/ Dual Power, 5190, 5200, 5340, 5600, 5610, 5700, 6600, 6610, 6700, 6710, 6810 | | | |
|  3rd Gear 28/35 Tooth w/ 7 or 8 Speed Transmissions | AME6NN7N315AA | \$ 162.90 | |
| Application: 3000, 3600 | | | |
|  Reverse Gear 28/32 Tooth | AMC5NN7K013E | \$ 101.70 | |
| Application: (5000 Series, 5100 - 10/1970 and Later w/ 8-Speed Transmissions), (5110, 5190, 5200, 5340, 5600, 5700, 6600, 6600C, 6600O, 6700 - w/ 8-Speed Transmissions), (5610, 6610, 6610O, 6710, 6810, 7610, 7610O, 7710, 7810 - Tractors), (5610S, 6610S, 7610S, 7810S, TB100, TB110, TB120 - w/ 8-Speed Transmissions and Creeper Gear Countershaft), (5640, 6640, 7740, 7740O, 7840, 7840O, 8240 - Prior to 10/1992 w/ 8-Speed Transmissions), (7010, 8010 - w/ 8-Speed Transmissions and Creeper Gear Countershaft, ASN 850001M), Ind/Const: 345C, 345D, 445C, 445D, 545C, 545D, 5500 Series Backhoe | | | |
|  Secondary Countershaft 35 Tooth, 16 Spline For Models w/ 8 Speed Non-Synchro Transmissions | AMC9NN7113B | \$ 185.00 | |

Ford®/New Holland®—Tractor

Transmission Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 2000, 3000, 4000 Series, 2310, 2600, 2610, 2810, 2910, 3230, 3600, 3610, 3910, 3930, 4600, 4610, 4630, 4830, 5000 Series, 5600, 5610, 5640, 5700, 6600, 6610, 6640, 6700, 6710, 7000 Series, 7600, 7610, 7700, 7710, 7810, 7740, 8240, TS90, TS100, TS110 | | | |
|  Countershaft Gear Coupling Sliding, 21 Tooth For Models w/ 8 Speed Non-Synchro Transmissions | AME0NN7106BA | \$ 60.00 | |
| Application: 2000, 3000, 4000 Series, 2310, 2610, 2810, 2910, 3230, 3610, 3910, 3930, 4110, 4330, 4610, 4630, 4830, 5000 Series, 5030, 5610, 5640, 6610, 6640, 7000 Series, 7010, 7610, 7710, 7740, 7840, 8010, 8240, Dexta, Super Dexta, TS90, TS100, TS110 | | | |
|  Front Gear Shift Coupling Assembly 28 Tooth, 17 Spline For most Models w/ 6, 7 or 8 Speed Transmissions | AME6NN7N072AA | \$ 50.00 | |
| Application: 2000 Series, 2100, 2110, 2600, 2610, 2810, 2910, 3000 Series, 3100, 3230, 3330, 3400, 3430, 3500, 3550, 3600, 3610, 3900, 3910, 3930, 4000 Series, 4100, 4110, 4130, 4140, 4190, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4610, 4630, 4830, 5000 Series, 5030, 5100, 5110, 5190, 5200, 5340, 5600, 5610, 5640, 5700, 6600, 6610, 6640, 6700, 6710, 6810, 7000 Series, 7010 ASN 850001M, 7100, 7200, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 8010 ASN 800001M, 8240, TS90, TS100, TS110 | | | |
|  Rear Gear Shift Coupling Assembly 28 Tooth, 20 Spline | AME6NN7N072BA | \$ 95.00 | |
| Application: 2000, 2100, 2600, 3000, 3100, 3400, 3500, 3550, 3600, 3900, 4100, 4200, 4400, 4410, 6710, 6810, 7100, 7600, 7610, 7700, 7710, 8000, 8700, 9000, 9700, TW10, TW20, TW30 | | | |
|  Clutch Pedal Return Spring | AMC7NN7N598A | \$ 5.60 | |
| Application: 2100, 2110, 2300, 3000, 3100, 3120, 3190, 3310, 3400, 3600, 3610, 4110 | | | |
|  Main Input Shaft 17.75" Long, 19 Tooth, 10 Spline | AMC7NN7017AB | \$ 110.00 | |
| Application: T7.220, T7.235, T7.250, T7.260 - Power Command | | | |
| Friction Disc, Transmission Engagement Clutch | AM5163844 | \$ 11.10 | |
| Application: T9010, T9020, T9030, T9040, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430 | | | |
| Clutch Disc 6.70" ID, 11.61" OD | AM427603A1 | \$ 433.40 | |
| Clutch Disc | AM427601A1 | \$ 124.00 | |
| Application: T9010, T9020, T9030, T9040, TJ275, TJ280, TJ325, TJ380, TJ425, TJ430 | | | |
| Clutch Disc 6.70" ID, 11.61" OD | AM427602A1 | \$ 234.30 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Transmission Discs

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 8160, 8260, 8360, 8560, (T6030, T7040 - Power Command), (T6050, T6070, T6080, T6090, T7.170 - Range Command and Power Command), (T7030, T7050, T7060, T7.185, T7.200, T7.220, T7.230, T7.235, T7.245, T7.260 - Excluding Auto Command), T7.165, T7.165S, (T7.175, T7.190, T7.225 - Excluding Auto Command MY15, MY18), (T7.210 Excluding Non Tier 4B Auto Command and Tier 4B Auto Command MY15, MY18), T7.215S, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190 | | | |
| Transmission Clutch Pack Includes (6) Inner Spline Discs and (6) Outer Spline Discs Replaces 5167875, 5167876 | AM87530788 | \$ 81.70 | |
| Application: 8160, 8260, 8360, 8560, T6030, T6050, T6070, T6080, T6090, T7.165, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.225, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Transmission Clutch Pack Please verify model year and serial number for fit before ordering Includes (8) Inner Spline Discs and (8) Outer Spline Discs | AM87530796 | \$ 152.80 | |
| Application: T6030, T6050, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7.165, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, TM120, TM130, TM140, TM155, TM175, TM190 | | | |
| Transmission Clutch Pack Please verify model year and serial number for fit before ordering Includes (8) Inner Spline Discs and (8) Outer Spline Discs Replaces 5165058, 5165059 | AM87530789 | \$ 132.00 | |

PTO Assembly Components

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: TM120, TM130, TM155, TM175, TM190 | | | |
| PTO Damper Replaces 47126791, 47127097 | AM87302871 | \$ 249.00 | |
| Application: 231, 233, 234, 333, 334, 335, 340, 531, 535, 2000 1965 and Later, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, 3190, 3300, 3310, 3330, 3400, 3600, 3610, 3910, 4000 1965 and Later, 4100, 4110, 4190, 4200, 4330, 4340, 4400, 4410 | | | |
| PTO Shifter Fork Replaces 81801836 | AMC5NN720A | \$ 15.00 | |
| Application: TL70, TL70A, TL80, TL100, TL100A | | | |
| PTO Clutch Disc 44 Spline, 3.85" ID, 5.23" OD, 0.059" Thick | AM5165950 | \$ 9.20 | |
| Application: (TL70, TL80, TL90, TL100 BSN C4738) | | | |
| Separator Plate, PTO Clutch | AM5165954 | \$ 8.10 | |
| Application: T6010, T6020, T6030, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.290, T7.315 Excluding Tier 4B MY18, TM175, TM190, TS100A, TS110A, TS115A, TS130A, TS135A | | | |
| Friction Disc, PTO Clutch | AM5163844 | \$ 11.10 | |
| Application: 3600, 4100, 4600, 5000, 5100, 5110, 5600, 5610, 5610S, 5640, 5900, 6000, 6410, 6600, 6610, 6610S, 6640, 6700, 6710, 6810, 7000, 7010, 7100, 7410, 7600, 7610, 7610S, 7700, 7710, 7740, 7810, 7810S, 7910, 8000, 8010, 8200, 8210, 8340, 8600, 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, 9000, 9200, 9600, 9700, TW10, TW20 | | | |
| PTO Brake Band Replaces 81819772, 83924796, 83956644, 89845550, C7NNB726D, E0NNB726AA | AME0NNB726AB | \$ 35.50 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7030, T7040, T7050, T7060, T7070, TM175, TM190, TS100A, TS115A, TS125A, TS130A, TS135A, T7.165, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.195S, T7.200, T7.210, T7.215S, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.275, T7.290, T7.300, T7.315, T7.340 | | | |
| PTO Brake Band 0.91" Wide | AM87391136 | \$ 94.50 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

PTO Shafts and Hubs

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 5000, 5100, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7100, 7200, 7600, 7610, 7700, 7710 - w/ 8 Speed Non-Synchro Transmissions | | | |
| PTO Shaft - Internal PTO Drive 39.87" Long, 20 & 25 Spline Requires AME1NNN777AB 20 Spline PTO Hub when replacing C5NN7A684A 15 Spline Shaft | AME4NN7A684AA | \$ 334.10 | |
| Application: 5000, 5600, 5610, 5700, 6600, 6610, 6700, 6710, 7000 Series, 7600, 7610, 7700, 7710 | | | |
| PTO Shaft - Internal PTO Drive 25.40" Long, 21 & 25 Spline | AMC5NNA701A | \$ 130.00 | |
| Application: 8000, 8200, 8400, 8600, 8700, 9200, 9600, 9700 | | | |
| PTO Shaft - Internal PTO Drive 37.50" Long, 2 Sets of Splines, 22 & 25 Spline Use w/ AMD8NNN778AA PTO Hub | AMD8NN7A684BA | \$ 438.30 | |
| PTO Shaft - Internal PTO Drive 37.562" Long, 20 Spline Use w/ AME1NNN777AB PTO Hub | AMC9NN7A684A | \$ 576.60 | |
| Application: 8000, 8700, 9000, 9700 | | | |
| PTO Shaft - Internal PTO Drive 37.50" Long, 20 Spline Use w/ AME1NNN777AB PTO Hub | AMC7NN7A684D | \$ 438.50 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T6.120, T6.140, T6.150, T6.155, T6.160, T6.165, T6.175, T7.185, T7.200, T7.210, T7.220, T7.235, T7.250, T7.260, T7.270, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
| PTO Shaft 540 RPM, 6 Tooth Front Spline Replaces 5182612, 5182613 | AM47130743 | \$ 165.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.225, TS100, TS100A, TS110, TS110A, TS115, TS115A, TS125A, TS130, TS135A | | | |
| PTO Shaft 9.33" Long, 22 Spline | AM87308746 | \$ 221.60 | |
| Application: TW10, TW20, TW30 | | | |
| PTO Shaft - Internal PTO Drive 37.50" Long, 22, 22 & 25 Spline Use w/ AMD8NNN778AA PTO Hub | AMD8NN7A684AB | \$ 405.70 | |
| Application: TM120, TM175, TS125A | | | |
| PTO Shaft 1000 RPM, 21 Spline, 1 3/8" Spline Diameter | AM47130744 | \$ 124.50 | |
| Application: 5000 Series, 5100, 5110, 5600, 5610, 5640, 5700, 5900, 6600, 6610, 6640, 6700, 6710, 6810, 7000 Series, 7010, 7100, 7200, 7410, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 7910, 8010, 8210, 8240, 8400, 8600, 8700, 9000, 9200, 9600, 9700, TS90, TS100, TS110 | | | |
| PTO Hub 20 Spline Use w/ AMC7NN7A684D & AMC9NN7A684A PTO Shafts | AME1NNN777AB | \$ 62.00 | |
| Application: 5000, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7000, 7600, 7610, 7700, 7710 | | | |
| PTO Hub 15 Spline | AMC5NNN777A | \$ 60.00 | |
| Application: 8000 Series, 8200, 8400, 8530, 8600, 8630, 8700, 8730, 8830, 9000 Series, 9200, 9600, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| PTO Hub 22 Spline Use w/ AMD8NN7A684BA & AMD8NN7A684AB PTO Shafts | AMD8NNN778AA | \$ 149.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor






PTO Clutch Parts

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 5000, 5100, 5200, 5340, 5600, 5610, 5700, 5900, 6600, 6610, 6700, 7000, 7100, 7200, 7600, 7610, 7700, 7710 | | | |
| PTO Clutch Pack 3 5/8" Overall Height Includes (4) Friction Discs Replaces 83903939, D5NNN707A | AMD2NNN751D | \$ 225.00 | |
| Application: 5000, 5100, 5200, 5340, 5600, 5700, 5900, 6600, 6700, 7000, 7100, 7200, 7600, 7700 | | | |
| PTO Clutch Pack 4-Plate, Preloaded Housing Includes (3) Friction Discs Replaces 83908229, D3NNN751D, D5NNN707A | AMD5NNN751A | \$ 249.00 | |
| Application: 5110, 5610, 5610S, 5640, 5900, 6410, 6610, 6640, 6710, 6810, 7410, 7610, 7710, 7740, 7810, 7840, 7910, 8100, 8210, 8240, 8340, TB80, TB85, TB90, TB100, TB110, TB120, TS90, TS100, TS110 | | | |
| PTO Clutch Pack 3 7/8" Overall Height Includes (5) Friction Discs Replaces 81871420, E0NNN751BB | AME0NNN751BA | \$ 225.00 | |
| Application: 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 | | | |
| Dual Power Clutch Plate External Spline, 4.495" ID, 6.058" OD Replaces 83934543, 83958329, 89823827 | AM83958330 | \$ 10.40 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| PTO Clutch Plate External Spline, 4.495" ID, 6.058" OD Replaces 83934543, 83958329, 89823827 | AM83958330 | \$ 10.40 | |
| Application: 5000 Series, 5600, 5610, 5700, 6600, 6610, 6700, 6710, 7000 Series, 7600, 7610, 7700, 7710, 7810 | | | |
| PTO Drive Clutch Hub 25/52 Tooth, 10-Plate Hub | AMF1NNN750AA | \$ 175.70 | |
| Application: 5610S, 5640, 6610S, 6640, 7010, 7740, 7840, 8240, 8340, (9030E, 9030V - 04/1994 and Later), TB80, TB85, TB90, TB100, TB110, TB120, TS90, TS100, TS110, TS115, TS6000, TS6020, TS6030, TV140, TV145, TV6070, (9030E, 9030V - 04/1994 and Later) | | | |
| PTO Drive Clutch Hub 26 Tooth Gear, 23 Internal Spline, 52 External Spline Replaces 83999197, 83999198, E9NNN750AB | AM81865535 | \$ 181.50 | |
| Application: 5000 Series, 5600, 5700, 6600, 6700, 7000 Series, 7600, 7700 | | | |
| PTO Drive Clutch Housing w/ Bushing When Used on 5000 and 7000 Series w/ Single Speed PTO, Replacing C9NN7R007A Direct Drive Housing Plate w/ D5NN7R007A Drive Housing Plate Is Required | AMD5NNN707A | \$ 308.60 | |
| Application: 2000, 2310, 2600, 2610, 2810, 2910, 3000, 3600, 3610 | | | |
| PTO Clutch Sleeve Replaces 81801828 | AMC5NN717A | \$ 212.80 | |
| Application: 5000 Series, 7000 Series | | | |
| PTO Drive Clutch Valve Support w/ Relief Hole | AMC7NNN776C | \$ 24.00 | |
| Application: 5000 Series, 5600, 5610, 5640, 5700, 5900, 6600, 6610, 6640, 6700, 6710, 6810, 7000 Series, 7010, 7600, 7610, 7700, 7710, 7740, 7810, 8010, 8200, TS90, TS100 | | | |
| PTO Drive Clutch Valve Support w/o Relief Hole | AMD2NNN776A | \$ 24.00 | |
| Application: 5110, 5610, 5610S, 5640, 6610, 6610S, 6640, 6710, 6810 1981 and Later, (7010, 8010 ASN 850001M), 7610, 7710, 7740, 7810, 7810S, 7840, 7910, 8000, 8200, 8210, 8240, 8530, 8600, 8630, 8700, 8730, 8830, 9000, 9200, 9600, 9700, TB80, TB85, TB90, TB100, TB110, TB120, TS90, TS100, TS110, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| Internal Spline Plate Replaces 81870603, 83934543, 83958329 | AM83925696 | \$ 11.95 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Differentials and Components

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 2000 Series, 2310, 2600, 2610, 2810, 2910, 3000 Series, 3230, 3600, 3610, 3900, 3910, 3930, 4000 Series, 4600, 4610, 4630, 4830, 5000 Series, 5030, 5600, 5610, 5640, 5700, 6600, 6610, 6640, 6700, 7000 Series, 7010, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 8240, TB100, TB110, TB120, TS90, TS100, TS110, TS115 | | | |
|  Side Gear w/ Smooth Outer Surface | AM81803445 | \$ 85.00 | |
|  Side Gear w/ Splined Outer Surface Replaces C5NN4239A | AM81803451 | \$ 100.00 | |
|  Differential Spider Replaces C5NN4211A | AM81876885 | \$ 70.00 | |
|  Differential Pinion Gear Replaces 957E4292B, E1ADDN4213B | AM81728114 | \$ 45.00 | |
|  Differential Pinion Thrust Washer | AM508E4230A | \$ 3.50 | |

Rear Axles and Components

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 8N, NAA 1948-54 | | | |
| Rear Axle Shaft | AM8N4235B | \$ 147.00 | |
| Application: 5000, 5600, 5700, 6600, 6700, Ind: 650, 5500, 6500 | | | |
| Rear Axle Shaft | AMC5NN4244N | \$ 228.75 | |
| Application: 8N, NAA, NAB | | | |
| Rear Axle Hub | AM8N1171 | \$ 102.00 | |

Ford®/New Holland®—Tractor

PTO Output Shafts

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 600, 700, 800, 900 | | | |
| PTO Output Shaft Conversion Kit Converts PTO Output Shaft from 1 1/8" to 1 3/8" Includes PTO Output Shaft, Shaft Cover, Front Bearing, Seals, Snap Rings, Collar and Tapered Pin | AMNCA700-38 | \$ 107.00 | |
| Application: NAA 1953-54 | | | |
| PTO Output Shaft Conversion Kit Converts PTO Output Shaft from 1 1/8" to 1 3/8" Includes PTO Output Shaft, Shaft Cover, Front Bearing, Seals, Gasket, Snap Rings, Collar and Tapered Pin | AMNAA700-38 | \$ 135.00 | |
| Application: 2N, 8N, 9N | | | |
| PTO Output Shaft Includes 1 3/8" Shaft, Front Bearing, Seals and Snap Rings | AM9N700-38 | \$ 95.00 | |
| Application: 2000, (2310, 2610, 2810, 2910, 3610, 3910 - 1981-04/83), 2600, 3000, 3600, 4000 Series | | | |
| PTO Output Shaft, 540 RPM 10 Tooth, 6 Spline 29.46" Long, 1.375" Spline Diameter | AME5NNA728AA | \$ 75.00 | |
| Application: 5000, 5100, 5200, 5600, 6600, 6700, 7000, 7100, 7200, 7600, 7700, 8000, 8600, 8700, 9000, 9600, 9700 - w/ 2 Speed PTO | | | |
| PTO Output Shaft, 540 RPM 11.475" Long, 36 & 38 Tooth Drive Splines | AMD2NNB728A | \$ 120.00 | |
| Application: 5000, 5100, 5200, 5600, 5700, 6600, 6700, 7000, 7100, 7200, 7600, 7700, 8000, 8600, 8700, 9000, 9600 - w/ 2 Speed PTO | | | |
| PTO Output Shaft, 1000 RPM 11.475" Long, 38 Tooth Drive Spline | AMD2NNB728B | \$ 222.00 | |
| Application: 5000 w/ Independent PTO, 5100, 5200, 7000 w/ Independent PTO, 7100, 7200 - w/ Single Speed PTO | | | |
| PTO Output Shaft, 540 RPM 10.88" Long, 29 Tooth Drive Spline | AMD2NNN752C | \$ 90.00 | |
| Application: 5000 Series, 5110, 5600, 5610, 5700, 5900, 6600, 6610, 6700, 6710, 6810, 7000 Series, 7600, 7610, 7700, 7710 - w/ Single Speed PTO | | | |
| PTO Output Shaft, 540 RPM 12.03" Long, 29 Tooth Drive Spline | AME4NNN752AA | \$ 106.00 | |
| Application: 5100, 5110, 5600, 5610, 5640, 5900, 6410, 6600, 6610, 6640, 6700, 6710, 6810, 7100, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 7910, 8000, 8210, 8240, 8340, 8670, TW5, TW10, TW15, TW20, TW25 - w/ 2 Speed PTO | | | |
| PTO Output Shaft, 540 RPM 11.719" Long, 8 Tooth Drive Spline | AME6NNB728AA | \$ 149.00 | |
| Application: 5100, 5110, 5600, 5610, 5640, 5900, 6410, 6600, 6610, 6610S, 6640, 6700, 6710, 6810, 7100, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 7910, 8000, 8210, 8240, 8340, 8670, 8700, 9700, TS100, TW5, TW10, TW15, TW20, TW25 | | | |
| PTO Output Shaft, 1000 RPM 11.719" Long, 8 Spline Replaces 86511620, D8NNB728BA | AMD8NNB728BC | \$ 205.90 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
| PTO Output Shaft, 1000 RPM 20 Spline, 1 3/4" Diameter | AM9840406 | \$ 362.80 | |
| PTO Output Shaft, 1000 RPM 21 Spline, 1 3/8" Diameter | AM9843942 | \$ 440.70 | |

Ford®/New Holland®—Tractor

PTO Adapters

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: Tractors up to 70HP | | | |
| PTO Adapter Small 540 to 1000 Spline, 4 1/8" Overall Length Changes PTO from 1 3/8" x 6 spline to 1 3/8" x 21 spline and extends the PTO shaft 4 1/8" | AMX59112 | \$ 45.00 | |
| PTO Adapter Small 1000 to 540 Spline, 6 3/8" Overall Length Reduces PTO from 1 3/8" x 21 spline to 1 3/8" x 6 spline and extends the PTO shaft 4 1/8" | AMX59108 | \$ 45.00 | |
| Application: Tractors up to 100HP | | | |
| PTO Adapter Large 1000 to 540 Spline, 7 1/2" Overall Length Reduces PTO from 1 3/4" x 20 spline to 1 3/8" x 6 spline and extends the PTO shaft 4 5/8" | AMX59109 | \$ 84.00 | |
| PTO Adapter Large 1000 to Small 1000 Spline, 7" Overall Length Reduces PTO from 1 3/4" x 20 spline to 1 3/8" x 21 spline and extends the PTO shaft 4 5/8" | AMX59110 | \$ 71.00 | |

PTO Gears

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 5610, 5610S, 5640, 6610, 6610S, 6640, 6710, 7010S, 7610, 7610S, 7710, 7740, 7810, 7810S, 7840, 7910, 8210, 8240, 8340 | | | |
| PTO Drive Gear - Double For 540 & 1000 RPM 2-Speed Independent PTO, 20 & 41 Tooth Drive Gear | AME0NN745AA | \$ 270.00 | |
| PTO Driven Gear - 1000 RPM For 540 & 1000 RPM 2-Speed Independent PTO, 8 Splines, 84 Tooth - Helical | AME0NNA726BA | \$ 442.00 | |
| PTO Driven Gear - 540 RPM For 540 & 1000 RPM 2-Speed Independent PTO, 70 Tooth | AME0NNA726AD | \$ 325.00 | |
| Application: 5000, 5600, 5610, 5700, 6600, 6610, 6700, 6710, 7000 Series, 7600, 7610, 7700, 7710 | | | |
| PTO Driven Gear 81 Tooth Gear, 10 1/8" Outside Diameter | AMC5NNA726A | \$ 271.50 | |

Brake Shoes

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 8N, NAA | | | |
| Brake Shoe Set Set of 4 | AM8N2200B | \$ 68.00 | |
| Application: 501, 600, 700, 800, 900, (2000, 4000 - w/ 4 Cylinder Engine) | | | |
| Brake Shoe Set Set of 4 | AMNCA2218B | \$ 27.00 | |
| Application: 2N, 9N | | | |
| Brake Shoe Replaces 9N2219A | AM9N2019 | \$ 45.60 | |
| Application: 231, 335, 2000, 2110, 2310, 2600, 2610, 3000, 3400, 3500, 3600, 3610, Ind: 3500 - All w/ 3 Cylinder Engines | | | |
| Brake Shoe 2" Wide, Sold Individually (2) Required Per side When Converting 1 1/2" Wide Shoes to 2" Wide Shoes, (8) 957E2069A Pins Are Required | AMC7NN2218A | \$ 43.90 | |
| Application: 2000, 2600, 2610, (3000, 4110 - 12/1966 and Later), 3600, 3610 | | | |
| Brake Shoe 1 1/2" Wide, Sold Individually (2) Required Per Side | AMD9NN2218AA | \$ 28.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Brake Components

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: Models w/ Internal Wet Brakes | | | |
| Brake Rod Seal | AM86576339 | \$ 3.00 | |
| Application: 8N | | | |
| Brake Drum | AM8N1126 | \$ 197.00 | |
| Application: 230A, 231, 233, 234, 333, 334, 335, 530A, 531, 2000 Series, 2100, 2110, 2120, 2300, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 3000 Series, 3100, 3120, 3190, 3300, 3310, 3330, 3400, 3500, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 4000 Series, 4110, Ind: 3500 | | | |
| Brake Drum | AMC5NN1126E | \$ 60.00 | |
| Application: 2000, 2110, 2310, 2600, 2610, 3000, 3400, 3600, 4110, Ind/Const: 230A, 233, 234, 333, 334, 335, 530A, 531 | | | |
| Brake Backing Plate Replaces 81815610 | AMC5NN2212D | \$ 200.00 | |
| Application: 2810, 2910, 3100, 3900, 3910, 4100, 4110, 4600, 4610, Ind: 445, 445A, 445C, 445D, 455 | | | |
| Brake Plate 4.488" ID, 8.228" OD Replaces 81802536 | AMC5NN2N315B | \$ 9.50 | |
| Application: 3000 Series, 4000 Series, 5000 Series, 5600, 5610, 5900, 6600, 6610, 6810, 7000 Series, 7600, 7610, 7710, 7810 | | | |
| Actuator Rod | AMC7NN2466B | \$ 32.00 | |
| Application: (3600, 4100, 4600 - 1975-81), 5000 1969 and Later, 5100, 5110, 5200, 5600, 5610, 5700, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7100, 7200, 7600, 7610, 7700, 7710, 7810, 7910, 8210 | | | |
| Brake Actuator Assembly Replaces C7NN2N316A | AMC7NN2N317A | \$ 115.10 | |
| Application: 5000, 5100, 5200, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6600C, 6610, 6640, 6700, 6710, 7000, (7010, 8010 ASN 800001M), 7100, 7200, 7600, 7600C, 7700, 7710, 7740, 7810, 7840, 7910, 8210, 8240, 8340, TB80, TB85, TB90, TB100, TB110, TB120, TS90, TS100, TS110, TS115, TV140, TV145, TV6070 | | | |
| Brake Disc 22 Tooth, 0.19" Thick, 2.086" ID, 8.819" OD Replaces 83956599, C5NN2A097A, C7NN2A097B, E6NN2A097AA | AM87518036 | \$ 33.00 | |
| Application: 8160, 8260, 8360, 8560, (TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 BSN C4806) | | | |
| Friction Disc, Handbrake 34 Spline, 4.126" ID, 7.067" OD, 0.236" Thick | AM5146036 | \$ 59.20 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T5.95, T5.105, T5.115, T6.120, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.225, T7.230, T7.245, T7.260, T7.270, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 ASN D4806, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
| Brake Pad Single Sided, 0.131" Thick | AM5199607 | \$ 14.70 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T5.95, T5.105, T5.110, T5.115, T5.120, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, TM115, TM125, TM135, TM150, TM165, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
| Brake Plate Splined, 4.134" ID, 7.441" OD, 0.177" Wide | AM47127225 | \$ 22.50 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6.120, T6.140, T6.150, T6.155, T6.160, T6.165, T6.175, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
| Brake Disc | AM5191497 | \$ 145.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, TS100A, TS115A, TS125A, TS135A | | | |
| Brake Disc | AM47131048 | \$ 80.00 | |
| Application: T7030, T7040, T7050, T7060, T7070, T7.165S, T7.175, T7.190, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270 | | | |
| Brake Disc 14 Tooth, 2.36" ID, 12.87" OD, 0.374" Thick | AM84201664 | \$ 185.60 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Brake Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: TL70, TL80, TL90, TL100, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Master Cylinder Replaces 82006194, 82018664 | AM84558759 | \$ 189.50 | |
| Application: TV140, TV145, TV6070 | | | |
| Clutch Master Cylinder Replaces 86011371 | AM3129807R92 | \$ 198.30 | |

Manual Steering Gearbox Assemblies

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 2000, 2100, 2150, 2300, 2310, 2610, 3000, 3055, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3610, 3910, 4000, 4110, Ind: 230A, 530A | | | |
| Steering Column Assembly | AME0NN3503AA | \$ 300.00 | |
| Application: 5100, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 7100, 7600 - Models w/ Cylinder under Radiator | | | |
| Steering Column Assembly | AMD7NN3503A | \$ 680.00 | |
| Application: 8N ASN 216989 | | | |
| Steering Gearbox | AM8N3548B | \$ 425.00 | |
| Application: 600, 800, 2000, 3000, 4000, NAA | | | |
| Steering Gearbox Arm | AM86542743 | \$ 104.60 | |

Power Steering Gearbox Assembly and Components

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 5600, 6600, 7600 1975-81 w/o Cab | | | |
| Steering Column Assembly For Power Steering Assembly | AME1NN3N503BC | \$ 1,423.00 | |

Ford®/New Holland®—Tractor

Steering Shafts

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: 8N ASN 216989, 600, 800, 2000, 4000, NAA - w/ 4 Cylinder Engines | | | |
| Steering Sector Shaft, Right Hand Single, Works w/ OEM Gears | AM251293 | \$ 245.00 | |
| Application: 1300, 1500, 1700, 3000, 3600, 3900 Replaces SBA334130041, SBA34130041 | | | |
| Steering Sector Shaft 15/16" to 1" Taper, 5 Tooth, 36 Spline | AM38180-16120 | \$ 158.50 | |
| Application: 2000, 3000, 4000 | | | |
| Rocker Shaft Replaces DKN3575B | AMC9NN3575C | \$ 156.00 | |
| Application: 2000, 2600, 3000, 3600, 3900, 4100 | | | |
| Manual Steering Shaft w/ Nut 26.25" Long | AMD2NN3A710B | \$ 66.00 | |
| Application: 5000, 5100, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 7410, 7700 | | | |
| Manual Steering Shaft w/ Nut 28.75" Long Replaces C5NN3A710B | AMD2NN3A710A | \$ 60.00 | |
| Application: 5000, 5100, 5340, 7000, 7100 | | | |
| Steering Shaft 28.65" Long | AMC5NN3A710A | \$ 175.00 | |
| Application: Jubilee, NAA | | | |
| Manual Steering Shaft 22.75" Overall Length Worm Shaft | AMNAA3575C | \$ 127.00 | |

Drawbars and Components

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 2000, 2600, 2610, 2810, 2910, 3000, 3100, 3230, 3430, 3600, 3610, 3910, 3930, 4130, 4610, 4630, 4830 | | | |
| Drawbar 2" x 1" x 32.875" w/ 1.50" Offset, (2) 0.970" Diameter Holes: 1.75" & 3.75" from Front | AM82009197 | \$ 177.00 | |
| Application: (2000, 3000, 4110 - w/ Swinging Drawbar), 2600, 2610, 2810, 2910, 3100, 3600, 3610, 3910, 4610 | | | |
| Drawbar 2" x 1" x 30.875" w/ 1.75" Offset, (2) 0.906" Diameter Holes: 1.25" & 3.25" from Front | AM86531346 | \$ 65.00 | |
| Application: 2600, 3600, 3900, 4100, 4600, Ind: 515, 532 | | | |
| Drawbar 2" x 1.25" x 34.625", (4) 0.937" Diameter Holes: 1.343", 3.343", 5.718" & 7.718" from Front | AMC5NN805F-SPL | \$ 134.20 | |
| Application: (2810, 2910, 3910, 4100, 4110, 4600 - w/ Clevis), (3230, 3430, 3930, 4130, 4630, 4830 - 07/1990 and Later), 4000 w/ 540 RPM PTO, 5030 09/1992 and Later | | | |
| Drawbar 2" x 1.25" x 32.50" w/ 2.75" Offset, (2) 0.922" Diameter Holes: 1.375" & 5.75" from Front | AMC5NN805J | \$ 124.50 | |
| Application: 3230, 3430, 3930, 4130, 4630, 4830, 5030 | | | |
| Drawbar 2" x 1.25" x 32.63" | AM86520237 | \$ 172.50 | |
| Application: 3900, 4000 w/ 540 or 1000 RPM PTO, 4400, 4600 | | | |
| Drawbar 2" x 1.25" x 34.63" w/ 2.75" Offset, (4) 0.937" Diameter Holes: 1.343", 3.34", 5.718" & 7.718" from Front | AMC5NN805F | \$ 161.90 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Drawbars and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 4100, 4600, 5000 Series, 5100, 5110, 5200, 5340, 5600, 5610, 5700, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7000 Series, 7100, 7200, 7410, 7600, 7610, 7700, 7710 | | | |
| Drawbar 2.344" x 1.156" x 33.125", (2) 1.18" Diameter Holes: 1.75" & 4.75" from Front | AMD2NN805A | \$ 94.30 | |
| Application: (5000, 7000 - 1965-06/73), 7100, 7200 | | | |
| Drawbar 2.25" x 1.375" x 34.75" | AMC5NN805A | \$ 114.00 | |
| Application: 5100, 5110, 5600, 5610, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7000, 7100, 7410, 7600, 7610, 7700, 7710, 7810, 7910, 8210 | | | |
| Drawbar, Standard Duty 2.50" x 1.375" x 36.90", (3) 1.165" Diameter Holes: 1.25", 3.25", & 7.75" from Front For Both Single Speed & Dual Speed PTO Tractors because of the Third Hole in the Front of the Drawbar | AME0NN805AC | \$ 100.00 | |
| Application: 5640, 6640, 7740, 7840, 8240, 8340 | | | |
| Drawbar 2.25" x 1.625" x 36.25", (3) 1.156" Diameter Holes at 1.25", 3.25" & 7.75" from Front For Standard Swinging Drawbar | AME9NN805AA | \$ 184.00 | |
| Application: 7810, 78100, 7910, 8000, 8210, 8400, 8530, 8600, 8630, 8700, 8730, 8830, 9000, 9200, 9600, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
| Drawbar 3" x 1.375" x 42.50", (2) Holes at 1.125" & 3.25" from Front Replaces 83902378, C9NN805A | AMD3NN805A | \$ 264.50 | |
| Application: 8210, (8160, 8260, 8360, 8560 BSN C3857 w/ Rollers), (TS90, TS100, TS110, TS115 ASN C3855 w/ Swinging Drawbar) | | | |
| Drawbar 3" x 1.375" x 41.75", (2) 1.141" Diameter Holes at 1.125" & 2.75" from Front Replaces 82010158 | AME3NN805AA12B | \$ 184.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Drawbar Replaces 310529A1, 719663006, 719663016 | AM87680426 | \$ 868.10 | |
| Application: T8010, T8020, T8030, T8040, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Drawbar Replaces 277702A1, 87773807 | AM277702A2 | \$ 916.70 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Drawbar 5" x 2" x 57.125", (6) Holes: 1.625", 3.8125", 7.375", 9.50", 11.625" & 13.75" from Front | AM426511A1 | \$ 750.00 | |
| Application: TG215, TG245, TG275, TG305 | | | |
| Drawbar Cat IV | AM87688072 | \$ 864.30 | |
| Application: 230A, 231, 233, 333, 335, 420, 515, 530A, 531, 532, 535, 2000 Series, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 3000 Series, 3055, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3600, 3610, 3900, 4000 Series, 4100, 4110, 4600, 5600, 5700, 6600, 6700, 7600, 7700, Ind: 3500 | | | |
| Drawbar Hanger | AMD1NN809A | \$ 270.00 | |

Hammer Straps

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T6010, T6020, T6030, T6050, T6070, T6080, T6090, T7030, T7040, T7050, T7070, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.170, T7.175, T7.185, T7.190, T7.195S, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.260, T7.270, TM120, TM130, TM140, TM155, TM175, TM190, TS100A, TS115A, TS125A, TS130A, TV140 | | | |
| Hammer Strap | AM82026931 | \$ 120.90 | |
| Application: TG210, TG230, TG255, TG285 | | | |
| Hammer Strap | AM232615A3 | \$ 135.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Rockshaft Components

| Description | Part Number | Retail Price | Core |
|---|-----------------------|--------------|------|
| Application: 8160, 8260, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Rockshaft Control Shaft | AM5171027 | \$ 375.00 | |
| Application: TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Rockshaft Lift Arm Replaces 5171960 | Left Hand AM87317739 | \$ 235.00 | |
| Application: TM140, TM150 | | | |
| Rockshaft Lift Arm | Right Hand AM87317740 | \$ 235.00 | |

Lift Link Assemblies and Components

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Leveling Box Assembly w/ Fork, Right Hand | AM8N577A | \$ 54.00 | |
| Application: 2N, 8N, 9N, 501, 541, 600, 601, 611, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 960, 961, 971, 981, (2000, 4000 - w/ 4 Cylinder Engine), 2120, 4120 | | | |
| Leveling Box Fork, Right Hand 9" Long | AMECON585A | \$ 16.00 | |
| Application: 2N, 8N, 9N, 600, 700, 800, 900, 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 3000, 3120, 3300, 3310, 3330, 3400, 3500, 3600, 3610, 4110, 4600, NAA | | | |
| Leveling Box Fork, Left Hand Replaces 81802071, 87712987 | AMC5NNB863A | \$ 28.00 | |
| Application: 2N, 8N, 9N, NAA | | | |
| Lift Rod Assembly, Left Hand Replaces 9N564B, 182544M92, 81801642 | AM1884720M1 | \$ 40.00 | |
| Application: 600, 601, 800, 801, 2000, 2610, 3000, 3100, 3600, 3610, 4000 | | | |
| Leveling Rod Assembly Replaces C5NN585D, C7NN564B | AMC5NNR862A | \$ 45.00 | |
| Application: 2000 Series w/ 3 Cylinder Engines, 2600, 2610, 3000, 3100, 3600, 3610, Ind/Utility: 340, 2100, 3400, 3550, 4110, 4200 | | | |
| Leveling Box Assembly w/ Fork, Right Hand Adjusts from 20.25" to 25.25" center-to-center on mounting holes | AME0NN569AA | \$ 68.00 | |
| Application: 4000, 4600 | | | |
| Leveling Box Assembly w/ Fork, Right Hand Adjusts from 27.25" to 32.25" center-to-center on mounting holes | AMC5NN569AM | \$ 101.50 | |
| Lift Link Assembly, Left Hand Includes Knuckle, Rod and Fork | AM4N564B | \$ 63.00 | |
| Application: 5000, 5100, 5110, 5200, 5340, 5600, 5610, 5700, 5900, 6000, 6410, 6600, 6600C, 6600O, 6610, 6610O, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7600, 7600C, 7610, 7610O, 7700, 7710 | | | |
| Lift Link Assembly w/ Fork, Left Hand Replaces C5NNB863CA, VPL2229 | AMD2NNN984A | \$ 81.00 | |
| Application: 5000, 5100, 5200, 5600, 6600, 6610, 6700, 7100, 7200, 7600, 7700 | | | |
| Leveling Box Assembly w/ Fork, Right Hand Adjusts from 25.00" to 31.00" center-to-center on mounting holes | AMD2NNN983WF | \$ 145.00 | |
| Components: | | | |
| Right Hand Level Box Assy W/O Fork | AMD2NNN983A | \$ 100.00 | |
| Fork | AMC7NNA935C | \$ 50.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Lift Link Assemblies and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 5110, 5610, 5900, 6410, 6710, 6810, 7410, 7610, 7710 | | | |
| Leveling Box Assembly w/ Fork, Right Hand Adjusts from 20.25" to 25.25" center-to-center on mounting holes | AME0NN569WF | \$ 165.00 | |
| Components: | | | |
| Right Hand Level Box Assy w/o Fork | AME0NN569KB | \$ 85.00 | |
| Fork | AMD5NNA935B | \$ 90.00 | |
| Application: 5640, 6640, 6640O, 7740, 7740O, 7840, 7840O, 8240, 8340, TV140 | | | |
| Leveling Box Assembly w/ Fork, Right Hand Replaces 82021056, F0NNA935AA, F0NNA954CD | AM83991548 | \$ 360.00 | |
| Application: 5000, 5100, 5110, 5200, 5340, 5600, 5610, 5700, 5900, 6410, 6600, 6610, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7600, 7610, 7700, 7710, 8600, 8700, 9000, 9600, 9700, TW10, TW20, TW30 | | | |
| Bevel Gear For Lift Link Assemblies Replaces 81821842 | AMC7NN568B | \$ 17.00 | |
| Application: 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 3000, 3100, 3120, 3300, 3310, 3330, 3400, 3500, 3600, 3610, 4110, 4600SU | | | |
| Lift Link Assembly, Left Hand Assembly Includes Knuckle, Rod and Fork Replaces C5NN564D, C5NNR862A, E0NNB484DA | AM2N564B | \$ 39.50 | |
| Application: T7030, T7040, T7050, T7060, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260 | | | |
| Lift Link Assembly Replaces 5188140, 47133994 | AM84253931 | \$ 270.00 | |
| Application: T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435 | | | |
| Lift Link Assembly | AM84281303 | \$ 200.00 | |
| Application: T5.95, T5.105, T5.115 | | | |
| Lift Link | AM84479014 | \$ 395.00 | |
| Application: T6.180, T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6.125, T6.145, T6.155, T6.165, T6.175, TS100A, TS115A, TS125A, TS135A | | | |
| Stabilizer Lift Link | AM82034576 | \$ 375.00 | |
| Application: TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165 | | | |
| Stabilizer Lift Link | AM47125971 | \$ 425.00 | |

Ford®/New Holland®—Tractor

Lower Lift Links

| Description | Part Number | Retail Price | Core |
|--|-------------------------------|--------------|------|
| Application: (600, 601, 700, 701, 800, 801, 900, 901, 2000, 4000 - w/ 4 Cylinder), (2000, 3000, 3610 - w/ 3 Cylinder) | | | |
| Lower Lift Arm, Cat I 32.25" Long, 7/8" Hole | Right Hand AMD0NN555D | \$ 40.00 | |
| | Left Hand AMD0NN555C | \$ 40.00 | |
| Application: 2310, 2600, 2610, 3000 Series, 3055, 3100, 3310, 3600, 3610, 3900, 4000 Series, 4600, 4610SU, Ind/Utility: 230A, 231, 233, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 3550 | | | |
| Lower Lift Arm, Cat I 33" Long, 0.875" Hole | Right Hand AME5NN555AA | \$ 150.00 | |
| | Left Hand AME5NN556AA | \$ 150.00 | |
| Application: 2810, 2910, 3000, 3055, 3230, 3430, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4200, 4330, 4340, 4400, 4410, 4600, 4610, 4610SU, 4630, 4830, 5030, Ind/Utility: 250C, 260C, 345D, 445D, 515, 532, 535, 545D, 3550, 4500 | | | |
| Lower Lift Arm, Cat II 35" Long, 1 1/8" Hole | Right or Left Hand AM82002004 | \$ 90.00 | |
| Application: 2310, 2600, 2610, 2810, 2910, 3000 Series, 3055, 3100, 3230, 3310, 3430, 3600, 3610, 3900, 3910, 3930, 4000 Series, 4100, 4110, 4130, 4200, 4330, 4340, 4400, 4410, 4600, 4610SU, 4630, 4830, 5030, Ind/Utility: 230A, 231, 233, 250C, 260C, 333, 334, 335, 340, 340A, 340B, 345C, 345D, 420, 445, 445A, 445C, 445D, 450, 515, 530A, 531, 532, 535, 540, 540A, 540B, 545, 545A, 545C, 545D, 3550, 4500 | | | |
| Lift Arm Replacement Ball, Cat I 0.875" ID, 2.25" OD Use w/ AME5NN556AA, AME5NN555AA or AM82002004 Lift Arm w/ Removable Ball | AME1ADDN995233 | \$ 8.10 | |
| Application: 5000 Series, 5100, 5200, 5340, 5600, 5700, 6600, 6600C, 6600O, 6700, 7000 Series, 7100, 7200, 7600, 7600C, 7700 | | | |
| Lower Lift Arm, Cat II 35" Long, 1 1/8" Hole | Right or Left Hand AMD2NN555E | \$ 64.75 | |
| Application: 5000 Series, 5600, 5610, 5700, 5710, 6600, 6610, 6700, 6710, 7000 Series, 7600, 7610, 7700, 7710 | | | |
| Lower Lift Arm, Cat II 37" Long, 1 1/8" Hole | Right or Left Hand AM82002013 | \$ 147.00 | |

Three Point Hitch Components

| Description | Part Number | Retail Price | Core |
|--|---------------------------------|--------------|------|
| Application: 2910, 3910, 4110, 4620 | | | |
| Stabilizer Assembly Complete Assembly w/o Bracket and U-Bolts | Right or Left Hand AMD9NNB856BB | \$ 70.00 | |
| Stabilizer Bracket | Right Hand AMC7NND933B | \$ 30.00 | |
| Stabilizer Bracket | Left Hand AMC7NND932B | \$ 30.00 | |
| Stabilizer Bracket U-Bolt | AMC5NN16N321A | \$ 9.00 | |
| Application: 5610, 6610, 6710, 7710, 8210 | | | |
| Stabilizer Assembly Complete Assembly w/o Bracket and U-Bolts | Right or Left Hand AMD9NNB856AA | \$ 70.00 | |
| Application: 5610, 6610, 6710, 7610, 7710, 8210 | | | |
| Stabilizer Bracket | Right Hand AMC7NND933A | \$ 30.00 | |
| Stabilizer Bracket | Left Hand AMC7NND932A | \$ 30.00 | |
| Stabilizer Bracket U-Bolt | AM388838S36 | \$ 8.00 | |
| Application: 5000, 5100, 5110, 5200, 5340, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6610, 6640, 6700, 6710, 6810, 7000, 7100, 7200, 7600, 7610, 7700, 7710, 7740, 7810, 7840, 7910, 8210, 8240, 8340 | | | |
| Draft Control Yoke Replaces 81827128 | AMD2NN546A | \$ 71.00 | |




Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Quick Hitch

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TS100, TS110, TS115 Pull Arm Latch, CAT III Right or Left Hand For Flat/Hook Style Pull Arm Replaces 3903314M91, 86017137, CH167802 | AMAL117727 | \$ 60.00 | |









Hydraulic Lift Components

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: T6030, T6050, T6070, T6080 Hydraulic Lift Cylinder | AM87392350 | \$ 370.00 | |
| Application: 2N, 8N, 9N Hydraulic Lift Cylinder Housing | AM9N510D | \$ 60.00 | |
|  Hydraulic Lift Ram Arm | AM8N545B | \$ 60.00 | |
| Application: 600, 700, 800, 900, 2000, 4000 - w/ 4 Cylinder Engines Hydraulic Lift Ram Arm | AMNCA545B | \$ 70.00 | |
|  Hydraulic Lift Ram Arm | AMC5NN545B | \$ 60.00 | |
| Application: 2000 Series, 2100, 2110, 2120, 2150, 2300, 2310, 2600N, 2600V, 2610V, 3000 Series, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3600N, 3600V, 3610N, 3610V, 4000 Series, 4110 - w/ 3 Cylinder Engines Hydraulic Lift Ram Arm | AMC5NN545B | \$ 60.00 | |
|  Hydraulic Lift Ram Arm | AMC7NN545C | \$ 153.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.






Ford®/New Holland®—Tractor

Hydraulic Lift Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 2310, 2600, 2610, 2910, 3600, 3610, 3900, 3910, 4600, Ind: 230A, 231, 233, 234, 333, 334, 335, 340, 340A, 340B, 530A, 531 | | | |
|  Hydraulic Lift Arm, Right Hand Use on AMC5NN544D Hydraulic Lift Shaft | AMC5NNB920D | \$ 50.00 | |
|  Hydraulic Lift Arm, Left Hand Use on AMC5NN544D Hydraulic Lift Shaft | AMC5NNB921D | \$ 50.00 | |
| Application: 5000 Series, 5600, 5610, 5700, 6600, 6610, 6700, 7000, 7600, 7610, 7700, 7810, 7910, 8210 | | | |
|  Hydraulic Lift Arm, Right Hand Use on AMC5NN544B Hydraulic Lift Shaft | AME3NN838AA | \$ 85.00 | |
|  Hydraulic Lift Arm, Left Hand Use on AMC5NN544B Hydraulic Lift Shaft | AME3NN839AA | \$ 80.00 | |
| Application: 2310, 2600, 2610, 2910, 3600, 3610, 3900, 3910, 4600, Ind: 230A, 231, 233, 234, 333, 334, 335, 340, 340A, 340B, 530A, 531 | | | |
|  Hydraulic Lift Shaft | AMC5NN544D | \$ 120.00 | |
| Application: 5000 Series, 5600, 5610, 5700, 6600, 6610, 6700, 7000, 7600, 7610, 7700, 7810, 7910, 8210 | | | |
|  Hydraulic Lift Shaft | AMC5NN544B | \$ 145.20 | |
| Application: 2N, 8N, 9N, 600, 700, 800, 900, (2000, 4000 - w/ 3 or 4 Cylinder Engine), 2310, 2600, 2610, 3000, 3600, 3610, 3910, 4600, NAA, Dexta, Super Dexta, Ind: 230A, 234, 334, 335, 340A 10/1981-04/83, 530A | | | |
|  Lift Cylinder Rod Replaces 957E526 | AM86563314 | \$ 43.30 | |
| Application: 5000, 5600, 5610, 5640, 5700, 6600, 6610, 6640, 6700, 7000, 7600, 7610, 7640, 7700, 7710, 7740, 7810, 7840, 8210, 8240, 8340, TS90, TS100, TS110 | | | |
|  Lift Cylinder Rod | AMC7NN526D | \$ 35.00 | |

Ford®/New Holland®—Tractor

Hydraulic Lift Components (...continued)

| Description | | Part Number | Retail Price | Core |
|---|---|-------------|--------------|------|
| Application: | 2N, 8N, 9N | | | |
|  | Hydraulic Lift Piston | AM9N530B | \$ 21.75 | |
| Application: | 5600, 5610, 5640, 5700, 5710, 6600, 6610, 6640, 6700, 7600, 7610, 7640, 7700, 7710, 7810, 7840, 7910, 8210, 8240, 8340, 8530, 8630, 8730, 8830, TS90, TS110, TS115, TW5, TW15, TW25, TW35 | | | |
|  | Hydraulic Lift Piston 4.125" Diameter | AMD5NN530A | \$ 30.00 | |
| Application: | 8000, 8200, 8400, 8600, 8700, 9200, 9600, TW5, TW15 | | | |
|  | Snap Ring For Hydraulic Lift Position Control Lever to Shaft | AM505026 | \$ 1.50 | |
| Application: | 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, 3230, 3300, 3310, 3330, 3400, 3430, 3600, 3610, 3900, 3910, 3930, 4000, 4100, 4110, 4130, 4140, 4200, 4330, 4340, 4400, 4410, 4600, 4610, 4630, 4830, 5030, Ind: 345C, 345D, 420, 445, 445D, 450, 535, 540, 545, 545D, 3500, 3550, 4500 | | | |
|  | Draft Control Spring Housing Replaces 81815737 | AMC5NNN905B | \$ 65.00 | |
| Application: | T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  | Solenoid, Hitch Valve Replaces 87775314 | AM188105A1 | \$ 70.00 | |

Ford®/New Holland®—Tractor

Toplink Assemblies

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 230A, 2000 Series, 2600, 2610, 3000 Series, 3600, 3610, Ind/Utility: 334, 335, 530A | | | |
| Toplink Assembly Cat I, 3/4" Holes | AME0NN576DA | \$ 42.00 | |
| Application: 2810, 2910, 3000 Series, 3055, 3900, 3910, 4000, 4100, 4110, 4600, 4600SU, 4610, 5000, 5100, 5110, 5200, 5600, 5610, 5700, 5900, 6000, 6600, 6610, 6700, 6710, 6810, 7000, 7100, 7200, 7410, 7600, 7610, 7700, 7710, Ind/Utility: 340, 340A, 340B, 445, 445A, 450, 540, 540A, 540B, 545, 545A, 3550 | | | |
| Toplink Assembly Cat II, 1" Holes | AMD0NN576A | \$ 46.00 | |
| Application: 3000 Series, 3910, 4000 Series, 4100, 4110, 4600, 4610, 4610SU, Ind/Utility: 340, 340A, 340B, 445, 445A, 450, 515, 532, 535, 540, 540A, 540B, 545, 545A, 3550, 4500 | | | |
| Toplink Assembly Cat I & II, 3/4" & 1" Holes | AMD6NN576C | \$ 115.00 | |
| Application: T7030, T7040, T7050, T7060, T7070, TM175, TM190 | | | |
| Toplink Assembly | AM87595426 | \$ 385.00 | |
| Application: 2000 1965 and Later w/ 3 Cylinder Engine, (2600, 3000, 3600, 3600N - 1975 and Later), 2610 1981-04/83, (3610, 3610N - 1981-82) | | | |
| Hydraulic Lift Rocker | AME0NN535AA | \$ 75.00 | |
| Application: 2N, 8N, 9N, 800, 900, (2000, 4000 - w/ 4 Cylinder Engines, Hi-Clearance) | | | |
| Toplink Bracket | AMNCA535A | \$ 60.00 | |
| Application: 2000, 2310, 2600, 2610, 3000, 3600, 3610, 4000SU, 4600SU, 4610SU | | | |
| Toplink Bracket Replaces E0NN535AA | AMC7NN535C | \$ 60.00 | |
| Application: 2000 w/ 3 Cylinder Engines, 2600 - 1975 and Later | | | |
| Toplink Bracket | AMC7NN535B | \$ 55.00 | |
| Application: 2810, 2910, 3000 1965 and Later, 3055, 3600 1975 and Later, 3610 1981-1982, 3910, 4000 3 Cylinder 1965 and Later, 4100, 4110, 4610 1981 and Later, 4610SU, Ind/Utility: 340, 340A, 340B, 445, 445A, 450, 540, 540A, 540B, 545, 545A, 3550, 4400, 4500 | | | |
| Toplink Bracket | AME2NN535BA | \$ 112.00 | |

Sway Blocks

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 8160, 8260, 8360, 8560, T7030, T7040, T7050, T7060, T7070, T7.195S, T7.215S, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.300, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190 | | | |
| Sway Block, Right Hand | AM47125870 | \$ 340.90 | |
| Sway Block, Left Hand | AM47125871 | \$ 340.90 | |
| Application: T7030, T7040, T7050, T7060, T7070, T7.195S, T7.215S, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.275, T7.290, T7.300, T7.315, T7.340 | | | |
| Sway Block Plate 3.63" Wide, 3.50" Height, 0.62" Thick, 2.562" Center-to-Center, 0.662" Hole Diameter | AM87332334 | \$ 49.60 | |
| Application: T7030, T7040, T7050, T7060, T7070, T7.195S, T7.215S, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.300 | | | |
| Sway Block Plate 3.63" Wide, 3.50" Height, 0.91" Thick, 2.562" Center-to-Center, 0.662" Hole Diameter | AM87332342 | \$ 48.60 | |
| Application: T7030, T7040, T7050, T7060, T7070, T7.195S, T7.215S, T7.220, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.300, TM175, TM190 | | | |
| Sway Block Plate 3.63" Wide, 3.50" Height, 0.17" Thick, 2.562" Center-to-Center, 0.662" Hole Diameter | AM87332350 | \$ 39.90 | |
| Sway Block Plate 3.94" Length, 3.65" Height, 2.562" Center-to-Center, M16x1.5 Thread | AM87712866 | \$ 93.80 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Battery Box Components

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 8N | | | |
| Battery Box | AM8N10732 | \$ 41.00 | |
| Battery Hold Down | AMNCA10718A | \$ 18.90 | |
| Application: 9N, 600, 700, 800, 900, 2000, 4000, Jubilee, NAA | | | |
| Battery Box Primer Coated, Ready for Paint For 6 Volt Battery | AMCONN10732T | \$ 57.60 | |
| Application: 501, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 661, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 861, 871, 900, 901, 941, 950, 951, 960, 971, 981, (2000, 4000 - w/ 4 Cylinder Engine), 2031, 2111, 2120, 2130, 2131, 4031, 4120, 4121, 4130, 4131, NAA, NAB, Ind/Const: 1801, 1811, 1821, 1841, 1871, 1881, 2030, 2130, 4030, 4040, 4140 | | | |
| Battery Tray For 6 Volt Battery | AMCONN10732 | \$ 45.00 | |
| Application: 2000, 2100, 2110, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3055, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3600, 3610, 3900, 3910, 4000, 4100, 4110, 4140, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4600SU, 4610, 4610SU, 5000, 5100, 5110, 7810 - 1965-01/31/67 w/ Diesel Engine | | | |
| Battery Tray 19.75" x 9" Overall Dimensions Replaces 81814352, C5NN10723A, C5NN10723B | AMC5NN10723H | \$ 152.30 | |

Side Panels and Hoods

| Description | Part Number | Retail Price | Core |
|--|-------------------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Side Panel | Right Hand AM8N16618A-R | \$ 86.00 | |
| | Left Hand AM8N16618A-L | \$ 85.00 | |
| Application: 600, 800, 900, NAA | | | |
| Side Panel | Right Hand AMC3NN16653A | \$ 140.00 | |
| | Left Hand AMC3NN16652A | \$ 140.00 | |
| Application: 8N | | | |
| Hood | AM8N16612 | \$ 391.50 | |
| Application: 2000, 2100, 2110, 2120, 2300, 2310, 3000, 3055, 3100, 3110, 3120, 3300, 3310, 3330, 3400, 3500, 3550, 4000, 4100, 4110, 4140, 4330, 4340, 4400, 4410, 4500, 7000, 7100, 7200 | | | |
| Hood 31" Long | Right Hand AMC5NN16625F | \$ 83.00 | |
| Application: 6600, 6610 | | | |
| Hood Replaces C5NN16626J, C7NN16626C | Left Hand AMD5NN16626 | \$ 84.00 | |

Ford®/New Holland®—Tractor

Front Grilles, Nose Cones and Components

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Grille | AM8N8204 | \$ 70.00 | |
| Application: 231, 233, 333, 335, 515, 531, 532, 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 3900, 4100, 4600, 4600D, 4600U, 4600SU, 5600, 6600, 6600C, 6600D, 7600, 7600C | | | |
| Grille 1-Piece | AMD5NN8200C | \$ 74.00 | |
| Application: 2600, 3600, 3900, 4100, 4600, 5600, 6600, 7600 | | | |
| Grille | AMD5NN8200A | \$ 25.00 | |
| Application: 2000, 3000, 4000, 5000 Series | | | |
| Upper Front Grille, Plastic | AMC9NN8A163AG | \$ 21.00 | |
| Application: 2000, 4000 - w/ 4 Cylinder Engine | | | |
| Front Grille | AMC3NN8200A | \$ 86.00 | |
| Application: 2000, 3000, 4000, 5000 Series - 01/1965-12/74 | | | |
| Lower Front Grille, Plastic Replacement lower grille section for tractors w/ external headlights | AMD1NN8151A | \$ 18.00 | |
| Application: 2310, 2610, 2810, 2910, 3610, 3910, 4110, 4910, Ind: 230A, 335, 530A | | | |
| Nose Cone Replaces E4NN6A858AA | AME4NN16A858AA | \$ 291.00 | |
| Application: 231, 233, 333, 531, 2000, 2600, 3000, 3600, 4100 | | | |
| Bumper Axle Mount | AMD8NN17750AA | \$ 275.00 | |
| Application: 5610, 5700, 6610, 6700, 6710, 7410, 7610, 7700, 7710, 7810, 7810O, 7910, 8000, 8210, 8530, 8630, 8700, 9000, 9700, TW5, TW10, TW15, TW20 | | | |
| Outer Grille Screen, Right Hand | AMD5NN8150A | \$ 88.60 | |
| Outer Grille Screen, Left Hand Replaces 83909848 | AMD5NN8151A | \$ 106.40 | |







Fenders and Components

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 2N, 8N, 9N, NAA | | | |
| Fender w/ Bracket Right or Left Hand | AMCONN16312A | \$ 165.10 | |
| Fender w/o Bracket, Skin Only Right or Left Hand | AMCONN16312SK | \$ 125.10 | |
| Application: 601, 611, 621, 631, 641, 651, 661, 671, 681, 801, 811, 821, 841, 851, 861, 871, 881, 2000, 2031, 2150, 2300, 2310, 2600, 2610, 2810, 2910, 3000, 3100, 3110, 3120, 3150, 3230, 3300, 3310, 3330, 3400, 3430, 3500, 3600, 3610, 3900, 3910, 3930, 4000, 4000SU, 4030, 4031, 4120, 4121, 4131, 4400, 4500, 4600, 4600SU, 4610 | | | |
| Fender w/ Bracket, Clam Shell Right or Left Hand | AMC5NN16312AK | \$ 128.00 | |
| Application: 2600, 2610, 2810, 2910, 3600, 3610, 3910, 3930, 4100, 4110, 4600, 4610, 4630, 4830, 5030, 5600, 5610, 6600, 6610, 7600, 7610, Ind: 515, 532, 535 | | | |
| Fender, Flat Top Right Hand | AMD8NN16312ABB | \$ 279.00 | |
| Fender, Flat Top Left Hand | AME5NN16313DA | \$ 160.00 | |
| Bracket Right or Left Hand | AMD3NN16N319A | \$ 220.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor






Lighting

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: 8N, 600, 620, 630, 640, 650, 660, 700, 740, 800, 820, 840, 850, 860, 900, 950, 960, Jubilee, NAA, NAB Light Bulb, Sealed Beam 4 1/2" Diameter Round Bulb Dimpled Lens 6 Volt | AM8N15514 | \$ 30.00 | |
| Application: Versatile®: 190, 220, 250, 260, 285, 290, 305, 310, 340, 375, 400, 405, 435, 535, 550, 575  LED Floodlight Conversion Kit (2) 6.50" x 4.50" Oval Lights, Each Light is 5000 Lumens, 60 Watts, 5 Amps For 12 Volt to 24 Volt Systems Includes Mounting Brackets, Stainless Steel Hardware and Wiring Harness (Plug-and-Play) | AMTL8320-KIT | \$ 386.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, Versatile®: 2145, 2160, 2180, 2210  LED Light Kit Includes Right Hand and Left Hand LED Headlight**, (2) Cab Mount LED Floodlights*, (6) Cab/Fender Mount LED Floodlights*, Connectors and Stainless Steel Mounting Hardware For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring *3600 Lumens, 40 Watts, 3.30-3.33 Amps **8200 Lumens, 90 Watts, 7.50 Amps | AMX34162 | \$ 1,300.00 | |
| Application: T6020, T6040, T6060, T7030, T7040, T7050, T7060, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A Replaces 82031075 | | | |
|  LED Upper Cab Light 6" x 3" x 2.50" Rectangle Light 3000 Lumens, 40 Watts, 3.33 Amps For 12 Volt to 24 Volt Systems Due to cab variations, please verify correct part number before ordering | AMTL7040 | \$ 102.00 | |
|  LED Upper Cab Light 6" x 3" x 2.50" Rectangle Light 3000 Lumens, 40 Watts, 3.33 Amps For 12 Volt to 24 Volt Systems Due to cab variations, please verify correct part number before ordering | AM82031078 | \$ 85.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, Versatile®/Buhler®: 2145, 2160, 2180, 2210 | | | |
|  LED Headlight, Right Hand Hi/Lo Beam and Side Beam 8200 Lumens, 90 Watts, 7.50 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Replaces 86514346, 86514347 | AMTL8970R | \$ 253.00 | |
|  LED Headlight, Left Hand Hi/Lo Beam and Side Beam 8200 Lumens, 90 Watts, 7.50 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Replaces 86514348, 86514349 | AMTL8970L | \$ 253.00 | |
| Application: T6010, T6020, T6030, T6040, T6060, T6070, T7030, T7040, T7060, TL80A, TL90A, TL100A, TN60A | | | |
| LED Headlight Floodlight Pattern 6.50" x 6" x 4.50" 3200 Lumens, 32 Watts, 2.6 Amps For 12 Volt to 24 Volt Systems Plug-and-Play for Direct Replacement Replaces 82035642 | AMTL6025 | \$ 148.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|-------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | | |
|  | LED Headlight Front Mount 3.37" Diameter Round Light 3200 Lumens, 32 Watts, 2.60 Amps For 12 Volt to 24 Volt Systems Replaces the factory bulb/housing Plug-and-Play Installation | AMTL6020 | \$ 115.00 | |
| | LED Headlight Front Mount 3.37" Diameter Round Light 3200 Lumens, 40 Watts, 2.60 Amps For 12 Volt to 24 Volt Systems Will Bolt into Factory Light Housing Plug-and-Play Installation | AMX34172 | \$ 103.00 | |
| Application: Universal Equipment | | | | |
|  | LED Floodlight All-Position Light 4.25" x 4.25" Square Light 2650 Lumens, 48 Watts, 4 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL105F | \$ 85.50 | |
| | LED Wide Floodlight All-Position Light 5" x 7" Rectangle Light 3800 Lumens, 35 Watts For 12 Volt to 24 Volt Systems | AMX34171 | \$ 85.00 | |
|  | LED Floodlight All-Position Light 6.25" x 1.75" Rectangle Light 1300 Lumens, 18 Watts, 1.50 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL118F | \$ 57.00 | |
| | LED Floodlight All-Position Light 4.25" Round Light 2650 Lumens, 42 Watts, 3.50 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL115F | \$ 66.00 | |
|  | LED Floodlight All-Position Light 5" Round Light 3200 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL180 | \$ 102.00 | |
| | LED Floodlight All-Position Light Round Light 6900 Lumens, 50 Watts, 4.10 Amps For 9 Volt to 32 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL500F | \$ 135.00 | |
|  | LED Floodlight All-Position Light 4.30" Round Light 5040 Lumens, 50 Watts, 4.10 Amps For 12 Volt to 24 Volt Systems Includes Stainless Steel Adjustable Mounting Bracket | AMAT305931 | \$ 121.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|-------------|--------------|------|
| Application: | Universal Equipment | | | |
|  | LED Floodlight, Sealed Beam Fender Mount 4.50" Diameter Round Light 1250 Lumens, 18 Watts, 1.50 Amps Trapezoid Pattern For 12 Volt to 24 Volt Systems | AMTL3010 | \$ 50.00 | |
|  | LED Floodlight Fender Mount 4.50" Diameter Sealed Beam Round Light 1250 Lumens, 18 Watts, 1.20 Amps Trapezoid Pattern For 12 Volt to 24 Volt Systems Lasts 50 times longer than halogen lighting, vibration resistant w/ no filament failures, uses original mount and wiring, Operating temperature of -40°F to 140°F / -40°C to 60°C | AMRE336111 | \$ 45.00 | |
|  | LED Floodlight Cab and Fender Mount 6" x 3.50" Rectangle Light 3600 Lumens, 40 Watts, 3 Amps | AMX34146 | \$ 85.00 | |
| Application: | 2310, 2600, 3600, 4000, 4100, 4200, 4600, 5000, 5200, 5600, 5900, 6600, 6700, 7000, 8600, 8700, 9000, 9700 | | | |
|  | Halogen Floodlight, Sealed Beam 4.50" Diameter Round Light 2-Terminal Connection For 12 Volt Systems Replaces A47179, AR104119, E3NN15330AA | AMH7606 | \$ 13.00 | |
| Application: | 8160, 8260, 8360, 8560, 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115, Versatile®/Buhler®: 2145, 2160, 2180, 2210 | | | |
|  | LED Floodlight Cab Mount 6" x 3.50 Rectangle Light 3600 Lumens, 40 Watts, 3 Amps Post on Side Deutsch Connector | AM9846126 | \$ 86.00 | |
| Application: | 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  | LED Floodlight Cab Mount 6" x 3" Rectangle Light 3600 Lumens, 40 Watts, 3.33 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Includes Deutsch Connector, Mounting Bracket and Stainless Steel Hardware Replaces 9824851 | AMTL3050 | \$ 105.00 | |
| Application: | T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T6.120, T6.140, T6.150, T6.155, T6.160, T6.165, T6.175, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270 | | | |
|  | LED Floodlight Oval Light 3000 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Includes Connector and Stainless Steel Hardware Replaces 84254557, 84273088 | AMTL7060 | \$ 111.00 | |








Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | Part Number | Retail Price | Core |
|--|--------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, T9030, T9040, T9050, T9060, T9.390, T9.435, T9.450, T9.480, T9.505, T9.530, T9.560, T9.565, T9.600, T9.615, T9.645, T9.670, T9.700, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 Replaces 87435762, 87773385 | | | |
|  <p>LED Floodlight Lower Front, Cab, Fender and ROPS 6" x 3.50" x 3" Rectangle Light 3600 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Includes Connector, Plug-and-Play</p> | AMTL3030 | \$ 106.00 | |
|  <p>LED Floodlight Lower Front, Cab, Fender and ROPS 6" x 3.50" x 3" Rectangle Light 3600 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Includes Connector, Plug-and-Play</p> | AM92269C1 | \$ 95.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  <p>LED Floodlight Fender Mount w/ Hollow Bolt 6" x 3.50" Rectangle Light 3600 Lumens, 40 Watts, 3.33 Amps For 12 Volt to 24 Volt Systems Uses Original Wiring Includes Deutsch Connector, Mounting Bracket and Stainless Steel Hardware</p> | AMTL3085 | \$ 105.00 | |
|  <p>LED Floodlight Fender Mount w/ Hollow Bolt 6" x 3.50" 3600 Lumens, 40 Watts, 3.33 Amps For 12 Volt to 24 Volt Systems Uses Original Wiring Includes Deutsch Connector, Mounting Bracket and Stainless Steel Hardware</p> | AM20-1730T91 | \$ 80.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  <p>LED Floodlight Side Mount 6" x 3.50" x 3" Rectangle Light 3600 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Requires Splicing into Original Wiring</p> | AMTL3075 | \$ 105.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 | | | |
|  <p>LED Floodlight Side Mount 6" x 3.50" Rectangle Light 3600 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Includes Swivel Mounting Bracket and Hardware</p> | AMTL3070 | \$ 105.00 | |
|  <p>LED Floodlight Side Mount 6" x 3.50" Rectangle Light 3600 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Includes Swivel Mounting Bracket and Hardware</p> | AM92266C1 | \$ 85.00 | |








Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | Part Number | Retail Price | Core |
|---|--------------|--------------|------|
| Application: Versatile®: 190, 220, 250, 260, 265, 270, 290, 300, 305, 310, 320, 335, 360 Replaces 86038024 | | | |
|  <p>LED Floodlight Hood Mount 5.50" x 3.75" Oval Light 3000 Lumens, 35 Watt, 2.90 Amps For 12 Volt to 24 Volt Systems Use Original Mount and Wiring, Plug-and-Play</p> | AMTL8220 | \$ 121.00 | |
|  <p>LED Floodlight Hood Mount 5.50" x 3.75" Oval Light 3000 Lumens, 39 Watts, 2.90 Amps For 12 Volt to 25 Volt Systems Includes Connector, Plug-and-Play</p> | AMRE271574 | \$ 108.00 | |
| Application: Versatile®: 190, 220, 250, 260, 285, 290, 305, 310, 340, 375, 400, 405, 435, 535, 550, 575 | | | |
|  <p>LED Floodlight Upper Front and Rear Cab, Rear Fender and Mid Mount 6.50" x 4" Oval Light 5200 Lumens, 65 Watts, 5.40 Amps For 12 Volt to 24 Volt Systems Housing Has Powder Coat Finish Includes Mounting Bracket and Stainless Steel Hardware</p> | AMTL5680 | \$ 135.00 | |
|  <p>LED Floodlight Upper Front and Rear Cab, Rear Fender and Mid Mount 6.50" x 4" Oval Light 5500 Lumens, 65 Watts For 12 Volt to 24 Volt Systems Housing Has Powder Coat Finish Includes Connector and Bracket for Plug-and-Play Installation</p> | AMAH212523 | \$ 100.00 | |
| Application: 5640, 6640, 6640O, 7740, 7740O, 7840, 7840O, 8160, 8240, 8260, 8340, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TV140 | | | |
|  <p>LED Floodlight/Spotlight Combo Grille Mount 6" x 4" Rectangle Light 3500 Lumens, 60 Watts, 5 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware</p> | AMTL7740 | \$ 124.00 | |
|  <p>LED Floodlight/Spotlight Combo Grille Mount 6" x 4" Rectangle Light, 3500 Lumens, 60 Watts, 5 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware</p> | AMF0NN1305AB | \$ 111.00 | |
| Application: TS90, TS100, TS110, TS115 | | | |
|  <p>LED Floodlight/Spotlight Combo Hood Mount 6" x 4" Rectangle Light 3500 Lumens, 60 Watts, 5 Amps For 12 Volt to 24 Volt Systems Includes Connector, Mounting Brackets and Stainless Steel Hardware</p> | AMTL6070 | \$ 157.00 | |








Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|---|-------------|--------------|------|
| Application: | Universal Equipment | | | |
|  | LED Spotlight All-Position Light 4.25" x 4.25" Square Light 1400 Lumens, 27 Watts, 2.20 Amps For 12 Volt to 24 Volt Systems | AMTL100S | \$ 50.00 | |
|  | LED Spotlight All-Position Light 6.25" x 1.75" Rectangle Light 1300 Lumens, 18 Watts, 1.50 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL118S | \$ 57.00 | |
|  | LED Spotlight All-Position Light 4.25" x 4.50" Round Light 6900 Lumens, 50 Watts, 4.10 Amps For 9 Volt to 32 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL500S | \$ 135.00 | |
| Application: | 233, 333, 2000, 2100, 2110, 2120, 2150, 2300, 2310, 2600, 2600N, 2600R, 2600V, 3000, 3055, 3100, 3110, 3120, 3150, 3300, 3310, 3330, 3400, 3500, 3550, 3600, 3600N, 3600NO, 3600R, 3600V, 3900, 4000, 4100, 4110, 4140, 4200, 4330, 4340, 4400, 4410, 4500, 4600, 4600NO, 4600O, 4600SU, 5000, 5100, 5200, 5340, 5600, 5700, 6600, 6600C, 6600O, 6700, 6710, 7000, 7100, 7200, 7600, 7600C, 7700, 7710, 7910, 8000, 8210, 8600, 8700, 9000, 9600, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  | LED Trapezoid Light Fender Mount 4.50" Sealed Beam Round Light 2200 Lumens, 24 Watts, 2 Amps For 12 Volt to 24 Volt Systems Uses Original Mount and Wiring Replaces RE336111 | AMTL3015 | \$ 55.00 | |
| Application: | 2310, 2600, 2610, 2810, 2910, 3600, 3610, 3910, 3930, 4200, 4600, 4600SU, 4610, 5200, 5600, 5610, 5900, 6600, 6610, 7000, 7200, 7600, 7610 Replaces D9NN13005CA, D4NN13002C | | | |
|  | LED Trapezoid Light Fender Mount 4.50" Sealed Beam Round Light 2800 Lumens, 40 Watts, 3.30 Amps For 12 Volt to 24 Volt Systems Rear Stud Mount w/ Built-In Heat Sink Includes Both Long and Short Rubber Bezels | AMTL2060 | \$ 115.00 | |
|  | LED Floodlight Hood, Front and Rear Fender Mount 5" Diameter Round Light 2800 Lumens, 40 Watts, 3.30 Amps Trapezoid Pattern 1/2" rear stud mount w/ built-in heat sink for cooling, a brighter light and longer life, Includes both long and short rubber bezels, For use w/ stud mounted front fender lights | AMAR85859 | \$ 103.00 | |
|  | Headlight Sealed Beam, 12 Volt, 2-Wire | AMRE25126 | \$ 55.00 | |










Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|---|-------------|--------------|------|
| Application: | Universal Equipment | | | |
|  | LED Magnetic Warning Light All-Position Light 360° Flashing Light, Multiple Patterns 14" x 6.75" Rectangle Light Magnetic Base or Solid Mount For 12 Volt to 24 Volt Systems Includes Cigarette Lighter Adapter, Wiring and Switch | AMTL1200 | \$ 215.00 | |
| Application: | 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, Versatile®: 2145, 2160, 2180, 2210 | | | |
|  | LED Warning Light, Right Hand Cab Mount 4.75" x 3.25" x 2.50" Rectangle Light Amber Lens, 7 Watts, 0.60 Amp For 12 Volt to 24 Volt Systems Includes Stainless Steel Hardware Replaces 86507530 | AMTL7015R | \$ 57.00 | |
|  | LED Warning Light, Left Hand Cab Mount 4.75" x 3.25" x 2.50" Rectangle Light Amber Lens, 7 Watts, 0.60 Amp For 12 Volt to 24 Volt Systems Includes Stainless Steel Hardware Replaces 86507530 | AMTL7015L | \$ 57.00 | |
| Application: | 9030E, 9030V, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, Versatile®: 256, 276, 276-II, 756, 836, 846, 856, 876, 936, 946, 956, 976, 1156 | | | |
|  | LED Warning Light Cab Mount 6.75" x 3.15" Rectangle Light 9 Watts, 0.75 Amp For 12 Volt to 24 Volt Systems Replaces 92260C1, 107324C91, 130882C91, 216044C91, 216044C92, 9706415, 83977683, 86012669, 86014019, 86016518, 86023276, 87053368 | AMX34180 | \$ 57.00 | |
|  | LED Warning Light Cab Mount 6.75" x 3.15" Rectangle Light 9 Watts, 0.75 Amp For 12 Volt to 24 Volt Systems Replaces 92260C1, 107324C91, 130882C91, 216044C91, 216044C92, 9706415, 83977683, 86012669, 86014019, 86016518, 86023276, 87053368 | AM92185C1 | \$ 47.00 | |
| Application: | T9020, T9030, T9040, T9050, T9060, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 | | | |
|  | Warning Light, Side Marker Amber Lenses | AM367321A1 | \$ 35.60 | |
| Application: | Universal Equipment | | | |
|  | Warning Beacon 360° Flashing Beacon, Amber Lens For 0.9435" Diameter Pipe Replaces 84337818, AZ44705, AZ101891 | AM82018390 | \$ 73.70 | |










Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|-------------|--------------|------|
| Application: Universal Equipment | | | | |
|  | LED Warning Beacon 360° Flashing Beacon 2.75" x 5.25" Light Polycarbonate Amber Lens and Housing For 12 Volt to 24 Volt Systems Includes Solid Mounting Pad and Stainless Steel Hardware | AMTL2100 | \$ 34.00 | |
|  | LED Warning Beacon 360° Flashing Beacon 5" x 10" Amber Lens, 48 Watts, 4 Amps For 12 Volt to 24 Volt Systems Brackets Sold Separately | AMTL2000-1 | \$ 98.00 | |
|  | LED Warning Beacon 360° Flashing Beacon, 3 Different Patterns 5" x 10" Light Amber Lens, 48 Watts, 4 Amps For 12 Volt to 24 Volt Systems Brackets Sold Separately | AMX33131 | \$ 85.00 | |
|  | Warning Beacon Bracket Use w/ AMX33131 LED Warning Beacon, TL2000 | AMX33132 | \$ 17.00 | |
|  | Warning Beacon Bracket Use w/ AMX33131 LED Warning Beacon, TL2000 | AMX33133 | \$ 17.00 | |
|  | Warning Beacon Bracket Use w/ AMX33131 LED Warning Beacon, TL2000 | AMX33137 | \$ 17.00 | |
|  | Warning Beacon Bracket Use w/ AMX33131 LED Warning Beacon, TL2000 | AMX33135 | \$ 17.00 | |
|  | LED Light Bar Flood/Spotlight Combo 10" Long, 5700 Lumens, 50 Watts, 4.20 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL10SRC | \$ 145.00 | |
|  | LED Light Bar Floodlight/Spotlight Combo 14" Long, 5400 Lumens, 72 Watts, 6 Amps Die Cast Aluminum Housing, Polycarbonate Lens For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Heavy Duty Stainless Steel Hardware | AMTLB410C | \$ 169.00 | |

Ford®/New Holland®—Tractor

Lighting (...continued)

| Description | | Part Number | Retail Price | Core |
|---|--|---------------|--------------|------|
| Application: | Universal Equipment | | | |
|  | LED Light Bar Floodlight/Spotlight Combo 30" Long, 13600 Lumens, 150 Watts, 12.50 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware | AMTL30SRC | \$ 259.00 | |
|  | LED Light Bar 30" Long, 13860 Lumens, Cree Bulbs | AMLED30 | \$ 130.00 | |
|  | LED Light Bar Floodlight/Spotlight Combo 40" Long, 17300 Lumens, 200 Watts, 16.70 Amps For 12 Volt to 24 Volt Systems Includes Mounting Brackets and Stainless Steel Hardware | AMTL40SRC | \$ 337.00 | |
|  | LED Light Bar 40" Long, 18200 Lumens, Cree Bulbs | AMLED40 | \$ 160.00 | |
|  | LED Light Bar Floodlight/Spotlight Combo 42" Long, 14500 Lumens, 240 Watts, 19 Amps For 12 Volt to 24 Volt Systems Includes Mounting Bracket and Stainless Steel Hardware Replaces 1163691 | AMTLB440C | \$ 328.00 | |
|  | LED Magnetic Work Light All-Position Light 3.25" Square Floodlight 900 Lumens 3 Modes: 30% Intensity, 100% Intensity and S.O.S. Pattern Magnetic Base Includes Lithium Ion Battery, Cigarette Lighter and DC Charger | AMTL2460 | \$ 89.00 | |
| Application: | 2N, 8N, 9N | | | |
|  | Light Switch Replaces 9N11652, 830517M91 | AM9N11652B | \$ 7.00 | |
| Application: | 2000, 2310, 2600, 2610, 2810, 2910, 3000, 3600, 3610, 3910, 4000, 4110, 4600, 4610, 5000, 5110, 5600, 5610, 6410, 6610, 6710, 6810, 7000, 7600, 7610, 7710, 7910, 8210 | | | |
|  | Light Switch Replaces C5NN11654C, D6NN11N650A, EDPN11654AA | AM251405 | \$ 12.00 | |
| Application: | 2310, 2610, 2810, 2910, 3610, 3910, 3930, 4110, 4610, 4630, 4830, 5110, 5610, 6410, 6610, 6710, 6810, 7410, 7610, 7710, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35, Ind/Const: 230A, 234, 250C, 260C, 334, 335, 340, 340A, 340B, 345C, 345D, 445, 445A, (445C, 445D, 545C, 545D - w/o Cab), 450, 530A, 540, 540A, 540B, 545, 545A | | | |
|  | Light Switch | AME3NN11654AA | \$ 14.75 | |

Ford®/New Holland®—Tractor



Cab Components—Miscellaneous

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|-----------|
| Application: 8670, 8670A, 8770, 8770A | | | |
| Reman Monitor Replaces 86025959, 86027424, 86027424R | AM84595297R | \$ 3,880.00 | \$ 250.00 |
| Application: T6030, T6050, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T7.170, T7.185, T7.200, T7.210, T7.220, T7.235, T7.250, T7.260, T7.270 | | | |
| Reman Monitor Replaces 293255A3, 295133A5, 87668610 | AM84604338R | \$ 1,375.00 | \$ 500.00 |
| Application: T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435 | | | |
| Monitor Bracket Well-suited for use w/ multiple monitors, less restriction of operator's view improves safety. Assembly hardware and tray pad included, monitor mounting hardware not included. | AMSS3178 | \$ 211.50 | |
| Application: (T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435 - 2014 and Later) | | | |
| Monitor Bracket Well-suited for use w/ multiple monitors, less restriction of operator's view improves safety. Assembly hardware and tray pad included, monitor mounting hardware not included. | AMSS3192 | \$ 173.50 | |
| Application: Most Models | | | |
| Tablet Holder, Rail Mount Universal tablet mount, heavy duty, rail mount Standard double knuckle w/ 9" extension, will hold tablets up to 11" w/ (4) cutouts for camera lens 360° rotation for portrait or landscape viewing Limited Lifetime Warranty | AMX19135 | \$ 100.00 | |

Cab Doors

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 3600, 4600, 4610, 5600, 5610, 6600, 6610, 6710, 7600, 7610, 7700, 7710, 7910, 8200, 8210, 8530, 8630, 8700, 8730, 8830, 9700, TW5, TW10, TW15, TW20, TW25, TW35 | | | |
| Door Molding Kits Sold in Pairs, w/ Blue Push Pins | AMX19105 | \$ 199.00 | |

Glass

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Front Windshield Glass Hinged | AM82032042 | \$ 255.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Front Windshield Glass Replaces 82030483 | AM87304257 | \$ 335.00 | |

Ford®/New Holland®—Tractor








Glass (...continued)

| Description | Part Number | Retail Price | Core |
|---|------------------|--------------|------|
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  Lower Windshield Glass, Right Hand Replaces 89827540 | AM9827540 | \$ 54.50 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Lower Front Glass, Right Hand Replaces 82030487 | AM87566891 | \$ 128.00 | |
|  Lower Front Glass, Left Hand Replaces 82030488 | AM87566892 | \$ 105.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Lower Front Glass, Right Hand Replaces 82030485 | AM87304259 | \$ 91.00 | |
|  Lower Front Glass, Left Hand Replaces 82030486 | AM87304261 | \$ 118.00 | |
| Application: 233, 234, 333, 334, 2600, 2610, 3600, 3610, 3910, 4100, 4110, 4600, 4610, 5110, 5600, 5610, 5700, 6410, 6600, 6610, 6700, 6710, 6810, 7410, 7600, 7610, 7700, 7710, 7910, 8000 Series, 8210, 8700, 9000 Series, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  Wing Window | AMD5NN9425722B | \$ 80.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  Side Glass, Right Hand Hinged Replaces 9861002, 89861002 | AM86521435 | \$ 67.50 | |
| Application: (5610, 6640, 7740, 7840, 8240, 8340 - Prior to 10/1995), (8670, 8770, 8870, 8970 - 09/1993 and Later), 8670A, 8770A, 8870A, 8970A | | | |
| Door Glass, Left Hand Replaces 83994233, 86508175, 89823599 | AME9NN94032N18BB | \$ 174.50 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5050, TS6020, TS6030, TS6.110, TS6.120, TS6.125, TS6.140 | | | |
|  Door Glass, Right Hand | AM87620223 | \$ 389.60 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.





Ford®/New Holland®—Tractor

Glass (...continued)

| Description | Part Number | Retail Price | Core |
|--|-----------------|--------------|------|
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  <p>Door Glass, Right Hand Replaces 82027356, 87528172</p> | AM84280178 | \$ 550.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435, TG215, TG245, TG275, TG305 | | | |
|  <p>Door Glass, Left Hand</p> | AM344730A2 | \$ 417.80 | |
| Application: TN55D, TN55S, TN60DA, TN60SA, TN60VA, TN65D, TN65F, TN65S, TN65V, TN70D, TN70DA, TN70F, TN70NA, TN70S, TN70SA, TN70VA, TN75D, TN75DA, TN75F, TN75FA, TN75S, TN75SA, TN75V, TN75VA, TN80F, TN85DA, TN85FA, TN85SA, TN90F, TN95DA, TN95F, TN95FA, TN95NA, TN95VA | | | |
|  <p>Door Glass, Left Hand Replaces 5196841</p> | AM44910453 | \$ 392.80 | |
| Application: TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  <p>Door Glass, Left Hand Replaces 82027357, 87560786</p> | AM87528171 | \$ 525.00 | |
| Application: 5110, 5600, 5610, 6600, 6610, 6810, 7410, 7600, 7610, 7700, 7710, 7810, 7910, 8000, 8210, 8530, 8630, 8700, 8730, 8830, 9000, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  <p>Upper Door Glass, Right or Left Hand Tinted Replaces 82015335, 82019226, D8NN9421410BA</p> | AM83914255 | \$ 59.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  <p>Rear Glass Replaces 9823602, 89823602</p> | AM86002901 | \$ 189.50 | |
| Application: 5640, 6640, 7740, 7840, 8240, 8340 - Prior to 06/1994 w/ SuperLux Cab | | | |
|  <p>Rear Glass Replaces 81865244, 83995319</p> | AMF0NN9442038BA | \$ 149.50 | |

Ford®/New Holland®—Tractor

Glass (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  Rear Glass Replaces 82030887, 87663400 | AM87744542 | \$ 200.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.420, T8.435, TG215, TG245, TG275, TG305 | | | |
|  Rear Glass Tinted Replaces 242667A4 | AM87309738 | \$ 319.00 | |
| Application: 4635, 4835, 5635, (5640, 6640, 7740, 7840, 8240, 8340 - 11/1995 and Later w/ SuperLux Cab), 7635, (8160, 8260, 8360, 8560, TS90, TS100, TS110, TS115 - w/ D3814 Engine w/ SuperLux Cab) | | | |
|  Upper Rear Glass Replaces 5178304, 82005316, VPM7343 | AM82016997 | \$ 225.00 | |
| Application: 4835, 5635, 6635, 7635, 8160, 8260, 8360, 8560, T5040, T5050, T5060, T5070, TL70, TL70A, TL80, TL80A, TL90, TL90A, TL100, TL100A, TM115, TM120, TM125, TM130, TM135, TM140, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115 | | | |
|  Lower Rear Glass | AM82000485 | \$ 27.00 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5050, TS6030 | | | |
| Lower Rear Glass | AM5089562 | \$ 223.80 | |
| Application: (T8010, T8020, T8030, T8040, T8050 BSN Z8RW08527), TG210, (TG215, TG245, TG275, TG305 BSN Z8RW08527), TG230, TG255, TG285 | | | |
| Weatherstrip For Cab Door | AM87534532 | \$ 24.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Weatherstrip For Rear Cab Window | AM87534532 | \$ 24.00 | |
| Application: (T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 ASN Z8RW08528), T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435 | | | |
| Weatherstrip For Cab Door | AM84160023 | \$ 23.10 | |

Ford®/New Holland®—Tractor

Gas Struts

| Description | Part Number | Retail Price | Core |
|--|-----------------|--------------|------|
| Application: 8160, 8260, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TV140, TV145, TV6070 Replaces 82007029 | | | |
| Gas Strut, Hood | AM82019392 | \$ 26.00 | |
| Application: TD4020F, TD4030F, TD4040F | | | |
| Gas Strut, Hood | AM5097656 | \$ 41.10 | |
| Application: 4835, 5635, 6635, 7635, TL70, TL80, TL80A, TL90, TL90A, TL100, TL100A | | | |
| Gas Strut, Roof Hatch | AM82002925 | \$ 19.00 | |
| Application: 5110, 5610, 5640, 6410, 6610, 6640, 6710, 6810, 7610, 7710, 7740, 7810, 7840, 7910, 8210, 8240, 8340, 8530, 8560, 8630, 8730, 8830, TW5, TW15, TW25, TW35 | | | |
| Gas Strut, Roof Hatch | AM83949895 | \$ 19.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
| Gas Strut, Door | AM1280263C1 | \$ 19.00 | |
| Application: T6000, T7000 | | | |
| Gas Strut, Door Left Hand | AM87374182 | \$ 33.00 | |
| Application: TM120, TM130, TM140, TM155, TM175, TM190 | | | |
| Gas Strut, Door | AM82027922 | \$ 19.00 | |
| Application: 230A, 234, 334, 335, 530A, 1710, 1710O, 1910, 2310, 2610V, 2810, 2910, 3230, 3430, 3610, 3610V, 3910, 3910H, 3910N, 3910R, 3910V, 3930, 3930H, 3930N, 3930NO, 4110, 4110N, 4110NO, 4110O, 4110V, 4130, 4130N, 4130NO, 4610, 4610N, 4610NO, 4610O, 4610SU, 4610V, 4630, 4630N, 4630NO, 4630O, 4830, 4830N, 4830O, 5030, 5030O, 5110, 5610, 6410, 6610, 6610O, 6710, 6810, 7410, 7610, 7610O, 7710, Ind: 45D, 545D | | | |
| Gas Strut, Rear Window Replaces 3038161M91, 3476187M1, 83932024 | AME2NN9444000AA | \$ 15.50 | |
| Application: 2310, 2610, 2810, 2910, 3430, 3610, 3910, 3930, 4110, 4130, 4610, 4630, 4830, 5030, 5110, 5610, 6410, 6610, 6710, 6810, 7410, 7610 | | | |
| Gas Strut, Rear Window | AM83932028 | \$ 35.00 | |
| Application: 4835, 5635, 5640, 6635, 6640, 7635, 7740, 7840, 8160, 8240, 8340, 8360, 8560, TL65, TL70, TL80, TL90, TL100, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115 Replaces 81865239, F0NN9444000BA | | | |
| Gas Strut, Rear Window | AM82019393 | \$ 19.00 | |
| Application: 5110, 5610, 6410, 6610, 6710, 6810, 7610, 7710, 7810, 7910, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 | | | |
| Gas Strut, Rear Window | AME4NN9444000AA | \$ 15.00 | |
| Application: T2310, T2320, T2410, T2420, TC40DA, TC45DA | | | |
| Gas Strut, Rear Window | AM84320293 | \$ 19.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T7030, T7040, T7050, T7060, TS100A, TS115A, TS125A, TS130A, TS135A | | | |
| Gas Strut, Rear Window | AM82022486 | \$ 19.00 | |

Ford®/New Holland®—Tractor


Fuel Tanks

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 2N, 8N, 9N | | | |
| Fuel Tank, Metal | AM9N9002 | \$ 135.00 | |
| Application: 600, 620, 630, 640, 650, 660, 700, 740, 800, 820, 840, 850, 860, 900, 950, 960, NAA, NAB | | | |
| Fuel Tank For gas models only unless return line has been added for diesel models Tank has option for fuel sender, must be purchased separately Use w/ AM311292 Valve in the bottom of the tank | AMNAA9002E | \$ 245.00 | |
| Fuel Shut Off Valve | AM311292 | \$ 42.00 | |
| Application: 600, 800, 900, (2000, 4000 - w/ 4 Cylinder Engines), NAA | | | |
| Fuel Tank, Metal Only Flat Bottom | AMNAA600 | \$ 220.00 | |

Steering Wheels

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: 8N, 231, 233, 234, 333, 334, 335, 340, 501, 515, 531, 532, 535, 541, 600, 601, 611, 620, 621, 630, 631, 640, 641, 650, 651, 660, 671, 681, 700, 701, 740, 741, 771, 800, 801, 811, 820, 821, 840, 841, 850, 851, 860, 861, 871, 881, 900, 901, 941, 950, 951, 961, 971, 981, 2000, 2120, 2130, 2310 All Purpose, 2600, 2610, 2810, 2910, 3000, 3110, 3120, 3230, 3300, 3310, 3330, 3400, 3430, 3600, 3610, 3900, 3910, 3930, 4000, 4110, 4120, 4130, 4140, 4330, 4340, 4400, 4410, 4600, 4610, 4630, 4830, 5000, 5030, 5100, 5110, 5340, 5600, 5610, 5900, 6600, 6610, 7000, 7600, 7610, NAA, NAB, (2100, 2110 - w/ Power Steering), (2300, 2310 Narrow - w/ Manual Steering) | | | |
| Steering Wheel 36 Spline, 18" Diameter, 0.785" Hub Diameter | AMD6NN3600B | \$ 20.00 | |
| Application: 8N 1948-52, 600, 700, 800, 900, (2000, 4000 - w/ 4-Cylinder Engine 1953-64), NAA, Jubilee | | | |
| Steering Wheel 17 5/8" Diameter, 36 Spline Hub, 11/16" Shaft | AM8N3600 | \$ 26.00 | |
| Application: 2N 1939-47, 9N | | | |
| Steering Wheel 17 5/8" Diameter, Keyed Hub, 11/16" Shaft | AM180576M1 | \$ 23.00 | |
| Application: 1100, 1110, 1120, 1200, 1210, 1215, 1220, 1320, 1520, 1620, 1720, 1920, 2120, 3415, TC30, TC1510, TC1520 | | | |
| Steering Wheel 15 3/4" Diameter, 18 Spline Hub For 3 1/2" Steering Shaft Replaces 66611-41400, SBA334300050, SBA334310110 | AM32400-16800 | \$ 64.00 | |
| Application: Major, Super Major | | | |
| Steering Wheel 6-Spline Hub, 18" Diameter 3 Covered Spokes Replaces 81717476, E1ADKN3600A | AME1ADKN3600 | \$ 59.10 | |








Air Conditioning and Components

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: 5610, 6610, 6710, 6810, 7410, 7610 | | | |
|  <p>Compressor Conversion Kit Rotary Tecumseh HR980 to Sanden Includes Compressor, Mounting Bracket, Hoses, O-Rings and Mounting Hardware Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10189 | \$ 595.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 5700, 6700, 7700 | | | |
|  <p>Compressor Conversion Kit York to Sanden Includes Compressor, Mounting Brackets, Compressor Manifold, Hoses, O-Rings, Belt and Mounting Hardware Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10195 | \$ 595.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |
| Application: 5700, 6710, 8000, 8600, 8700, 9000 | | | |
|  <p>Compressor Conversion Kit York Style to Aftermarket Sanden Style Includes Compressor, Mounting Brackets, Compressor Manifold, O-Rings and Mounting Hardware See Manufacturer for Oil Type and Quantity</p> | AMX10263 | \$ 475.00 | |
| | AMX10273 | \$ 14.00 | |
| | | | |
| Application: 6610, 6710, 7710 | | | |
|  <p>Compressor Conversion Kit Tecumseh, York Upright to Sanden Includes Compressor, Mounting Bracket, Compressor Manifold, Hoses and Mounting Hardware Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10194 | \$ 595.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |
| Application: 7710 | | | |
|  <p>Compressor Conversion Kit Rotary Tecumseh HR980 to Sanden Includes Compressor, Mounting Bracket, Hose, O-Rings and Mounting Hardware</p> | AMX10190 | \$ 595.00 | |
| | AME9NN19N601CA | \$ 100.00 | |
| | | | |
| Application: 7810 | | | |
|  <p>Compressor Conversion Kit Rotary Tecumseh HR980 Style to Seltec Style Includes Compressor, Mounting Bracket, Hose, O-Rings and Mounting Hardware</p> | AMX10191 | \$ 595.00 | |
| | | | |
| Application: 7910, 8210 | | | |
|  <p>Compressor Conversion Kit Rotary Tecumseh HR980 Style to Sanden Style Includes Compressor, Mounting Bracket, Hose, O-Rings and Mounting Hardware</p> | AMX10192 | \$ 595.00 | |
| | AME9NN19N601CA | \$ 100.00 | |
| | | | |
| Application: 8700, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  <p>Compressor Conversion Kit Tecumseh, York Upright to Sanden Includes Compressor, Mounting Bracket, Binary Switch, Hoses, O-Rings and Mounting Hardware For R134a Applications Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10193 | \$ 595.00 | |
| | AME9NN19N601CA | \$ 100.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor








Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: 8700, 9700, TW10, TW20, TW30 | | | |
|  <p>Compressor Conversion Kit Tecumseh, York Upright to Sanden Style Includes, Compressor, Mounting Bracket, Binary Switch, Hoses, O-Rings and Mounting Hardware For R12 Applications, Must Use Original Belt Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10196 | \$ 595.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |
| Application: TW5, TW15, TW25, TW35 | | | |
|  <p>Compressor Conversion Kit Rotary Tecumseh HR980 to Sanden Includes Compressor, Mounting Bracket, Binary Switch, Hose, O-Rings and Mounting Hardware Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AMX10188 | \$ 475.00 | |
| | AME9NN19N601CA | \$ 100.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| Application: Versatile®: 750, 800, 825, 835, 850, 855, 875, 895, 900, 935, 950 | | | |
|  <p>Compressor Conversion Kit York Style to Sanden Style Single Groove Long Body Replacement Kit, Replaces York/Tecumseh Single Groove w/ 2.82" Gauge Line (measure from front side mounting hole to center groove of clutch on original York)</p> | AMX10241 | \$ 490.00 | |
| | | | |
| | | | |
| | | | |
| Application: 233, 333, 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 4100 1975-81, 4600, 4600NO, 4600O, 4600SU, 5100, 5600, 5700, 6600, 6600C, 6600O, 6700, 7600, 7600C, 7700, 8000, 8600, 8700, 9000, 9600, 9700, TW10, TW20, TW30 | | | |
|  <p>Compressor, York Style Right Hand Suction, Rotolock Clutch Not Included Requires Synthetic Ester Oil 100V, 9.50 oz (281 cc)</p> | AM54-032 | \$ 230.00 | |
| | AM470 | \$ 110.00 | |
| | AMX10273 | \$ 14.00 | |
| | | | |
| Application: 233, 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 4100, 4600, 4600NO, 4600O, 4600SU, 5600, 5700, 6600, 6600C, 6600O, 6700, 7600, 7600C, 7700, 8000 Series, 8600, 8700, 9000 Series, 9600, 9700, TW10, TW20, TW30, Ind: 333, Versatile®: 700, 750, 800, 825, 835, 850, 855, 875, 895, 900, 935, 950 Replaces 130222, 618606, D2NN19D623A, D3NN19D623A | | | |
|  <p>Compressor, York Style Left Hand Suction, Rotolock Clutch Not Included Requires Synthetic Ester Oil 100V, See Manufacturer for Oil Quantity</p> | AMX10225 | \$ 270.00 | |
| | AM470 | \$ 110.00 | |
| | AMX10273 | \$ 14.00 | |
| | | | |
| Application: 5110, 5610, 5900, 6410, 6610, 6610O, 6710, 6810, 7410, 7610, 7610O, 7710, 7740, 7810, 7810O, 7910, 8000, 8210, 8530, 8630, 8700, 8730, 8830, 9030, 9710, FW20, TW5, TW15, TW25, TW35 | | | |
|  <p>Compressor, Sanden SD7H15 Style 12 Volt, w/ 2-Groove Clutch, 5.19" (132 mm) Clutch Diameter, O-Ring Connections, w/o Charge Ports Requires Pag Oil 100V, 6.76 oz (200 cc)</p> | AME8NN19D629AA | \$ 250.00 | |
| | AMX10267 | \$ 13.15 | |
| | AMX10274 | \$ 12.75 | |
| | | | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor







Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|---|--------------|-----------|
| Application: 5640, 6640, 7740, 7840, 78400, 8240, 8340 - 11/1991-03/94 Replaces F0NN19D629AB, F0NN19D629AA | | | |
|  | Compressor, Sanden SD510 Style 12 Volt, w/ 8-Groove Clutch, 5.25" (133 mm) Clutch Diameter, w/o Charge Ports, Top Pad Mount Requires Synthetic Ester Oil 100V, 10.00 oz (300 cc) | AMX10127 | \$ 225.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: 5640, 6640, 7740, 7840, 78400, 8240, 8340 Replaces F0NN19D629AA, F0NN19D629AB | | | |
|  | Compressor, Sanden SD510 Style 12 Volt, w/ 6-Groove Clutch for Serpentine Belt, 4.90" (125 mm) Clutch Diameter, Top Pad Mount Aftermarket Requires R12 Mineral Oil, 6.12 oz (180 cc) | AMX10209 | \$ 265.00 |
| | | | |
| Application: (5640, 6640, 7740, 7840, 78400, 8240, 8340 - 11/1995 and Later), TS90, TS100, TS110, TS115 Replaces 82008688, 82016157 | | | |
|  | Compressor, Sanden SD7H15 12 Volt, w/ Serpentine Belt, 4.68" (119 mm) Clutch Diameter, Vertical #8 and #10 O-Rings, w/o Charge Ports Requires Synthetic Ester Oil 100V, 5.46 oz (135 cc) | AMX10129 | \$ 235.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: 8160, 8260, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TV140, TV145 Replaces 82008689, 82002069 | | | |
|  | Compressor, Sanden SD7H15 Style 12 Volt, w/ 8-Groove Clutch for Serpentine Belt, 4.68" (119 mm) Clutch Diameter, Vertical #8 and #10 O-Ring Requires Synthetic Ester Oil 100V, 4.56 oz (135 cc) | AM82016158 | \$ 394.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: (8670, 8770, 8870, 8970 - 1993 and Later), 8670A, 8770A, 8870A, 8970A Replaces 9824775 | | | |
|  | Compressor w/ Dust Cover, Sanden 12 Volt, w/ Serpentine Clutch, 5.19" (132 mm) Clutch Diameter, Horizontal #8 and #10 O-Ring Requires Synthetic Ester Oil 100V, 9.13 oz (270 cc) | AMX10128 | \$ 240.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: 9030E, 9030V, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, Versatile®: 2360, 2375 | | | |
|  | Compressor, Sanden SD7H15 12 Volt, w/ 2-Groove Clutch, 5.25" (133 mm) Clutch Diameter, Horizontal Tube O-Ring, w/o Charge Ports Requires Synthetic Ester Oil 100V, 10.14 oz (300 cc) | AMX10187 | \$ 275.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: FW20, FW30, FW40, FW60, Versatile®: 160, 555*, 835, 855*, 875, 895*, 945, 975, 1150 *Verify by Serial Number Replaces SFD351224T91 | | | |
|  | Compressor, Sanden SD508 Style 12 Volt, w/ 2-Groove Clutch, 5.19" (132 mm) Clutch Diameter, Vertical #8 and #10 Flare Fittings, w/ R12 Charge Ports Requires R12 Mineral Oil, 5.91 oz (175 cc) | AMX10178 | \$ 260.00 |
| | | | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.








Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|---|--------------|-----------|
| Application: (T4020, T4030, T4040, T4050 - Deluxe), T4020V, T4030F, T4030N, T4030V, T4040F, T4040N, T4040V, T4050F, T4050N, T4050V, T4060F, T4060N, T4060V, T5040, T5050, T5060, T5070, (T4.65, T4.75 - Non Tier 4A), T4.65V, T4.75F, T4.75V, T4.85F, T4.85V, T4.95F, T4.95V, T4.105F, T4.105V, TD5010, TD5020, TD5030, TD5050 | | | |
|  | Compressor, Sanden SD7H15 12 Volt, w/ 4-Groove Serpentine Clutch, 4.409" (112 mm) Clutch Diameter Requires Pag Oil 100V, 6.46 oz (190 cc) | AM87519620 | \$ 320.00 |
| | Ultra Pag Double End Capped, 100V, 8 oz | AMX10267 | \$ 13.15 |
| | Universal Pag Oil, 8 oz | AMX10274 | \$ 12.75 |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, (T5.110, T5.120, T5.130, T5.140 - Auto Command), T6.120, T6.125, T6.140, T6.145*, T6.150, T6.155*, T6.160*, T6.165*, T6.175*, T6.180, T7.165, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.200, T7.210, T7.225, TS100A, TS115A, TS125A, TS130A, TS135A *Verify by Serial Number Replaces 87709785 | | | |
|  | Compressor, Sanden SD7H15 Style 12 Volt, w/ 4-Groove Clutch for Serpentine Belt, 4.409" (112 mm) Clutch Diameter, 2-Wire, WV Head, Direct Mount Requires Synthetic Ester Oil 100V, See Manufacturer for Oil Quantity | AM87802912 | \$ 281.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: T8010, T8020, T8030, T8040, T8050, T9030, T9040, T9050, T9060, T8.330, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ375, TJ425, TJ450, TJ480, TJ500, TJ530 Replaces 317008A2, 317008A3, 86992688, 87775469, 504078610 | | | |
|  | Compressor, Sanden SD7H15HD 12 Volt, w/ 8-Groove Clutch, 5.98" (152 mm) Clutch Diameter, Horizontal Tube O-Ring, Direct Mount Requires Pag Oil 100V, 9.64 oz (285 cc) | AM86993463 | \$ 281.00 |
| | Ultra Pag Double End Capped, 100V, 8 oz | AMX10267 | \$ 13.15 |
| | Universal Pag Oil, 8 oz | AMX10274 | \$ 12.75 |
| Application: T9010, T9020, TJ275, TJ280, TJ325, TJ330, Ind: LV80, U80 Replaces 317008A2, 317008A3, 47809628, 86992688, 86993463, 504290050 | | | |
|  | Compressor, Sanden SD7H15 12 Volt, w/ 2-Groove Clutch, 6" Clutch Diameter, Horizontal Tube O-Ring Requires Synthetic Ester Oil 100V, 9.60 oz (285 cc) | AMX10125 | \$ 245.00 |
| | Premium Synthetic Ester Oil, 100V, 12 oz | AMX10273 | \$ 14.00 |
| Application: T8010, T8020, T8030, T8040, T8050, (T8.320, T8.350, T8.380 - Prior to 08/2019), (T8.410, T8.435 - Excluding PLM Intelligence), (T9030, T9040, T9050, T9060 - w/ Z6F200013-Z7F204001), T9.390, T9.505, T9.560, T9.600 Track Ready Excluding MY17, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ380, TJ430, TJ480, TJ530 | | | |
|  | Compressor Clutch SD7H15 Clutch w/ 12 Volt Coil, 8-Groove, 5.98" (152 mm) Clutch Diameter, Key-Type Hub Replaces 8775538 | AM403585A1 | \$ 159.50 |
| | | | |
| Application: T9010, T9020, TJ275, TJ280, TJ325, TJ330, Ind: LV80, U80 | | | |
|  | Compressor Clutch SD7H15 Clutch w/ 12 Volt Coil, 2-Groove, 5.98" Clutch Diameter, 0.47" Goove Width Use w/ AMX10125 Compressor | AM135324A2 | \$ 159.00 |
| | | | |








Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|---------------|--------------|------|
| Application: TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190 | | | |
|  Compressor Clutch SD7H15 Clutch w/ 12 Volt Coil, 4-Groove, 4.41" (112 mm) Clutch Diameter, Key-Type Hub | AM87334407 | \$ 175.00 | |
| Application: TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TV140, TV145 | | | |
|  Compressor Clutch SD7H15 Clutch w/ 12 Volt Coil, 8-Groove, 4.68" (119 mm) Clutch Diameter, 3.56 mm Groove Width, Key-Type Hub, Dust Cover Not Included Replaces 82025343 | AM87334399 | \$ 229.00 | |
| Application: Versatile®: 700, 750, 800, 825, 835, 850, 855, 875, 895, 900, 935, 950 | | | |
|  Compressor Clutch SCSA06C Clutch, 4.80" Coil w/ 1/2" Single Groove, Splined-Type Shaft | AM6A671-97310 | \$ 173.00 | |
| Application: Universal Equipment | | | |
|  High Pressure Switch Normally Open, Opens at 305 PSI, Closes at 395 PSI, 7/16"x20 Thread | AMX10276 | \$ 36.00 | |
| Application: Ind: LV80, U80, U80B, U80C | | | |
|  High Pressure Switch Normally Open, Opens at 275 PSI, Closes at 330 PSI, 10 mm Metric Thread Replaces 544975C1, 1651985C1, AG262906 | AM232948A1 | \$ 37.00 | |
| Application: Universal Equipment | | | |
|  Low Pressure Switch Normally Open, Opens at 6 PSI, Closes at 45 PSI, Standard 7/16"x20 Thread | AMX10277 | \$ 56.00 | |
| Application: 5110, 5610, 5640, 6610, 66100, 6640, 6710, 6810, 7410, 7610, 76100, 7710, 7740, 7810 1989-02/96, 78100, 7840, 78400, 7910, 8160, 8210, 8240, 8260, 8340, 8360, 8530, 8560, 8630, 8730, 8830, TD60D, TD70D, TD75D, TD80D, TD90D, TD95D Excluding HC PLUS, TD5010, TD5020, TD5030, TD5050, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90 Emissionised, TS100, TS110, TS115, TS6020, TS6030, TW5, TW15, TW25, TW35 | | | |
|  Low Pressure Switch Normally Open, Opens at 9 PSI, Closes at 28 PSI, 7/16"x20 Thread Replaces F0NN19E561AA | AM87356362 | \$ 45.00 | |







Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 9030E, 9030V, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, TV140, TV145, TV6070 | | | |
|  <p>Low Pressure Switch Normally Open, Opens at 6 PSI, Closes at 31 PSI For use on low side of system. Shuts compressor off before going into vacuum. Wires switch in series w/ coil wire for low side protection.</p> | AMX10226 | \$ 22.00 | |
| Application: (T5.110, T5.120 - Excluding Dual and Electro Command), T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T5.130, T5.140, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.165S, T7.170, T7.175, T7.185, T7.190, T7.195S, T7.200, T7.210, T7.215S, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.275, T7.290, T7.315, (T9.435, T9.480, T9.530, T9.600 - w/ CVT), T9.565 w/o Track Ready, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A | | | |
|  <p>Low Pressure Switch Normally Open, Opens at 20 PSI, Closes at 7 PSI, 10 mm Metric Thread</p> | AM84419250 | \$ 65.20 | |
| Application: TG210, TG230, TG255, TG285, TJ425, TJ430, TJ450, TJ500 | | | |
|  <p>Low Pressure Switch Normally Open, Opens at 5 PSI, Closes at 18 PSI, 10 mm Metric Thread</p> | AM87000228 | \$ 45.00 | |
| Application: Ind: LV80, U80, U80B, U80C | | | |
|  <p>Low Pressure Switch Normally Closed, Opens at 23 PSI, Closes at 7 PSI, 10 mm Metric Thread</p> | AM122579A1 | \$ 44.00 | |
| Application: 233, 333, 2600, 3600, 4100, 4600, 5110, 5600, 5610, 5700, 6410, 6600, 6610, 6700, 6710, 6810, 7410, 7600, 7610, 76100, 7700, 7710, 7810, 7910, 8000, 8210, 8530, 8630, 8700, 8730, 8830, 9000, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  <p>Rotary Adjustable Thermostatic Switch 19 1/2" Capillary Tube Replaces D6NN19N683B</p> | AM87015296 | \$ 115.70 | |
| Application: 256, 836, 7840, 8000, 8200, 8240, 8340, 8600, 8700, 9000, 9030, 9030E, 9030V, 9200, 9600, 9700, 9710, Ind: 8400, Versatile®: 256, 276, 276-II, 500, 555, 700, 750, 756, 800, 825, 835, 836, 846, 850, 855, 856, 875, 876, 895, 900, 935, 945, 946, 950, 955, 956, 975, 976, 1150, 1156, D6 Replaces 9672323 | | | |
|  <p>Rotary Adjustable Thermostatic Switch 36" Capillary Tube</p> | AMX10251 | \$ 62.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T7.165, T7.170, T7.175, T7.185, T7.190, T7.195S, T7.200, T7.210, T7.215S, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.315, TM120, TM130, TM140, TM155, TM175, TM190, TS100A, TS110A, TS115A, TS130A, TS135A | | | |
|  <p>Trinary Switch 7/16"x20 Female Thread Replaces 82019426, 87699591</p> | AM84233818 | \$ 56.00 | |







Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|--|--------------|----------|
| Application: 233, 333, 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 4100, 4600, 4600NO, 4600O, 4600SU, 5600, 5700, 6600, 6600C, 6600O, 6700, 7600, 7600C, 7700, 8000, 8700, 9000, 9700, TW10, TW20, TW30 Replaces D6NN19N644B | | | |
|  | Receiver Drier 4" x 7 1/2", Side Mount Bracket, R12 and R134a Compatible, Inlet: #8 Quick Coupler, 7/8"-20 Thread, Outlet: #6 Male O-Ring | AMX10179 | \$ 29.00 |
| Application: 4835, 5635, 6635, 7635, 8670, 8970, L65, T5040, T5050, T5060, T5070, (T4.65, T4.75 - Non Tier 4A), TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5050, TD5.75, TL70, TL80, TL80A, TL90, TL90A, TL100, TL100A, TN60DA, TN60SA, TN70DA, TN70SA, TN75DA, TN75SA, TN85DA, TN95DA | | | |
|  | Receiver Drier w/o High Pressure Switch | AM5165615 | \$ 39.00 |
| Application: (5110, 5610, 6610, 6710, 6810, 7410, 7610, 7710 - 1981-85), 6610O, 7610O, 8000 Series, 8210, 9000 Series, 9700, (7910, 8210, TW5, TW15, TW25, TW35 -1982-85), (8700, 9700, TW10, TW20, TW30 - 1981 & Later) Replaces E2NN19825AA, E0NN19825AA14L | | | |
|  | Receiver Drier 4" x 9 1/2", Inlet - #6 Female O-Ring, Outlet - #6 Female O-Ring, R12 and R134a Compatible | AMX10157 | \$ 39.00 |
| Application: (5110, 5610, 6610, 6710, 6810, 7410, 7610, 7710, 7910, 8210, TW5, TW15, TW25, TW35 - 1985 and Later), 6610O, 7610O, 7810 1988 and Later, 7810O, 8530, 8630, 8730, 8830 Replaces E4NN19825AB, E4NN19825AA | | | |
|  | Receiver Drier 4" x 7 1/4", Inlet - #6 Male O-Ring, Outlet - #6 Male O-Ring, R12 and R134a Compatible | AMX10158 | \$ 38.00 |
| Application: (5640, 6640, 7740, 7840, 8240, 8340 - 1991-95), 7840O Replaces F0NN19825AB, F0NN19825AC, 82000471 | | | |
|  | Receiver Drier 3" x 15", Inlet - #6, 3/8" Ford Springlock, Outlet - #6, 3/8" Ford Springlock, R12 and R134a Compatible | AMX10159 | \$ 45.00 |
| Application: (5640, 6640, 7740, 7840, 8240, 8340 - 1995 and Later), 7840O, 8160, 8260, 8360, 8560, TM115, TM125, TM135, TM150, TM165, TS90, TS100, TS110, TS115 Replaces 82007131, 82015699, 82012480 | | | |
|  | Receiver Drier 3" x 10", Inlet - #6 Male O-Ring, Outlet - #6 Female O-Ring, R12 and R134a Compatible | AMX10160 | \$ 48.00 |







Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | | Part Number | Retail Price | Core |
|---|---|-------------|--------------|------|
| Application: | 8000, 8600, 9000, 9600 Replaces D3NN19825A | | | |
|  | Receiver Drier 3" x 6" Male Flare, R12 and R134a Compatible | AMX10211 | \$ 22.00 | |
| Application: | 8970A, 8670, 8670A, 8770, 8770A, 8870, 8970, 8870A Replaces 86508374 | | | |
|  | Receiver Drier 3" x 10", Inlet - #6 Male O-Ring, Outlet - #6 Female O-Ring R12 and R134a Compatible | AM86026354 | \$ 46.00 | |
| Application: | 9030, 9030E, 9030V, Versatile®: 150, 276, 836, 846, 856, 876, 936, 946, 956 976 Replaces 9672494, 9827053 | | | |
|  | Receiver Drier 3" x 10 1/2" Male O-Ring, R12 and R134a Compatible | AMX10218 | \$ 27.00 | |
| Application: | 9030E, 9030V, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, TV140 Reference 9705765 | | | |
|  | Receiver Drier 3" x 9" Male O-Ring, Male Switch Port, R12 and R134 Compatible | AMX10205 | \$ 27.00 | |
| Application: | (Boomer 3040, Boomer 3045, Boomer 3050, Boomer 4055, Boomer 4060, Boomer 50D, T2310, T2320, T2410, TC40DA, TC45DA - w/ Cab), T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A, TS6020, TS6030, TV145 Replaces 87374420, 82023593, 87343822 | | | |
|  | Receiver Drier 2 1/2" x 6" Male and Female O-Ring, R12 and R134a Compatible | AMX10214 | \$ 34.00 | |
| Application: | FW20, FW30, FW40, FW60 Replaces SFD605818T3 | | | |
|  | Receiver Drier 3" x 9 1/2" Male Flare, Male Switch Port, R12 and R134a Compatible | AMX10210 | \$ 32.00 | |

Ford®/New Holland®—Tractor







Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: FW20, FW30, FW40, FW60 | | | |
|  <p>Receiver Drier 3" x 9.50", Male Switch Port - 7/16" Flare, Inlet - #6, 3/8" Male Flare, Outlet - #6, 3/8" Male Flare w/ Barbed Fitting, R12 and R134a Compatible Replaces 60-5818T4</p> | AM01-7778T1 | \$ 40.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9010, T9020, T9030, T9040, T9050, T9060, T8.275, (T8.300, T8.350 - 04/2014-10/19), T8.330, T8.360, T8.380 Prior to 08/2019, T8.390, T8.410, T8.420, T8.435, T9.390, T9.435, T9.450, (T9.480, T9.530, T9.565, T9.600, T9.645 - w/ 4WD), T9.505, T9.560, T9.615, T9.670, T9.700, TG215, TG245, TG275, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ450, TJ480, TJ500, TJ530, (TS6.110, TS6.120, TS6.140 - 07/2012 and Later), TV6070 | | | |
|  <p>Receiver Drier 4" x 7 1/2", Inlet - #6 Female O-Ring, Outlet - #6 Male O-Ring, R12 and R134a Compatible</p> | AMX10154 | \$ 28.00 | |
| Application: Versatile®: (900, 700 - 1972-75), (800, 850 - 1973-75) Replaces V18395, V107619 | | | |
|  <p>Receiver Drier 3" x 8 1/4" Male Flare, Female Switch Port - OE Parker, R12 and R134a Compatible</p> | AM72161835 | \$ 30.00 | |
| Application: 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 4100 1975-81, 4600, 4600NO, 4600O, 4600SU, 5110, (5600, 5700, 6600, 6700, 7700 - 1977 and Later), 5610 1988 and Later, 5900, 6410, 6600C, 6600O, (6610, 6710, 6810, 7410, 7610, 7710 - 1981 and Later), 6610O, 7600, 7600C, 7610O, 7810 1988 and Later, 7810O, (7910, 8210, TW5, TW15, TW25, TW35 - 1982 and Later), (8000, 8600, 9000, 9600- 1973 and Later), 8530, 8630, (8700, 9700, TW10, TW20, TW30 - 1976 and Later), 8730, 8830 Replaces D3AH19849AA, D6AH19849AA, E7NN198499AA, 83906905, 83960933, 87022814 | | | |
|  <p>Expansion Valve Bulb Type, Externally Equalized, R12 and R134a Compatible, 28" Tube Length, O-Ring Connection</p> | AMX10148 | \$ 18.00 | |
| Application: 4635, 4835, 5635, 6635, 7635, T4050F, T4050V, T5030, T5040, T5050, T5060, T5070, T7510, T7520, T7530, T7540, T7550, TL70, TL70A, TL80, TL80A, TL90, TL90A, TL100, TL100A, TN55D, TN55S, TN60DA, TN60SA, TN65D, TN65S, TN65V, TN70D, TN70DA, TN70F, TN70S, TN70SA, TN75D, TN75DA, TN75F, TN75FA, TN75S, TN75SA, TN75V, TN80, TN80F, TN85DA, TN85FA, TN90F, TN95DA, TN95F, TN95FA, TN95VA Replaces 82002793 | | | |
|  <p>Expansion Valve Flange Type, O-Ring Connection, R12 and R134a Compatible</p> | AMX10260 | \$ 26.00 | |
| Application: (5640, 6640, 7740, 7840, 8240, 8340 - 1991 and Later), 7840O, 8160, 8260, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115 Replaces F0NN19849AB, 82000932 | | | |
|  <p>Expansion Valve Block Type, R12 and R134a Compatible, O-Ring Connection</p> | AMX10149 | \$ 40.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.





Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | | Part Number | Retail Price | Core |
|---|---|----------------|--------------|------|
| Application: | 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A, T8010, T8020, T8030, T8040, T8050, T8.275, T8.300, (T8.320, T8.380, T8.410, T8.435, T9.480, T9.530, T9.600 - Excluding PLM Intelligence), T8.330, T8.350 Prior to 08/2019, T8.360, T8.390, T8.420, T9020, T9030, T9040, T9050, T9060, T9.390, (T9.435, T9.565, T9.645, T9.700 - Prior to 10/2019), T9.450, T9.505, T9.560, T9.615, T9.670, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530, TL70, TL80, TL90, TL100, TV145, TV6070, Ind: LV80, U80C Tier 4B Replaces 86505794 | | | |
|  | Expansion Valve Block Type, R12 and R134a Compatible, O-Ring Connection | AMX10150 | \$ 27.00 | |
| Application: | FW20, FW30, FW40, FW60 Replaces F3960933, 83906905, 83915986, 83972479 | | | |
|  | Expansion Valve Internally Regulated w/ 12" Capacity Tube w/ Flare Connection, R12 and R134a Compatible | AMX10215 | \$ 31.00 | |
| Application: | TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5010, TD5020, TD5030, TD5050, TM120, TM130, TM140, TM155, TM175, TM190, TS6020, TS6030, TS6.110*, TS6.120*, TS6.125*, TS6.140* *Verify by Serial Number | | | |
|  | Expansion Valve | AM82034858 | \$ 51.00 | |
| Application: | TV140, TV145 Replaces ABPN83308011, F1NN19849AA | | | |
|  | Expansion Valve Block Type, R12 and R134a Compatible, O-Ring Connection | AMX10151 | \$ 24.00 | |
| Application: | 7910, 8000 Series, 8210, 8530, 8630, 8700, 8730, 8830, 9000 Series, TW5, TW10, TW15, TW20, TW25, TW30, TW35 | | | |
|  | Compressor to Condenser Hose | AMD8NN19N601CB | \$ 150.00 | |
| Application: | TL70, TL80, TL90, TL100 | | | |
|  | Compressor to Condenser Hose Replaces 5174142 | AM5176356 | \$ 95.00 | |

Ford®/New Holland®—Tractor








Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: TM120, TM130, TM140, TM155, TM175, TM190 | | | |
|  Compressor to Condenser Hose | AM87303475 | \$ 125.00 | |
| Application: Versatile®: 950, 953 | | | |
| Compressor to Condenser Hose | AMV30155 | \$ 78.00 | |
| Application: T8.275, T8.300, T8.320, T8.330, T8.350, T8.360, T8.380, T8.390, T8.410, T8.420, T8.435 | | | |
|  Receiver Drier to Cab Drier, End Hose | AM47460967 | \$ 57.00 | |
| Application: 5640, 6640, 7740 | | | |
| Receiver Drier to Quick Coupler Hose | AM82008916 | \$ 120.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 | | | |
|  Condenser to Receiver Drier Hose | AM87312057 | \$ 57.00 | |
| Application: T8.380, T8.410, T8.435 | | | |
| Condenser to Receiver Drier Hose | AM84242790 | \$ 69.00 | |
| Application: TL70, TL80, TL90, TL100 | | | |
| Condenser to Receiver Drier Hose | AM5193128 | \$ 77.00 | |
| Application: (5640, 6640, 7740 - w/ Sanden Compressor), TS90, TS100, TS110, TS115 | | | |
|  Return Line, Front Rubber Suction Hose Replaces Original Steel Line Replaces 82009874, 82013168, 82026275 | AMX10283 | \$ 65.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|---------------|--------------|------|
| Application: T8010, T8020, T8030, T8040, T8050, (T9020, T9030, T9040, T9050, T9060 ASN Z7F204001 - w/ 4WD), T8.275, T8.300, (T8.320, T8.350, T8.380, T8.410, T8.435, T9.435, T9.480, T9.530, T9.565, T9.600, T9.700 - Excluding PLM Intelligence), T8.330, T8.360, T8.390, T8.420, T9.390, T9.450, T9.505, T9.560, T9.615, T9.645, T9.670, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 | | | |
|  Liquid Roof Steel Line | AM322840A1 | \$ 57.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, (T9030, T9040, T9050, T9060 ASN Z7F204001), T8.275, T8.300, (T8.320, T8.350, T8.380, T8.410, T8.435, T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 - Excluding PLM Intelligence), T8.330, T8.360, T8.390, T8.420, T9020 4WD, T9.390, T9.450, T9.505, T9.560, T9.615, T9.670, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ480, TJ500, TJ530 | | | |
|  Roof Suction Steel Pipe | AM322839A1 | \$ 105.00 | |
| Application: Versatile®: 750, 800, 825, 835, 850, 855, 875, 895, 935, 950 | | | |
|  Suction Hose, Compressor End | AMV31072 | \$ 68.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A | | | |
|  Blower Motor Update Kit, Heavy Duty 3-Speed Resistor 12 Volt, Mounting Base: 18.50" x 5.50" For models w/ Plastic Blower Housing Replaces F36903, F42775, F45196, F96901 | AMX10304 | \$ 265.00 | |
| Application: 4835, 5635, 6635, 7635, L65, T5040, T5050, T5060, T5070, TL70, TL80, TL80A, TL90, TL90A, TL100, TL100A, TS6020, TS6030 | | | |
|  Blower Motor Assembly 12 Volt Mounting Base Length: 24.625" x 5" 4.50" Overall Height Replaces 82002761, 82004366 | AM90070010 | \$ 250.00 | |
| Application: 5110, 5610, 5900, 6410, 6610, 66100, 6710, 6810, 7410, 7610, 76100, 7710, 7810, 78100, 7910, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 | | | |
|  Blower Motor Assembly 12 Volt, 3-Speed, High Efficiency Replaces 83949905 | AME4NN18456AA | \$ 320.00 | |
| Application: 9030, 9030E, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, TV140, Versatile®: 256, 276, 276-II, 756, 836, 846, 856, 876, 936, 946, 956, 976, 1156 | | | |
|  Blower Motor Assembly | AM9705742 | \$ 259.00 | |







Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Air Conditioning and Components (...continued)

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.







Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 234, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 2810, 2910, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 3910, 3910H, 3910N, 3910R, 3910V, 4100, 4110 01/1981-02/90, 4110N, 4110NO, 4110O, 4110V, 4600, 4600NO, 4600SU, 4610, 4610N, 4610NO, 4610O, 4610SU, 4610V, 5110, 5600, 5610, 5700, 6600, 6600C, 6600O, 6610, 6610O, 6700, 6710, 6810, 7410, 7600, 7600C, 7610, 7700, 7710, 7810, 7810O, 7910, 8000 Series, 8210, 8530, 8630, 8670, (8700, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35 - 1982 and Later), 8730, 8830, 9000 Series, 9030E, 9030V, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884, Ind: 230A, 233, 333, 334, 335, 530A, Versatile®: 256, 276, 276-II, 836, 846, 856, 876, 936, 946, 956, 976, 1156 Replaces 86010530 | | | |
|  Blower Motor, Vented Single Speed, Double Shaft, 2-Wire, Reversible, 3/8" Shaft Diameter, 4 3/8" Long | AMX10118 | \$ 110.00 | |
| Application: 500, 555, 700, 750, 800, 825, 835, 850, 855, 875, 895, 900, 935, 945, 950, 955, 975, Versatile®: 835 1980-84, 875 1981-84, 895, (935, 950 - 1980-82), 945, 955, 975 Replaces V56663, N7389 | | | |
|  Blower Motor 12 Volt, Vented Motor, Reversible Single Speed, 2-Wire Motor w/ 3/8" Shaft | AMX10221 | \$ 115.00 | |
| Application: 5640, 6640, 7740, 7840, 7840O, 8160, 8240, 8260, 8340, 8360, 8560, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115 Replaces 81870361, F0NN18456AA, F0NN18456AB | | | |
|  Blower Motor Double Shaft, 2-Wire, 5/16" Shaft Diameter, 2 1/4" and 2 1/2" Long | AMX10115 | \$ 102.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A Replaces 86508360 | | | |
|  Blower Motor Single Speed, Double Shaft, 2-Wire, Reversible, 5/16" Shaft Diameter, 3 5/8" Long | AMX10111 | \$ 56.00 | |
| Application: FW20, FW30, FW40, FW60 - 1977 and Later Replaces SFD014005T1 | | | |
|  Blower Motor 12 Volt, 3-Speed, Single Shaft, 6-Wire, Reversible, Stud or Strap Mount, 5/16" Shaft Diameter, 1 3/4" Long | AMX10106 | \$ 77.00 | |
| Application: T6020 Tier 3 Elite, T6030*, T6040, T6050 Excluding Delta and Plus, T6060, T6070 Excluding Plus, T6080, T6090, T7030, T7040, T7050, T7060, T7070, T8010, T8020, T8030, T8040, T8050, (T9020, T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 - w/ 4WD), (T9030, T9040, T9050, T9060 ASN Z7F204001), T6.12 5 Excluding MY18, T6.140, T6.145*, T6.150, T6.155*, T6.160, T6.165*, T6.175*, T6.180*, T7.170, T7.175*, T7.185, T7.190, T7.200, T7.210*, T7.220, T7.225 04/2014, T7.230, T7.235, T7.245*, T7.250, T7.260, T7.270, T8.275, T8.300, (T8.320, T8.350 - Prior to 08/2019), T8.330, T8.360, T8.380, T8.390, T8.410*, T8.420, T8.435*, T9.390, T9.450, T9.505, T9.560, T9.615, T9.670, TG215, TG245, TG275, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530 *Verify by Serial Number | | | |
|  Blower Motor Resistor 5 Spade, 3-Speed | AM87306706 | \$ 140.00 | |







Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: (T6030, T6050, T6070, T6080, T6090 SN Z*BK 40001-50000), T7030, T7040, T7050, T7060, T7070, T5.130, T5.140, T6.120, T6.125 (MY18), (T6.140, T6.150 - w/o Auto Command), T6.145*, T6.155*, T6.160*, T6.165*, T6.175*, T6.180, T7.165, T7.165S Stage V, T7.170, T7.175*, T7.185, T7.190*, T7.195S, T7.200, T7.210*, T7.215S, T7.220, T7.225 06/2015 and Later, T7.230*, T7.235, T7.245*, T7.250, T7.260*, T7.270*, T7.275*, T7.290*, T7.315, (T5.100, T5.120 -Excluding Dual Command & Electro Command), (T8.320, T8.350, T8.380, T8.410, T8.435 Excluding PLM Intelligence - Prior to 08/2019), (T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 - w/ MY17) *Verify by Serial Number | | | |
|  Blower Motor Resistor Replaces 84342778 | AM48116714 | \$ 92.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG210, TG215, TG230, TG245, TG255, TG275, TG285, TG305 | | | |
|  Blower Motor Resistor Use w/ AM8422524 | AM401360A1 | \$ 82.00 | |
| Application: 500, 555, 700, 750, 800, 825, 835, 850, 855, 875, 895, 900, 935, 945, 950, 955, 975, Versatile®: 835, (855, 875 - 1981-84), 895, (935, 950 - 1980-84), 945, 975 Replaces V56663, N7389 | | | |
|  Blower Wheel Reversible, Double Vented, Steel Wheel, 3 3/4" Diameter, 4" Long, 3/8" Shaft | AMX10212 | \$ 21.00 | |
| Application: 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 2810, 2910, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 3910, 3910H, 3910N, 3910R, 3910V, 4100, 4110, 4110N, 4110NO, 4110O, 4110V, 4600, 4600NO, 4600O, 4600SU, 4610, 4610N, 4610NO, 4610O, 4610SU, 4610V, 5110, 5600, 5610, 5700, 5900, 6600, 6600C, 6600O, 6610, 6610O, 6700, 6710, 6810, 7410, 7600, 7600C, 7610, 7610O, 7700, 7710, 7810, 7910, 8000 Series, 8210, 8700, 9000 Series, 9700, TW5, TW10, TW15, TW20, TW25, TW30, TW35, Ind: 230A, 233, 234, 333, 334, 335, 530A Replaces D5NN18459A | | | |
|  Blower Wheel, Right Hand, CW Double Vented Steel, 4 1/4" Diameter, 3/8" Shaft, Offset 2 1/4", 3 1/2" | AMX10217 | \$ 30.00 | |
| | AMX10216 | \$ 28.00 | |
| Application: 5110, 5610, 6410, 6610, 6610O, 6710, 6810, 7410, 7610, 7610O, 7710, 7810, 7810O, 7910, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 | | | |
|  Blower Wheel, Steel 3.75" Diameter, 4" Long, 0.375" Shaft, Double Vented Replaces 83953316, E5NN18459AA, E5NN18459BA | AMH84107 | \$ 30.00 | |
| Application: 5640, 6640, 7740, 7840, 8160, 8240, 8260, 8340, 8360, 8560, TD60D, TD70D, TD75D, TD80D, TD90D, TD95D, TD5020, TD5030, TD5050, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS110, TS115, TS6020, TS6030, TS6.110, TS6.120, TS6.125 | | | |
|  Blower Speed Resistor | AM81870363 | \$ 55.00 | |








Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------------|--------------|------|
| Application: 233, 234, 2310, 2600, 2600N, 2600R, 2600V, 2610, 2610V, 2810, 2910, 3600, 3600N, 3600NO, 3600R, 3600V, 3610, 3610NO, 3610V, 3910, 3910H, 3910N, 3910R, 3910V, 4100, 4110, 4110N, 4110NO, 4110O, 4110V, 4600, 4600NO, 4600O, 4600SU, 4610, 4610N, 4610NO, 4610O, 4610SU, 4610V, 5110, 5600, 5610, 5640, 5700, 5900, 6410, 6600, 6600C, 6600O, 6610, 6610O, 6640, 6700, 6710, 6810, 7410, 7600, 7600C, 7610, 7610O, 7700, 7710, 7740, 7810, 7810O, 7840, 7840O, 7910, 8000 Series, 8160, 8210, 8240, 8260, 8340, 8360, 8530, 8560, 8630, 8700, 8730, 8830, 9000 Series, 9700, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90 Emissionised, TS100, TS115, TW5, TW10, TW15, TW20, TW25, TW30, TW35, Ind: 230A, 333, 334, 335, 530A | | | |
|  Blower Motor Switch 3-Speed | AMD5NN15122A | \$ 19.00 | |
| Application: (Boomer 45D, Boomer 50D, Boomer 3040, Boomer 3045, Boomer 3050, Boomer 4055, Boomer 4060, T2310, T2320, T2410, T2420, TC40DA, TC45DA - w/ Cab), Boomer 46D, Boomer 54D | | | |
|  Blower Motor Switch 3-Speed Replaces 168822C1, 168822C2, AH84588 | AMX10261 | \$ 16.00 | |
| Application: 233, 2600, 2600N, 2600R, 2600V, 3600, 3600N, 3600NO, 3600R, 3600V, 4100 1975-81, 4600, 4600NO, 4600O, 4600SU, 5110, 5600, 5610, 5700, 5900, 6410, 6600, 6600C, 6600O, 6610, 6610O, 6700, 6710, 6810, 7410, 7600, 7600C, 7610, 7610O, 7700, 7710, 7910, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35, Ind: 333 | | | |
|  Condenser w/ Oil Cooler Core: 16 3/8" x 19" x 2" | AME1NN19N656BA15M | \$ 275.00 | |
| Application: 4835, 5635, 6635, 7635, L65, TL70, TL80, TL90, TL100 | | | |
|  Condenser Core: 19.25" x 15.75" x 2" | AM5166770 | \$ 434.00 | |
| Application: 5610, 6610, 7610, 7810 | | | |
|  Condenser Overall: 15 3/4" x 13 1/2" Core: 13" x 11" x 2 1/2" | AME0NN19710AB | \$ 395.00 | |
| Application: 5640, 6640, 7740, 7840, 7840O, 8240, 8340, (TS90, TS110 - 11/1997-09/03), TS100, TS115 | | | |
|  Condenser Overall: 20.375" x 14.50" Core: 18" x 12" x 2.50" 3 Rows | AM84468607 | \$ 460.00 | |









Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|----------------|--------------|------|
| Application: 5640, 6640, 7740, 7840, 8240, 8340  Condenser Core: 12" x 18" x 2.50" Overall: 14" x 20.375" 3 Rows Replaces 82000923 | AMF0NN19710BD | \$ 355.00 | |
| Application: 7910, 8000 Series, 8210, 8730, 8830, 9000 Series, (8530, 8630, 8700, 9700 - 1979 and Later), (TW5, TW10, TW15, TW20, TW25, TW30, TW35 - 1979 and Later w/ Cooler)  Condenser Overall: 23" x 18" x 19" Core: 18" x 2.75" | AME5NN19N656BA | \$ 520.00 | |
| Application: 8000 Series, 8210, 8530, 8630, 8700, 8830, 9000 Series, TW5, TW10, TW15, TW20, TW25, TW30, TW35 - 1983-89 w/o Oil Cooler  Condenser w/o Oil Cooler Overall: 22 1/8" x 9" Core: 17 1/2" x 9" x 2" | AMD8NN19710BB | \$ 315.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A - w/ Condenser in Front of Oil Cooler  Condenser Core: 21 1/2" x 26" x 1 1/4" | AM86501402 | \$ 520.00 | |
| Application: 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884  Condenser Overall: 31.375" x 2.875" Core: 28.50" x 17" x 1.75" 2 Rows | AM86012467 | \$ 625.00 | |
| Application: PowerStar™ 65, PowerStar™ 75, T5040, T5050, T5060, T5070, T4.55, T4.65, T4.75  Condenser Serpentine Style Rows Core: 19" x 14" x 1.25" | AM87542953 | \$ 245.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080  Condenser Overall: 21.25" x 19.50" Core: 15.625" x 20.50" x 0.875" Parallel Flow | AM84158364 | \$ 410.00 | |









Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: T6010, (T6020, T6030 - Excluding Elite), TS100A, TS110A, TS115A, TS125A, TS130A, TS135A, TS6020, TS6030 | | | |
|  <p>Condenser Replaces 82022311, 82035720, 87532909</p> | AM84156148 | \$ 350.00 | |
| Application: (T6020, T6030, T6040, T6050 - Tier 3 Elite), T6050, T6060, T6070, T6080 | | | |
|  <p>Condenser Core: 15.625" x 20.50" x 0.875" Replaces 87574212</p> | AM87641371 | \$ 383.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, TG215, TG245, TG275, TG305 | | | |
|  <p>Condenser w/ Fuel Cooler</p> | AM87360035 | \$ 420.00 | |
| Application: T8.380*, T8.410*, T8.435* *Verify by Serial Number | | | |
|  <p>Condenser w/ Fuel Cooler Overall: 30 5/8" x 16 3/4" Core: 24 3/4" x 13" x 2 5/8" 3 Rows</p> | AM84345653 | \$ 359.50 | |
| Application: T9010, T9020, T9030, T9040, T9050, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ500 | | | |
|  <p>Condenser</p> | AM87315600 | \$ 608.00 | |
| Application: T9.615, T9.670 | | | |
|  <p>Condenser</p> | AM84210956 | \$ 935.00 | |
| Application: TD60D, TD70D, TD75D, TD80D, TD90D, TD95D | | | |
|  <p>Condenser Core: 18" x 12" x 2.75" Replaces 5094971, 5096603</p> | AM84215855 | \$ 375.00 | |
| Application: (TD70D, TD80D, TD90D, TD95D - Tier 2), TD95DHC, TD5010, TD5020, TD5030, TD5050, TD5.75 | | | |
|  <p>Condenser Core: 15.50" x 20" x 1.25" Non-Serviceable Must Use Original Mounting Brackets Serpentine Style Rows</p> | AM84342887 | \$ 370.00 | |

Ford®/New Holland®—Tractor







Air Conditioning and Components (...continued)

| Description | Part Number | Retail Price | Core |
|--|----------------|--------------|------|
| Application: TL70A, TL80A, TL90A, TL100A  | | | |
| Condenser Core: 21" x 18.75" x 1.75" Overall: 22" x 20.50" 4 Rows | AM47132050 | \$ 560.00 | |
| Application: TM120, TM130, TM140, TM155, TM175, TM190 Replaces 82019424, 82019425, 82023592  | | | |
| Condenser Core: 20" x 2 3/4" x 11 3/4" | AM82033407 | \$ 380.00 | |
| Application: 234, 9184, 9280, 9282, 9384, 9480, 9482, 9484, 9680, 9682, 9684, 9880, 9882, 9884  | | | |
| Evaporator w/ Heater Core Block Type Valve | AM86012468 | \$ 625.00 | |
| Application: 2600, 3600, 4100 12/1974 and Later, 4600, 4600SU, 5600, 5700, 6600, 6700, 7600, 7700, 8000, 8700, 9000, 9700, TW10, TW20, TW30  | | | |
| Evaporator w/ Heater Coil Replaces D5NN18N315A, D5NN18N315B | AMD5NN18N315C | \$ 355.00 | |
| Application: (5110, 5610, 6610, 6710, 6810, 7410, 7610, 7710, 7910, 8210 - 1981-09/85), 8700, 9700, TW10, TW20, (TW5, TW15, TW25, TW35 - 1982-85)  | | | |
| Evaporator Bulb Type Valve Overall: 30 3/4" x 6 1/4" x 6 1/2" Core: 19" x 6" x 4 3/8" | AME0NN18N315AA | \$ 315.00 | |
| Application: (5110, 5610, 6610, 6710, 6810, 7410, 7610, 7710, 7910, 8210, 8530, 8630, 8730, 8830, TW5, TW15, TW25, TW35 - 10/1985 and Later), 7810 02/1988 and Later  | | | |
| Evaporator w/ Heater Core Bulb Type Valve Core: 19" x 4 1/2" x 6" Overall: 27 1/2" x 6" x 8 1/2" | AME4NN18N315AD | \$ 917.00 | |
| Application: 5640, 6640, 7740, 7840, 78400, 8160, 8240, 8260, 8340, 8360, 8560, TD60D, TD70D, TD75D, TD80D, TD90D, TD95D 11/2002-14, TD5010, TD5020, TD5030, TD5050, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90 Emissionised, TS100, TS110, TS115, TS6020, TS6030  | | | |
| Evaporator Core: 25 1/2" x 5" Replaces 82034855 | AM82009238 | \$ 350.00 | |
| Application: 5640, 6640, 7740, 7840, 8160, 8240, 8260, 8340, 8360, 8560, TD60D, TD70D, TD75D, TD80D, TD90D, TD95D Prior to 2014, TD5010, TD5020, TD5030, TD5050, TM115, TM120, TM125, TM130, TM135, TM140, TM150, TM155, TM165, TM175, TM190, TS90, TS100, TS110, TS115, TS6020, TS6030  | | | |
| Evaporator Core: 25 1/2" x 3 1/8" x 5" | AM82034855 | \$ 357.00 | |

Prices Subject to Change without Prior Notice. The use of original equipment manufacturer (OEM) part numbers or trademarks, e.g. Case® and John Deere®, are for reference purposes only and for indicating product use and compatibility. Our company and the listed replacement parts contained herein are not sponsored, approved or manufactured by the OEM. All parts are New unless designated Reman in the description.

Ford®/New Holland®—Tractor

Air Conditioning and Components (...continued)


| Description | Part Number | Retail Price | Core |
|---|-------------|--------------|------|
| Application: 8670, 8670A, 8770, 8770A, 8870, 8870A, 8970, 8970A  Evaporator Block Type Valve Core: 3.125" x 23.50" x 6" Overall: 5" x 28" 6.125" | AM86505779 | \$ 245.00 | |
| Application: 8670, 8670A, 8770, 8770A, 8870, 8970, 8970A - 06/1996 and Later  Evaporator Block Type Valve Overall: 27 3/4" x 3 1/8" x 6" Core: 23 3/8" x 3 1/8" x 6" | AM86014818 | \$ 260.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A, T6.120, T6.125 Excluding MY18, (T6.140, T6.150, T6.160 - Excluding Auto Command), T6.145 Tier 4B 03/2015-01/18, T6.155*, T6.165*, T6.175*, T6.180*, T7.170, T7.185, T7.200, T7.210*, T7.220, T7.235, T7.250, T7.270 *Verify by Serial Number  Evaporator Core: 18 3/4" x 5" x 6 3/4" | AM82033007 | \$ 356.00 | |
| Application: T6010, T6020, T6030, T6040, T6050, T6060, T6070, T6080, T6090, T7030, T7040, T7050, T7060, T7070, (T5.110, T5.120 - Auto Command Stage V and Dynamic Command Stage V), T5.130, T5.140, T6.120, T6.125, T6.140, T6.145, T6.150, T6.155, T6.160, T6.165, T6.175, T6.180, T7.165, T7.170, T7.175, T7.185, T7.190, T7.195S, T7.200, T7.210, T7.215S, T7.220, T7.225, T7.230, T7.235, T7.245, T7.250, T7.260, T7.270, T7.275, T7.290, T7.315, TS100A, TS110A, TS115A, TS125A, TS130A, TS135A  Evaporator Core: 18 1/2" x 3 3/4" x 5" | AM82033008 | \$ 265.00 | |
| Application: T8010, T8020, T8030, T8040, T8050, T9020 4WD, (T9030, T9040, T9050, T9060 ASN Z7F204001), T8.275, T8.300, (T8.320, T8.350, T8.380, T8.390, T8.410, T9.390 - Prior to 08/2019), T8.330, T8.360, T8.420, T8.435 04/2014-08/19, (T9.435, T9.480, T9.530, T9.565, T9.600, T9.645, T9.700 - Excluding PLM Intelligence), T9.450, T9.505, T9.560, T9.615, T9.670, TG215, TG245, TG275, TG305, TJ275, TJ280, TJ325, TJ330, TJ375, TJ380, TJ425, TJ430, TJ450, TJ480, TJ500, TJ530  Evaporator | AM86990262 | \$ 347.00 | |
| Application: TG210, TG230, TG255, TG285  Evaporator w/ Heater Core | AM86990263 | \$ 455.00 | |

Ford®/New Holland®—Tractor

Shop Manuals and Collections

| Description | Part Number | Retail Price | Core |
|--|-------------|--------------|------|
| Application: Series: 2N, 8N, 9N | | | |
| Ford® | IT-FO-4 | \$ 34.00 | |
| Application: Models: NAA | | | |
| Ford® | IT-FO-19 | \$ 34.00 | |
| Application: Series: 501, 600, 601, 700, 701, 800, 801, 900, 1801, (2000, 4000 - w/ 4 Cylinder Engines) | | | |
| Ford® | IT-FO-20 | \$ 34.00 | |
| Application: Series: (2000, 3000, 4000 - w/ 3 Cylinder Engines) Covers Models Prior to 1975 | | | |
| Ford® | IT-FO-31 | \$ 34.00 | |
| Application: Models: 2310, 2600, 2610, 3600, 3610, 4100 1974 and Later, 4110, 4600, 4610 Prior to 1984, 4600SU, 4610SU Prior to 1984 | | | |
| Ford® | IT-FO-41 | \$ 34.00 | |
| Application: Series: 5000, 5600, 5610, 6600, 6610, 6700, 6710, 7000, 7600, 7610, 7700, 7710 | | | |
| Ford® | IT-FO-42 | \$ 34.00 | |
| Application: Models: 1100, 1110, 1200, 1210, 1300, 1310, 1500, 1510, 1700, 1710, 1900, 1910, 2110 | | | |
| Ford® | IT-FO-44 | \$ 34.00 | |
| Application: Models: TW5, TW15, TW25, TW35 | | | |
| Ford® | IT-FO-45 | \$ 34.00 | |
| Application: Models: 1120, 1220, 1320, 1520, 1720, 1920, 2120 | | | |
| Ford® | IT-FO-46 | \$ 34.00 | |
| Application: Models: 3230, 3430, 3930, 4630, 4830 | | | |
| Ford® | IT-FO-47 | \$ 34.00 | |
| Application: Models: 2000 Super Dexta, 5000 Super Major, Commander 6000, Fordson Dexta, Fordson Super Dexta, Fordson Major Diesel, Fordson Power Major, Fordson Super Major, New Performance Fordson Major, New Performance Super Dexta, TW10, TW20, TW30, Series: 1000, 1600, 6000, 8000, 8600, 8700, 9000, 9600, 9700 | | | |
| Ford Collection® | IT-FO-201 | \$ 34.00 | |
| Application: Models: 5640, 6640, 7740, 7840, 8240, 8340 | | | |
| Ford® | IT-FO-48 | \$ 34.00 | |

Air Conditioning Parts and Components



**Blower Motors • Compressors • Condensers
Evaporators • Expansion Valves • Receiver Driers**

LEDs Light Up Your World

LEDs are extremely energy efficient & more durable than traditional incandescent light bulbs. Other benefits include a much longer lifespan, reduced maintenance costs and higher safety.



**LED kits and single replacement lights available for tractors, combines,
harvesters, balers, loaders, skid steers, telehandlers and more.**

Abilene Machine LLC


Family-Owned Since 1980



As one of the largest and most innovative ag replacement parts companies, getting you the parts you need is a responsibility we take seriously. We stock more than 40,000 new, used and remanufactured parts at 4 locations nationwide.

Rims are Available

For Ford®/New Holland® Tractors



Single Rims

Dual Rims





Ag Replacement Parts

Honest. Personal. Service.

Engine Overhaul Kits and Parts

To succeed, farms depend on their equipment's ability to perform day-in, day-out. Make sure your engine is up to the task. Whether you need to make a quick repair or want to fine-tune your entire engine, we can help with our extensive inventory of high-quality overhaul kits and engine parts.

Multiple Options

We offer a wide variety of overhaul kits to fit any need. Our kits cover diesel and gas machines and are built to fit most makes, including John Deere®, Case IH®, International®, Ford®, New Holland®, Allis Chalmers® and more. We offer remanufactured shortblocks and longblocks. We also carry inframe and complete remanufactured engines, as well as used engines to fit any need and budget.

Components

Our high-quality component parts are thoroughly tested and competitively priced. Kits range from basic to comprehensive and may include:

- Cylinder kits
- Piston pin bushings
- Rod bearings
- Main bearings
- Camshaft bushings
- Camshaft plug
- Front and rear crankshaft seals
- Gasket set with seals
- Connecting rod bolts

One-Year Warranty

Abilene Machine offers a standard one-year warranty on new, used and remanufactured parts for peace of mind.

Abilene Machine is a family-owned and operated company that's been serving farmers for over 40 years. With an inventory of more than 40,000 parts and four locations across the United States, we'll make sure you get dependable, durable parts shipped fast.

Abilene, Kansas
Bishopville, South Carolina
Sioux Falls, South Dakota
Billings, Montana

785-670-6741

AbileneMachine.com


All parts are new unless designated remanufactured in the description. Products listed are replacement parts only — not original equipment manufacturers. OEM names and brands are used for identification purposes only.

Grammer® Seat Identification Guide

Grammer® seats are ultimately designed for the people who use them, with maximum comfort and intuitive operation being major design principles. After all, the operator shouldn't fit the seat; the seat should fit the operator.

We offer several seat options – including the 721, 731, 741 and 742 shown below – with more available online. Let us help you easily pick the best fit by reviewing the seat number identification guide and determining your seating needs!

7 2 1



| Type of Seat Top | Width of Seat Cushion | Height of Backrest |
|------------------------|---------------------------|-----------------------|
| 3 = 1 Pan (Gator Seat) | 1 = Narrow, 15.70"-17.70" | 1 = Low Back, 17.70" |
| 5 = Small, 2-Part Seat | 2 = Medium, 15.70"-19.50" | 2 = High Back, 20.50" |
| 7 = Large, 2-Part Seat | 3 = Wide, 19.50"-21.30" | |
| | 4 = Extra Wide, 21.30"+ | |



731



741



742



Abilene Machine LLC

785-670-6741 | AbileneMachine.com

Kansas | Montana | South Carolina | South Dakota

Notes

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.



Ag Replacement Parts

Honest. Personal. Service.



Grammer® Seats

You spend a lot of time in your cab, and having high-quality seating is about more than being comfortable. It's about protecting your back and keeping you going. Whether you need to make a repair or want a plug-and-play replacement, we can help with our extensive inventory of Grammer® seats.

Grammer® seats are the gold standard for cab seats. These extremely durable seats are plug-and-play, so you can easily install them and get back in the field. We offer models with mechanical and air ride suspensions, so you can find a seat that fits you (and your farm equipment) perfectly.

We also offer buddy seats, assemblies and individual components including cushions, suspensions and

additional replacement parts. We have you covered for many makes and models, including John Deere®, Case IH®, International®, New Holland®, Bobcat® and more.

For more than 40 years, Abilene Machine has been helping distributors, dealers and repair shops like yours succeed by providing top-rated parts at great prices — all with exceptional service. See how our family-owned company can help your business grow.

Abilene, Kansas
Bishopville, South Carolina
Sioux Falls, South Dakota
Billings, Montana

785-670-6741
AbileneMachine.com

All parts are new unless designated remanufactured in the description. Products listed are replacement parts only — not original equipment manufacturers. OEM names and brands are used for identification purposes only.



Abilene Machine LLC
P.O. Box 129
Abilene, KS 67410
(785) 670-6741

Honest. Personal. Service.



Abilene Machine LLC
(785) 670-6741



AbileneMachine.com

©2024 Abilene Machine LLC. Abilene Machine® is a registered trademark of Abilene Machine LLC.

 Follow Abilene Machine
on Facebook

November 2024